

10-3FL., No. 31-1, Lane 169, Kang Ning St., Hsi Chih City, Taipei Hsien 221, Taiwan R.O.C. TEL: 886-2-2695-2378

FAX: 886-2-2695-7078

PIFA Antenna Report

Prepared by

ALLIS COMMUNICATIONS CO., LTD.

10-3Fl, NO. 31-1, Lane 169, Kang Ning St., Hsi Chih City,

Taipei Hsien 221, Taiwan R.O.C.



10-3FL., No. 31-1, Lane 169, Kang Ning St., Hsi Chih City, Taipei Hsien 221, Taiwan R.O.C. TEL: 886-2-2695-2378

FAX: 886-2-2695-7078

1. TEST CONDITIONS

Tested By: Ivan Chang Date: December 19, 2007

Test Equipment: HP 8722D Network Analyzer

NSI Spherical near-field measurement system

2. TEST RESULT


Result List

Item	Peak Gain
V-CUT	-4.573dB
H-CUT	-3.007dB

PS: (1) AR: Axial Ratio.

V-CUT : Z-Y H-CUT : X-Y

Diagrams







10-3FL., No. 31-1, Lane 169, Kang Ning St., Hsi Chih City, Taipei Hsien 221, Taiwan R.O.C. TEL: 886-2-2695-2378

FAX: 886-2-2695-7078

H-CUT Polar plot



H-CUT






10-3FL., No. 31-1, Lane 169, Kang Ning St., Hsi Chih City, Taipei Hsien 221, Taiwan R.O.C. TEL: 886-2-2695-2378

FAX: 886-2-2695-7078

V-CUT Polar plot



V-CUT

