


## **Appendix 1**

**Test Results** 





### 20dB Bandwidth

Tx frequency: 2410MHz



Date: 3.AUG.2010 14:58:51






Date: 3.AUG.2010 14:33:09




#### Tx frequency: 2481MHz



Date: 3.AUG.2010 14:44:18




# Band Edge Compliance Tx frequency: 2410MHz (radiated measurement)



STALBUER / 120011 / 00100716096-001/ CAR RX 2410MHz / VERT. Date: 29.JUL.2010 15:00:17






STALBUER / 120011 / 00100716096-001/ CAR RX 2410MHz / HORI.

Date: 29.JUL.2010 15:01:46




Tx frequency: 2481MHz (radiated measurement)



STALBUER / 120011 / 00100716096-003/ CAR RX 2480MHz / VERT.

Date: 29.JUL.2010 15:28:20





STALBUER / 120011 / 00100716096-003/ CAR RX 2480MHz / HORI.

Date: 29.JUL.2010 15:29:30