Registration number: W6M21903-18857-C-1

FCC ID: YY3-182010


## **Appendix**

## **Measurement diagrams**

Spurious Emissions radiated



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 183.5671           | 46.34             | peak     | -10.75                 | 35.59              | 43.50             | 100             | 245               | -7.91          |         |
|     | 276.8737           | 42.73             | peak     | -6.18                  | 36.55              | 46.00             | 100             | 150               | -9.45          |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 32.6808            | 46.12             | QP       | -8.36                  | 37.76              | 40.00             | 100             | 50                | -2.24          |         |
|     | 183.5671           | 43.74             | peak     | -10.75                 | 32.99              | 43.50             | 100             | 35                | -10.51         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH1


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4824.000           | 45.21             | peak     | 0.73                   | 45.94              | 74.00             | 150             | 230               | -28.06         |         |
|     | 7236.000           | 40.49             | peak     | 5.42                   | 45.91              | 74.00             | 150             | 110               | -28.09         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4824.013           | 53.09             | peak     | 0.73                   | 53.82              | 74.00             | 150             | 214               | -20.18         |         |
| *   | 4824.013           | 45.08             | AVG      | 0.73                   | 45.81              | 54.00             | 150             | 214               | -8.19          |         |
|     | 7236.000           | 39.97             | peak     | 5.42                   | 45.39              | 74.00             | 150             | 110               | -28.61         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9648.000           | 35.65             | peak     | 8.28                   | 43.93              | 74.00             | 150             | 90                | -30.07         |         |
| *   | 12060.000          | 34.52             | peak     | 14.17                  | 48.69              | 74.00             | 150             | 305               | -25.31         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9648.000           | 36.47             | peak     | 8.28                   | 44.75              | 74.00             | 150             | 65                | -29.25         |         |
| *   | 12060.000          | 35.35             | peak     | 14.17                  | 49.52              | 74.00             | 150             | 130               | -24.48         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |  |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|--|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |  |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH6


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4874.000           | 41.31             | peak     | 0.69                   | 42.00              | 74.00             | 150             | 80                | -32.00         |         |
| *   | 7311.000           | 40.20             | peak     | 5.57                   | 45.77              | 74.00             | 150             | 130               | -28.23         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4873.748           | 48.08             | peak     | 0.69                   | 48.77              | 74.00             | 150             | 265               | -25.23         |         |
|     | 7311.000           | 40.82             | peak     | 5.57                   | 46.39              | 74.00             | 150             | 230               | -27.61         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.14             | peak     | 8.57                   | 43.71              | 74.00             | 150             | 65                | -30.29         |         |
| *   | 12185.000          | 33.12             | peak     | 15.16                  | 48.28              | 74.00             | 150             | 140               | -25.72         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 34.69             | peak     | 8.57                   | 43.26              | 74.00             | 150             | 50                | -30.74         |         |
| *   | 12185.000          | 33.69             | peak     | 15.16                  | 48.85              | 74.00             | 150             | 110               | -25.15         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH6


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH6


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH11


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4921.844           | 46.14             | peak     | 0.71                   | 46.85              | 74.00             | 150             | 315               | -27.15         |         |
|     | 7386.000           | 39.73             | peak     | 5.99                   | 45.72              | 74.00             | 150             | 220               | -28.28         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4921.844           | 46.61             | peak     | 0.71                   | 47.32              | 74.00             | 150             | 60                | -26.68         |         |
|     | 7386.000           | 40.06             | peak     | 5.99                   | 46.05              | 74.00             | 150             | 235               | -27.95         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 35.76             | peak     | 9.27                   | 45.03              | 74.00             | 150             | 65                | -28.97         |         |
| *   | 12310.000          | 34.87             | peak     | 14.62                  | 49.49              | 74.00             | 150             | 195               | -24.51         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 35.73             | peak     | 9.27                   | 45.00              | 74.00             | 150             | 190               | -29.00         |         |
| *   | 12310.000          | 33.95             | peak     | 14.62                  | 48.57              | 74.00             | 150             | 305               | -25.43         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH11


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH11


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4824.000           | 42.20             | peak     | 0.73                   | 42.93              | 74.00             | 150             | 40                | -31.07         |         |
| *   | 7236.000           | 40.60             | peak     | 5.42                   | 46.02              | 74.00             | 150             | 170               | -27.98         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4824.000           | 43.34             | peak     | 0.73                   | 44.07              | 74.00             | 150             | 65                | -29.93         |         |
| *   | 7236.000           | 40.42             | peak     | 5.42                   | 45.84              | 74.00             | 150             | 140               | -28.16         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9648.000           | 35.13             | peak     | 8.28                   | 43.41              | 74.00             | 150             | 225               | -30.59         |         |
| *   | 12060.000          | 34.30             | peak     | 14.17                  | 48.47              | 74.00             | 150             | 180               | -25.53         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9648.000           | 36.36             | peak     | 8.28                   | 44.64              | 74.00             | 150             | 230               | -29.36         |         |
| *   | 12060.000          | 34.46             | peak     | 14.17                  | 48.63              | 74.00             | 150             | 165               | -25.37         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH1

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

Test Mode: TX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11g CH6


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH6

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4874.000           | 41.67             | peak     | 0.69                   | 42.36              | 74.00             | 150             | 45                | -31.64         |         |
| *   | 7311.000           | 40.77             | peak     | 5.57                   | 46.34              | 74.00             | 150             | 270               | -27.66         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4873.748           | 44.22             | peak     | 0.69                   | 44.91              | 74.00             | 150             | 80                | -29.09         |         |
| *   | 7311.000           | 40.82             | peak     | 5.57                   | 46.39              | 74.00             | 150             | 35                | -27.61         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.95             | peak     | 8.57                   | 44.52              | 74.00             | 150             | 65                | -29.48         |         |
| *   | 12185.000          | 33.71             | peak     | 15.16                  | 48.87              | 74.00             | 150             | 305               | -25.13         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.31             | peak     | 8.57                   | 43.88              | 74.00             | 150             | 265               | -30.12         |         |
| *   | 12185.000          | 33.47             | peak     | 15.16                  | 48.63              | 74.00             | 150             | 140               | -25.37         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH6

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH6

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH11

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4924.000           | 41.33             | peak     | 0.71                   | 42.04              | 74.00             | 150             | 70                | -31.96         |         |
| *   | 7386.000           | 40.48             | peak     | 5.99                   | 46.47              | 74.00             | 150             | 145               | -27.53         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4921.844           | 44.10             | peak     | 0.71                   | 44.81              | 74.00             | 150             | 305               | -29.19         |         |
| *   | 7386.000           | 40.26             | peak     | 5.99                   | 46.25              | 74.00             | 150             | 240               | -27.75         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 34.95             | peak     | 9.27                   | 44.22              | 74.00             | 150             | 65                | -29.78         |         |
| *   | 12310.000          | 34.13             | peak     | 14.62                  | 48.75              | 74.00             | 150             | 130               | -25.25         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 35.12             | peak     | 9.27                   | 44.39              | 74.00             | 150             | 60                | -29.61         |         |
| *   | 12310.000          | 34.89             | peak     | 14.62                  | 49.51              | 74.00             | 150             | 300               | -24.49         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH11

Note:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical


EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11g CH11

Note:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 181.6232           | 46.83             | peak     | -10.77                 | 36.06              | 43.50             | 100             | 210               | -7.44          |         |
|     | 282.7054           | 42.32             | peak     | -5.97                  | 36.35              | 46.00             | 100             | 95                | -9.65          |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 30.0000            | 46.12             | peak     | -8.01                  | 38.11              | 40.00             | 100             | 25                | -1.89          |         |
|     | 181.6232           | 43.66             | peak     | -10.77                 | 32.89              | 43.50             | 100             | 70                | -10.61         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment | l |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|---|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |   |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4785.571           | 42.90             | peak     | 0.72                   | 43.62              | 74.00             | 150             | 45                | -30.38         |         |
| *   | 7236.000           | 40.48             | peak     | 5.42                   | 45.90              | 74.00             | 150             | 215               | -28.10         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4801.603           | 43.15             | peak     | 0.75                   | 43.90              | 74.00             | 150             | 40                | -30.10         |         |
| *   | 7236.000           | 41.27             | peak     | 5.42                   | 46.69              | 74.00             | 150             | 215               | -27.31         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9648.000           | 35.42             | peak     | 8.28                   | 43.70              | 74.00             | 150             | 55                | -30.30         |         |
| *   | 12060.000          | 34.75             | peak     | 14.17                  | 48.92              | 74.00             | 150             | 280               | -25.08         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9648.000           | 35.36             | peak     | 8.28                   | 43.64              | 74.00             | 150             | 65                | -30.36         |         |
| *   | 12060.000          | 34.82             | peak     | 14.17                  | 48.99              | 74.00             | 150             | 305               | -25.01         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH6


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4874.000           | 41.42             | peak     | 0.69                   | 42.11              | 74.00             | 150             | 265               | -31.89         |         |
| *   | 7311.000           | 40.23             | peak     | 5.57                   | 45.80              | 74.00             | 150             | 180               | -28.20         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4874.000           | 41.32             | peak     | 0.69                   | 42.01              | 74.00             | 150             | 230               | -31.99         |         |
| *   | 7311.000           | 40.08             | peak     | 5.57                   | 45.65              | 74.00             | 150             | 65                | -28.35         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.10             | peak     | 8.57                   | 43.67              | 74.00             | 150             | 40                | -30.33         |         |
| *   | 12185.000          | 33.97             | peak     | 15.16                  | 49.13              | 74.00             | 150             | 230               | -24.87         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.49             | peak     | 8.57                   | 44.06              | 74.00             | 150             | 80                | -29.94         |         |
| *   | 12185.000          | 33.09             | peak     | 15.16                  | 48.25              | 74.00             | 150             | 115               | -25.75         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH6


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH6


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH11


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4924.000           | 41.71             | peak     | 0.71                   | 42.42              | 74.00             | 150             | 40                | -31.58         |         |
| *   | 7386.000           | 40.64             | peak     | 5.99                   | 46.63              | 74.00             | 150             | 170               | -27.37         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4924.000           | 40.99             | peak     | 0.71                   | 41.70              | 74.00             | 150             | 90                | -32.30         |         |
| *   | 7386.000           | 40.74             | peak     | 5.99                   | 46.73              | 74.00             | 150             | 65                | -27.27         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 35.92             | peak     | 9.27                   | 45.19              | 74.00             | 150             | 90                | -28.81         |         |
| *   | 12310.000          | 34.65             | peak     | 14.62                  | 49.27              | 74.00             | 150             | 305               | -24.73         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 34.64             | peak     | 9.27                   | 43.91              | 74.00             | 150             | 265               | -30.09         |         |
| *   | 12310.000          | 33.86             | peak     | 14.62                  | 48.48              | 74.00             | 150             | 305               | -25.52         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH11


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11b CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11b CH11


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH1

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4824.000           | 47.33             | peak     | 0.73                   | 48.06              | 74.00             | 150             | 225               | -25.94         |         |
|     | 7236.000           | 40.56             | peak     | 5.42                   | 45.98              | 74.00             | 150             | 130               | -28.02         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4824.212           | 58.43             | peak     | 0.73                   | 59.16              | 74.00             | 150             | 260               | -14.84         |         |
| *   | 4824.212           | 44.09             | AVG      | 0.73                   | 44.82              | 54.00             | 150             | 260               | -9.18          |         |
|     | 7236.000           | 40.46             | peak     | 5.42                   | 45.88              | 74.00             | 150             | 215               | -28.12         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9648.000           | 36.18             | peak     | 8.28                   | 44.46              | 74.00             | 150             | 90                | -29.54         |         |
| *   | 12060.000          | 35.95             | peak     | 14.17                  | 50.12              | 74.00             | 150             | 65                | -23.88         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9648.000           | 35.30             | peak     | 8.28                   | 43.58              | 74.00             | 150             | 66                | -30.42         |         |
| *   | 12131.263          | 36.20             | peak     | 14.87                  | 51.07              | 74.00             | 150             | 220               | -22.93         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH1

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11g CH6


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4865.731           | 47.23             | peak     | 0.70                   | 47.93              | 74.00             | 150             | 80                | -26.07         |         |
|     | 7311.000           | 40.61             | peak     | 5.57                   | 46.18              | 74.00             | 150             | 95                | -27.82         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4873.748           | 49.67             | peak     | 0.69                   | 50.36              | 74.00             | 150             | 65                | -23.64         |         |
|     | 7311.000           | 40.74             | peak     | 5.57                   | 46.31              | 74.00             | 150             | 80                | -27.69         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.53             | peak     | 8.57                   | 44.10              | 74.00             | 150             | 115               | -29.90         |         |
| *   | 12185.000          | 33.70             | peak     | 15.16                  | 48.86              | 74.00             | 150             | 240               | -25.14         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.65             | peak     | 8.57                   | 44.22              | 74.00             | 150             | 140               | -29.78         |         |
| *   | 12185.000          | 33.02             | peak     | 15.16                  | 48.18              | 74.00             | 150             | 220               | -25.82         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH6

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

Test Mode: TX 802.11g CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH11

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4921.844           | 47.21             | peak     | 0.71                   | 47.92              | 74.00             | 150             | 305               | -26.08         |         |
|     | 7386.000           | 40.18             | peak     | 5.99                   | 46.17              | 74.00             | 150             | 240               | -27.83         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4921.844           | 49.10             | peak     | 0.71                   | 49.81              | 74.00             | 150             | 230               | -24.19         |         |
|     | 7386.000           | 40.50             | peak     | 5.99                   | 46.49              | 74.00             | 150             | 195               | -27.51         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 35.09             | peak     | 9.27                   | 44.36              | 74.00             | 150             | 65                | -29.64         |         |
| *   | 12310.000          | 34.43             | peak     | 14.62                  | 49.05              | 74.00             | 150             | 120               | -24.95         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 36.39             | peak     | 9.27                   | 45.66              | 74.00             | 150             | 80                | -28.34         |         |
| *   | 12310.000          | 34.47             | peak     | 14.62                  | 49.09              | 74.00             | 150             | 135               | -24.91         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH11

Note:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11g CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: TX 802.11g CH11

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 2375.170           | 63.45             | peak     | -4.29                  | 59.16              | 74.00             | 150             | 13                | -14.84         |         |
| *   | 2375.170           | 46.81             | AVG      | -4.29                  | 42.52              | 54.00             | 150             | 13                | -11.48         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4824.000           | 46.57             | peak     | 0.73                   | 47.30              | 74.00             | 150             | 65                | -26.70         |         |
|     | 7236.000           | 40.73             | peak     | 5.42                   | 46.15              | 74.00             | 150             | 235               | -27.85         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4822.729           | 58.10             | peak     | 0.73                   | 58.83              | 74.00             | 150             | 249               | -15.17         |         |
| *   | 4822.729           | 43.26             | AVG      | 0.73                   | 43.99              | 54.00             | 150             | 249               | -10.01         |         |
|     | 7236.000           | 41.14             | peak     | 5.42                   | 46.56              | 74.00             | 150             | 135               | -27.44         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9894.289           | 37.19             | peak     | 9.68                   | 46.87              | 74.00             | 150             | 90                | -27.13         |         |
| *   | 12060.000          | 34.78             | peak     | 14.17                  | 48.95              | 74.00             | 150             | 355               | -25.05         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9648.000           | 36.95             | peak     | 8.28                   | 45.23              | 74.00             | 150             | 65                | -28.77         |         |
| *   | 12060.000          | 34.55             | peak     | 14.17                  | 48.72              | 74.00             | 150             | 230               | -25.28         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n20 CH1


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n20 CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n20 CH6


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4873.748           | 48.07             | peak     | 0.69                   | 48.76              | 74.00             | 150             | 115               | -25.24         |         |
|     | 7311.000           | 40.17             | peak     | 5.57                   | 45.74              | 74.00             | 150             | 280               | -28.26         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4872.746           | 59.47             | peak     | 0.69                   | 60.16              | 74.00             | 150             | 240               | -13.84         |         |
| *   | 4872.746           | 44.60             | AVG      | 0.69                   | 45.29              | 54.00             | 150             | 240               | -8.71          |         |
|     | 7311.000           | 40.25             | peak     | 5.57                   | 45.82              | 74.00             | 150             | 65                | -28.18         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.42             | peak     | 8.57                   | 43.99              | 74.00             | 150             | 90                | -30.01         |         |
| *   | 12185.000          | 33.78             | peak     | 15.16                  | 48.94              | 74.00             | 150             | 170               | -25.06         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.97             | peak     | 8.57                   | 44.54              | 74.00             | 150             | 135               | -29.46         |         |
| *   | 12185.000          | 32.99             | peak     | 15.16                  | 48.15              | 74.00             | 150             | 240               | -25.85         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n20 CH6


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

Test Mode: TX 802.11n20 CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n20 CH11

Note:


M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4913.828           | 46.25             | peak     | 0.69                   | 46.94              | 74.00             | 150             | 80                | -27.06         |         |
|     | 7386.000           | 40.30             | peak     | 5.99                   | 46.29              | 74.00             | 150             | 305               | -27.71         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4922.826           | 59.18             | peak     | 0.71                   | 59.89              | 74.00             | 150             | 257               | -14.11         |         |
| *   | 4922.826           | 43.30             | AVG      | 0.71                   | 44.01              | 54.00             | 150             | 257               | -9.99          |         |
|     | 7386.000           | 40.29             | peak     | 5.99                   | 46.28              | 74.00             | 150             | 165               | -27.72         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 35.49             | peak     | 9.27                   | 44.76              | 74.00             | 150             | 95                | -29.24         |         |
| *   | 12310.000          | 34.63             | peak     | 14.62                  | 49.25              | 74.00             | 150             | 305               | -24.75         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9848.000           | 35.19             | peak     | 9.27                   | 44.46              | 74.00             | 150             | 80                | -29.54         |         |
| *   | 12310.000          | 34.62             | peak     | 14.62                  | 49.24              | 74.00             | 150             | 125               | -24.76         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment | l |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|---|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |   |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n20 CH11

Note:


M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n20 CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 181.6232           | 46.86             | peak     | -10.77                 | 36.09              | 43.50             | 100             | 35                | -7.41          |         |
|     | 280.7615           | 41.75             | peak     | -6.02                  | 35.73              | 46.00             | 100             | 170               | -10.27         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 31.9440            | 46.16             | QP       | -8.27                  | 37.89              | 40.00             | 100             | 210               | -2.11          |         |
|     | 121.3627           | 37.52             | peak     | -6.55                  | 30.97              | 43.50             | 100             | 90                | -12.53         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 2375.131           | 68.43             | peak     | -4.29                  | 64.14              | 74.00             | 150             | 22                | -9.86          |         |
| *   | 2375.131           | 50.65             | AVG      | -4.29                  | 46.36              | 54.00             | 150             | 22                | -7.64          |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 2375.791           | 68.12             | peak     | -4.29                  | 63.83              | 74.00             | 150             | 22                | -10.17         |         |
| *   | 2375.791           | 50.61             | AVG      | -4.29                  | 46.32              | 54.00             | 150             | 22                | -7.68          |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4841.683           | 45.08             | peak     | 0.72                   | 45.80              | 74.00             | 150             | 65                | -28.20         |         |
| *   | 7266.000           | 40.61             | peak     | 5.46                   | 46.07              | 74.00             | 150             | 230               | -27.93         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4841.683           | 48.41             | peak     | 0.72                   | 49.13              | 74.00             | 150             | 305               | -24.87         |         |
|     | 7266.000           | 40.79             | peak     | 5.46                   | 46.25              | 74.00             | 150             | 65                | -27.75         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9688.000           | 35.65             | peak     | 8.31                   | 43.96              | 74.00             | 150             | 40                | -30.04         |         |
| *   | 12110.000          | 34.63             | peak     | 14.75                  | 49.38              | 74.00             | 150             | 215               | -24.62         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9688.000           | 36.12             | peak     | 8.31                   | 44.43              | 74.00             | 150             | 90                | -29.57         |         |
| *   | 12110.000          | 34.61             | peak     | 14.75                  | 49.36              | 74.00             | 150             | 305               | -24.64         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n40 CH1

Note:


M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n40 CH1

Note:


M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH4

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH4

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 2374.409           | 63.10             | peak     | -4.30                  | 58.80              | 74.00             | 150             | 343               | -15.20         |         |
|     | 2374.409           | 43.52             | AVG      | -4.30                  | 39.22              | 54.00             | 150             | 343               | -14.78         |         |
|     | 2509.880           | 61.36             | peak     | -3.71                  | 57.65              | 74.00             | 150             | 77                | -16.35         |         |
| *   | 2509.880           | 43.63             | AVG      | -3.71                  | 39.92              | 54.00             | 150             | 77                | -14.08         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH4

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4905.811           | 43.97             | peak     | 0.68                   | 44.65              | 74.00             | 150             | 90                | -29.35         |         |
| *   | 7311.000           | 40.50             | peak     | 5.57                   | 46.07              | 74.00             | 150             | 305               | -27.93         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH4

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4897.796           | 47.83             | peak     | 0.67                   | 48.50              | 74.00             | 150             | 225               | -25.50         |         |
|     | 7311.000           | 40.64             | peak     | 5.57                   | 46.21              | 74.00             | 150             | 80                | -27.79         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH4

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 35.56             | peak     | 8.57                   | 44.13              | 74.00             | 150             | 250               | -29.87         |         |
| *   | 12185.000          | 33.87             | peak     | 15.16                  | 49.03              | 74.00             | 150             | 130               | -24.97         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH4

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9748.000           | 34.99             | peak     | 8.57                   | 43.56              | 74.00             | 150             | 65                | -30.44         |         |
| *   | 12185.000          | 33.95             | peak     | 15.16                  | 49.11              | 74.00             | 150             | 305               | -24.89         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH4

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n40 CH4

Note:


M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH4

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

Test Mode: TX 802.11n40 CH4

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH7

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 2509.599           | 62.93             | peak     | -3.71                  | 59.22              | 74.00             | 150             | 15                | -14.78         |         |
| *   | 2509.599           | 44.80             | AVG      | -3.71                  | 41.09              | 54.00             | 150             | 15                | -12.91         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n40 CH7

Note:


M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH7

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4921.844           | 44.88             | peak     | 0.71                   | 45.59              | 74.00             | 150             | 305               | -28.41         |         |
| *   | 7356.000           | 40.60             | peak     | 5.82                   | 46.42              | 74.00             | 150             | 225               | -27.58         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH7

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 4921.844           | 48.43             | peak     | 0.71                   | 49.14              | 74.00             | 150             | 90                | -24.86         |         |
|     | 7356.000           | 41.19             | peak     | 5.82                   | 47.01              | 74.00             | 150             | 145               | -26.99         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH7

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9808.000           | 35.57             | peak     | 8.92                   | 44.49              | 74.00             | 150             | 45                | -29.51         |         |
| *   | 12260.000          | 34.37             | peak     | 14.79                  | 49.16              | 74.00             | 150             | 125               | -24.84         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH7

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9808.000           | 35.09             | peak     | 8.92                   | 44.01              | 74.00             | 150             | 65                | -29.99         |         |
| *   | 12260.000          | 34.33             | peak     | 14.79                  | 49.12              | 74.00             | 150             | 305               | -24.88         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH7

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 802.11n40 CH7

Note:


M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 802.11n40 CH7

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

Test Mode: TX 802.11n40 CH7

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 181.6232           | 47.40             | peak     | -10.77                 | 36.63              | 43.50             | 100             | 135               | -6.87          |         |
|     | 282.7054           | 41.87             | peak     | -5.97                  | 35.90              | 46.00             | 100             | 270               | -10.10         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 30.0000            | 43.77             | peak     | -8.01                  | 35.76              | 40.00             | 100             | 330               | -4.24          |         |
|     | 181.6232           | 42.69             | peak     | -10.77                 | 31.92              | 43.50             | 100             | 10                | -11.58         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4804.000           | 41.60             | peak     | 0.75                   | 42.35              | 74.00             | 150             | 45                | -31.65         |         |
| *   | 7206.000           | 41.60             | peak     | 5.38                   | 46.98              | 74.00             | 150             | 170               | -27.02         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4804.000           | 41.77             | peak     | 0.75                   | 42.52              | 74.00             | 150             | 90                | -31.48         |         |
| *   | 7206.000           | 41.56             | peak     | 5.38                   | 46.94              | 74.00             | 150             | 45                | -27.06         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9608.000           | 34.74             | peak     | 8.25                   | 42.99              | 74.00             | 150             | 65                | -31.01         |         |
| *   | 12010.000          | 33.49             | peak     | 13.50                  | 46.99              | 74.00             | 150             | 130               | -27.01         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9608.000           | 34.29             | peak     | 8.25                   | 42.54              | 74.00             | 150             | 65                | -31.46         |         |
| *   | 12010.000          | 34.16             | peak     | 13.50                  | 47.66              | 74.00             | 150             | 130               | -26.34         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 2402MHz

Note:


M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2441MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2441MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2441MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4882.000           | 41.44             | peak     | 0.68                   | 42.12              | 74.00             | 150             | 70                | -31.88         |         |
| *   | 7323.000           | 40.98             | peak     | 5.64                   | 46.62              | 74.00             | 150             | 65                | -27.38         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2441MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4882.000           | 41.17             | peak     | 0.68                   | 41.85              | 74.00             | 150             | 55                | -32.15         |         |
| *   | 7323.000           | 40.82             | peak     | 5.64                   | 46.46              | 74.00             | 150             | 120               | -27.54         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2441MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9764.000           | 35.00             | peak     | 8.66                   | 43.66              | 74.00             | 150             | 305               | -30.34         |         |
| *   | 12388.276          | 36.13             | peak     | 15.61                  | 51.74              | 74.00             | 150             | 125               | -22.26         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2441MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9764.000           | 35.04             | peak     | 8.66                   | 43.70              | 74.00             | 150             | 305               | -30.30         |         |
| *   | 12205.000          | 32.19             | peak     | 15.20                  | 47.39              | 74.00             | 150             | 265               | -26.61         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2441MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 2441MHz

Note:


M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2441MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical


EUT: W6M21903-18857 Power: 120 Va.c.

M/N: Distance: 3m Test Mode: TX 2441MHz

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 2480MHz

Note:


M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |

Distance: 3m



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4960.000           | 40.96             | peak     | 0.77                   | 41.73              | 74.00             | 150             | 80                | -32.27         |         |
| *   | 7440.000           | 41.84             | peak     | 5.99                   | 47.83              | 74.00             | 150             | 45                | -26.17         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4960.000           | 41.83             | peak     | 0.77                   | 42.60              | 74.00             | 150             | 110               | -31.40         |         |
| *   | 7440.000           | 41.34             | peak     | 5.99                   | 47.33              | 74.00             | 150             | 280               | -26.67         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9920.000           | 34.52             | peak     | 9.70                   | 44.22              | 74.00             | 150             | 250               | -29.78         |         |
| *   | 12400.000          | 33.87             | peak     | 15.76                  | 49.63              | 74.00             | 150             | 130               | -24.37         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9920.000           | 34.88             | peak     | 9.70                   | 44.58              | 74.00             | 150             | 260               | -29.42         |         |
| *   | 12454.910          | 35.42             | peak     | 15.94                  | 51.36              | 74.00             | 150             | 305               | -22.64         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 2480MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 2480MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 183.5671           | 47.03             | peak     | -10.75                 | 36.28              | 43.50             | 100             | 225               | -7.22          |         |
|     | 282.7054           | 40.86             | peak     | -5.97                  | 34.89              | 46.00             | 100             | 140               | -11.11         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_30-1000MHz Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
| *   | 30.0000            | 44.94             | peak     | -8.01                  | 36.93              | 40.00             | 100             | 50                | -3.07          |         |
|     | 72.7655            | 46.73             | peak     | -14.16                 | 32.57              | 40.00             | 100             | 170               | -7.43          |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 2402MHz


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4804.000           | 41.51             | peak     | 0.75                   | 42.26              | 74.00             | 150             | 65                | -31.74         |         |
| *   | 7206.000           | 41.28             | peak     | 5.38                   | 46.66              | 74.00             | 150             | 305               | -27.34         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4804.000           | 41.84             | peak     | 0.75                   | 42.59              | 74.00             | 150             | 55                | -31.41         |         |
| *   | 7206.000           | 41.73             | peak     | 5.38                   | 47.11              | 74.00             | 150             | 120               | -26.89         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9608.000           | 34.51             | peak     | 8.25                   | 42.76              | 74.00             | 150             | 45                | -31.24         |         |
| *   | 12010.000          | 33.80             | peak     | 13.50                  | 47.30              | 74.00             | 150             | 125               | -26.70         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9608.000           | 35.14             | peak     | 8.25                   | 43.39              | 74.00             | 150             | 80                | -30.61         |         |
| *   | 12010.000          | 33.94             | peak     | 13.50                  | 47.44              | 74.00             | 150             | 250               | -26.56         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical


EUT: W6M21903-18857 Power: 120 Va.c.

M/N: Distance: 3m
Test Mode: TX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 2402MHz


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2440MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2440MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2440MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4880.000           | 41.77             | peak     | 0.69                   | 42.46              | 74.00             | 150             | 60                | -31.54         |         |
| *   | 7320.000           | 40.70             | peak     | 5.62                   | 46.32              | 74.00             | 150             | 120               | -27.68         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2440MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4880.000           | 41.88             | peak     | 0.69                   | 42.57              | 74.00             | 150             | 230               | -31.43         |         |
| *   | 7320.000           | 40.64             | peak     | 5.62                   | 46.26              | 74.00             | 150             | 65                | -27.74         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2440MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9760.000           | 35.29             | peak     | 8.64                   | 43.93              | 74.00             | 150             | 45                | -30.07         |         |
| *   | 12200.000          | 33.60             | peak     | 15.24                  | 48.84              | 74.00             | 150             | 270               | -25.16         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2440MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9760.000           | 34.72             | peak     | 8.64                   | 43.36              | 74.00             | 150             | 45                | -30.64         |         |
| *   | 12200.000          | 32.41             | peak     | 15.24                  | 47.65              | 74.00             | 150             | 120               | -26.35         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2440MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Test Mode: TX 2440MHz

Note:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2440MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 2440MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4960.000           | 41.20             | peak     | 0.77                   | 41.97              | 74.00             | 150             | 250               | -32.03         |         |
| *   | 7440.000           | 41.54             | peak     | 5.99                   | 47.53              | 74.00             | 150             | 305               | -26.47         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4960.000           | 41.36             | peak     | 0.77                   | 42.13              | 74.00             | 150             | 90                | -31.87         |         |
| *   | 7440.000           | 41.86             | peak     | 5.99                   | 47.85              | 74.00             | 150             | 65                | -26.15         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9920.000           | 33.54             | peak     | 9.70                   | 43.24              | 74.00             | 150             | 240               | -30.76         |         |
| *   | 12400.000          | 33.11             | peak     | 15.76                  | 48.87              | 74.00             | 150             | 160               | -25.13         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 9920.000           | 33.84             | peak     | 9.70                   | 43.54              | 74.00             | 150             | 65                | -30.46         |         |
| *   | 12400.000          | 34.02             | peak     | 15.76                  | 49.78              | 74.00             | 150             | 120               | -24.22         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: TX 2480MHz


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: TX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class C\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Test Mode: TX 2480MHz

Note:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1308.617           | 43.09             | peak     | -9.00                  | 34.09              | 74.00             | 150             | 275               | -39.91         |         |
| *   | 4044.088           | 42.77             | peak     | 0.16                   | 42.93              | 74.00             | 150             | 240               | -31.07         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 3272.545           | 42.43             | peak     | -2.44                  | 39.99              | 74.00             | 150             | 35                | -34.01         |         |
| *   | 4464.930           | 41.96             | peak     | 0.79                   | 42.75              | 74.00             | 150             | 260               | -31.25         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11b CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH1

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11b CH1


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11b CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1028.056           | 41.59             | peak     | -7.83                  | 33.76              | 74.00             | 150             | 65                | -40.24         |         |
| *   | 4142.284           | 42.26             | peak     | 0.67                   | 42.93              | 74.00             | 150             | 270               | -31.07         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 4478.958           | 41.92             | peak     | 0.83                   | 42.75              | 74.00             | 150             | 124               | -31.25         |         |
| *   | 7004.008           | 41.40             | peak     | 5.45                   | 46.85              | 74.00             | 150             | 56                | -27.15         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11b CH6


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11b CH6


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11b CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11b CH6


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1112.224           | 43.04             | peak     | -9.16                  | 33.88              | 74.00             | 150             | 55                | -40.12         |         |
| *   | 3272.545           | 41.50             | peak     | -2.44                  | 39.06              | 74.00             | 150             | 276               | -34.94         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1294.589           | 42.97             | peak     | -9.02                  | 33.95              | 74.00             | 150             | 85                | -40.05         |         |
| *   | 3160.321           | 42.11             | peak     | -2.77                  | 39.34              | 74.00             | 150             | 243               | -34.66         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11b CH11


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11b CH11

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11b CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11b CH11


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1673.347           | 43.28             | peak     | -7.57                  | 35.71              | 74.00             | 150             | 65                | -38.29         |         |
| *   | 4478.958           | 42.44             | peak     | 0.83                   | 43.27              | 74.00             | 150             | 243               | -30.73         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.73             | peak     | -8.23                  | 35.50              | 74.00             | 150             | 92                | -38.50         |         |
| *   | 3819.639           | 41.38             | peak     | -0.58                  | 40.80              | 74.00             | 150             | 217               | -33.20         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: RX 802.11g CH1

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: RX 802.11g CH1

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: RX 802.11g CH1

Note:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11g CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.15             | peak     | -8.23                  | 34.92              | 74.00             | 150             | 55                | -39.08         |         |
| *   | 4464.930           | 42.08             | peak     | 0.79                   | 42.87              | 74.00             | 150             | 213               | -31.13         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.08             | peak     | -8.23                  | 34.85              | 74.00             | 150             | 46                | -39.15         |         |
| *   | 4478.958           | 42.00             | peak     | 0.83                   | 42.83              | 74.00             | 150             | 293               | -31.17         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: RX 802.11g CH6

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: RX 802.11g CH6

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH6

| I  | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: RX 802.11g CH6

Note:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1392.785           | 43.41             | peak     | -9.03                  | 34.38              | 74.00             | 150             | 265               | -39.62         |         |
| *   | 4142.284           | 42.43             | peak     | 0.67                   | 43.10              | 74.00             | 150             | 240               | -30.90         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 44.04             | peak     | -8.23                  | 35.81              | 74.00             | 150             | 43                | -38.19         |         |
| *   | 4030.060           | 41.55             | peak     | 0.13                   | 41.68              | 74.00             | 150             | 137               | -32.32         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: RX 802.11g CH11

Note:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH11

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


Test Mode: RX 802.11g CH11

Note:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11g CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11g CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.10             | peak     | -8.23                  | 34.87              | 74.00             | 150             | 275               | -39.13         |         |
| *   | 3258.517           | 42.06             | peak     | -2.46                  | 39.60              | 74.00             | 150             | 230               | -34.40         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 3356.713           | 42.35             | peak     | -2.45                  | 39.90              | 74.00             | 150             | 216               | -34.10         |         |
| *   | 4394.790           | 42.51             | peak     | 0.63                   | 43.14              | 74.00             | 150             | 90                | -30.86         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n20 CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11n20 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n20 CH1


Note:

M/N:

| I  | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.49             | peak     | -8.23                  | 35.26              | 74.00             | 150             | 35                | -38.74         |         |
| *   | 4478.958           | 42.12             | peak     | 0.83                   | 42.95              | 74.00             | 150             | 269               | -31.05         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH6

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.51             | peak     | -8.23                  | 35.28              | 74.00             | 150             | 241               | -38.72         |         |
| *   | 3805.611           | 41.42             | peak     | -0.63                  | 40.79              | 74.00             | 150             | 175               | -33.21         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11n20 CH6

| I  | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11n20 CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH6

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n20 CH6


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1659.319           | 42.94             | peak     | -7.65                  | 35.29              | 74.00             | 150             | 144               | -38.71         |         |
| *   | 4142.284           | 42.09             | peak     | 0.67                   | 42.76              | 74.00             | 150             | 265               | -31.24         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH11

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.23             | peak     | -8.23                  | 35.00              | 74.00             | 150             | 21                | -39.00         |         |
| *   | 2879.760           | 42.89             | peak     | -3.72                  | 39.17              | 74.00             | 150             | 147               | -34.83         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n20 CH11


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11n20 CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n20 CH11

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n20 CH11


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1378.757           | 43.10             | peak     | -9.02                  | 34.08              | 74.00             | 150             | 65                | -39.92         |         |
| *   | 3595.190           | 41.69             | peak     | -1.31                  | 40.38              | 74.00             | 150             | 245               | -33.62         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH1

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 3286.573           | 41.49             | peak     | -2.43                  | 39.06              | 74.00             | 150             | 157               | -34.94         |         |
| *   | 4310.621           | 41.58             | peak     | 0.94                   | 42.52              | 74.00             | 150             | 290               | -31.48         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n40 CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n40 CH1


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH1

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment | l |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|---|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |   |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n40 CH1


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH4

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.49             | peak     | -8.23                  | 35.26              | 74.00             | 150             | 213               | -38.74         |         |
| *   | 3286.573           | 42.50             | peak     | -2.43                  | 40.07              | 74.00             | 150             | 60                | -33.93         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH4

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 3679.359           | 42.09             | peak     | -1.09                  | 41.00              | 74.00             | 150             | 57                | -33.00         |         |
| *   | 4156.313           | 42.32             | peak     | 0.78                   | 43.10              | 74.00             | 150             | 169               | -30.90         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH4

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n40 CH4


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH4

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11n40 CH4

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n40 CH4


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n40 CH4


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH7

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1547.094           | 43.15             | peak     | -8.30                  | 34.85              | 74.00             | 150             | 62                | -39.15         |         |
| *   | 4464.930           | 41.87             | peak     | 0.79                   | 42.66              | 74.00             | 150             | 240               | -31.34         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH7

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1855.711           | 44.11             | peak     | -6.27                  | 37.84              | 74.00             | 150             | 216               | -36.16         |         |
| *   | 3146.293           | 43.56             | peak     | -2.86                  | 40.70              | 74.00             | 150             | 70                | -33.30         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH7

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n40 CH7


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH7

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 802.11n40 CH7

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 802.11n40 CH7

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 802.11n40 CH7


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.34             | peak     | -8.23                  | 35.11              | 74.00             | 150             | 357               | -38.89         |         |
| *   | 3146.293           | 42.65             | peak     | -2.86                  | 39.79              | 74.00             | 150             | 129               | -34.21         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1392.785           | 42.39             | peak     | -9.03                  | 33.36              | 74.00             | 150             | 42                | -40.64         |         |
| *   | 4478.958           | 42.37             | peak     | 0.83                   | 43.20              | 74.00             | 150             | 175               | -30.80         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2402MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2402MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2402MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2441MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1533.066           | 42.23             | peak     | -8.37                  | 33.86              | 74.00             | 150             | 175               | -40.14         |         |
| *   | 3146.293           | 42.15             | peak     | -2.86                  | 39.29              | 74.00             | 150             | 240               | -34.71         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2441MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2441MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2441MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2441MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1294.589           | 43.10             | peak     | -9.02                  | 34.08              | 74.00             | 150             | 95                | -39.92         |         |
| *   | 4142.284           | 42.54             | peak     | 0.67                   | 43.21              | 74.00             | 150             | 60                | -30.79         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2441MHz


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2441MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2441MHz


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.39             | peak     | -8.23                  | 35.16              | 74.00             | 150             | 65                | -38.84         |         |
| *   | 4478.958           | 41.74             | peak     | 0.83                   | 42.57              | 74.00             | 150             | 90                | -31.43         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.29             | peak     | -8.23                  | 35.06              | 74.00             | 150             | 275               | -38.94         |         |
| *   | 3370.742           | 42.86             | peak     | -2.46                  | 40.40              | 74.00             | 150             | 40                | -33.60         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2480MHz


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2480MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 42.66             | peak     | -8.23                  | 34.43              | 74.00             | 150             | 225               | -39.57         |         |
| *   | 4128.257           | 41.94             | peak     | 0.55                   | 42.49              | 74.00             | 150             | 32                | -31.51         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.15             | peak     | -8.23                  | 34.92              | 74.00             | 150             | 42                | -39.08         |         |
| *   | 3272.545           | 42.41             | peak     | -2.44                  | 39.97              | 74.00             | 150             | 175               | -34.03         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2402MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2402MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2402MHz


Note:

M/N:

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2440MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1364.729           | 42.94             | peak     | -9.02                  | 33.92              | 74.00             | 150             | 275               | -40.08         |         |
| *   | 3118.236           | 42.60             | peak     | -3.04                  | 39.56              | 74.00             | 150             | 80                | -34.44         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2440MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1561.122           | 43.39             | peak     | -8.23                  | 35.16              | 74.00             | 150             | 230               | -38.84         |         |
| *   | 3188.377           | 42.39             | peak     | -2.59                  | 39.80              | 74.00             | 150             | 65                | -34.20         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2440MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2440MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2440MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2440MHz


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2440MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2440MHz


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1238.477           | 42.72             | peak     | -9.26                  | 33.46              | 74.00             | 150             | 85                | -40.54         |         |
| *   | 4394.790           | 42.10             | peak     | 0.63                   | 42.73              | 74.00             | 150             | 270               | -31.27         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

| Mk. | Frequency<br>(MHz) | Reading<br>(dBuV) | Detector | Corr. factor<br>(dB/m) | Result<br>(dBuV/m) | Limit<br>(dBuV/m) | Ant.Pos<br>(cm) | Tab.Pos<br>(deg.) | Margin<br>(dB) | Comment |
|-----|--------------------|-------------------|----------|------------------------|--------------------|-------------------|-----------------|-------------------|----------------|---------|
|     | 1084.168           | 42.56             | peak     | -8.84                  | 33.72              | 74.00             | 150             | 35                | -40.28         |         |
| *   | 1561.122           | 43.04             | peak     | -8.23                  | 34.81              | 74.00             | 150             | 267               | -39.19         |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

EUT: W6M21903-18857 Power: 120 Va.c.

Test Mode: RX 2480MHz


Note:

M/N:

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber


Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 2480MHz

|    | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Horizontal

EUT: W6M21903-18857 Power: 120 Va.c.


M/N: Distance: 3m

Test Mode: RX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |



Tel:+886-2-6606-8877 Fax:+886-2-6606-8879



Site: Chamber

Condition: FCC\_part 15 RE-Class B\_Above 1GHz\_PK Polarization: Vertical

Test Mode: RX 2480MHz

|     | Frequency | Reading | Detector | Corr. factor | Result   | Limit    | Ant.Pos | Tab.Pos | Margin | Comment |
|-----|-----------|---------|----------|--------------|----------|----------|---------|---------|--------|---------|
| Mk. | (MHz)     | (dBuV)  |          | (dB/m)       | (dBuV/m) | (dBuV/m) | (cm)    | (deg.)  | (dB)   |         |