

检测报告 Test Report



报告编号 A224001457710100102E

第 1 页 共 6 页

Report No. A224001457710100102E

Page 1 of 6

报告抬头公司名称 中山市伟立塑料制品有限公司

Company Name
Shown on Report ZHONGSHAN WEILI PLASTIC PRODUCTS CO., LTD

地 址 中山市阜沙镇安居街 85 号之一(关迪明首层第一间)
Address ONE OF NO.85 ANJU STREET, FUSHA TOWN, ZHONGSHAN CITY,
GUANGDONG PROVINCE

以下测试之样品及样品信息由申请者提供并确认

The following sample(s) and sample information was/were submitted and identified by/on the behalf of the client

样品名称	塑料箱
Sample Name	Plastic Box
样品接收状态	正常
Sample Receiving State	Normal
样品接收日期	2024.01.08
Sample Received Date	Jan. 8, 2024
样品检测日期	2024.01.08-2024.01.17
Testing Period	Jan. 8, 2024-Jan. 17, 2024

批 准
Approved by

日 期
Date 2024.01.17
Jan. 17, 2024

肖业湘

授权签字人

Approved Signatory

华测检测认证集团股份有限公司

Certification Testing International Group Co., Ltd.



No. R6F2C06D0A

广东省深圳市宝安区 70 区鸿威工业园

Hongwei Industrial Zone, Bao'an 70 District, Shenzhen, Guangdong, China

检测报告
Test Report

报告编号 A224001457710100102E
Report No. A224001457710100102E

第 2 页 共 6 页
Page 2 of 6

检测要求

Test Requested

序号 No.	测试项目 Test Item
1	抗压试验 Compression test

检测结果：请参见后续页面。
Test Result(s): Please see the following pages.

测试样品

Tested Sample(s)

样品编号 Sample No.	样品名称 Sample Name	样品数量 Quantity
A2240014577101001	塑料箱 Plastic Box	1pc

样品图片

Sample Photo(s)



A2240014577101001①



A2240014577101001②

检测报告 Test Report

报告编号 A224001457710100102E

第 3 页 共 6 页

Report No. A224001457710100102E

Page 3 of 6

测试项目：抗压试验

Test Item: Compression test

1. 测试设备 Test Equipment

设备名称 Equipment Name	型 号 Model
纸箱抗压试验机 Carton compression tester	BF-W-5TDS

2. 环境条件 Environmental Conditions

温度：24.8℃； 湿度：47%RH

Temperature: 24.8℃; Humidity: 47%RH

3. 测试标准 Test Standard: 依客户要求 According to the customer's requirements

4. 测试条件

Test Condition

使产品底面朝下放置到抗压机下压板上正中位置

Place the bottom side of the product downward on the middle position of the lower pressure plate of the compressor

以 13mm/min 的速度给样品施加压力，直到达到力值

Apply pressure to the sample at the speed of 13mm/min, and release the force value after reaching the test force value.

力值：100 kgf

Force value: 100 kgf

检测报告
Test Report

报告编号A224001457710100102E第 4 页 共 6 页

Report No. A224001457710100102EPage 4 of 6

5. 测试结果

Test Result(s)

样品编号 Sample No.	判定依据 Criterion	测试结果 Test results	结论 Conclusion
A2240014577101001	观察外观是否有凹陷、鼓胀、破损、变形等不良现象。 Observe whether there are dents, swelling, damage, deformation and other undesirable phenomena in the appearance.	测试后，目视检查样品外观无机械损伤。 After the test, there was no visible mechanical damage on the sample by visual inspection.	符合 Pass
备注:判定依据由客户提供 Remark: the criterion is supplied by client			

测试图片

Test Photo(s)



CTI GROUP CO., LTD.
章
ices

检测报告 Test Report

报告编号 A224001457710100102E


第 5 页 共 6 页

Report No. A224001457710100102E

Page 5 of 6

测试曲线

Test Curve



测试后样品图片

Sample Photo(s) after the test



①



②

检测报告 Test Report

报告编号 A224001457710100102E

第 6 页 共 6 页

Report No. A224001457710100102E

Page 6 of 6

备注：本报告中的数据结果供科研、教学、企业内部质量控制、企业产品研发等目的用。

Remark: The testing data and result(s) in this report is(are) just for scientific research, education, internal quality control and product development etc.

声明：

Statement:

1.检测报告无批准人签字、“专用章”及报告骑缝章无效；

This report is considered invalid without approved signature, special seal and the seal on the perforation;

2.报告抬头公司名称及地址、样品及样品信息由申请者提供，申请者应对其真实性负责，CTI 未核实其真实性；

Company Name and Address shown on Report, the sample(s) and sample Information was/were provided by the applicant who should be responsible for the authenticity which CTI hasn't verified;

3.本报告检测结果仅对受测样品负责；

The result(s) shown in this report refer(s) only to the sample(s) tested;

4.未经 CTI 书面同意，不得部分复制本报告。

Without written approval of CTI, this report can't be reproduced except in full;

5.如检测报告中的英文内容与中文内容有差异，以中文为准。

In case of any discrepancy between the English version and Chinese version of the testing reports(if generated), the Chinese version shall prevail.

*** 报告结束 ***

*** End of Report ***