

Prova 1: A Tabela de Roteamento "Confusa" (Limitação de Auto-Summary)


```
Router>show ip route
Codes: L - local, C - connected, S - static, R - RIP, M - mobile, B - BGP
       D - EIGRP, EX - EIGRP external, O - OSPF, IA - OSPF inter area
       N1 - OSPF NSSA external type 1, N2 - OSPF NSSA external type 2
       E1 - OSPF external type 1, E2 - OSPF external type 2, E - EGP
       i - IS-IS, L1 - IS-IS level-1, L2 - IS-IS level-2, ia - IS-IS inter area
       * - candidate default, U - per-user static route, o - ODR
       P - periodic downloaded static route

Gateway of last resort is not set

10.0.0.0/8 is variably subnetted, 4 subnets, 2 masks
C    10.0.0.0/30 is directly connected, Serial0/0/0
L    10.0.0.2/32 is directly connected, Serial0/0/0
C    10.0.0.4/30 is directly connected, Serial0/0/1
L    10.0.0.5/32 is directly connected, Serial0/0/1
R    172.16.0.0/16 [120/1] via 10.0.0.6, 00:00:26, Serial0/0/1
      [120/1] via 10.0.0.1, 00:00:17, Serial0/0/0
```

Como o RIPv1 é *classful*, os Roteadores 1 e 3 não enviaram a máscara /24. Eles resumiram a rede para a classe B padrão (/16). O Roteador 2 recebeu a mesma rota de dois lados diferentes e criou um balanceamento de carga incorreto.

Prova 2: O Protocolo "Cego" (Limitação da Falta de Máscara)



Aqui provamos que o pacote de atualização do RIPv1 simplesmente não possui um campo para carregar a máscara (Subnet Mask). Ele é cego para sub-redes.

Prova 3: A Falha na Prática (O Ping Quebrado)

```
C:\>ping 172.16.2.10

Pinging 172.16.2.10 with 32 bytes of data:

Reply from 172.16.1.1: Destination host unreachable.
Reply from 172.16.1.1: Destination host unreachable.
Reply from 172.16.1.1: Destination host unreachable.
Reply from 172.16.1.1: Destination host unreachable.

Ping statistics for 172.16.2.10:
    Packets: Sent = 4, Received = 0, Lost = 4 (100% loss),
```

