ALERT meeting

AHDC alignment

Felix Touchte Codjo

IJCLab

April 27, 2026

Updates - wire alignment

- I started the alignment of the wires, but I faced some issue...
- On the right, we have the residual LR distribution for some wires (belonging to fitted tracks)
- Some of them are well centered (it comes from the previous layer alignment)
- Others are weird.
- At the beginning, we noticed that they usually appear by pair.
- They may have been switched.



Updates - wire alignment

- I started the alignment of the wires, but I faced some issue...
- On the right, we have the residual LR distribution for some wires (belonging to fitted tracks)
- Some of them are well centered (it comes from the previous layer alignment)
- Others are weird.
- At the beginning, we noticed that they usually appear by pair.
- They may have been switched.



Updates - wire alignment

- We decided to look at the wire disposition per layer versus the electron's ϕ
- The two red circles match the two set of weird distributions that we saw in the last slides



Updates - wire alignment

- I have initially listed 29 bad distributions
- I have already inverted the wires (L21C18, L21C19) and (L22C20, L22C22). That fixed five of them (the filled blue circles)
- 24 are still under investigating (the filled black circles)
- They are almost arranged into groups.
- It is possible that only one wire exchange degrades the residual distribution of the whole group of bad wires



Updates - wire alignment

- Here are the distribution of the bad wires of the first group
- The difficulty here is that we may have some exchanges between wires belonging to different layers. Work in progress...