

Site: Flores da Cunha, RS

Process: Pintura a pó - linha contínua.

Product: Powder


Data Collection Details:

Created By
Number of Probes
Sample Interval
Data Loaded
Collection Started
Max. Internal Temp.
Logger
Logger ID
Operator
Time Printed

Download
6
0:05,00 (mm:ss,t)
24/03/2026 10:21:55
24/03/2026 08:13:47
76,1 °C
EasyTrack2
#20176
ARRODRIGUES
24/03/2026 11:00:15

Notes:

Dalemolle Estruturas Metálicas.
Flores da Cunha, RS
Termografia 1
Estufa contínua,
Set Point : 190°C - Epristinta
Set Point : 170°C - WEG
Velocidade da linha: 0,8 m/min
24/04/2026



Probe	Datapaq Value				Maximum / Minimum				Time at Temperature			
	Min Temp 140,0 Max Temp 220,0°C				Maximum (°C)	Max. Reached (mm:ss,tt)	Minimum (°C)	Min. Reached (mm:ss,tt)	Time Above 190,0°C (mm:ss,tt)	Time To Reach 190,0°C (mm:ss,tt)	Time Above 170,0°C (mm:ss,tt)	Time To Reach 170,0°C (mm:ss,tt)
	160,0°C 12:00,00 (mm:ss,tt)	180,0°C 10:00,00 (mm:ss,tt)	190,0°C 09:00,00 (mm:ss,tt)	Datapaq Value								
#1 (°C) Ar Superior	111:40,00	35:15,00	00:00,00	1092	189,8	100:35,00	24,9	-03:10,00	00:00,00	***	97:20,00	03:10,00
#2 (°C) Chapa 8 mm : ponto superior dir.	95:15,00	81:50,00	32:40,00	1076	192,9	69:20,00	24,6	-03:10,00	32:40,00	57:55,00	89:50,00	22:00,00
#3 (°C) Chapa 1" ponto central	63:50,00	31:45,00	00:00,00	790	186,3	103:20,00	24,4	-03:10,00	00:00,00	***	49:40,00	65:00,00
#4 (°C) Chapa 4,26 mm ponto superior esq.	98:30,00	77:40,00	00:00,00	1052	188,8	104:45,00	24,9	-03:10,00	00:00,00	***	94:35,00	21:10,00
#5 (°C) Chapa 6,30 mm ponto inferior dir	86:05,00	05:55,00	00:00,00	888	181,9	103:20,00	23,9	-03:10,00	00:00,00	***	78:20,00	35:20,00
#6 (°C) Ar Inferior	95:35,00	03:05,00	00:00,00	932	181,4	98:15,00	24,2	-03:10,00	00:00,00	***	28:30,00	28:45,00