

Report

- **Reference:** XXXXX
- **Name:** XXXX YYYY
- **Emirate:** Dubai
- **Inspected on:** 2025-09-23

Vehicle

- **Title:** XXXXXXXX XXXXXX
- **Model year:** 2021
- **Manufacturing year:** 2021
- **Chassis number:** JN8BY2NY4M9345338
- **Odometer:** 115,224km
- **Condition:** Used
- **Gearbox:** Automatic
- **Fuel type:** Gasoline
- **Cylinders:** 6
- **Engine size:** 4.0 L

Additional specs

- **Regional specs:** GCC
- **Exterior color:** White
- **Interior color:** Black
- **Interior type:** Fabric
- **Steering side:** Left hand
- **Drivetrain:** 4x4
- **Wheels:** 20" alloy
- **Keys:** 1
- **Doors:** 5
- **Seats:** 7

Warranty

/

Service

S

- **Warranty :** Not available
- **With service history :** Third party

Inspector summary

Body

- 3 Accident reported, full body painted, flooded vehicle.
- Front and rear bumper required repair and repainted

Exterior

- Body dents and scratches.
- Both side door moulding chrome have dents.

Interior

- Normal wear and tear, underseats rusty
- Left side folding mirror not working

Mechanical

- Front brake pads remaining percentage 60%, Rear brake pads remaining percentage 70%
- Recommended to do major service including spark plugs, gear oil and filter gasket, All filters includes Air, AC, Fuel filter, change front and rear differential and transfer case oil.
- Severe rust and mud underneath see photo attached.
- Change all tyres and perform wheel alignment and wheel balancing
- Need to do steam washing and apply underneath rust removal and treatment.

Electrical

- For tyre and battery report see diagnostic attachment.
- Tyre pressure light is ON







For any questions regarding this report, please contact
AutoHub Operations Manager










 **+971 54 2XX XXXX**(Phone or WhatsApp)

Available Daily (except Saturday) from 10:00 AM to 2:00 PM and 3:00 PM to 8:00 PM
















Exterior





Interior

















Tires



Mechanical





Video

View Video

Click to access the inspection video link

Vehicle Diagnostic Reports



Before Test Drive

A pre-drive computer diagnostic report that provides a full scan of the vehicle's electronic systems to establish

Download



Battery Report



After Test Drive

A post-drive diagnostic report highlighting any detected fault codes or irregularities in the vehicle's systems after

Download



Tire Report

A battery health assessment report detailing voltage, charge status, starting power, and internal resistance.

Download

A report on tire tread depth and brake disc wear, including visual inspection notes and safety-based

Download

Vehicle specifications

Performance

Differential Lock

Safety

Child Safety Seats (ISOFIX)

Front Parking Sensors

Rear Parking Sensors

Anti-Lock Brakes (ABS)

EBD

Alarm

Traction Control System

Anti Glare Rear View Mirror

Tire Pressure Monitor

Interior - Entertainment

Digital Driver Display

Bluetooth Interface

AUX Audio System

USB

Touch Screen

Interior - Comfort

Dual-Zone Climate Control AC

Keyless Entry

Keyless Start

Power Steering

Cruise Control

Power Front Windows

Power Rear Windows

Power Locks



Power Mirrors

✗	Power Folding Mirrors	Left side not working
✓	Fabric Seats	
Exterior		
✓	Roof Carrier	
✓	LED Headlight	
Inspection Checklist		
Body Exterior		
✓	Glass	
✓	Door locks / operation	
✓	Fuel filler cover / Petrol cap	
Electric Controls		
✓	Ignition lock / Starting system	
✓	Battery charging system	
✓	Headlights	
✓	Rear lights	
✓	Horn	
✓	Window operation	
✓	Wipers / Jet washers	
Exhause System		
✓	Inlet manifold	
✓	Outlet manifold	
✓	Pipes	
✓	Silencer(s)	
✓	Head shields and mountings	
✓	Joints and couplings	
Convenience		
✓	Keys and remove controls	
Brakes		
✗	Disc and pads	Rusty



Road Test

✖ Engine - performance	Need service and perform oil flushing
------------------------	---------------------------------------

✓	Engine - excessive smoke	
✓	Evidence of overheating	
✓	Gearbox operation and noise level	
✓	Instruments and controls functioning	
✗	Suspension noise	Worn out
✓	Road holding stability	
✗	Warning lights	tyre pressure light is on
Wheels and Tyres		
✗	Front right tyre	Uneven wear
✗	Front left tyre	Uneven wear
✗	Back right tyre	Uneven wear
✗	Back left tyre	Uneven wear
Interior and Luggage Compartment		
✓	Seat belts	
✓	Internal mirrors	
✓	Boot / Tailgate lock	
Engine Compartment		
✓	Coolant level	
✓	Coolant leaks	
✓	Radiator cap	
✓	Hoses and pipes	
✓	Drive belts	
✓	Engine oil level	
✓	External engine leaks	
✓	Fuel pump and pipes	
✓	Cold starting	
✓	Fast idle when engine cold	
✓	Noise level when engine cold	
✓	Excess smoke	
Suspension, Underframe and Steering		
✓	Engine underside leaks	

✓	Steering joints and ball joints	
✓	Steering rack	
✓	Chassis members	
✓	Power steering	
✓	Wheels, hubs and bearings	
✓	Pipes and hoses	
✗	Dampers and bushes	Worn out
✗	Sub frames and mountings	Severe rust
✗	Evidence of floor / chassis corrosion	Severe rust
Clutch and Transmission		
✗	Transmission	Need servicing

Damage points



ad ed Broken Scrat ch

20%
OFF

Use Code: REP20

As a valued AutoHub customer, you get an exclusive 20% discount on window tinting! Simply mention the code when you contact us to book your service or enter it when booking online. This offer is available for a limited time!

Redeem the

Inspection Disclaimer

English

This inspection report reflects the condition of the vehicle at the time of inspection only. It is intended to assist you in evaluating the vehicle's general condition. It does not constitute a warranty, guarantee, or recommendation to buy or sell the vehicle.

- **Scope of inspection:** The inspection is strictly limited to the items listed in this report. It is a visual, non-invasive, and non-mechanical inspection. Components are not dismantled, and internal parts are not examined.
- **Exclusions:** The inspection does not include the vehicle's service history, accident history, or recall notices. AutoHub also does not verify mileage, features, or specifications provided by the seller.
- **Hidden or intermittent issues:** While AutoHub uses standardized inspection methods, certain defects may remain undetected, especially intermittent or hidden problems not apparent at the time of inspection.
- **Future condition:** Mechanical and electrical components can fail at any time. AutoHub is not responsible for any issues, defects, or failures that occur after the inspection has been completed.
- **Liability:** AutoHub shall not, under any circumstances, be liable to compensate or reimburse the customer for repair costs, whether arising from undetected issues, later failures, or differences between this report and subsequent assessments by third parties.

Use of report: This report is prepared exclusively for the client who ordered the inspection. It may be shared with others, but AutoHub accepts no responsibility or liability if relied upon by any third party. The report is provided for information only and should not be considered a guarantee or warranty.

العربية

- بيع. الشراء أصية ب تالة أ ك اننا أعتبر ضري مركبة، وعامة لحالة اييم اى تاعدتك ع ه مغرض م.ط. فحص فت ا و مركبة فلة اكس د تقرير يا ا
- داخلية. مكونات اص ا م في زاء، و أ كيك أم تي.كانيكي. ير م خلي و ر تري غ ص ب ف.تقرير. ا ا ه مذكورة فبنود اى ا ط عتصر ففحص ي:**فحص: ا ق ا**
- بائع. ل ا ق مذكورة ممزايا ا مواصفات ا كيلومترات ادا ا ع حقق م توهاب لا أ ا أ.ستدعاء. عارات ا ا حوادث أريخ ا ت مركبة أ صيانة ل ل ا مل س ي فحص لا:**استثناءات:**
- فحص. ت اهر و تتي لامخفية ا ا متقطعة أ مشاكل اوصا ا تشفة، خر معيوب غضا قى ب تيارية، ق ص م اليب ف توهاب أ تخدام ا ا رغم مى ا:**متقطعة: ا مخفية أ عطل ا**
- فحص. تهاء اداهر ب اكل ت م طال أ أ أولة ع ر م توهاب غ.ت. و أ عطل ف ت لكهربائية قميكانيكية و مكونات ا:**مستقبلية: حالة ا**

لث. ف ث ط ق م ييم لاي تتقرير و ا ان هوقات ب فقة أ طال لا أ تشفة أ ر م طال غ أ ناتجة ع صلاح ا اليف ا اد ت س و يض أ أولية ت ظروف، م ا ف م ظ ت أ توهاب، ت حمل أ ت:**مسؤولية:**

ة. ي ط و معلومات فرض ا ق ت م لتقرير م.لث. ف ث ل ط ق يه معتماد ع ا ا تؤولية إ م حمل أ توهاب لا كن أرى، و راف أ أ اركته م كن م.فحص. ب اذي ط عميل اريال د د تقرير م ا ا:**تقرير: تخدام ا**

ب ا عذار. ضمنا أ و كفا

Still need support? Please [contact](#) for any additional inquiries

Thank you for your business