


Micro-Cantilever Fracture Toughness Data Summary

Room Temperature Only (Missing Dataset 02: No HT data)

(a) Distribution by Interface



(b) G_c vs. Beam Geometry (Size Effect Check)

