

The breadcrumb persists in the .noinit region (top of RAM), so after the reset the firmware can report the failing bank addresses and values over the diagnostics USART