Service Inspection Sheet

Name: Chris Suwoo
Year/Model: 2018 Lexus IS250
Date: 04/29/2024
RO #: 82093
Odometer: 123,329
VIN: 1GCHK23U56F132343
Email: chrisuwoo@email.com
Phone: 7788553645

☑ Inspected & Okay ☐ Requires Future Attention ☐ Requires Immediate Attention

Body Condition | Lights | Tires

LEFT FRONT
☑ 9/32
☐ ____
☐ ____

RIGHT FRONT
☑ 9/32
☐ ____
☐ ____

☐ ☐ ☑ Headlights



LEFT REAR
☑ 8/32
☐ ____
☐ ____

RIGHT REAR
☑ 8/32
☐ ____
☐ ____

☑ ☐ ☐ Turn Signals ☑ ☐ ☐ Tail Lights

☐ Tire Rotation Needed ☐ Alignment Needed ☐ Wheel Balance Needed

Comments:

Left front low beam light is out

Operating Systems

☐	☐	☑	ENGINE AIR FILTER
☑	☐	☐	ENGINE DRIVE BELT(S)
☑	☐	☐	COOLING SYSTEM HOSES AND LINES
☐	☐	☑	CABIN AIR FILTER
☑	☐	☐	A/C OUTPUT
☑	☐	☐	SPARK PLUGS
☑	☐	☐	FUEL SYSTEM/THROTTLE BODY
☑	☐	☐	DRIVELINE FLUIDS
☑	☐	☐	SUSPENSION - SHOCKS AND STRUTS
☑	☐	☐	EXHAUST SYSTEM
☑	☐	☐	ENGINE OR TRANSMISSION OIL LEAKS
☑	☐	☐	OTHER LEAKS
☑	☐	☐	DRIVE AXLE/BOOTS
☑	☐	☐	OTHER (PLEASE COMMENT)

Comments:

Replace air filter and cabin filter

WIPERS

☐	☐	☑	FRONT WIPERS
☑	☐	☐	REAR (IF APPLICABLE)
☑	☐	☐	WINDSHIELD CONDITION

BATTERY

☑	☐	☐	BATTERY CONDITION
☑	☐	☐	CABLES & CONNECTIONS

Comments:

Front wipers streaky, rear wipers n/a

VITAL FLUIDS

☑	☐	☐	ENGINE OIL
☑	☐	☐	TRANSMISSION FLUID
☑	☐	☐	POWER STEERING FLUID
☑	☐	☐	COOLANT
☑	☐	☐	BRAKE FLUID
☑	☐	☐	WASHER FLUID
☐	☐	☐	HIGH VOLTAGE COOLANT

Comments:

Topped up washer fluid

Brake System

Left Front
☑ 50% or more
☐ 20%-50%
☐ 20% or less

Right Front
☑ 50% or more
☐ 20%-50%
☐ 20% or less



Left Rear
☐ 50% or more
☐ 20%-50%
☑ 20% or less

Right Rear
☐ 50% or more
☐ 20%-50%
☑ 20% or less

Comments:

Replace rear brake pads @ 3mm

TECHNICIAN: Ian Pinili

FINISH