




Genesis Electrified GV70
FL SUV, 5 DOORS
April, 2026



Pedestrian protection active system



	Airbag		Airbag inflator		Seat belt Pretensioner		SRS control unit
	Battery low-voltage		Gas strut / Preloaded spring		High strength zone		Fuse box disabling high voltage
	Battery pack, high-voltage		High voltage power cable		High voltage component		Pedestrian protection active system

1. Identification / Recognition



LACK OF ENGINE NOISE DOES NOT MEAN VEHICLE IS OFF: SILENT MOVEMENT OR INSTANT RESTART CAPABILITY EXISTS UNTIL VEHICLE IS FULLY SHUT DOWN.



Brand Logo

Charging Door

GENESIS



2. Immobilisation / stabilisation / lifting

■ Vehicle Securing

1





2



1. For vehicles with automatic transmissions, press the brake pedal and shift the gear to Parking mode by pressing the “P” button.
2. Engage the Electronic Parking Brake (EPB) by pulling the switch and secure the wheels.

■ Vehicle Lifting Points Underneath the Vehicle:




3. Disable direct hazards / safety regulations





IN CASE OF AN ACCIDENT, WHERE AIRBAGS AND SEATBELT PRETENSIONER WERE ACTIVATED, THE HV-SYSTEM SWITCH'S OFF AUTOMATICALLY.
FOR ALL OTHER CASES USE THE DISABLING METHODS BELOW



■ Access to the 12V Battery (Located in the Trunk)



or



1. Press the trunk release button on the lower driver's side or the trunk switch.

2. Remove the tray inside the trunk board.

Deactivation Method:

- 12V Battery 



- H.V. Battery 

 The "high-voltage switch" does not fully detach, 




4. Access to the occupants

■ Seat Adjustment



■ Steering Column Adjustment




■ Glass




- 1-2 : Laminated Glass
- 3 : Tempered, Laminated(OPT) Glass
- 4-5 : Tempered Glass

■ High-Strength Steel Frame

-  High-Strength Steel(100K ↑)
-  CFRP



5. Stored energy / liquids / gases / solids

	697V	
	12V	
	R-1234yf 900g ± 25g	




WHEN COOLANT LEAKS FROM THE BATTERY PACK, IT CAN BECOME UNSTABLE WITH RISK OF THERMAL RUNAWAY. CHECK BATTERY PACK TEMPERATURE WITH THERMAL IMAGING CAMERA



6. In case of fire



Use large amount of water.





BATTERY RE-IGNITION!





Warning gas lifter!



Risk of missile effect of hood and tailgate.

7. In case of submersion



Do not touch any of the high-voltage components or cables including the high voltage cut-off switch, as doing so poses an electrocution hazard. Work on the vehicle only after the vehicle has been pulled out of the water.



8. Towing / transportation / storage


OK :




Not OK :



Front Hook



Rear Hook



9. Important additional information

10. Explanation of pictograms used

	General warning sign		Warning, Electricity		Electric Vehicle
	Air-conditioning component		Use thermal Infrared camera		Use water to extinguish the fire
	Acute toxicity		Corrosives		Environmental hazard
	Explosive		Flammable		Hazardous to the human health
	Hood		Trunk		