


EWR D&I ANNOTATION



FAN-000001L093001DP129-4460

Artemis # : 000001L093001DP129

Record Created Date : 09/13/2010

Printed Date : 10/27/2010

Description : DI10-006. SEQ ID 129. 2009 Q3. VEHICLE IN QUESTION IS A 2007 CHEVY COBALT THAT WAS TRAVELLING ON THE HIGHWAY. POLICE REPORT STATES THAT THE DRIVER WAS TRAVELING TOO FAST FOR THE CONDITIONS AND TRIED NEGOTIATING A RIGHT HAND CURVE. THE VEHICLE STARTED TO ROTATE, WENT OFF THE ROAD, STRUCK A PHONE BOX, AND ROLLED. THE DRIVER WAS EJECTED DURING THE INCIDENT AND WAS KILLED. THE WIFE OF THE DRIVER SAYS THE AIR BAGS DID NOT DEPLOY AND SHOULD HAVE. THE VEHICLE WAS TOTALLED. THE PRE CRASH DATA SHOWS THE VEHICLE GOING ABOUT 42MPH BEFORE THE ACCIDENT, BUT THE MAXIMUM CHANGE IN VELOCITY WAS LESS THAN 11MPH. GM STATES THAT THEY WILL NOT HONOR THE REQUEST FOR DAMAGES. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

July 6, 2010

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI10-006

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents
For Reporting Category: L
For the following Sequence IDs: 6, 12, 13, 14, 15, 16, 17, 46, 47, 50, 60, 61, 93, 103, 105, 106, 115, 119, 129, 132, 135, 147, 161, 171, 185, 186, 187, 188, 189, 190, 192, 193, 194, 215, 231, 239, 242, 271, 278, 281, 297, 321, 326, 342, 344, 349, 350, 352, 355, 375, 384, 386, 450, 451, 452, 462, 467, 471, 478, 495

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **August 6, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

AUG 18 2010

August 17, 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI10-006

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated July 6th, 2010 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2009.

GM's response is comprised of 62 disks for the incidents that are the subject of DI10-006.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 6 48649735-678866 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 6 48649735-678866_00_**Request and Responses**. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI10-006
6 48649735-678866
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. **Provide a copy of the Police Accident Report.**

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 6 48649735-678866 **_01_001** - is the first document responsive to Inquiry no. 1.
 6 48649735-678866 **_02_001** - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI10-006, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(60 Vehicles from the Light Vehicle Template)			
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)		TYPE
6	5GAER23D19J		NISM
12	1G4HD57267U		NISM
13	1G4HD57287U		NISM
14	1G4HE57Y48U		NISM
15	1G4HD57278U		NISM
16	1G4HD57218U		NISM
17	1G4HD57248U		NISM
46	1G6DT57V380		NISM
47	1G6DF577880		NISM
50	1G6DS57V890		NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
60	1G6KD57Y17U [REDACTED]	NISM
61	1G6KD57947U [REDACTED]	NISM
93	KL1TJ58Y05B [REDACTED]	NISM
103	KL1TD66E09B [REDACTED]	NISM
105	KL1TD56E19B [REDACTED]	NISM
106	2G1FC1EV0A9 [REDACTED]	NISM
115	1G1AK55F267 [REDACTED]	PAR
119	1G1AK15F967 [REDACTED]	NISM
129	1G1AK55F677 [REDACTED]	NISM
132	1G1AK58F887 [REDACTED]	NISM
135	1G1AM58B187 [REDACTED]	NISM
147	1G1YY26W185 [REDACTED]	LIT
161	2CNFLGEYXA6 [REDACTED]	NISM
171	3GNDA13D57S [REDACTED]	NISM
185	2G1WF52E349 [REDACTED]	NISM
186	2G1WF52E659 [REDACTED]	NISM
187	2G1WH52K359 [REDACTED]	NISM
188	2G1WF52E859 [REDACTED]	NISM
189	2G1WF52E659 [REDACTED]	NISM
190	2G1WF52E359 [REDACTED]	NISM
192	2G1WC581469 [REDACTED]	NISM
193	2G1WB58K669 [REDACTED]	NISM
194	2G1WB58K069 [REDACTED]	NISM
215	2G1WB5ENXA1 [REDACTED]	NISM
231	1G1ZG57BX84 [REDACTED]	NISM
239	1G1ZH57B69F [REDACTED]	NISM
242	1G1ZK57749F [REDACTED]	NISM
271	2GCEK19T541 [REDACTED]	NISM
278	1GCEK19C47Z [REDACTED]	NISM
281	2GCEK19J171 [REDACTED]	NISM
297	1GCHK73K79F [REDACTED]	NISM
321	1GNEC13T75R [REDACTED]	LIT
326	2CNBJ13C036 [REDACTED]	NISM
342	1GNDD13S142 [REDACTED]	NISM
344	1GNDD13S042 [REDACTED]	NISM
349	1GNDD13S852 [REDACTED]	NISM
350	1GNDD13S352 [REDACTED]	NISM
352	1GNDD13S362 [REDACTED]	NISM
355	1GNDS13SX62 [REDACTED]	NISM
375	1GNDV23178D [REDACTED]	PAR
384	1GKER137X8J [REDACTED]	NISM
386	1GTDS43E888 [REDACTED]	LIT
450	1G2AL18H797 [REDACTED]	NISM
451	1G2AS18H197 [REDACTED]	NISM
452	1G2AS18H297 [REDACTED]	NISM
462	1G2ZH57N784 [REDACTED]	NISM
467	1G2ZG57N994 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
471	1G2ZM577194 [REDACTED]	PAR
478	2G2WP552061 [REDACTED]	LIT
495	1G8ZS57B49F [REDACTED]	NISM

2. **Provide a copy of the Police Accident Report.**

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. **At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 62 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot shows a legal case cover sheet for 'ERIC D. PARIS, ESQ., S/B# 147836' vs. 'V. CHEVROLET'. The document is titled 'CIVIL CASE COVER SHEET' and includes various checkboxes for case type, complexity, and remedies. Annotations on the right side of the image provide instructions for navigating through the document and scaling the view:

- Step 7: Next File (Image)**: Points to the 'Next Image' button.
- Step 7: Next Page**: Points to the 'Next page' button (Ctrl+PgDn).
- Step 8: Scale Image**: Points to the 'Scale' dropdown menu, which includes options for 'Fit Scale to fit', '1:2 Scale 50%', '1:1 Scale 100%', and '2:1 Scale 200%'.
- Step 7: Image Properties**: Points to the 'Image Properties' button.

The cover sheet itself contains the following information:

ATTESTATION BY PLAINTIFF'S ATTORNEY
 ERIC D. PARIS, ESQ., S/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91766
 TELEPHONE NO. 909-469-5127 FAX NO. 909-469-5126

DEFENDANT'S NAME V. CHEVROLET

CIVIL CASE COVER SHEET
☐ Limited ☒ Unlimited

Complex Case Designation
☐ Complex ☐ Joinder

FILED WITH FIRST APPEARANCE BY DEFENDANT
☐ Cal. Rules of Court, rule 18-11

PLEASE COMPLETE ALL FIVE (5) SECTIONS BELOW

1. Check one box below for the case type that best describes this case:

- ☒ Auto (22)
- ☐ Other PFDVD (Personal Injury/Property Damage/Wrongful Death) Tort
- ☐ Arbitration (24)
- ☐ Product liability (24)
- ☐ Medical negligence (45)
- ☐ Other PFDVD (23)
- ☐ Non-PFDVD (Other) Tort
- ☐ Business tort/unfair business practice (27)
- ☐ Civil rights (e.g., discrimination, false arrest) (30)
- ☐ Defamation (e.g., slander, libel) (13)
- ☐ Fraud (14)
- ☐ Intellectual property (15)
- ☐ Professional negligence (e.g., legal malpractice) (25)
- ☐ Other non-PFDVD tort (32)
- ☐ Employment
- ☐ Wrongful termination (26)
- ☐ Other employment (15)
- ☐ Contract
- ☐ Breach of confidentiality (36)
- ☐ Collections (e.g., money owed, open book accounts) (28)
- ☐ Insurance coverage (18)
- ☐ Other contract (37)
- ☐ Real Property
- ☐ Eminent domain/expropriation/condemnation (14)
- ☐ Wrongful eviction (30)
- ☐ Other real property (e.g., over lease) (38)
- ☐ Unlawful Detainer
- ☐ Commercial (21)
- ☐ Residential (32)
- ☐ Drugs (34)
- ☐ Judicial Review
- ☐ Asset forfeiture (35)
- ☐ Pollution/contamination/nuisance (11)
- ☐ Will or testament (33)
- ☐ Other (39)

2. This case ☒ is ☐ is not complex under rule 18-09 of the California Rules of Court.

3. Type of remedies sought (check all that apply):

- ☒ Monetary ☐ Nonmonetary, declaratory or equitable relief

4. Number of causes of action (specify): FIVE

5. This case ☐ is ☒ is not a class action suit.

Case: JULY 3, 2009

ERIC D. PARIS, ESQ., S/B# 147836

NOTICE
 Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (see under the Probate, Family, or Welfare and Institutions Code) (Cal. Rules of Court, rule 18-09).
 If this case is complex under rule 18-09 of the California Rules of Court, you must attach this to the action or proceeding.
 When this is a complex case, this cover sheet must be used for statistical purposes only.

CIVIL CASE COVER SHEET

DI10-006
129 48649657 – 678717
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

.

.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Injury
Address	City	Involved Dir		Safety	Yes
State ZipCd	Con Acct	Source	Phone	Updated	9/22/2009 05:13:58 PM
Serial #/VIN 1G1AK55F677	Model Year 2007	Priority	Medium	License #	CHEVROL
Make Chevrolet	Warr. Start 10/04/2005	Status	Open	Owner	MARQUEMO
Model Cobalt	Mileage 42000	Sub-Status		Opened	9/21/2009 08:30:34 AM
Abstract Collision - Fatality - Restraints - (SIR) - Driver Front				Closed	
Customer Description	***This is a BRC PAR Case. Please do not assume. Forward any inquiries to Monica Marquez at ext.21072 ***				

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	8/9/2009 09:30:45 PM	Y	0	1	Concrete	Dry	n/a	37-0423-09
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		5'8"		no				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Boone	Ronnie	(770) 246-5525	State Farm Insurance					
Incident Loc	Highway 52 Dahlonega GA	Incident Desc	Her husband was going into an S curb and the car rolled 3 times and the airbag did not deploy and killed my husband					
Component	Restraints - (SIR) - Driver Front	Damage Desc	the veh was totalled					
Vehicle Loc	State Farm Insurance (Georgia)	Add'l Info	my husband was declared dead on arrival on the hospilla					
Emgcy Svc Names	Lumpkin County Police Dept	Maint Loc	CARL BLACK CHEVROLET 535 MURFREESBORO RD NASHVILLE TN 37210-3509 615-748-					

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	unknown
Vehicle Speed		Weather Condition	unknown	Prop Owner	unknown	Property Type	unknown	
Last Service Date		Loc Last Service		Property Location	unknown	Prop Est Repair Cost		
Veh Est Repair Cost		Spec Equip Installer	unknown	Prop Damage Description	unknown			
Primary Veh Use		Inspection Type	Restraint System SIR/Seat Belt	Inspected By	Inspection Not Performed	Inspection Date/Time		
Veh Damage Description	unknown of speed - the veh was totalled			Explain Other	File forwarded to ESIS			

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	airbag did not deploy
Injury Description	Medical Rpt#	Treatment Location	Treated By			
Fatality	unknown	unknown	unknown			
Street Address	City	State	Zip Code			

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 05:22:03 PM	MARQUEM O	MARQUEMO	Scheduled Follow-up		Scheduled Alarm		Follow up with ESIS

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

THIS IS NOT A SCHEDULED CALL (SOCC). PLEASE DO NOT ADVISE THE CUSTOMER OF THIS SCHEDULED ACTIVITY. FORWARD ANY QUESTIONS TO OCRS.

Check file to see if it has been picked up by ESIS. If so, close file.

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 05:20:48 PM	MARQUEM O	ESISBIQU	Escalation	ESIS - Fatalities	In Progress		Assign to ESIS

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Fatality

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 05:09:45 PM	MARQUEM O	MARQUEMO	Ownership Changed	Ownership Escalated to BRC	Done	9/22/2009 05:09:45 PM	Ownership Escalated to BRC

Contact Last Name Contact First Name Account BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:57:27 PM	KINZERTH	MARQUEMO	Ownership Changed		Done	9/22/2009 12:57:27 PM	Service Request Ownership has changed FROM: REYESJ1 TO: MARQUEMO

Contact Last Name Contact First Name Account BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:57:09 PM	KINZERTH	MARQUEMO	BRC PAR	Initial Contact- AVM	Done	9/22/2009 05:20:38 PM	Called

Contact Last Name Contact First Name Account BAC Code

Comments

No address in file to located closest DVM - Located dir in GMVIS and found: BURT CHEVROLET/HERTZ
14501 HERTZ QUAIL SPRINGS PARKWAY
OKLAHOMA CITY , OK 73134-2628
No DVM called

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:57:00 PM	KINZERTH	MARQUEMO	BRC PAR	Initial Contact- Dealer	Done	9/22/2009 05:12:43 PM	no call needed
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

No need to call Dlr. Vehicle beyond warranty and has not been to dealer in two years.

Monica Marquez/BRCPAR/ATX X21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:56:52 PM	KINZERTH	MARQUEMO	BRC PAR	Initial Contact- Phone	Done	9/22/2009 05:15:22 PM	Called
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

No call made - Fatality Involved - sending file over to ESIS. No contact made back to customer.

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:56:42 PM	KINZERTH	MARQUEMO	BRC PAR	Acknowledgement	Done	9/22/2009 05:15:14 PM	Called
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

No call made - Fatality Involved - sending file over to ESIS. No contact made back to customer.

Monica Marquez/BRCPAR/ATX
x21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:56:33 PM	KINZERTH	MARQUEMO	Notify CRM		Done	9/22/2009 05:14:31 PM	File Assigned

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:56:26 PM	KINZERTH	MARQUEMO	Research		Done	9/22/2009 05:14:27 PM	Research VIN

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS Performed VIN Scan:

GMVIS: Found No Open Recalls

VIN: Found No Duplicate File

SVC History: No Service History Related to Allegation

Monica Marquez/BRC PAR/ATX
X21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:56:04 PM	KINZERTH	MARQUEMO	BRC PAR	Case Assigned	Done	9/22/2009 05:12:08 PM	Assigned to Monica Marquez x21072

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:55:57 PM	KINZERTH	REYESJ1	SR Opened		Done	9/22/2009 12:55:57 PM	SR in Status of Closed has been Re-Opened by KINZERTH
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 12:55:56 PM	KINZERTH	REYESJ1	SR Closed - Satisfied		Done	9/22/2009 12:55:56 PM	Service Request has been Closed Satisfied.
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 10:28:17 AM	REYESJ1	KINZERTH	Escalation	Initiate PAR	Done	9/22/2009 12:55:51 PM	Assigning activity to PAR QUEUE
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days

Received and assigned in PAR
Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 10:22:24 AM	REYESJ1	REYESJ1	Outbound Call Customer	Left Message	Done	9/22/2009 10:25:59 AM	7708719205
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

CRs left msg that file will be forwarded to PAR that will call her w/ in 2 business days

Johanna_Reyes/CAC/T1/LVL1/MLa.

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 10:21:01 AM	REYESJ1	REYESJ1	Inbound Call Customer	Voice Mail Received	Done	9/22/2009 10:25:44 AM	
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Cust left msg:

VIN-1g1ak551677
mileage-42,000
Insurance claim-S1561GCC1YK -Ronnie Boone
37-0423-09 - Police report
Cellphone #

Johanna_Reyes/CAC/T1/LVL1/Mla.

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 09:58:54 AM	REYESJ1	REYESJ1	Scheduled Outbound Call Cust	Follow-up Attempt	Done	9/22/2009 10:25:48 AM	follow up call
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Sept 24 @ 9-11 am est

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/22/2009 09:57:17 AM	REYESJ1	REYESJ1	Outbound Call Customer	Left Message	Done	9/22/2009 09:58:53 AM	
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Crs left msg and contact info

Johanna_Reyes/CAC/T1/LVL1/Mla.

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/21/2009 09:01:35 AM	REYESJ1	REYESJ1	Scheduled Outbound Call	Initial Attempt	Done	9/22/2009 09:57:16 AM	verify VIN and other info

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/21/2009 08:31:11 AM	REYESJ1	REYESJ1	Inbound Call Customer	Complex Request	Done	9/21/2009 09:00:31 AM	airbags did not deploy

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Cust Sts:

-my husband was going around the curb and the car rolled and either of the airbag deployed and it killed my husband
-2007 Cobalt and i dont have the papers here...am at work and everything is in the house
-it happened last Aug 9, 2009

Cust Sks:

-why airbag did not deploy

Crs Advsd:

-informed cust that CRS will document concern but need all the info like VIN, Police report # and insurance claim # before file can be forwarded to PAR
-provided cust the SR #

Cust Sts:

-ill call later when i arrive home
-thank you

Johanna_Reyes/CAC/T1/LVL1/Mla.

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
C48	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Front

GM Vehicle Inquiry System Summary

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AK55F677
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AK69 -2007 COBALT 4-DOOR LS SEDAN			Warranty Start Date :		10/04/2006	
BARS Order Type :	50 - FLEET						
Delivering Dealer :	BURT CHEVROLET/HERTZ 14501 HERTZ QUAIL SPRINGS PARKWAY OKLAHOMA CITY , OK 73134-2628			Selling Source :		13 - CHEVROLET	
				Site Code :		10076	
				Business Associate Code :		113019	
Service Contract :	No	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns

SERVICE INFORMATIONAL ITEMS

Type	Number	Description	Posted Date	Status
EI	09110	SIR/AIRBAG LIGHT ILLUMINATED, DTC B0081 SET(REF. TSB 09-09-41-003)	05/05/2009	See Bulletin

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	10/04/2006	10 miles	10/04/2009	36010 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	10/04/2006	10 miles	10/04/2012	100010 miles
60/100000 POWERTRAIN COVERAGE LIMITED WARRANTY	10/04/2006	10 miles	10/04/2011	100010 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	10/04/2006	10 miles	10/04/2014	80010 miles
36/36000 FEDERAL EMISSION	10/04/2006	10 miles	10/04/2009	36010 miles

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
09/19/2007	P53756	#	Z2084 - ROADSIDE SERVICE (FLAT TIRE)	22000 miles
10/03/2006	A78479	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 2009 General Motors. All Rights Reserved.

GM Vehicle Inquiry System Claim History

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AK55F677	
-------	-------------	--

CLAIM HISTORY

Repair Order Date :		09/19/2007		Repair Order Number :		P53756		Odometer Reading :		22000 miles	
Serviced By :		GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117				Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
09/28/2007	834	01	#	Z2084 - ROADSIDE SERVICE (FLAT TIRE)		N/A		C	N/A	\$ 42.75	N

Repair Order Date :		10/03/2006		Repair Order Number :		A78479		Odometer Reading :		0 miles	
Serviced By :		HERTZ CORPORATION 14501 HERTZ QUAIL SPRINGS PARKWAY OKLAHOMA CITY, OK 73134-2606				Selling Source :			13 - CHEVROLET		
						Site Code :			99339		
						Business Associate Code :			126633		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
10/06/2006	732	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME		N/A		N/A	N/A	\$ 61.19	N

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 2009 General Motors. All Rights Reserved.

GM Vehicle Inquiry System Vehicle Build

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN	1G1AK55F677
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AK69 -2007 COBALT 4-DOOR LS SEDAN		
Gross Vehicle Weight Rating :	1702 kg (3753 lb)	Order Number :	KJRGMG
Build Date :	10/03/2006	Build Plant :	177A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AL0 - SENSOR INDICATOR INFLATABLE RESTRAINT, FRT PASS/CHILD PRESENCE DETECTOR
AR9 - DELUXE FRONT BUCKET SEAT	AT8 - RESTRAINT PROVISIONS CHILD, RR SEAT, RR FACING
B8P - GM PRODUCTION WEEK #40	B84 - BODY COLOR, BODYSIDE MOLDINGS
C67 - ELECT. FRONT AIR CONDITIONER	DC8 - MIRROR, O/S MANUAL FLDG, BLK
D36 - MIRROR I/S R/V TILT	FCH - HERTZ RENT A CAR
FE1 - SUSPENSION SYSTEM-SOFT RIDE	FE9 - FEDERAL EMISSIONS
FLT - FLEET PROCESSING OPTION	FY1 - TRANS/AXLE 3.63 RATIO
IPB - INTERIOR TRIM DESIGN	J41 - BRAKE, FRONT DISC/REAR DRUM
K64 - 115 AMP GENERATOR	LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO
L61 - ENGINE, 2.2L DOHC 4V ECOTEC	MN5 - 4 SPEED AUTO TRANSMISSION
MX0 - TRANSMISSION, 4 SPD AUTOMATIC	NT7 - FEDERAL EMISSION TIER 2
N45 - 3 SPOKE STEERING WHEEL	PG1 - 15" STEEL WHEEL
QTU - P195/60R15 TOURING BW TIRES	R6F - IDENTIFY B-CODE USERS
R6K	R6P - PREMIUM PAINT
R9N - HEATED LEATHER APPOINTED FRONT BUCKET SEATS	UQ4 - BASE SPEAKER SYSTEM
U1C - AM/FM STEREO, CD PLAYER	VK3 - FRONT LICENSE PLATE BRACKET
VQ2 - FLEET ORDERING AND ASSISTANCE	VT7 - OWNERS MANUAL ENGLISH

VX7 - LONG TERM DAILY RENTAL PROGRAM	V2G - FULL FUEL FILL CREDIT
V73 - STATEMENT OF VEHICLE CERT.- U.S. /CANADA	1LS - 1LS BASE PACKAGE
1SZ - OPTION PACKAGE DISCOUNT	14B - GRAY
14I - GRAY	41U - BLACK
6AR - FRONT SPRING	7AR - FRONT SPRING
8AA - REAR SPRING	9AA - REAR SPRING

© 2009 General Motors. All Rights Reserved.


Accident Number (b) (6)		Agency NCIC No. (b) (6)		DPS 523E GEORGIA MOTOR VEHICLE (1/2004) ACCIDENT REPORT		County Lumpkin		Date Received		Page 1 Of 2	
Date 08/09/2009		Day Of Week ☒ Sun ☐ M ☐ T ☐ W ☐ Th ☐ F ☐ S		Time 2144		Off. Arrived 2206		Total Number Of Vehicles Injured Fatalities 1 0 1		Inside City Of	
Road Of Occurrence GA 52								At Its Intersection With Eastwood Terrace		Corrected Report Yes	
Not At Its Intersection But 1								1 Interstate 2 Lowest St Rt 3 Co Road 4 City St 1		Suppl. To Original Yes	
And Continuing in the Direction Checked Above Buffington Road								1 Interstate 2 Lowest St Rt 3 ☒ Co Road 4 City St 5 Co Lane		Hit and Run? Yes	
The Next Reference Point is 1 Interstate 2 Lowest St Rt 3 ☒ Co Road 4 City St 5 Co Lane											
Driver # 1				Last Name [REDACTED]				First [REDACTED]			
Middle [REDACTED]				Address [REDACTED]				City Cumming, GA			
State GA				Zip [REDACTED]				DOB [REDACTED]			
Driver's License No. [REDACTED]				Class C				State GA			
Male ☒				Female ☐							
Posted Speed 45				Insurance Co. State Farm				Policy No. [REDACTED]			
Year 2007				Make Chevrolet				Model Cobalt			
VIN 1G1AK55F677				Vehicle Color Black							
Tag # [REDACTED]				State TN				County [REDACTED]			
Year 2009											
Trailer Tag # [REDACTED]				State [REDACTED]				County [REDACTED]			
Year [REDACTED]											
☒ Same as Driver				Owner's Last Name [REDACTED]				First [REDACTED]			
Middle [REDACTED]				Address [REDACTED]				City Cumming, GA			
State GA				Zip [REDACTED]							
Removed By Norrell's Towing				Request ☒ List							
Alcohol Test 1				Type 1				Results Pend			
Drug Test 1				Type 1				Results Pend			
Driver Condition 2				Direction of Travel 3				Vision Obscured 1			
Vehicle Condition 1				Vehicle Maneuver 10				Contributing Factors 10 22			
Most Harmful Event 1				Vehicle Class 1				Vehicle Type 1			
Traffic Control 6				Device Inoperative? Yes				No			
Injured Taken To Not Transported				By [REDACTED]							
EMS Notified Time 2144				EMS Arrival Time 2152				Hospital Arrival Time [REDACTED]			
Report By: TFC M.H. Cox #725				Department GSP Cumming				Report Date 08/09/2009			
Checked By: CPL A.W. Coleman #413				Date Checked 08/10/2009							
Witness(es) Name None Located				Address [REDACTED]				City [REDACTED]			
Zip Code [REDACTED]				Telephone No. [REDACTED]							
DMVS MICROFILM NUMBER (DO NOT WRITE IN THIS SPACE)											
COMMERCIAL VEHICLES ONLY											
Carrier Name Vehicle #						Carrier Name Vehicle #					
Address [REDACTED]						Address [REDACTED]					
City [REDACTED]						City [REDACTED]					
State [REDACTED]						State [REDACTED]					
Zip [REDACTED]						Zip [REDACTED]					
Number Of Axes 1		G.V.W.R. [REDACTED]		Fed. Reportable 1 Yes 2 No		Cargo Body Type [REDACTED]		Number Of Axes 1		G.V.W.R. [REDACTED]	
Vehicle Conf. 1		I.C.C.M.C. # [REDACTED]		U.S. D.O.T. # [REDACTED]		Interstate Intrastate 1		Vehicle Conf. 1		I.C.C.M.C. # [REDACTED]	
C.D.L. ? 1 Yes 2 No		C.D.L. Suspended ? 1 Yes 2 No		Hazardous Materials ? 1 Yes 2 No		Released ? 1 Yes 2 No		C.D.L. ? 1 Yes 2 No		C.D.L. Suspended ? 1 Yes 2 No	
Vehicle Placarded ? 1 Yes 2 No		Hazardous Materials ? 1 Yes 2 No		Released ? 1 Yes 2 No				Vehicle Placarded ? 1 Yes 2 No		Hazardous Materials ? 1 Yes 2 No	
Released ? 1 Yes 2 No								Released ? 1 Yes 2 No			
If Yes, Name or 4 Digit Number From Diamond or Box 1 Digit Number From Bottom of Diamond						If Yes, Name or 4 Digit Number From Diamond or Box 1 Digit Number From Bottom of Diamond					
Ran Off Road [REDACTED]						Down Hill [REDACTED]					
Cargo Loss [REDACTED]						Separation Of Units [REDACTED]					

Georgia Uniform Vehicle Accident Report Overlay

ALCOHOL AND/OR DRUG TEST GIVEN 1- Yes 2- No 3- Refused		PEDESTRIAN/INWELMER 1- Crossing At A Crosswalk 2- Crossing at Crosswalk 3- Walking with Traffic 4- Walking Against Traffic 5- Running or Walking on Vehicle		CONTRIBUTING FACTORS 1- No Contributing Factors 2- DUI 3- Following Too Close 4- Failed to Yield 5- Exceeding Speed Limit 6- Drugged Stop Sign/Sign 7- Wrong Side Of Road 8- Weather Conditions 9- Improper Passing 10- Driver Lost Control 11- Changed Lanes Improperly 12- Obeyed A Sign 13- Improper Turn 14- Parked Improperly 15- Mechanical or Vehicle Failure 16- Surface Defects 17- Misjudged Clearance 18- Improper Backing 19- No Signal/Improper Signal 20- Driver Condition 21- Driver's Vehicle 22- Too Fast For Conditions 23- Improper Passing or Struck Bus 24- Disregard Rules Officer 25- Distracted 26- Other 27- Cell Phone 28- Inattentive		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart	
TYPE TEST 1- Blood 2- Breath 3- Urine 4- Other		FIRST HARMFUL, SECOND MOST HARMFUL EVENT NO COLLISION 1- Overturn 2- Fire/Explosion 3- Immersion 4- Jackknife 5- Other Non-Collision		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart			
VEHICLE CONDITION 1- No Known Defects 2- Tire Failure 3- Brake Failure 4- Improper Lights 5- Steering Failure 6- Stick Tires 7- Other		COLLISION WITH OBJECT NOT FIXED 6- Pedestrian 7- Motorcycle 8- Railway Train 9- Animal 10- Parked Motor Vehicle 11- Motor Vehicle In Motion 12- Motor Vehicle In Motion In Other Roadway 13- Other Object (Not Fixed) 14- Deer 15- Impaired Pedestrian 16- Bridge Pier/Abutment 17- Bridge Pier/End 18- Bridge Rail 19- Gravel Face 20- Gravel End 21- Median Barrier 22- Highway Traffic Sign 23- Other 24- Utility Pole 25- Other Road 26- Other Road 27- Other 28- Other 29- Other 30- Other 31- Other 32- Other 33- Other 34- Other 35- Other 36- Other 37- Other 38- Other 39- Other 40- Other 41- Other 42- Other 43- Other 44- Other 45- Other 46- Other 47- Other 48- Other 49- Other 50- Other 51- Other 52- Other 53- Other 54- Other 55- Other 56- Other 57- Other 58- Other 59- Other 60- Other 61- Other 62- Other 63- Other 64- Other 65- Other 66- Other 67- Other 68- Other 69- Other 70- Other 71- Other 72- Other 73- Other 74- Other 75- Other 76- Other 77- Other 78- Other 79- Other 80- Other 81- Other 82- Other 83- Other 84- Other 85- Other 86- Other 87- Other 88- Other 89- Other 90- Other 91- Other 92- Other 93- Other 94- Other 95- Other 96- Other 97- Other 98- Other 99- Other 100- Other		VEHICLE CLASS 1- Private/Owned 2- Police 3- Fire 4- School 5- Other Gov. Owned 6- Military 7- Commercial Vehicle (For Acc. Reporting Purposes Only) 8- Other			
VEHICLE INWELMER 1- Turning Left 2- Turning Right 3- Making U-turn 4- Stopped 5- Straight 6- Changing Lanes 7- Backing 8- Parked 9- Passing 10- Negotiating A Curve 11- Entering/Leaving Parking 12- Entering/Leaving Driveway		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart			
VEHICLE CONDITION 1- No Known Defects 2- Tire Failure 3- Brake Failure 4- Improper Lights 5- Steering Failure 6- Stick Tires 7- Other		COLLISION WITH FIXED OBJECT 15- Impaired Pedestrian 16- Bridge Pier/Abutment 17- Bridge Pier/End 18- Bridge Rail 19- Gravel Face 20- Gravel End 21- Median Barrier 22- Highway Traffic Sign 23- Other 24- Utility Pole 25- Other Road 26- Other Road 27- Other 28- Other 29- Other 30- Other 31- Other 32- Other 33- Other 34- Other 35- Other 36- Other 37- Other 38- Other 39- Other 40- Other 41- Other 42- Other 43- Other 44- Other 45- Other 46- Other 47- Other 48- Other 49- Other 50- Other 51- Other 52- Other 53- Other 54- Other 55- Other 56- Other 57- Other 58- Other 59- Other 60- Other 61- Other 62- Other 63- Other 64- Other 65- Other 66- Other 67- Other 68- Other 69- Other 70- Other 71- Other 72- Other 73- Other 74- Other 75- Other 76- Other 77- Other 78- Other 79- Other 80- Other 81- Other 82- Other 83- Other 84- Other 85- Other 86- Other 87- Other 88- Other 89- Other 90- Other 91- Other 92- Other 93- Other 94- Other 95- Other 96- Other 97- Other 98- Other 99- Other 100- Other		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart			
VEHICLE INWELMER 1- Turning Left 2- Turning Right 3- Making U-turn 4- Stopped 5- Straight 6- Changing Lanes 7- Backing 8- Parked 9- Passing 10- Negotiating A Curve 11- Entering/Leaving Parking 12- Entering/Leaving Driveway		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart			
VEHICLE INWELMER 1- Turning Left 2- Turning Right 3- Making U-turn 4- Stopped 5- Straight 6- Changing Lanes 7- Backing 8- Parked 9- Passing 10- Negotiating A Curve 11- Entering/Leaving Parking 12- Entering/Leaving Driveway		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart			
VEHICLE INWELMER 1- Turning Left 2- Turning Right 3- Making U-turn 4- Stopped 5- Straight 6- Changing Lanes 7- Backing 8- Parked 9- Passing 10- Negotiating A Curve 11- Entering/Leaving Parking 12- Entering/Leaving Driveway		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart		VEHICLE TYPE 1- Passenger Car 2- Pickup Truck 3- Truck Tractor (Flatbed) 4- Tractor/Trailer 5- Tractor With Trailer 6- Logging Truck 7- Logging Tractor/Trailer 8- Single Unit Truck 9- Panel Truck 10- Van 11- Utility Passenger Vehicle 12- Vehicle With Trailer 13- Bus 14- Truck Towing Heavy Trailer 15- Ambulance 16- Motorized Recreational Vehicle 17- Motorcycle, Scooter, Moped 18- Moped 19- Recreycle, Bicycle 20- Farm or Construction Equip. 21- All Terrain Vehicle 22- Other 23- Cart			

FRONT PAGE

BACK PAGE

TRAFFICWAY FLOW 1. Two-way Trafficway With No Physical Separation 2. Two-way Trafficway With a Physical Separation 3. Two-way Trafficway With a Physical Barrier 4. One-way Trafficway 5. Continuous Turning Lane		LOCATION AT AREA OF IMPACT 1. On Roadway 2. On Shoulder 3. Off Roadway 4. Median 5. Ramp 6. Cane		AGE 00 - Up To One Year 01 - 97 Adult Age 98 - Ninety-eight Or Older 99 - Unknown		SEX M - Male F - Female	
WEATHER 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet 6. Fog 7. Other		ROAD COMPOSITION 1. Concrete 2. Black Top 3. Tar And Gravel 4. Dirt 5. Gravel 6. Other		INJURY CODE 0 - Not Injured 1 - Killed 2 - Serious 3 - Visible 4 - Complaint		TAKEN FOR TREATMENT 1 - Yes 2 - No	
SURFACE CONDITION 1. Dry 2. Wet 3. Snowy 4. Icy 5. Other 6. Mud 7. Sand 8. Slush 9. Oil		CONTRIBUTING ROAD DEFECTS 1. No Defects 2. Deteriorative Shoulders 3. Holes, Deep Ruts, Bumps 4. Loose Material On Surface 5. Water Standing 6. Road Under Construction 7. Running Water 8. Other		CONSTRUCTION/MAINTENANCE ZONE CODES 0 - None 1 - Construction 2 - Maintenance 3 - Utility 4 - Unknown type		ELECTION 1 - Not Elected 2 - Trapped 3 - Totally Elected 4 - Partially Elected	
LIGHT CONDITION 1. Daylight 2. Dark 3. Dawn 4. Dark - Lighted 5. Dark - Not Lighted		ROAD CHARACTER 1. Straight And Level 2. Straight On Grade 3. Straight On Hillcrest 4. One And Level 5. One On Grade 6. One On Hillcrest		SAFETY EQUIPMENT 0 - None Used 1 - Shoulder Belt 2 - Lap Belt 3 - Lap and Shoulder Belt 4 - Child Safety Seat (Properly Used) 5 - Child Safety Seat (Improperly Used) 6 - Motorcycle Helmet 7 - Boy's Helmet 8 - Unknown		EXTINGUISHING EQUIPMENT USED 1 - Yes 2 - No	
MANNER OF COLLISION 1. Angle 2. Head On 3. Rear End 4. Sideswipe - Same Direction 5. Sideswipe - Opposite Direction 6. Not A Collision With a Motor Vehicle		DAMAGE TO VEHICLE 1 - None 2 - Slight 3 - Moderate 4 - Extensive 5 - Fire Present		AIR BAG FUNCTION 0 - No Air Bag In This Seat 1 - Deployed Air Bag 2 - Non-Deployed Air Bag 3 - Deployed Side 4 - Deployed other Directions 5 - Deployed Multiple Directions 6 - Non-Deployed Front 7 - Non-Deployed Side 8 - Non-Deployed Other Direction 9 - Non-Deployed Multiple Direction		SEATING POSITION 	
POINTS OF INITIAL CONTACT 00 - Outrigger 13 - Top 14 - Undercarriage 15 - Non-Contact Vehicle							

5

ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Annette Rigdon
Claims Administrator

November 11, 2009

[REDACTED]
Nashville, TN [REDACTED]

RE: Claimant: [REDACTED]
Our File No.: 678717
Our Client: General Motors Company
Date/Event: 8-09-09
Vehicle: 2007 Chev. Cobalt
VIN: 1G1AK55F677 [REDACTED]

Dear Stephanie:

This will confirm that we have completed our review of your claim regarding your 2007 Chev. Cobalt. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors Company, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Annette Rigdon
Claims Administrator

CDR File Information

User Entered VIN	1G1AK55F677
User	RYAN JAHR ESIS/GM
Case Number	678717
EDR Data Imaging Date	Friday, October 16 2009
Crash Date	Sunday, August 9 2009
Filename	1G1AK55F677ACM CDR
Saved on	Friday, October 16 2009 at 10:31:20 AM
Collected with CDR version	Crash Data Retrieval Tool 3.3
Reported with CDR version	Crash Data Retrieval Tool 3.3
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

IMPORTANT NOTICE: Robert Bosch LLC recommends that the latest production release of Crash Data Retrieval software be utilized when viewing, printing or exporting any retrieved data from within the CDR program. This ensures that the retrieved data has been translated using the most recent information including but not limited to that which was provided by the manufacturers of the vehicles supported in this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data
- no module is present to send the pre-crash data

- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

Multiple Event Data

Associated Events Not Recorded	2
An Event(s) Preceded the Recorded Event(s)	Yes
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	Yes
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	Yes

System Status At AE

Vehicle Identification Number	**1AK55F*7*
Low Tire Pressure Warning Lamp (If Equipped)	Invalid
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Neutral
Transmission Selector Position (If Equipped)	Neutral
Traction Control System Active (If Equipped)	Invalid
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	80
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	Invalid	Invalid
Cruise Control Resume Switch Active (If Equipped)	Invalid	Invalid
Cruise Control Set Switch Active (If Equipped)	Invalid	Invalid


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	42	29	0	0	0
Engine Speed (RPM)	1472	960	704	896	704
Percent Throttle	13	15	15	12	13
Accelerator Pedal Position (percent)	0	0	0	0	0
Antilock Brake System Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Lateral Acceleration (feet/s ²) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Steering Wheel Angle (degrees) (If Equipped)	0	0	0	0	0


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Non-Deployment

Ignition Cycles At Investigation	5676
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	5662
Ignition Cycles At Event	5673
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	UNBUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Automatic Passenger SIR Suppression System Validity Status at AE	Invalid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	10.87
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	110
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	No
Vehicle Event Data (Pre-Crash) Associated With This Event	No
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.68	0.68	0.68	0.68	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	-0.68	-0.68	-0.68	-2.03	-3.39	-5.42	-6.78	-8.81	-9.49	-10.85	-10.85	-10.85	-10.85	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 68 00 00 00 00 00 00
$02 10 00 00 00 00 00 00
$03 01 00 00 00 00 00 00
$04 00 00 00 00 00 00 00
$05 80 00 00 00 00 00 00
$06 00 0A 00 00 0A 39 15
$07 00 89 00 00 00 00 00
$08 00 FF 00 00 00 00 00
$09 00 6D 6C 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 05 0F 00 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 00 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F 00 00 00 00 00 00 00
$10 47 31 41 4B 35 35 46
$11 36 37 37 31 37 38 34
$12 37 39 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 00 00 00 00 00 00 00
$18 00 00 00 00 00 00 00
$19 00 00 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 02 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 00 00 00 00 00 00 00
$1F 28 00 00 00 00 00 00
$20 40 00 00 00 00 00 00
$21 00 00 00 00 F0 00 00
$22 00 94 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 00 FF F0 16 1E 00 00
$2F 00 FE 16 2C 03 00 00
$30 9D 00 00 00 00 00 00
$31 00 00 00 00 00 00 00
$32 00 00 00 80 00 00 00
$33 21 1F 26 25 22 00 00
$34 0B 0E 0B 0F 17 00 00
$35 00 00 00 2F 44 00 00
$36 00 00 00 00 00 00 00
$37 00 00 00 09 09 00 E2
$38 85 00 40 00 03 C0 00
$39 00 00 00 00 00 80 00
$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00
$3C 00 00 00 00 00 00 C0
$3D 31 41 4B 35 35 46 00
```

```

$3E 37 17 84 79 00 00 00
$3F AA 00 90 00 00 00 00
$40 00 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 00 FF F0 16 1E 00 00
$43 FE 16 29 00 00 00 00
$44 00 00 00 00 00 00 00
$45 00 00 00 00 00 00 00
$46 00 00 00 00 00 00 00
$47 00 00 FF 00 FF 00 00
$48 FF 00 FD 00 FB 00 00
$49 F8 00 F6 00 F3 00 00
$4A F2 00 F0 01 F0 01 00
$4B F0 01 F0 01 00 00 00
$4C 00 00 00 00 00 00 00
$4D 00 00 00 00 00 00 00
$4E 00 00 00 00 00 00 00
$4F 00 00 00 00 00 00 00
$50 00 00 00 00 00 00 00
$51 50 00 00 00 00 00 00
$52 80 00 00 00 00 00 00
$53 0B 01 01 00 00 00 00
$54 00 00 00 00 00 00 00
$55 00 00 00 00 00 00 00
$67 00 00 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

```

```

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 36 31 38 37 33 44 33 44 39
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 06 32 35 31 35 46 5A 35
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 37 35 E1 72 6A 74 91 9A
$22 39 15
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA

```

```
$26 32 41 FA FA FA FA FA
$40 00 00
$41 3F 00 00 02 00 1A
$42 D0 C4
$43 00 00 8E 80
$44 C6 00 00 FC C0 C0
$45 07 01 07 01 05 01
$46 FF 1B 1B 64 28
$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
$48 18 08 08
$B0 58
$B1 FD FE 00
$B2 FF FF FF FF FF
$B4 41 53 33 39 31 35 32 32 32 36 31 4A 20 20 20 20
$B7 50 AA 04 0F 07
$B8 43 48 70 02 09
$C1 30 46 30 37
$CA 30 46 30 37
$CB 01 89 6E 6B
$CC 01 89 6E 6B
$D1 00 00
$DB 00 00
$DC 00 00
```

Comments

CONNECTION: DLC VEHICLE POWER SUPPLIED BY BATTERY PACK

MILEAGE: 48318

LAMP TEST: FLASHED ON KEY POWER UP STAYS OFF.

LOCATION: GAINESVILLE SALVAGE GAINESVILLE GEORGIA.

PRESENT: RYAN JAHR ESIS/GM

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.

CDR File Information

User Entered VIN	1G1AK55F677
User	RYAN JAHR ESIS/GM
Case Number	678717
EDR Data Imaging Date	Friday, October 16 2009
Crash Date	Sunday, August 9 2009
Filename	1G1AK55F677_ACM_CDR
Saved on	Friday, October 16 2009 at 10:31:20 AM
Collected with CDR version	Crash Data Retrieval Tool 3.3
Reported with CDR version	Crash Data Retrieval Tool 3.3
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

IMPORTANT NOTICE: Robert Bosch LLC recommends that the latest production release of Crash Data Retrieval software be utilized when viewing, printing or exporting any retrieved data from within the CDR program. This ensures that the retrieved data has been translated using the most recent information including but not limited to that which was provided by the manufacturers of the vehicles supported in this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non-Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data

1G1AK55F677178479



-no module is present to send the pre-crash data

1G1AK55F677 [REDACTED]

Page 2 of 14

Printed on: Friday, October 16 2009 at 10:32:44 AM

TA000104298

-Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.

-The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.

-If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.

-The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.

-Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

-Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.

-The Belt Switch Circuit is wired directly to the SDM.

Ignition Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$2F Bytes 3-4	\$162C	Ignition Cycles at Investigation	5676	cycles

Vehicle Status Data (Pre-Crash)

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID Pack \$31 Byte 1	\$00	Accelerator Pedal Position (-1 sec)	0	% full throttle
DPID Pack \$31 Byte 2	\$00	Accelerator Pedal Position (-2 sec)	0	% full throttle
DPID Pack \$31 Byte 3	\$00	Accelerator Pedal Position (-3 sec)	0	% full throttle
DPID Pack \$31 Byte 4	\$00	Accelerator Pedal Position (-4 sec)	0	% full throttle
DPID Pack \$31 Byte 5	\$00	Accelerator Pedal Position (-5 sec)	0	% full throttle
DPID \$31 Byte 6 bit 7	\$00	Accelerator Pedal Position Validity Status	Valid	
DPID \$32 Byte 1 bit 7	\$00	Brake Switch State (-1 sec)	OFF	
DPID \$32 Byte 1 bit 6	\$00	Brake Switch State (-2 sec)	OFF	
DPID \$32 Byte 1 bit 5	\$00	Brake Switch State (-3 sec)	OFF	
DPID \$32 Byte 1 bit 4	\$00	Brake Switch State (-4 sec)	OFF	
DPID \$32 Byte 1 bit 3	\$00	Brake Switch State (-5 sec)	OFF	
DPID \$32 Byte 2 bit 7	\$00	Brake Switch State Validity Status	Valid	
DPID \$32 Byte 3 bit 7	\$00	Cruise Control Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 6	\$00	Cruise Control Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 5	\$00	Cruise Control Resume Switch Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 4	\$00	Cruise Control Resume Switch Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 3	\$00	Cruise Control Set Switch Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 2	\$00	Cruise Control Set Switch Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 1	\$00	Reduced Engine Power Mode (-1sec)	OFF	
DPID \$32 Byte 3 bit 0	\$00	Reduced Engine Power Mode (-2sec)	OFF	
DPID \$32 Byte 4 bit 7	\$80	Cruise Control Active Validity Status If Equipped	Invalid	
DPID \$33 Byte 1	\$21	Throttle Position (-1 sec)	13	% full throttle
DPID \$33 Byte 2	\$1F	Throttle Position (-2 sec)	12	% full throttle
DPID \$33 Byte 3	\$26	Throttle Position (-3 sec)	15	% full throttle
DPID \$33 Byte 4	\$25	Throttle Position (-4 sec)	15	% full throttle
DPID \$33 Byte 5	\$22	Throttle Position (-5 sec)	13	% full throttle
DPID \$33 Byte 6 bit 7	\$00	Throttle Position Validity Status	Valid	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$34 Byte 1	\$0B	Engine Speed (-1 sec)	704	RPM
DPID \$34 Byte 2	\$0E	Engine Speed (-2 sec)	896	RPM
DPID \$34 Byte 3	\$0B	Engine Speed (-3 sec)	704	RPM
DPID \$34 Byte 4	\$0F	Engine Speed (-4 sec)	960	RPM
DPID \$34 Byte 5	\$17	Engine Speed (-5 sec)	1472	RPM
DPID \$34 Byte 6 bit 7	\$00	Engine Speed Validity Status	Valid	
DPID \$35 Byte 1	\$00	Vehicle Speed (-1 sec)	0	MPH
DPID \$35 Byte 2	\$00	Vehicle Speed (-2 sec)	0	MPH
DPID \$35 Byte 3	\$00	Vehicle Speed (-3 sec)	0	MPH
DPID \$35 Byte 4	\$2F	Vehicle Speed (-4 sec)	29	MPH
DPID \$35 Byte 5	\$44	Vehicle Speed (-5 sec)	42	MPH
DPID \$35 Byte 6 bit 7	\$00	Vehicle Speed Validity Status	Valid	
DPID \$36 Byte 1	\$00	Steering Wheel Angle (-1 sec) If Equipped	0	degrees
DPID \$36 Byte 2	\$00	Steering Wheel Angle (-2 sec) If Equipped	0	degrees
DPID \$36 Byte 3	\$00	Steering Wheel Angle (-3 sec) If Equipped	0	degrees
DPID \$36 Byte 4	\$00	Steering Wheel Angle (-4 sec) If Equipped	0	degrees
DPID \$36 Byte 5	\$00	Steering Wheel Angle (-5 sec) If Equipped	0	degrees
DPID \$36 Byte 6 bit 7	\$00	Steering Wheel Angle Validity Status If Equipped	Valid	
DPID \$37 Byte 1 bit 7	\$00	Antilock Brake System Active (-1 sec) If Equipped	No	
DPID \$37 Byte 1 bit 6	\$00	Antilock Brake System Active (-2 sec) If Equipped	No	
DPID \$37 Byte 1 bit 5	\$00	Antilock Brake System Active (-3 sec) If Equipped	No	
DPID \$37 Byte 1 bit 4	\$00	Antilock Brake System Active (-4 sec) If Equipped	No	
DPID \$37 Byte 1 bit 3	\$00	Antilock Brake System Active (-5 sec) If Equipped	No	
DPID \$37 Byte 2 bit 7	\$00	Traction Control System Active (-1 sec) If Equipped	No	
DPID \$37 Byte 3 bit 7	\$00	Vehicle Dynamics Control Active (-1 sec) If Equipped	No	
DPID \$37 Byte 3 bit 6	\$00	Vehicle Dynamics Control Active (-2 sec) If Equipped	No	
DPID \$37 Byte 3 bit 5	\$00	Vehicle Dynamics Control Active (-3 sec) If Equipped	No	
DPID \$37 Byte 3 bit 4	\$00	Vehicle Dynamics Control Active (-4 sec) If Equipped	No	
DPID \$37 Byte 3 bit 3	\$00	Vehicle Dynamics Control Active (-5 sec) If Equipped	No	
DPID \$37 Byte 4 bits 3-0	\$09	Transmission Range (-1 sec) If Equipped	Neutral	
DPID \$37 Byte 5 bits 3-0	\$09	Transmission Selector Position (-1 sec) If Equipped	Neutral	
DPID \$37 Byte 6 bit 7	\$00	Service Engine Soon (Non-Emission Related) Lamp (1 sec)	OFF	
DPID \$37 Byte 6 bit 6	\$00	Service Vehicle Soon Lamp (1 sec)	OFF	
DPID \$37 Byte 6 bit 3	\$00	Brake System Warning Lamp If Equipped	OFF	
DPID \$37 Byte 6 bit 1	\$00	Low Tire Pressure Warning Lamp If Equipped	OFF	
DPID \$37 Byte 7 bit 7	\$E2	Antilock Brake System Active Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 6	\$E2	Traction Control System Active Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 5	\$E2	Vehicle Dynamics Control Active Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 4	\$E2	Transmission Range Validity Status If Equipped	Valid	
DPID \$37 Byte 7 bit 3	\$E2	Transmission Selector Position Validity Status If Equipped	Valid	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$37 Byte 7 bit 2	\$E2	Service Engine Soon (Non-Emission Related) / Service Vehicle Soon Lamp Validity Status	Valid	
DPID \$37 Byte 7 bit 1	\$E2	Low Tire Pressure Warning Lamp Validity Status If Equipped	Invalid	
DPID \$38 Byte 1	\$85	Outside Air Temperature (-1 sec) If Equipped	80	
DPID \$38 Byte 2 bit 7	\$00	Outside Air Temperature Validity Status (-1 sec) If Equipped	Valid	
DPID \$38 Byte 5 bits 7-6	\$03	Left Front Door Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 5-4	\$03	Right Front Door Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 3-2	\$03	Rear Door(s) Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 1-0	\$03	Left Rear Door Status (-1 sec) If Equipped	Unused	
DPID \$38 Byte 6 bits 7-6	\$C0	Right Rear Door Status (-1 sec) If Equipped	Unused	
DPID \$38 Byte 7 bit 7	\$00	Left Front Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 6	\$00	Right Front Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 5	\$00	Rear Door(s) Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 4	\$00	Left Rear Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 3	\$00	Right Rear Door Validity Status If Equipped	Valid	
DPID \$39 Byte 1	\$00	Lateral Acceleration (-1 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 2	\$00	Lateral Acceleration (-2 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 3	\$00	Lateral Acceleration (-3 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 4	\$00	Lateral Acceleration (-4 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 5	\$00	Lateral Acceleration (-5 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 6 bit 7	\$80	Lateral Acceleration Validity Status If Equipped	Invalid	
DPID \$3A Byte 1	\$00	Yaw Rate (-1 sec) If Equipped	0	
DPID \$3A Byte 2	\$00	Yaw Rate (-2 sec) If Equipped	0	
DPID \$3A Byte 3	\$00	Yaw Rate (-3 sec) If Equipped	0	
DPID \$3A Byte 4	\$00	Yaw Rate (-4 sec) If Equipped	0	
DPID \$3A Byte 5	\$00	Yaw Rate (-5 sec) If Equipped	0	
DPID \$3A Byte 6 bit 7	\$80	Yaw Rate Validity Status If Equipped	Invalid	

VIN Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3D Byte 1	\$31	Vehicle Identification Number (VIN) Digit 3	1	
DPID \$3D Byte 2	\$41	Vehicle Identification Number (VIN) Digit 4	A	
DPID \$3D Byte 3	\$48	Vehicle Identification Number (VIN) Digit 5	K	
DPID \$3D Byte 4	\$35	Vehicle Identification Number (VIN) Digit 6	5	
DPID \$3D Byte 5	\$35	Vehicle Identification Number (VIN) Digit 7	5	
DPID \$3D Byte 6	\$46	Vehicle Identification Number (VIN) Digit 8	F	
DPID \$3E Byte 1	\$37	Vehicle Identification Number (VIN) Digit 10	(b) (6)	
DPID \$3E Byte 2 bits 7-4	\$17	Vehicle Identification Number (VIN) Digit 12		
DPID \$3E Byte 2 bits 3-0	\$17	Vehicle Identification Number (VIN) Digit 13		
DPID \$3E Byte 3 bits 7-4	\$84	Vehicle Identification Number (VIN) Digit 14		
DPID \$3E Byte 3 bits 3-0	\$84	Vehicle Identification Number (VIN) Digit 15		
DPID \$3E Byte 4 bits 7-4	\$79	Vehicle Identification Number (VIN) Digit 16		
DPID \$3E Byte 4 bits 3-0	\$79	Vehicle Identification Number (VIN) Digit 17		

Multiple Event Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3F Byte 1 bit 7	\$AA	An Event(s) Preceded the Recorded Event(s)	Yes	
DPID \$3F Byte 1 bit 6	\$AA	An Event(s) was in Between the Recorded Event(s)	No	
DPID \$3F Byte 1 bit 5	\$AA	An Event(s) Followed the Recorded Event(s)	Yes	
DPID \$3F Byte 1 bit 4	\$AA	The Event(s) Not Recorded was a Deployment Event(s)	No	
DPID \$3F Byte 1 bit 3	\$AA	The Event(s) Not Recorded was a Non-Deployment Event(s)	Yes	
DPID \$3F Byte 1 bits 2-0	\$AA	Associated Events Not Recorded	2	

Power Mode Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3F Byte 3 bits 7-6	\$90	Vehicle Power Mode Status	Run	
DPID \$3F Byte 3 bit 5	\$90	Remote Start Status If Equipped	Inactive	
DPID \$3F Byte 3 bit 4	\$90	Run/Crank Ignition Switch Logic Level	Active	

Non-Deployment Or Deployment #2 Event Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$40 Byte 1 bit 7	\$00	Crash Record Locked	No	
DPID \$40 Byte 1 bit 6	\$00	Deployment Event Recorded in the Non-Deployment Record	No	
DPID \$40 Byte 1 bit 5	\$00	Vehicle Event Data (Pre-Crash) Associated With This Event	No	
DPID \$40 Byte 2	\$A5	Event Recording Complete	Yes	
DPID \$41 Byte 1 bit 7	\$00	Driver 1st Stage Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 6	\$00	Driver 2nd Stage Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 5	\$00	Driver Side Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 4	\$00	Driver Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 3	\$00	Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 1 bit 2	\$00	Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 1 bit 1	\$00	Driver Knee Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 7	\$00	Passenger 1st Stage Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 6	\$00	Passenger 2nd Stage Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 5	\$00	Passenger Side Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 4	\$00	Passenger Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 3	\$00	Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 2 bit 2	\$00	Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 2 bit 1	\$00	Passenger Knee Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 7	\$00	Driver Anchor Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 6	\$00	Second Row Left Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 5	\$00	Third Row Left Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 3 bit 4	\$00	Second Row Right Side Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 3	\$00	Second Row Right Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 2	\$00	Third Row Right Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 3 bit 1	\$00	Center Rear Pretensioner Deployment Loop Commanded	No	
DPID \$42 Byte 1 bit 7	\$00	SIR Warning Lamp Status	OFF	
DPID \$42 Bytes 2-3	\$FFF0	SIR Warning Lamp ON/OFF Time Continuously	655200	seconds
DPID \$42 Bytes 4-5	\$161E	Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	5662	cycles
DPID \$43 Byte 1	\$FE	Ignition Cycles Since DTCs Were Last Cleared	254	cycles
DPID \$43 Bytes 2-3	\$1629	Ignition Cycles at Event	5673	cycles
DPID \$44 Bytes 1-2	\$0000	DTC number for fault #1	N/A	
DPID \$44 Byte 3	\$00	DTC fault type for fault #1	\$00	
DPID \$44 Bytes 4-5	\$0000	DTC number for fault #2	N/A	
DPID \$44 Byte 6	\$00	DTC fault type for fault #2	\$00	
DPID \$45 Bytes 1-2	\$0000	DTC number for fault #3	N/A	
DPID \$45 Byte 3	\$00	DTC fault type for fault #3	\$00	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$45 Bytes 4-5	\$0000	DTC number for fault #4	N/A	
DPID \$45 Byte 6	\$00	DTC fault type for fault #4	\$00	
DPID \$46 Bytes 1-2	\$0000	DTC number for fault #5	N/A	
DPID \$46 Byte 3	\$00	DTC fault type for fault #5	\$00	
DPID \$46 Bytes 4-5	\$0000	DTC number for fault #6	N/A	
DPID \$46 Byte 6	\$00	DTC fault type for fault #6	\$00	
DPID \$47 Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (10 ms after event enable or 70 ms before deployment)	0.00	MPH
DPID \$47 Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (10 ms after event enable or 70 ms before deployment)	0.00	MPH
DPID \$47 Byte 3	\$FF	SDM Recorded Vehicle Velocity Change for Axis #1 (20 ms after event enable or 60 ms before deployment)	-0.68	MPH
DPID \$47 Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (20 ms after event enable or 60 ms before deployment)	0.00	MPH
DPID \$47 Byte 5	\$FF	SDM Recorded Vehicle Velocity Change for Axis #1 (30 ms after event enable or 50 ms before deployment)	-0.68	MPH
DPID \$47 Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (30 ms after event enable or 50 ms before deployment)	0.00	MPH
DPID \$48 Byte 1	\$FF	SDM Recorded Vehicle Velocity Change for Axis #1 (40 ms after event enable or 40 ms before deployment)	-0.68	MPH
DPID \$48 Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (40 ms after event enable or 40 ms before deployment)	0.00	MPH
DPID \$48 Byte 3	\$FD	SDM Recorded Vehicle Velocity Change for Axis #1 (50 ms after event enable or 30 ms before deployment)	-2.03	MPH
DPID \$48 Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (50 ms after event enable or 30 ms before deployment)	0.00	MPH
DPID \$48 Byte 5	\$FB	SDM Recorded Vehicle Velocity Change for Axis #1 (60 ms after event enable or 20 ms before deployment)	-3.39	MPH
DPID \$48 Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (60 ms after event enable or 20 ms before deployment)	0.00	MPH
DPID \$49 Byte 1	\$F8	SDM Recorded Vehicle Velocity Change for Axis #1 (70 ms after event enable or 10 ms before deployment)	-5.42	MPH
DPID \$49 Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (70 ms after event enable or 10 ms before deployment)	0.00	MPH
DPID \$49 Byte 3	\$F6	SDM Recorded Vehicle Velocity Change for Axis #1 (80 ms after event enable or at deployment)	-6.78	MPH
DPID \$49 Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (80 ms after event enable or at deployment)	0.00	MPH
DPID \$49 Byte 5	\$F3	SDM Recorded Vehicle Velocity Change for Axis #1 (90 ms after event enable or 10 ms after deployment)	-8.81	MPH

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$49 Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (90 ms after event enable or 10 ms after deployment)	0.00	MPH
DPID \$4A Byte 1	\$F2	SDM Recorded Vehicle Velocity Change for Axis #1 (100 ms after event enable or 20 ms after deployment)	-9.49	MPH
DPID \$4A Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (100 ms after event enable or 20 ms after deployment)	0.00	MPH
DPID \$4A Byte 3	\$F0	SDM Recorded Vehicle Velocity Change for Axis #1 (110 ms after event enable or 30 ms after deployment)	-10.85	MPH
DPID \$4A Byte 4	\$01	SDM Recorded Vehicle Velocity Change for Axis #2 (110 ms after event enable or 30 ms after deployment)	0.68	MPH
DPID \$4A Byte 5	\$F0	SDM Recorded Vehicle Velocity Change for Axis #1 (120 ms after event enable or 40 ms after deployment)	-10.85	MPH
DPID \$4A Byte 6	\$01	SDM Recorded Vehicle Velocity Change for Axis #2 (120 ms after event enable or 40 ms after deployment)	0.68	MPH
DPID \$4B Byte 1	\$F0	SDM Recorded Vehicle Velocity Change for Axis #1 (130 ms after event enable or 50 ms after deployment)	-10.85	MPH
DPID \$4B Byte 2	\$01	SDM Recorded Vehicle Velocity Change for Axis #2 (130 ms after event enable or 50 ms after deployment)	0.68	MPH
DPID \$4B Byte 3	\$F0	SDM Recorded Vehicle Velocity Change for Axis #1 (140 ms after event enable or 60 ms after deployment)	-10.85	MPH
DPID \$4B Byte 4	\$01	SDM Recorded Vehicle Velocity Change for Axis #2 (140 ms after event enable or 60 ms after deployment)	0.68	MPH
DPID \$4B Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (150 ms after event enable or 70 ms after deployment)	0.00	MPH
DPID \$4B Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (150 ms after event enable or 70 ms after deployment)	0.00	MPH
DPID \$4C Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (160 ms after event enable or 80 ms after deployment)	0.00	MPH
DPID \$4C Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (160 ms after event enable or 80 ms after deployment)	0.00	MPH
DPID \$4C Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (170 ms after event enable or 90 ms after deployment)	0.00	MPH
DPID \$4C Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (170 ms after event enable or 90 ms after deployment)	0.00	MPH
DPID \$4C Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (180 ms after event enable or 100 ms after deployment)	0.00	MPH
DPID \$4C Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (180 ms after event enable or 100 ms after deployment)	0.00	MPH
DPID \$4D Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (190 ms after event enable or 110 ms after deployment)	0.00	MPH



Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$4D Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (190 ms after event enable or 110 ms after deployment)	0.00	MPH
DPID \$4D Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (200 ms after event enable or 120 ms after deployment)	0.00	MPH
DPID \$4D Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (200 ms after event enable or 120 ms after deployment)	0.00	MPH
DPID \$4D Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (210 ms after event enable or 130 ms after deployment)	0.00	MPH
DPID \$4D Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (210 ms after event enable or 130 ms after deployment)	0.00	MPH
DPID \$4E Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (220 ms after event enable or 140 ms after deployment)	0.00	MPH
DPID \$4E Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (220 ms after event enable or 140 ms after deployment)	0.00	MPH
DPID \$4E Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (230 ms after event enable or 150 ms after deployment)	0.00	MPH
DPID \$4E Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (230 ms after event enable or 150 ms after deployment)	0.00	MPH
DPID \$4E Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (240 ms after event enable or 160 ms after deployment)	0.00	MPH
DPID \$4E Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (240 ms after event enable or 160 ms after deployment)	0.00	MPH
DPID \$4F Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (250 ms after event enable or 170 ms after deployment)	0.00	MPH
DPID \$4F Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (250 ms after event enable or 170 ms after deployment)	0.00	MPH
DPID \$4F Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (260 ms after event enable or 180 ms after deployment)	0.00	MPH
DPID \$4F Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (260 ms after event enable or 180 ms after deployment)	0.00	MPH
DPID \$4F Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (270 ms after event enable or 190 ms after deployment)	0.00	MPH
DPID \$4F Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (270 ms after event enable or 190 ms after deployment)	0.00	MPH
DPID \$50 Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (280 ms after event enable or 200 ms after deployment)	0.00	MPH
DPID \$50 Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (280 ms after event enable or 200 ms after deployment)	0.00	MPH
DPID \$50 Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (290 ms after event enable or 210 ms after deployment)	0.00	MPH

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$50 Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (290 ms after event enable or 210 ms after deployment)	0.00	MPH
DPID \$50 Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (300 ms after event enable or 220 ms after deployment)	0.00	MPH
DPID \$50 Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (300 ms after event enable or 220 ms after deployment)	0.00	MPH
DPID \$51 Byte 1 bit 7	\$50	Driver Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 1 bit 6	\$50	Driver Belt Switch Circuit Status Monitored	Yes	
DPID \$51 Byte 1 bit 5	\$50	Passenger Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 1 bit 4	\$50	Passenger Belt Switch Circuit Status Monitored	Yes	
DPID \$51 Byte 1 bit 3	\$50	Front Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 1 bit 2	\$50	Front Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 7	\$00	Second Row Left Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 6	\$00	Second Row Left Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 5	\$00	Second Row Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 4	\$00	Second Row Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 3	\$00	Second Row Right Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 2	\$00	Second Row Right Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 7	\$00	Third Row Left Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 6	\$00	Third Row Left Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 5	\$00	Third Row Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 4	\$00	Third Row Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 3	\$00	Third Row Right Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 2	\$00	Third Row Right Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 4 bit 7	\$00	Driver Seat Position Status	Rearward	
DPID \$51 Byte 4 bit 6	\$00	Driver Seat Position Status Monitored	No	
DPID \$51 Byte 4 bit 5	\$00	Passenger Seat Position Status	Rearward	
DPID \$51 Byte 4 bit 4	\$00	Passenger Seat Position Status Monitored	No	
DPID \$52 Byte 1 bit 7	\$80	Automatic Passenger SIR Suppression System Validity Status	Invalid	
DPID \$52 Byte 1 bit 0	\$80	Automatic Passenger SIR Suppression System Status	Air Bag Suppressed	
DPID \$52 Bytes 2-3	\$0000	SDM Synchronization Counter	0	
DPID \$52 Byte 4 bit 7-6	\$00	Rollover Sensor Message Status	No Rollover Event	
DPID \$52 Byte 4 bit 5	\$00	Side Air Bag(s) Were First Commanded to Deploy Due to Side Impact Event	No	
DPID \$52 Byte 4 bit 4	\$00	Side Air Bag(s) Were First Commanded to Deploy Due to Rollover Event	No	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$52 Byte 4 bits 3-0	\$00	Rollover Sensor Status	Last message received contained errors	
DPID \$53 Byte 1	\$0B	Time From Algorithm Enable to Maximum SDM Recorded Vehicle Velocity Change	110	msec
DPID \$53 Bytes 2-3	\$0101	Maximum SDM Recorded Vehicle Velocity Change	10.87	MPH
DPID \$54 Byte 1 bit 7	\$00	Automatic Passenger SIR Suppression System Validity Status / Passenger SIR Suppression Switch Circuit Validity Status	Valid	
DPID \$54 Byte 1 bit 1	\$00	Automatic Passenger SIR Suppression System Status / Passenger SIR Suppression Switch Circuit Status	Air Bag Suppressed	
DPID \$54 Byte 2	\$00	Rollover Sensor - Time Between Successive Side Deploys	0	msec
DPID \$54 Byte 3	\$00	Rollover Sensor - Time From Rollover Enable to Deploy	0	msec
DPID \$55 Byte 1	\$00	Driver 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 2	\$00	Driver 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 3	\$00	Passenger 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 4	\$00	Passenger 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 5	\$00	Driver Side or Roof Rail/Head Curtain Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 6	\$00	Passenger Side or Roof Rail/Head Curtain Time From Algorithm Enable to Deployment Command Criteria Met	0	msec