


EWR D&I ANNOTATION



FAN-000001L102001DP150-4219

Artemis # : 000001L102001DP150**Record Created Date :****Printed Date :** 02/03/2011**Description :**

DI10-107. SEQ ID 150. 2010 Q2. THIS REPORT INCLUDES A CALL LOG AND POLICE REPORT FOR A 2006 CHEVY COBALT. THE DRIVER WAS TRAVELLING ON A STREET WHEN AN ONCOMING VEHICLE TURNED IN FRONT OF THEM CAUSING A HEAD ON COLLISION. THE FRONT OF THE VEHICLE WAS TOTALLED. THE DRIVER STATES SHE WAS GOING ABOUT 30MPH AND IS WONDERING WHY THE AIR BAGS DID NOT DEPLOY. SHE SAID THE DEALERSHIP TOLD HER THE REASON WAS BECAUSE THE SENSOR IS UNDER THE HEADLIGHT. GM HAS DENIED THE COMPLAINT. WITH THIS YEARS MODEL THERE ARE: VOQ-22. PURSUITS-1. RECALL-0. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

December 16, 2010

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI10-107

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 2nd quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 20, 52, 53, 54, 73, 81, 107, 108, 119, 150, 231, 263, 283, 298, 299, 317, 318, 324, 331, 349, 350, 351, 355, 440, 474, 486, 508, 546, 550	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the

information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **January 14, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

JAN 21 2011

January 20, 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI10-107

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated December 16, 2010 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 2nd quarter of 2010.

GM's response is comprised of 29 disks for the incidents that are the subject of DI10-107.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 20 307364907-693048 and 2007 BUICK LUCERNE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 20 307364907-693048_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI10-107
20 307364907-693048
2007 BUICK LUCERNE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those**



showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

20 307364907-693048_01_001- is the first document responsive to Inquiry no.1.
20 307364907-693048_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI10-107, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

<i>(29 Vehicles from the Light Vehicle Template)</i>		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
**20	1G4HP57297U [REDACTED]	NISM
52	1G6DM57T870 [REDACTED]	NISM
53	1G6DP577070 [REDACTED]	NISM
54	1G6DP577670 [REDACTED]	NISM
73	1GYUKBEF4AR [REDACTED]	NISM
81	3GYFNAEY5AS [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
107	2G1FJ1EJ0A9 [REDACTED]	NISM
108	2G1FT1EWXA9 [REDACTED]	NISM
119	1G1AK52F357 [REDACTED]	NISM
150	1G1AK55F667 [REDACTED]	NISM
231	1G1AK18F787 [REDACTED]	NISM
263	1G1AD5F54A7 [REDACTED]	NISM
283	2CNALPEW6A6 [REDACTED]	NISM
298	3GNBAADB5AS [REDACTED]	NISM
299	3GNBAADB5AS [REDACTED]	NISM
317	2G1WB58K089 [REDACTED]	NISM
318	2G1WT58N889 [REDACTED]	NISM
324	2G1WB5EK2A1 [REDACTED]	NISM
331	1G1ZT54835F [REDACTED]	NISM
349	1G1ZB5EB9AF [REDACTED]	NISM
350	1G1ZC5EB7AF [REDACTED]	NISM
351	1G1ZB5EB0A4 [REDACTED]	NISM
355	1G1ZE5E7XAF [REDACTED]	NISM
440	1GNDT13S962 [REDACTED]	NISM
474	1GKLVLED1AJ [REDACTED]	NISM
486	1GKDT13S352 [REDACTED]	NISM
508	2CTFLHEY1A6 [REDACTED]	NISM
546	1G2ZG57N084 [REDACTED]	NISM
550	1G2ZG57B394 [REDACTED]	NISM

** Sequence 20, is being submitted with missing police report photographs and a incorrect Crash Data Retrieval (CDR) file. Once the missing photographs and correct CDR file are recovered, they will be submitted with a new, updated file.

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney

work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

 FOR
M. CARMEN
BENAVIDES


M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 29 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (**Next Page**), or to view the next document within the file list (**Next Image**).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

ATTORNEY OR PARTY WHO HAS FILED THIS CASE WITH THE COURT, AND NOTHING ERIC D. PARIS, Esq., #/B# 147836 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES 281 S. THOMAS STREET SUITE 103 POMONA, CALIFORNIA 91766 TELEPHONE NO. 909-659-5127 FAX NO. 909-659-5126		FILED BY _____ DATE _____	
ATTORNEY FOR PLAINTIFF: SUPERIOR COURT FOR THE STATE OF CALIFORNIA INDIO COUNTY			
CASE NAME: CARDONIA V. CHEVROLET			
CIVIL CASE COVER SHEET ☐ Limited ☒ Unlimited		Complete Case Description ☐ Contractual ☐ Tort Filed with first appearance by defendant (Civil Rules of Court, rule 181f)	
Please complete all Part B items below.			
I. Check one box below for the main type of civil case. This case involves:			
☒ Auto (2) Other PERSONAL INJURY/PROPERTY DAMAGE/INVESTIGATING DRIVER/Traffic ☐ Automobile (4) ☐ Product liability (2) ☐ Medical malpractice (2) ☐ Other PERSONAL INJURY Non-PERSONAL INJURY/PROPERTY DAMAGE ☐ Business transaction/bankruptcy protection (2) ☐ Contracts (e.g., discrimination, labor union) (2) ☐ Defamation (e.g., slander, libel) (1) ☐ Fraud (1) ☐ Intellectual property (1) ☐ Professional negligence (e.g., legal malpractice) (2) ☐ Other non-PERSONAL INJURY/PROPERTY DAMAGE ☐ Employment ☐ No explicit limitation (2)		☐ Other employment (2) ☐ Contracted ☐ Breach of contract/warranty (2) ☐ Construction (e.g., injury work, open space) (indefinite) ☐ Insurance coverage (1) ☐ Other contract (2) ☐ Real estate/construction ☐ Wrongful claims (2) ☐ Other real property (e.g., title) (2) ☐ Unlabeled Defendant ☐ Constitutional (1) ☐ Environmental (2) ☐ Group (1) ☐ Judicial Review ☐ Social Welfare (1) ☐ Public or substantial interest (1)	
2. This case is ☒ is not, significant under rule 1800 of the California Rules regarding procedural judicial management.			
a. ☒ Large number of separately set awarded parties b. ☐ Large number of consideration cases c. ☐ Extensive motion practice taking difficult or novel issues that will be time consuming to resolve d. ☐ Cases involving either children or vulnerable adults e. ☒ Involvement of extraordinary evidence f. ☐ Substantial proof			
3. Type of named or sought (check all that apply): ☐ Plaintiff ☐ Defendant; declaratory action or injunctive relief ☐ Member of class or litigation group ☐ FIRE			
4. This case is ☐ is not, a class action suit. Date Filed: 3/1/2003			
ERIC D. PARIS, Esq., #/B# 147836 (Print last name and initials)			
NOTICE			
* Plaintiff must file this cover sheet with the first paper filed in the online or proceeding (as under the Probate, Family, or Welfare and Institutions Code) Civil Rules of Court, rule 1800. * The cover sheet is required for any verbal notice request by local court rules. * If this case is completed under rule 1800 or any of the California Rules of Court, you owe other parties to the extent of proceedings. * Unless this is a complex case, this cover sheet will be used for statistical purposes and			
CIVIL CASE COVER SHEET			

Step 7: Next File (Image)

Step 7: Next Page

Step 8: Scale Image

Step 7: Image Properties

DI10-107
150 307364858 – 692964
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No.		Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Collision
Address		City	Milwaukee	Involved Dir	Andrew Chevrolet, Inc.	Safety	Yes
State	WI	ZipCd		Source	Phone	Updated	5/13/2010 11:55:48 AM
Serial #/VIN	1G1AK55F667	Model Year	2009	Priority	Medium	License #	CHEVROL
Make	Chevrolet	Warr. Start	11/23/2005	Status	Open	Owner	FABIANBR
Model	Cobalt	Mileage	40000	Sub-Status	Dissatisfied	Opened	5/12/2010 12:25:51 PM
Abstract	Non-deployment - 06 Chevrolet Cobalt						
Customer Description	This is a BRC PAR Case. Do not assume case. Forward any inquiries to Brandy Fabian at ext 31065.						

Pre-PAR

PAR Notifiers	Incident Date/Time	Incident Location	Other Vehicle #	People in Vehicle	Road Surface	Weather	Road Condition	Fire Report	Police Report
Owner	5/7/2010 07:00:33 PM	N	1	4	Concrete	Wet	n/a		unk
Driver Last Name	First Name	DOB	Height	Weight	Disabilities				
			5'6"		None				
Insurance Agent Last Name	First Name	Phone #	Insurance Agency						
n/a			American Family Insurance						
Incident Loc	35th of north ave milw WI				Incident Desc	- my mom was driving the vehicle around 7 in the evening and then suddenly another vehicle drove in front of them, the guy was drunk its a good thing that my mom and her nephew did not die because of this incident the worst thing is the airbags did not deploy			
Component	front was totalled				Damage Desc	front was totalled			
Vehicle Loc	Andrew's Chev				Add'l Info	n/a			
Emergency Svc Names	Milwaukee PD				Maint Loc	n/a			

PAR Detail

Collision	Y	Non Collision		Property Damage	N	Thermal Evt	N	Spec Equip	nono
Vehicle Speed	30	Weather Condition	wet	Prop Owner	n/a	Property Type	n/a	Prop Est Repair Cost	\$0.00
Last Service Date		Loc Last Service		Property Location	n/a	Prop Damage Description	n/a	Inspected By	3rd Party Inspector
Veh Est Repair Cost	\$0.00	Spec Equip Installer	n/a	Inspected By	3rd Party Inspector	Inspection Date/Time			
Primary Veh Use	Personal	Inspection Type	Restraint System SIR/Seat Belt	Explains Other	non-deployment				
Veh Damage Description	frt end completely smashed in, totalled								

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone	Boating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	seatbelt
Injury Description	Medical Ref	Treatment Location	Treated By			
bumps and bruises	unk	unk Treatment Facility	ER doctor			
Street Address	City	State	Zip Code			
	Milwaukee	WI				

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/13/2010 12:20:30 PM	GARCIAJR	FABIANBR	Scheduled Follow-up		Scheduled Alarm		Waiting for ESIS to pick up
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/13/2010 12:19:34 PM	GARCIAJR	ESISBIQU	Escalation	ESIS - Injuries	In Progress		Injuries - ESIS
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							bumps and bruises

Joe GIPAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2010 06:24:01 PM	GARCIAJR	GARCIAJR	Ownership Changed	Ownership Escalated to BRC	Done	5/12/2010 06:24:01 PM	Ownership Escalated to BRC
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							

Confidential Comments

Service Request Detail

Activities

Created: 5/12/2010 01:22:35 PM Created By: KINZERTH Assigned To: FABIANBR Activity Type: Ownership Changed Status: Done Completed: 5/12/2010 01:22:35 PM Description: Service Request Ownership has changed FROM: DELEONMI TO: FABIANBR

Contact Last Name: Contact First Name: Account: BAC Code:

Comments:

Confidential Comments:

Created: 5/12/2010 01:22:23 PM Created By: KINZERTH Assigned To: FABIANBR Activity Type: BRC PAR Activity Sub-Type: Initial Contact- AVM Status: Done Completed: 5/13/2010 11:44:18 AM Description: I/m for FOM, Mary Sontag

Contact Last Name: Contact First Name: Account: BAC Code:

Comments:

FOM: Mary Sontag
Node: 630092
Mailbox: 8124

Calling to provide heads-up/FYI on cust's product allegation case.

Joe G/PAR/ATX

Confidential Comments:

Created: 5/12/2010 01:22:14 PM Created By: KINZERTH Assigned To: FABIANBR Activity Type: BRC PAR Activity Sub-Type: Initial Contact- Dealer Status: Done Completed: 5/13/2010 11:39:33 AM Description: Andrew Chevrolet

Contact Last Name: Contact First Name: Account: BAC Code:

Comments:

Called dir @

Crm stated calling to get any details that may be related to cust's product allegation case.

Svc adv, William, stated they have never seen this veh for any SIR concerns.

Joe g/PAR/ATX

Confidential Comments:

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2010 01:22:07 PM	KINZERTH	FABIANBR	BRC PAR	Initial Contact- Phone	Done	5/13/2010 12:19:29 PM	made initial ct w/cust
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Called daytime phone #, [REDACTED]

Crm stated calling to /u w/cust re the product allegation case, understand that veh was involved in a collision where the airbags did not deploy.

Cust stated that is correct, mother-in-law was going approx 30 mph when a drunk driver swerved in frt of her and she hit him, veh is completely smashed in the frt and the insurance company totaled it.

Cust stated her mother-in-law suffered some bumps and bruises but she went to a doctor to go get checked out, does not know the name of the facility or the name of the doctor.

Crm verfd pre-par and par detail screen info.

Crm also advised that will need to refer this file to our central claim dept, they will /u w/cust w/in 7-10 business days.

Cust stated that is fine.

Joe G/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2010 01:22:00 PM	KINZERTH	FABIANBR	BRC PAR	Acknowledgement	Done	5/13/2010 11:59:44 AM	acknowledgement made
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

see initial ct activity

Joe G/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2010 01:21:52 PM	KINZERTH	FABIANBR	Notify CRM		Done	5/12/2010 06:21:30 PM	File Assigned
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2010 01:21:45 PM	KINZERTH	FABIANBR	Research		Done	5/12/2010 06:22:47 PM	Research VIN

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Summary:

Repairs - no related repairs

Recalls - no open recalls

SR's - no other files for this veh

Joe G/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2010 01:21:29 PM	KINZERTH	FABIANBR	BRC PAR	Case Assigned	Done	5/12/2010 06:21:27 PM	Assigned to Brandy Fablan x31065

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2010 01:21:22 PM	KINZERTH	DELEONMI	SR Opened		Done	5/12/2010 01:21:22 PM	SR in Status of Closed has been Re-Opened by KINZERTH

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2010 01:21:21 PM	KINZERTH	DELEONMI	SR Closed - Satisfied		Done	5/12/2010 01:21:21 PM	Service Request has been Closed Satisfied.

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
5/12/2010 12:47:25 PM	DELEONMI	KINZERTH	Escalation	Initiate PAR	Done	5/12/2010 01:21:17 PM	Assigning activity to PAR QUEUE

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub Type	Set Status	Completed	Description
5/12/2010 12:46:28 PM	DELEONMI	DELEONMI	Inbound Call Customer	Complex Request	Done	5/12/2010 12:46:45 PM	PAR collision

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Cust Sts:

- 2006 Cobalt
- my mother was in an accident and the airbags did not deploy
- the dealership said that the sensor was under the head lights and that's the reason why it did not deploy, the thing is the vehicle was totalled
- my mom was driving the vehicle around 7 in the evening and then suddenly another vehicle drove in front of them, the guy was drunk it's a good thing that my mom and her nephew did not die because of this incident the worst thing is the airbags did not deploy
- she was driving at 35th of north ave mitw VN
- 2/2/32
- 2 nephews and a niece
- I don't know the phone number of the insurance company
- I don't have the police report number handy

Cust Sks:

- resolution

CRS Sts:

- par funnel
- CRS advised that a person from the PAR Department will contact the customer within 2 business days

Myk/CAC/Mia/Tier1/Lv 1 Auth

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front

GM Vehicle Inquiry System

Summary

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	1G1AK55F667
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AK69 -2006 COBALT 4-DOOR LS SEDAN	Warranty Start Date :	11/23/2005				
BARS Order Type :	70 - RETAIL - STOCK						
Delivering Dealer :	ANDREW CHEVROLET, INC. 1500 W SILVER SPRING DR GLENDALE, WI 53209-4419 (414) 228-6200	Selling Source :	13 - CHEVROLET				
		Site Code :	47012				
		Business Associate Code :	113344				
Service Contract :	No	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns
--

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information
--

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.
--

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	11/23/2005	8 miles	11/23/2008	36008 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	11/23/2005	8 miles	11/23/2011	100008 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	11/23/2005	8 miles	11/23/2013	80008 miles
36/36000 FEDERAL EMISSION	11/23/2005	8 miles	11/23/2008	36008 miles
60/60000 POWERTRAIN - U.S. LIMITED WARRANTY	11/23/2005	8 miles	11/23/2010	60008 miles

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading

08/14/2008	126217	#	E3531 - ARM ASSEMBLY, FRONT CONTROL - LOWER - LEFT - REPLACE	24463 miles
02/17/2006	038742	#	E7200 - IGNITION LOCK CYLINDER REPLACEMENT	1698 miles
09/13/2005	029380	I	Z6999 - PDI RELATED FLUID ADDS	2 miles
08/26/2005	A50145	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 2009 General Motors. All Rights Reserved.

**Warranty**

Mr. GMVIS 2

May 13, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMER**View Vehicle Summary**

This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

For this:

View V

Vehicle Information

VIN: 1G1AK55F667

Model: 1AK69-2006 COBALT 4-DOOR LS SEDAN

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: 0 Open

View V

View V

Comp

View V

Transa

Detail

View V

Inform

Required Field Actions

Open field actions are highlighted

Vehicle has no current record of required field actions.

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Vehicle has no current record of OnStar / XM Radio information.

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Powertrain Limited Warranty	02/23/2010	11/23/2005	8 MI	11/23/2010	60,008 MI

Special Coverage 09014	02/23/2010	11/23/2005	8 MI	11/23/2020	150,008 MI
Emission Select Component Ltd Wty	02/23/2010	11/23/2005	8 MI	11/23/2013	80,008 MI
Corrosion Limited Warranty	02/23/2010	11/23/2005	8 MI	11/23/2011	100,008 MI
Bumper to Bumper Limited Warranty	02/23/2010	11/23/2005	8 MI	11/23/2008	36,008 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History

[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
08/14/2008	126217	ZREG---Regular Vehicle Transaction		E3531 - Arm Assembly, Front Control - Lower - Left - Replace	24,463 MI
02/17/2006	038742	ZREG---Regular Vehicle Transaction		E7200 - Ignition Lock Cylinder Replacement	1,698 MI
09/13/2005	029380	ZPDI---Pre-Delivery Inspection		Z6999 - PDI Related Fluid Adds	2 MI
08/26/2005	A50145	ZPDI---Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.

**Warranty**

Mr. GMVIS 2

May 13, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

**INTERFACE WITH
CUSTOMER****View Vehicle Build**

This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available)

For this

View V

Vehicle Information

VIN: 1G1AK55F667

Model: 1AK69-2006 COBALT 4-DOOR LS SEDAN

Service Contract No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions [Open](#)[REQUEST ANOTHER VIN](#)

View V

View V

Comp

View V

Transa

Detail

View V

Inform

Vehicle Build

Model: 1AK69-2006 COBALT 4-DOOR LS SEDAN

Order Number: JJQRPM

Gross Vehicle Weight 1,707

Build Date: 08/26/2005

Build Plant: 7-

Option Codes

*GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker

14B - GRAY

14I - GRAY

1LS - 1LS BASE PACKAGE

1SZ - OPTION PACKAGE DISCOUNT

6AR - FRONT SPRING

7AR - FRONT SPRING

84U - MAJESTIC AMETHYST METALLIC

8AA - REAR SPRING

9AA - REAR SPRING

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS

AP9 - TRUNK CARGO CONVENIENCE NET

AR9 - DELUXE FRONT BUCKET SEAT

B34 - FLOOR MATS

B35 - REAR FLOOR MATS

B84 - BODY COLOR BODYSIDE MOLDINGS

C67 - ELECT. FRONT AIR CONDITIONER

DC8 - MIRROR, O/S MANUAL FLDG, BLK

DT4 - ASHTRAY AND LIGHTER

FE1 - SUSPENSION SYSTEM-SOFT RIDE

FE9 - FEDERAL EMISSIONS

FY1 - TRANS/AXLE 3.63 RATIO

IPB - INTERIOR TRIM DESIGN

J41 - POWER DISC FRONT BRAKES

JKK - SUSPENSION, REAR INSTALLED

K34 - CRUISE CONTROL

K64 - 115 AMP GENERATOR

L61 - 2.2L DOHC 4 CYL ENGINE

LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO

MN5 - 4 SPEED AUTO TRANSMISSION

MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE

N46 - 4 SPOKE STEERING WHEEL

NT7 - FEDERAL EMISSION TIER 2

PG1 - 15" STEEL WHEEL

QTU - P195/60R15 TOURING BW TIRES

R6P - PREMIUM PAINT

SLM - STOCK ORDERS

UN0 - AM/FM STEREO W/CD & RDS

UQ4 - BASE SPEAKER SYSTEM

V73 - STATEMENT OF VEHICLE CERT.-

VK3 - FRONT LICENSE PLATE MOUNT

U.S./CANADA


Added Option Codes

~AN - SPECIAL COVERAGE APPLIED

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.



Mr. GMVIS 2

May 13, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMER

View Vehicle Component Summary



This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build

For this:

- View V

Vehicle Information

VIN 1G1AK55F667

Model 1AK69-2006 COBALT 4-DOOR LS SEDAN

Service Contract No

Branded Title No

Warranty Block No

PDI Status No

Order Type: 70 - RETAIL - STOCK

Field Actions: [Open](#)[REQUEST A VIN](#)

- View V

- View V

- Comp

- View V

- Transa

Detail

- View V

- Inform

Vehicle Component

Component Code: CB-SEQ NUM (FLEX) BODY ASM

Traceability: 0430524

Source Plant: -

Part / Number Broadcast: 1ZZ

Date Scanned: 08/24/2005

Time Scanned: 05:07:00 Scan Station

Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors



Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail

②

This screen allows GMVIS users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN: 1G1AK55F667 [REDACTED] Model: 1AK69-2006 COBALT 4-DOOR LS SEDAN
Service Contract: No Branded Title: No Warranty Block: No PDI Status: No
Order Type: 70 - RETAIL - STOCK
Field Actions: [Open](#)

[REQUEST ANOTHER VIN](#)

For this:

[View V](#)[View V](#)[View V](#)[Compt](#)[View V](#)[Transa](#)[Detail](#)[View V](#)[Inform](#)

Job Card Date: 08/14/2008

Job Card Number: 126217

Repair Service Agent: 113344
ANDREW CHEVROLET, INC.
1500 W SILVER SPRING DR
GLENDALE WI 53209-4419
4142286200

Odometer Reading: 24,463 MI
Authorization Code

Process Date
08/19/2008

Transaction Type:
ZREG—Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op E3531-Arm Assembly, Front Control - Lower - Left - Replace

Causal Part Number

[See other Parts and/or Net Items](#)

Line Total: USD 276.94

Job Card Date: 02/17/2006

Job Card Number: 038742

Repair Service Agent: 113344
ANDREW CHEVROLET, INC.
1500 W SILVER SPRING DR
GLENDALE WI 53209-4419
4142286200

Odometer Reading: 1,698 MI
Authorization Code

Process Date
03/07/2006

Transaction Type:
ZREG—Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code
0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op E7200-Ignition Lock Cylinder Replacement

Causal Part Number

See other Parts and/or Net Items

Line Total: USD 42.98

Job Card Date: 09/13/2005

Job Card Number: 029380

Repair Service Agent: 113344
ANDREW CHEVROLET, INC.
1500 W SILVER SPRING DR
GLENDALE WI 53209-4419
4142286200Odometer Reading: 2 MI
Authorization CodeProcess Date
09/20/2005Transaction Type:
ZPDI—Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z6999-PDI Related Fluid Adds

Causal Part Number

See other Parts and/or Net Items

Line Total: USD 5.18

Job Card Date: 08/26/2005

Job Card Number: A50145

Repair Service Agent: 113344
ANDREW CHEVROLET, INC.
1500 W SILVER SPRING DR
GLENDALE WI 53209-4419
4142286200Odometer Reading: 0 MI
Authorization CodeProcess Date
08/30/2005Transaction Type:
ZPDI—Pre-Delivery Inspection

Transaction Expense Category

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time

Causal Part Number

Line Total: USD 100.54

Global Warranty Management. Site Map

Privacy Policy | Terms of Use

© 2005 General Motors

**Warranty**

Mr. GMVIS 2

May 13, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

**INTERFACE WITH
CUSTOMER****View Vehicle Delivery Information**

This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

For this

View V

Vehicle Information

VIN: 1G1AK55F667

Model: 1AK59-2006 COBALT 4-DOOR LS SEDAN

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: 0_Open

REQUEST A VIN

View V

View V

Compt

View V

Transa

Detail

View V

Inform

Invoice Information

Invoicing Service Agent: 113344

Invoice Date: 08/26/2005

ANDREW CHEVROLET, INC.

1500 W SILVER SPRING DR

GLENDALE WI 53209-4419 4142286200

Ship to Information

Invoicing Service Agent: 113344

Ship to Date: N/A

ANDREW CHEVROLET, INC.

1500 W SILVER SPRING DR

GLENDALE WI 53209-4419 4142286200

Delivery Information

Delivery Service Agent: 113344

Delivery Date: 11/23/2005

ANDREW CHEVROLET, INC.

Delivery Type: 015---RETAILLEASE-INDIVIDUAL

1500 W SILVER SPRING DR

Delivery Odometer: 8

GLENDALE WI 53209-4419 4142286200

In Service Information

Invoicing Service Agent:

In Service Date: N/A

In Service Type: 0000

In Service Odometer: 0

Global Warranty Management Site Map

Privacy Policy | Terms of Use

© 2005 General Motors

PK2009

☒ Reportable Accident		☐ On Emergency		☐ Amended		DOT Document Number (b) (6)		Document Override Number	
Agency Accident Number (b) (6)				Police Number					
4 - Accident Date 05/07/2010		5 - Time of Accident (Military Time) 1900		6 - Total Units 02		7 - Total Injured 01		8 - Total Killed 00	
2 - County MILWAUKEE - 10		3 - Municipality MILWAUKEE - 57 CITY				11 - Accident Location INTERSECTION			
14 - On Hwy No.		14 - On Street Name 35TH ST N		14 - Bus/Frnt/Rmp		15 - Est. Dist Ft/Mi		15 - Hwy. Dir	
16 - Fr/At Hwy No.		16 - Frnt/At Street Name NORTH AV W		16 - Business/Frontage/Ramp					
17 - Structure Type		17 - Structure Number		12 - Latitude			13 - Longitude		
80 - First Harmful Event MOTOR VEHICLE IN TRANSPORT				93 - Manner of Collision SIDESWIPE, OPPOSITE DIRECTION					
112 - Access Control NO CONTROL		113 - Road Curvature STRAIGHT		113 - Road Terrain LEVEL/FLAT		Surface Type			
115 - Traffic Way NOT-PHYSICALLY-DIVIDED (2-WAY TRAFFIC)									
117 - Relation To Roadway ON-ROADWAY									
114 - Light Condition DUSK		116 - Road Surface Condition WET			118 - Weather RAIN				
9 ☐ Hlt and Run		9 ☐ Government Property		9 ☐ Fire		9 ☐ Photos Taken		9 ☐ Trailer or Towed	
9 ☐ Truck, Bus, or Hazardous Materials		9 ☐ Load Spillage		9 ☐ Construction Zone		9 ☒ Names Exchanged			
101 ☐ Supplemental Reports		102 ☐ Witness Statements		103 ☐ Measurements Taken		79 - EMS Number			

Operator/Pedestrian

Unit Status		81 - Most Harmful Event: Collision With MOTOR VEHICLE IN TRANSPORT		23 - Dir Of Travel SOUTH		24 - Speed Limit 30		
36 - Operating as Classified D CLASS		37 - Endorsements		35 ☐ Operating Commercial Motor Vehicle				
29 - Driver's License Number/ [REDACTED]		30 - State WI		31 - Expiration Year 2012		34 - On Duty Accident		
253 Operator/Pedestrian Last Name [REDACTED]		25 - First Name [REDACTED]		25 - Middle Initial		25 - Suffix		
32 - Date Of Birth [REDACTED]		33 - Sex FEMALE						
28 - Address Street & Number [REDACTED]						28 - PO Box		
27 - City MILWAUKEE			27 - State WI		27 - Zip Code [REDACTED]		28 - Telephone Number (000) 000-0000 EXT.	
39 - Seat Position FRONT-SEAT-LEFT-SIDE-(MC/BIKE DRIVER, TRAIN CONDUCTOR)					40 - Safety Equipment SHOULDER-BELT-AND-LAP-BELT-USED			
38 - Injury Severity N - NO APPARENT INJURY		41 - Airbag NON-DEPLOYED		42 - Ejected NOT-EJECTED		44 ☐ Medical Transport		
43 - Trapped/Extricated NOT-TRAPPED		92 - Pedestrian Location		92 - Pedestrian Action				
119 - What Driver Was Doing GOING-STRAIGHT			120 - Traffic Control TRAFFIC-SIGNAL-OPERATING			62 - No. of Citations Issued 0		
64 - 1st Statute No.		64 - 2nd Statute No.		64 - 3rd Statute No.		64 - 4th Statute No.		
64 - 5th Statute No.								
122 - Driver Factors NOT-APPLICABLE								
88 - Driver or Pedestrian Cond APPEARED NORMAL				89 - Substance Presence NEITHER-ALCOHOL-NOR-DRUGS-PRESENT				
90 - Alcohol Test TEST NOT GIVEN			90 - Alcohol Content			91 - Drug Test TEST-NOT-GIVEN		

OPERATOR/PEDESTRIAN 01

91 - Drugs Reported
124 - Highway Factors NOT-APPLICABLE

Vehicle

VEHICLE 01	21 - Unit Type AUTOMOBILE	Vehicle Type PASSENGER-CAR				22 - Total Occupants 4
	56 - License Plate Number	57 - Plate Type AUT	58 - State WI	59 - Exp. Year 2010	55 - Vehicle Identification Number 1G1AK55F667	
	50 - Year 2006	51 - Make CHEV	52 - Model COBALT LS	53 - Body Style 4D	54 - Color PLE	100 - Skidmarks to Impact (Ft) 0
	94 - Vehicle Damage FRONT, FRONT PASSENGER SIDE, FRONT DRIVER SIDE					
	95 - Extent Of Damage SEVERE	96 ☐ Vehicle Towed Due To Damage		97 - Vehicle Removed By		
	123 - Vehicle Factors NOT-APPLICABLE					

Vehicle Owner

VEH OWNER 01	45 ☐ Vehicle Owner Same As Operator					
	46 - Vehicle Owner Last Name		48 - First Name	46 - Middle Initial	46 - Suffix	Date Of Birth
	46 - Company Name					
	47 - Address Street & Number			47 - PO Box		
	48 - City MILWAUKEE		48 - State WI	48 - Zip Code	49 - Telephone Number EXT.	

Insurance

INS 01	63 - Liability Insurance Company AMERICAN-FAMILY		60 ☒ Policy Holder Same As Owner
	61 - Policy Holder Last Name		61 - Policy Holder First Name
	61 - Policy Holder Company		

School Bus

BUS 01	Bus Travelling to/from ☐ To ☐ From	School Name	Body Make	Seating Capacity
	School District Contracted With			

Operator/Pedestrian

Unit Status		81 - Most Harmful Event: Collision With MOTOR VEHICLE IN TRANSPORT		23 - Dir Of Travel NORTH	24 - Speed Limit 30
36 - Operating as Classified D CLASS		37 - Endorsements		35 ☐ Operating Commercial Motor Vehicle	
26 - Driver's License Number		30 - State WI	31 - Expiration Year 1900	34 - On Duty Accident	
25 - Operator/Pedestrian Last Name		25 - First Name		25 - Middle Initial	25 - Suffix
32 - Date Of Birth		33 - Sex MALE			

OPERATOR/PEDESTRIAN 02	26 - Address Street & Number [REDACTED]		26 - PO Box [REDACTED]			
	27 - City MILWAUKEE		27 - State WI	27 - Zip Code [REDACTED]	28 - Telephone Number [REDACTED]	
	39 - Seat Position FRONT-SEAT-LEFT-SIDE-(MC/BIKE DRIVER, TRAIN CONDUCTOR)			40 - Safety Equipment SHOULDER-BELT-AND-LAP-BELT-USED		
	38 - Injury Severity C - POSSIBLE INJURY		41 - Airbag NON-DEPLOYED	42 - Ejected NOT-EJECTED	44 ☒ Medical Transport	
	43 - Trapped/Extricated NOT-TRAPPED		92 - Pedestrian Location		92 - Pedestrian Action	
	119 - What Driver Was Doing MAKING-LEFT-TURN		120 - Traffic Control TRAFFIC-SIGNAL-OPERATING		62 - No. of Citations Issued 2	
	64 - 1st Statute No. 346.18(2)	64 - 2nd Statute No. 343.44(1)(A)	64 - 3rd Statute No.		64 - 4th Statute No.	64 - 5th Statute No.
	122 - Driver Factors FAIL-TO-YIELD-RIGHT-OF-WAY					
	88 - Driver or Pedestrian Cond NOT OBSERVED		89 - Substance Presence UNKNOWN			
	90 - Alcohol Test TEST NOT GIVEN		90 - Alcohol Content		91 - Drug Test TEST-NOT-GIVEN	
91 - Drugs Reported						
124 - Highway Factors NOT-APPLICABLE						

Vehicle

VEHICLE 02	21 - Unit Type AUTOMOBILE		Vehicle Type PASSENGER-CAR			22 - Total Occupants 1
	50 - License Plate Number [REDACTED]		51 - Plate Type AUT	52 - State WI	53 - Exp Year [REDACTED]	55 - Vehicle Identification Number 1FACR32U5PG [REDACTED]
	50 - Year 1993	51 - Make FORD	52 - Model TAURUS GL	53 - Body Style 4D	54 - Color BLK	100 - Skidmarks to Impact (Ft) 0
	94 - Vehicle Damage FRONT, FRONT PASSENGER SIDE, MIDDLE PASSENGER SIDE, FRONT DRIVER SIDE					
	95 - Extent Of Damage MODERATE		96 ☐ Vehicle Towed Due To Damage		97 - Vehicle Removed By	
	123 - Vehicle Factors NOT-APPLICABLE					

Vehicle Owner

VEH OWNER 02	45 ☐ Vehicle Owner Same As Operator						
	46 - Vehicle Owner Last Name [REDACTED]		46 - First Name [REDACTED]		46 - Middle Initial B	46 - Suffix [REDACTED]	Date Of Birth [REDACTED]
	48 - Company Name						
	47 - Address Street & Number [REDACTED]			47 - PO Box			
	48 - City DEERFIELD		48 - State WI	48 - Zip Code [REDACTED]		49 - Telephone Number () - EXT.	

Insurance

INS 02	63 - Liability Insurance Company NONE		60 ☐ Policy Holder Same As Owner
	61 - Policy Holder Last Name	61 - Policy Holder First Name	
	61 - Policy Holder Company		

School Bus

BUS 02	Bus Travelling to/from ☐ To ☐ From	School Name	Body Make	Seating Capacity
	School District Contracted With			

Occupant

OCCUPANT 01	☒ Address Same As Operator				
	65 - Unit No 01	66 - Occupant Last Name [REDACTED]	66 - First Name [REDACTED]	66 - Middle Initial	66 - Suffix
	68 - Address Street & Number [REDACTED]		68 - PO Box		
	68 - City MILWAUKEE		68 - State WI	68 - Zip Code [REDACTED]	
	67 - Date of Birth [REDACTED]		69 - Sex MALE		
	71 - Seat Position SECOND-SEAT-LEFT-SIDE-(MC/BIKE PASSENGER, TRAIN BREAKMA			72 - Safety Equipment SHOULDER-BELT-AND-LAP-BELT-USED	
	70 - Injury Severity N - NO APPARENT INJURY		73 - Airbag NON-DEPLOYED	75 - Ejected NOT-EJECTED	77 ☐ Medical Transport
	76 - Trapped/Extricated NOT-TRAPPED		78 - Agency Space		

Occupant

OCCUPANT 02	☒ Address Same As Operator				
	65 - Unit No 01	66 - Occupant Last Name [REDACTED]	66 - First Name [REDACTED]	66 - Middle Initial	66 - Suffix
	68 - Address Street & Number [REDACTED]		68 - PO Box		
	68 - City MILWAUKEE		68 - State WI	68 - Zip Code [REDACTED]	
	67 - Date of Birth [REDACTED]		69 - Sex MALE		
	71 - Seat Position SECOND-SEAT-RIGHT			72 - Safety Equipment SHOULDER-BELT-AND-LAP-BELT-USED	
	70 - Injury Severity N - NO APPARENT INJURY		73 - Airbag NON-DEPLOYED	75 - Ejected NOT-EJECTED	77 ☐ Medical Transport
	76 - Trapped/Extricated NOT-TRAPPED		78 - Agency Space		

Occupant

OCCUPANT 03	☒ Address Same As Operator				
	65 - Unit No 01	66 - Occupant Last Name [REDACTED]	66 - First Name [REDACTED]	66 - Middle Initial	66 - Suffix
	68 - Address Street & Number [REDACTED]		68 - PO Box		
	68 - City MILWAUKEE		68 - State WI	68 - Zip Code [REDACTED]	
	67 - Date of Birth [REDACTED]		69 - Sex FEMALE		
	71 - Seat Position SECOND-SEAT-MIDDLE			72 - Safety Equipment LAP-BELT-ONLY-USED	
	70 - Injury Severity N - NO APPARENT INJURY		73 - Airbag NON-DEPLOYED	75 - Ejected NOT-EJECTED	77 ☐ Medical Transport

76 - Trapped/Extricated
NOT-TRAPPED

78 - Agency Space

Diagram and Narrative

DIAGRAM AND NARRATIVE	105 - PHOTOS BY
	Diagram is not drawn to scale W NORTH AVE N 35TH ST
UNIT TWO WHILE DRIVING S/B ON N 35TH STREET, ATTEMPTED A LEFT TURN, E/B ON TO W NORTH AVE IN FRONT OF UNIT ONE, CAUSING UNIT ONE TO STRIKE UNIT TWO, UNIT ONE WAS HEADED N/B AT THE TIME OF THE CRASH.	

Officer Information

OFFICER INFORMATION	125 - Officer Last Name CALLIES	125 - First Name KEVIN	125 - Middle Initial M	131 - Officer ID 16606
	129 - Law Enforcement Agency No. 006	130 - Law Enforcement Agency Name MILWAUKEE POLICE DEPARTMENT		
	126 - Law Enforcement Agency Address Street & Number 749 WEST STATE STREET			
	127 - City MILWAUKEE	127 - State WI	127 - Zip Code 53233	128 - Telephone Number (414) 933-4444 EXT.
	132 - Date Notified 05/07/2010	133 - Time Notified (Military Time) 2106	134 - Time Arrived (Military Time) 2106	135 - Date Of Report 05/07/2010
	Agency Accident Number 101271773	Police Number	19 - Special Study	
	18 - Agency Space			

5

ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Yvette Young
Claims Administrator

July 21, 2010

[REDACTED]
Milwaukee WI [REDACTED]

RE: Claimant: [REDACTED]
Our File No.: 692964
Our Client: General Motors LLC
Date/Event: 5/7/10
Vehicle: 2006 Chevrolet Cobalt
VIN: 1G1AK55F667 [REDACTED]

Dear [REDACTED]

This will confirm that we have completed our review of your claim regarding your Chevrolet Cobalt. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors LLC, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Yvette Young
Claims Administrator

Cc: [REDACTED]

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	1G1AK55F667
User	
Case Number	692964
EDR Data Imaging Date	Thursday, June 10 2010
Crash Date	Friday, May 7 2010
Filename	SIMS-1G1AK55F667 ACM.CDR
Saved on	Thursday, June 10 2010 at 01:14:56 PM
Collected with CDR version	Crash Data Retrieval Tool 3.4
Reported with CDR version	Crash Data Retrieval Tool 3.4
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

Comments

-DOWNLOAD AT IAA, N70W25277 INDIAN GRASS LANE, SUSSEX, WI
 -DLC USED
 -VEHICLE BATTERY DISCONNECTED VEHICLE POWERED THROUGH UNDER HOOD FUSE BOX
 -UNABLE TO DETERMINE MILEAGE

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data

- no data is received from the module sending the pre-crash data
- no module is present to send the pre-crash data
- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

01016_SDMEps_r001

Multiple Event Data

Associated Events Not Recorded	0
An Event(s) Preceded the Recorded Event(s)	No
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	No
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	No

System Status At AE

Vehicle Identification Number	**1AK55F*6
Low Tire Pressure Warning Lamp (If Equipped)	Invalid
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Third Gear
Transmission Selector Position (If Equipped)	Fourth Gear
Traction Control System Active (If Equipped)	Invalid
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	46
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	No	No
Cruise Control Resume Switch Active (If Equipped)	No	No
Cruise Control Set Switch Active (If Equipped)	No	No


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	25	25	25	26	25
Engine Speed (RPM)	1344	1344	1536	1344	1344
Percent Throttle	18	17	27	16	17
Accelerator Pedal Position (percent)	0	0	5	0	0
Antilock Brake System Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Lateral Acceleration (feet/s ²) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Steering Wheel Angle (degrees) (If Equipped)	0	0	0	0	0


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Non-Deployment

Ignition Cycles At Investigation	9707
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	9652
Ignition Cycles At Event	9653
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	BUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Automatic Passenger SIR Suppression System Validity Status at AE	Valid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	13.71
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	120
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	No
Vehicle Event Data (Pre-Crash) Associated With This Event	Yes
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-0.68	-0.68	-1.36	-2.03	-2.03	-3.39	-4.74	-6.78	-8.13	-10.84	-12.20	-13.55	-13.55	-13.55	-13.55
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.68	0.68	1.36	1.36	2.03	2.03	2.03	2.03	2.03	2.03
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 08 00 00 00 00 00 00
$02 30 00 00 00 00 00 00
$03 00 00 00 00 00 00 00
$04 00 00 00 00 00 00 00
$05 80 00 00 00 00 00 00
$06 00 0A 00 03 0A 00 00
$07 00 20 00 00 00 00 00
$08 00 00 00 00 00 00 00
$09 00 00 00 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 01 0F 01 00 00
$0C 00 00 00 00 00 00 C0
$0D 00 00 40 00 00 00 C0
$0E 00 00 00 00 00 00 00
$0F 00 00 00 00 00 00 00
$10 00 00 00 00 00 00 00
$11 00 00 00 00 00 00 00
$12 00 00 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 00 00 00 00 00 00 00
$18 00 00 00 00 00 00 00
$19 00 00 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 02 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 00 00 00 00 00 00 00
$1F 28 00 00 00 00 00 00
$20 40 00 00 00 00 00 00
$21 00 00 00 00 F0 00 00
$22 00 97 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 00 FF F0 25 EB 00 00
$2F 00 FE 25 EB 36 00 00
$30 9D 00 00 00 00 00 00
$31 00 00 0C 00 00 00 00
$32 00 00 00 00 00 00 00
$33 2C 29 44 2B 2F 00 00
$34 15 15 18 15 15 00 00
$35 28 2A 29 29 29 00 00
$36 00 00 00 00 00 00 00
$37 00 00 00 03 04 00 E2
$38 5F 00 40 00 03 C0 00
$39 00 00 00 00 00 80 00
$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00
$3C 00 00 00 00 00 00 C0
$3D 31 41 4B 35 35 46 00
```

```

$3E 36 65 01 45 00 00 00
$3F 00 00 90 00 00 00 00
$40 20 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 00 FF F0 25 B4 00 00
$43 FE 25 B5 00 00 00 00
$44 00 00 00 00 00 00 00
$45 00 00 00 00 00 00 00
$46 00 00 00 00 00 00 00
$47 00 FF 00 FF 00 FE 00
$48 00 FD 00 FD 01 FB 00
$49 01 F9 02 F6 02 F4 00
$4A 03 F0 03 EE 03 EC 00
$4B 03 EC 03 EC 03 EC 00
$4C 00 00 00 00 00 00 00
$4D 00 00 00 00 00 00 00
$4E 00 00 00 00 00 00 00
$4F 00 00 00 00 00 00 00
$50 00 00 00 00 00 00 00
$51 D0 00 00 00 00 00 00
$52 00 00 00 00 00 00 00
$53 0C 01 99 00 00 00 00
$54 00 00 00 00 00 00 00
$55 00 00 00 00 00 00 00
$67 00 00 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

```

```

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 35 31 37 35 32 31 38 58 52
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 05 32 31 35 34 47 59 47
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 33 19 2A B4 E6 87 91 9A
$22 90 11
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA

```

```
$26 32 41 FA FA FA FA FA
$40 00 00
$41 3F 00 00 02 00 1A
$42 F0 C4
$43 00 00 8E 80
$44 C6 00 00 FC C0 C0
$45 07 01 07 01 05 01
$46 FF 1A 1A 64 64
$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
$48 18 08 08
$B0 58
$B1 FD FE 00
$B2 FF FF FF FF FF
$B4 41 53 39 30 31 31 32 31 31 48 54 53 20 20 20 20
$B7 50 AA 04 0F 03
$B8 41 57 68 09 19
$C1 30 46 30 33
$CA 30 46 30 33
$CB 01 5A D1 33
$CC 01 5A D1 33
$D1 00 00
$DB 00 00
$DC 00 00
```

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.