


EWR D&I ANNOTATION

FAN-000001L092001DP101-3797

Artemis # : 000001L092001DP101**Record Created Date :****Printed Date :** 06/23/2010

Description : DI09-096. SEQ ID 101. 2009 Q2. DRIVER OF A 2007 COBALT WAS APPROACHING AN INTERSECTION WHEN ANOTHER VEHICLE ENTERED. COBALT T-BONED THE OTHER VEHICLE. FRONT END DAMAGE TO VEHICLE. PRE-CRASH DATA SHOWS VEHICLE AROUND 24 MPH. NO POLICE REPORT GIVEN. CUSTOMER ALLEGES AIR BAGS SHOULD HAVE DEPLOYED. VOQ-37. PURSUIT-0. TSB-0. RECALLS-0. *RM



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

December 16, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-096

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 2nd quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 3, 7, 15, 39, 63, 78, 81, 82, 85, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 98, 100, 101, 103, 105, 106, 107, 108, 109, 110, 131, 137, 145, 146, 148, 149, 158, 167, 168, 178, 209, 216, 219, 231, 243, 253, 254, 255, 256, 257, 258, 259, 261, 263, 264, 266, 270, 271, 276, 281, 282, 288, 289, 290, 291, 292, 293, 297, 299, 300, 311, 312, 327, 338, 339, 341, 343, 344, 345, 346, 348, 349, 351, 352, 354, 370, 382, 390, 391	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM's custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words "CONFIDENTIAL BUSINESS INFORMATION" must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new

requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

12660

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **January 22, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,



Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

11 February 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-096

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated December 16th, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 2nd quarter of 2009.

GM's response is comprised of 88 disks for the incidents that are the subject of DI09-096.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 3 18605620-675350 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 3 18605620-675350_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI09-096
3 18605620-675350
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. **Provide a copy of the Police Accident Report.**

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 3 18605620-675350 **_01_001** - is the first document responsive to Inquiry no. 1.
- 3 18605620-675350 **_02_001** - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI09-066, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

<i>(88 Vehicles from the Light Vehicle Template)</i>		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
3	5GAER23D69J [REDACTED]	NISM
7	UNKNOWN	NISM
15	5GADS13S142 [REDACTED]	NISM
39	1G6DU57V090 [REDACTED]	LIT
63	UNKNOWN	NISM
78	1G1AL52F957 [REDACTED]	NISM
81	1G1AK52F257 [REDACTED]	NISM
82	1G1AK55F167 [REDACTED]	NISM
85	1G1AK15F467 [REDACTED]	NISM
87	1G1AK55F267 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
88	1G1AM15B367	NISM
89	1G1AL15FX67	NISM
90	1G1AK15F367	NISM
91	1G1AL58F977	NISM
92	1G1AK15F077	NISM
93	1G1AK55F577	NISM
94	1G1AK15F477	NISM
95	1G1AK55F577	LIT
96	1G1AK15F077	NISM
98	1G1AK58FX77	NISM
100	1G1AK55FX77	NISM
101	1G1AK15F477	NISM
103	1G1AK18F887	NISM
105	1G1AL58F287	NISM
106	1G1AK18F187	NISM
107	1G1AL58F987	NISM
108	1G1AK58F987	NISM
109	1G1AL58F987	NISM
110	1G1AT58H097	NISM
131	3GNDA23P76S	NISM
137	3GNDA13D48S	NISM
145	2G1WF52E049	NISM
146	2G1WF52E249	NISM
148	2G1WH52K049	NISM
149	2G1WH52K049	NISM
158	2G1WT58N279	NISM
167	2G1WT57K791	NISM
168	2G1WC57M591	NISM
178	1G1ZG57B39F	NISM
209	1GCEK24009Z	NISM
216	1GCHK29K57E	NISM
219	1GBJC34K78E	NISM
231	1GNFC16047J	NISM
243	1GNFK33059R	NISM
253	1GNDS13S642	NISM
254	1GNDT13S052	NISM
255	1GNDT13S052	NISM
256	1GNDS13SX52	NISM
257	1GNDT13S852	NISM
258	1GNDT13S052	NISM
259	1GNDT13S352	NISM
251	1GNDT13S662	NISM
263	1GNDT13S682	NISM
264	1GNDT13S882	NISM
266	1GNDS33S892	NISM
270	1GNES16S866	NISM
271	1GNEV23D29S	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
276	1GNDU03E64D [REDACTED]	NISM
281	1GKEV23D59J [REDACTED]	NISM
282	1GKEV23D99J [REDACTED]	NISM
288	UNKNOWN	NISM
289	1GKDS13S442 [REDACTED]	NISM
290	1GKDT13S442 [REDACTED]	NISM
291	1GKDT13S552 [REDACTED]	NISM
292	1GKDS13S962 [REDACTED]	NISM
293	1GKDS13S462 [REDACTED]	NISM
297	1GKET16S956 [REDACTED]	NISM
299	1GKES12S046 [REDACTED]	NISM
300	1GKES12S956 [REDACTED]	NISM
311	3GTEC13C48G [REDACTED]	NISM
312	3GTEK13378G [REDACTED]	NISM
327	5GTDN136568 [REDACTED]	NISM
338	1G2ZF55B264 [REDACTED]	NISM
339	1G2ZF55B0642 [REDACTED]	NISM
341	1G2ZG558364 [REDACTED]	NISM
343	1G2ZH18N374 [REDACTED]	NISM
344	1G2ZG58B574 [REDACTED]	NISM
345	1G2ZH57N584 [REDACTED]	NISM
346	1G2ZG57B384 [REDACTED]	NISM
348	1G2ZH57N684 [REDACTED]	NISM
349	1G2ZF57B584 [REDACTED]	NISM
351	1G2ZJ57B494 [REDACTED]	NISM
352	1G2ZH36N994 [REDACTED]	NISM
354	6G2EC57Y19L [REDACTED]	NISM
370	2G2WP552881 [REDACTED]	NISM
382	5S3ET13S662 [REDACTED]	NISM
390	5GZER13737J [REDACTED]	NISM
391	5GZEV23748J [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing

responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read 'G. Kent', written in a cursive style.


Gay P. Kent,
Director, Product Investigations
and Safety Regulations

Enclosures: 88 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7**, and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

982.2(b)(1)

ATTORNEY OR PARTY-RELATED ATTORNEY FIRM, with an address and e-mail:
 ERIC D. PARIS, ESQ., S/B# 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 381 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91766
 TELEPHONE NO. 909-469-5127 FAX NO. 909-469-5126
 ATTORNEY FOR PLAINTIFF'S

WEST NAME OF COURT: SUPERIOR COURT, COUNTY OF SAN BERNARDINO, IF ANY
 SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIO COUNTY

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET
☐ Limited ☒ Unlimited

Complex Case Designation
☐ Counter ☐ Joinder
 Filed with first appearance by defendant
 (Cal. Rules of Court, rule 1811)

CASE NUMBER:
 ASSIGNED JUDGE:

Please complete all five (5) items below.

1. Check one box below for the case type that best describes this case:

☒ Auto Tort (22)
☐ Other PIP/DWD (Personal Injury/Property Damage/Wrongful Death) Tort
☐ Assisted (24)
☐ Product liability (24)
☐ Medical malpractice (45)
☐ Other PIP/DWD (23)
☐ Non-PIP/DWD (Other) Tort
☐ Business tort/unfair business practice (37)
☐ Child rights (e.g., discrimination, false arrest) (55)
☐ Defamation (e.g., slander, RAD) (13)
☐ Fraud (18)
☐ Intellectual property (19)
☐ Professional negligence (e.g., legal malpractice) (25)
☐ Other non-PIP/DWD tort (26)
☐ Employment
☐ Wrongful termination (36)
☐ Contract
☐ Breach of contract/warranty (46)
☐ Collection (e.g., money owed, open book accounts) (39)
☐ Insurance coverage (14)
☐ Other contract (37)
☐ Real Property
☐ Eminent domain/condemnation (14)
☐ Wrongful eviction (33)
☐ Other real property (e.g., quiet title) (28)
☐ Unlawful Detainer
☐ Commercial (31)
☐ Residential (32)
☐ Drugs (34)
☐ Juvenile Delinquency
☐ Asset forfeiture (26)
☐ Petition re: arbitration award (11)
☐ Will of decedent (52)
☐ Other probate matter (37)
☐ Provisionally Complex Civil Litigation (Cal. Rules of Court, rules 188a-1812)
☐ Antitrust/Trade regulation (33)
☐ Construction defect (10)
☐ Claims insurance monies tort (35)

2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring nonpartisan judicial management:
 a. ☒ Large number of separately represented parties b. ☐ Large number of parties
 c. ☒ Extensive motion practice raising difficult or novel issues that will be time-consuming to resolve d. ☐ Coordination in other counties
 e. ☒ Substantial amount of documentary evidence f. ☐ Substantial post-trial issues

3. Type of remedies sought (check all that apply):
 a. ☒ Monetary b. ☐ Nonmonetary, declaratory or injunctive relief c. ☐ Other

4. Number of causes of action (specify): FIVE

5. This case ☐ is ☒ is not a class action suit.

Date: JULY 3, 2003

ERIC D. PARIS, ESQ., S/B# 147836
 (Print or print name)

NOTICE
 • Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (except under the Probate, Family, or Welfare and Institutions Codes) (Cal. Rules of Court, rule 1800).
 • File this cover sheet in addition to any cover sheet required by local court rule.
 • If this case is complex under rule 1800 at seq. of the California Rules of Court, you must also file a notice of complexity.
 • Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

From Integrated for Mandatory Use
 Superior Court of California
 982.2(b)(1) Rev. January 1, 2008

CIVIL CASE COVER SHEET

Next Image
 Previous Image
 Next page Ctrl+PgDn
 Previous page Ctrl+PgUp
 Full screen image Ctrl+F11
 Slide show F10
 Fit Scale to fit F5
 Scale 50% F6
 Scale 100% F7
 Scale 200% F8
 Rotate left Ctrl+Alt+L
 Rotate right Ctrl+Alt+R
 Rotate by 180°
 Copy to clipboard
 Copy file to... Ctrl+C
 Move file to... Ctrl+X
 Rename file... F2
 Delete file... Del
 Export Image Information...
 Preferences... Ctrl+H

Step 7: Next File (Image)

Step 7: Next page

Step 8: Scale Image

Step 7: Image Properties

DI09-096
101 278516397 – 669566
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Documents. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Collision
Address	City Zephyrhills	Involved Dir	Buddy Foster Chevrolet, Inc.	Safety	Yes
State FL ZipCd	Con Acct	Source	Phone	Updated	4/10/2009 03:26:13 PM
Serial #/VIN 1G1AK15F477	Model Year 2007	Priority	Medium License # CHEVROL	Owner	MORALECR
Make Chevrolet	Warr. Start 05/24/2007	Status	Open	Opened	4/8/2009 01:14:00 PM
Model Cobalt	Mileage 51000	Sub-Status	Satisfied	Closed	
Abstract (ESIS) Restraints - (SIR) - Driver Front (Non-Deployment)					
Customer Description	This is a PAR file. Please do not Assume. Forward all inquiries to Crystal Morales @ 41326				

Pre-PAR

PAR Notice	Incident Date/Time	Injuries Y/N	Other Veh	# People in Veh	Road Surface	Road Cond	Fire Report	Police Report
Owner	4/1/2009 07:55:23 PM	Y	1	1	Concrete	Dry	n/a	Unknown
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
				None				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Unknown	Unknown	(809) 841-3000	GIECO					
Incident Loc	tampa florida-kennedy and del mavery blvd	Incident Desc	was in the left lane headed northbound on del mavery highway, approached intersection of kennedy and drunk driver ran a red light entering the intersection, didn't have time to stop and t-boned him.					
Component	air bag	Damage Desc	Totalled, front end crushed, passenger fender damaged					
Vehicle Loc	Buddy Foster Chevrolet	Add'l Info	State Farm Insurance (Other party's Insurance)					
Emgcy Svc Names	City of Tampa Police Department, Tampa FL	Main Loc	Independants Various Ones					

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	n/a
Vehicle Speed	45	Weather Condition	Clear	Prop Owner	n/a	Property Type	n/a	
Last Service Date	3/1/2009	Loc Last Service		Property Location	n/a	Prop Est Repair Cost		
Veh Est Repair Cost	\$8,000.00	Spec Equip Installer	n/a	Prop Damage Description	n/a			
Primary Veh Use	Personal	Inspection Type		Inspected By	Inspection Not Performed	Inspection Date/Time		
Veh Damage Description	Totalled, front end crushed, passenger fender damaged			Explain Other	File going to ESIS for injuries			

Service Request Detail

PAR Injuries

Last Name/First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
		Occupant of Owner's Vehicle		Driver	seat belt
Injury Description		Medical Rpt#		Treatment Location	Treated By
Neck sprain, back strain, right arm, right knee, bruising on hand, chronic headaches		Unknown		Memorial Hospital, Tampa Florida	Dr. Farag
Street Address	City/State	Zip Code			
	Zephyrhills FL				

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/10/2009 03:35:56 PM	AMSTUTST	ESISBIQU	Escalation	ESIS - Injuries	In Progress		assigned to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Injuries, Chronic Headaches							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/10/2009 03:26:13 PM	AMSTUTST	AMSTUTST	Ownership Changed	Ownership Escalated to BRC	Done	4/10/2009 03:26:13 PM	Ownership Escalated to BRC
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/10/2009 01:29:14 PM	KINZERTH	AMSTUTST	Notify CRM		Done	4/10/2009 03:38:14 PM	ESIS - Injuries
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/10/2009 01:25:41 PM	MORALECR	MORALECR	Scheduled Follow-up		Scheduled Alarm		Did Esis pick it up?
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/10/2009 01:24:00 PM	MORALECR	KINZERTH	BRC PAR	ESIS- Injuries	Done	4/10/2009 01:29:13 PM	Forward to ESIS
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							
Injuries-Chronic Headaches.							
Crystal Morales/PAR/ATX							
Received and assigned for ESIS escalation							
Thaddeus Kinzer/PAR Workflow/ATX							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/10/2009 01:17:51 PM	MORALECR	MORALECR	Outbound Call Dealer		Done	4/10/2009 01:23:39 PM	Buddy Foster Chevrolet @ (813) 782-1538
Contact Last Name	Contact First Name	Account	BAC Code				

Comments: CRS attempted to reach Buddy Foster Chevrolet svc mgr at (813) 782-1538.

Svc Mgr: Don Reeves

What vehicle services including maint have been performed on the vehicle at the dr?

No history on the vehicle at all.

Is there any evidence of abuse misuse or lack of maint?

None

Are there any known product concerns that relate to the customer's allegation?

None that I know of.

If an inspection becomes necessary would you host that inspection?

Yes.

Crystal Morales/PAR/ATX

Confidential Comments:

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/9/2009 05:34:00 PM	MORALECR	MORALECR	Scheduled Follow-up		Done	4/10/2009 11:32:05 AM	AVM INI
Contact Last Name	Contact First Name	Account	BAC Code				

Comments:

Confidential Comments:

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/9/2009 05:33:38 PM	MORALECR	MORALECR	Scheduled Follow-up		Done	4/10/2009 01:33:09 PM	Dealer INI and send to ESIS
Contact Last Name	Contact First Name		Account	BAC Code			
Comments							
Confidential Comments							
Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/9/2009 05:33:18 PM	MORALECR	MORALECR	Scheduled Follow-up		Done	4/10/2009 12:05:06 PM	Complete cust ini
Contact Last Name	Contact First Name		Account	BAC Code			
Comments							
Confidential Comments							
Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/9/2009 05:32:58 PM	MORALECR	MORALECR	Scheduled Follow-up		Done	4/10/2009 11:43:57 AM	Complete Ack
Contact Last Name	Contact First Name		Account	BAC Code			
Comments							
Confidential Comments							
Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 02:34:51 PM	KINZERTH	MORALECR	Ownership Changed		Done	4/8/2009 02:34:51 PM	Service Request Ownership has changed FROM: SERMONRA TO: MORALECR
Contact Last Name	Contact First Name		Account	BAC Code			
Comments							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 02:34:32 PM	KINZERTH	MORALECR	BRC PAR	Initial Contact- AVM	Done	4/10/2009 11:38:43 AM	Called Duffy Randy 404082 8815
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

DVM Name: Duffy Randy
Node/Mailbox: 404082 8815
This is Crystal Morales calling from the GM Product Allegation Dept to make you aware of a file that was received in your area.
The request number is: 71-715393425
The Customer's name is (spell): [REDACTED]
The dealer involved is: Buddy Foster Chevrolet, Inc.
Located in (be specific): Zephyrhills, FL
The vehicle is a (year/make/model): 2007 Chevrolet Cobalt
With current mileage: 51000
The last 8 digits of the VIN# are: 77 [REDACTED]
This involves: a mva where the customer alleges that the airbags should have deployed and did not. We will be fully investigating this allegation. This message is for informational purposes only, and requires no action on your part at this time. However, if you do have any questions please feel free to give me a call.
Provided contact info.

Crystal Morales/PAR/ATX

Confidential Comments [REDACTED]

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 02:34:23 PM	KINZERTH	MORALECR	BRC PAR	Initial Contact- Dealer	Done	4/10/2009 11:41:14 AM	Waved...
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Vehicle has not been to a dealer in over two years.

Crystal Morales/PAR/ATX

Confidential Comments [REDACTED]

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 02:34:13 PM	KINZERTH	MORALECR	BRC PAR	Initial Contact- Phone	Done	4/10/2009 12:06:48 PM	Called

Contact Last Name	Contact First Name	Account	BAC Code

Comments: Customer sts taht she was in the left lane headed northbound on del mavery highway, approached intersection of Kennedy and drunk driver ran a red light entering the intersection, didn't have time to stop and t-boned him.

Cust sts that she suffered neck sprain, back strain, arm and knee strain, bruising and chronic headaches since the accident.

Cust sks why the airbags did not deploy.

Cust has retained an attorney against the other driver.

CRS advsd that due to the nature of the file/injuries the case will need to go to our Central Claims office. CRS advsd that an agent from Central Claims will follow up with the customer in 7 to 10 business days. CRS advsd if no one has contacted cust by the 10th business day please contact me and I can provide their number and the name of the agent handling the case.

Crystal Morales/PAV/ATX

Confidential Comments:

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 02:34:05 PM	KINZERTH	MORALECR	BRC PAR	Acknowledgement	Done	4/10/2009 11:43:30 AM	Called

Contact Last Name	Contact First Name	Account	BAC Code

Comments: Crs Adv: This is Crystal Morales calling from the GM Product Allegation Dept. I have received your file and do require further information.

Cust was unavailable. CRS rec'd VM. CRS left detailed message with contact information.

Crystal Morales/PAV/ATX

Confidential Comments:

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 02:33:57 PM	KINZERTH	MORALECR	Notify CRM		Done	4/9/2009 12:23:31 PM	File Assigned

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

Confidential Comments:

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 02:33:50 PM	KINZERTH	MORALECR	Research		Done	4/9/2009 12:23:14 PM	Research VIN

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

Open Recalls: None
Closed Recalls: None

Previous Related Cases: None
Previous Closed Cases: None

Vehicle Build: Your vehicle has a frontal airbag for the driver and a frontal airbag for the right front passenger. Your vehicle may also have roof-mounted side impact airbags. Roof-mounted side impact airbags are available for the driver and the passenger seated directly behind the driver and for the right front passenger and the passenger seated directly behind that passenger. If your vehicle has roof-mounted side impact airbags, the word AIRBAG will appear on the airbag covering on the garnish trim near the ceiling and the side windows.

Crystal Morales/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 02:33:31 PM	KINZERTH	MORALECR	BRC PAR	Case Assigned	Done	4/9/2009 12:23:50 PM	Assigned to Crystal Morales x41326

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

File Removed.

Crystal Morales/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 02:13:37 PM	KINZERTH	SERMONRA	SR Opened		Done	4/8/2009 02:13:37 PM	SR In Status of Closed has been Re-Opened by KINZERTH

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

Confidential Comments

Service Request Detail

Activities

Created By:	Assigned To:	Activity Type:	Activity Sub-Type:	Status:	Completed:	Description:
4/8/2009 02:13:36 PM	KINZERTH	SERMONRA	SR Closed - Satisfied	Done	4/8/2009 02:13:36 PM	Service Request has been Closed Satisfied.
Contact Last Name:	Contact First Name:	Account:	BAC Code:			
Comments:						
Confidential Comments:						

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 01:24:08 PM	SERMONRA	KINZERTH	Escalation	Initiate PAR	Done	4/8/2009 02:13:32 PM	Assigning activity to PAR QUEUE
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
CRS advised that a person from the PAR Department will contact the customer within 2 business days.							
John Jones/cac/T1(hv1)/mla							
Received and assigned in PAR							
Thaddeus Kinzer/PAR Workflow/ATX							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
4/8/2009 01:21:51 PM	SERMONRA	SERMONRA	Inbound Call Customer	Complex Request	Done	4/8/2009 01:24:06 PM	complaint veh- air bag did not deploy
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
CUST STS:							
-had a head on collision on the first of this month and air bag did not deploy.							
CUST SKS: gm needs to investigate this							
CRS advised customer that their information will be forwarded to the Product Allegation Department within the BRC.							
John Jones/cac/T1(M1)/mla							
Confidential Comments							

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front

GM Vehicle Inquiry System Summary

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AK15F477
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AK37 -2007 COBALT 2-DOOR LS COUPE			Warranty Start Date :	05/24/2007		
BARS Order Type :	70 - RETAIL - STOCK						
Delivering Dealer :	BILL HEARD CHEVROLET, INC.-PLANT CITY PO BOX 3209 PLANT CITY , FL 33563-0004 (813) 752-5123			Selling Source :	13 - CHEVROLET		
				Site Code :	26042		
				Business Associate Code :	171064		
Service Contract :	No	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	05/24/2007	7 miles	05/24/2010	36007 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	05/24/2007	7 miles	05/24/2013	100007 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	05/24/2007	7 miles	05/24/2015	80007 miles
60/100000 POWERTRAIN COVERAGE LIMITED WARRANTY	05/24/2007	7 miles	05/24/2012	100007 miles
36/36000 FEDERAL EMISSION	05/24/2007	7 miles	05/24/2010	36007 miles

CLAIM HISTORY

R.O Date	R.O	Type	Labor Operation	Odometer
----------	-----	------	-----------------	----------

<http://198.208.187.167/gmvis/main/Summary?languageSelected=EN&VIN=1G1AK15F477...> 4/13/2009

	Number			Reading
10/09/2006	A83642	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System Claim History

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AK15F477
-------	-------------

CLAIM HISTORY

Repair Order Date :		10/09/2006		Repair Order Number :		A83642		Odometer Reading :		0 miles	
Serviced By :		BILL HEARD CHEVROLET, INC.-PLANT CITY PO BOX 3209 PLANT CITY, FL 33563-0004 (813) 752-5123				Selling Source :		13 - CHEVROLET			
						Site Code :		26042			
						Business Associate Code :		171064			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
10/13/2006	734	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME		N/A		N/A	N/A	\$ 104.92	N

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System Vehicle Build

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN	1G1AK15F477
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AK37 -2007 COBALT 2-DOOR LS COUPE		
Gross Vehicle Weight Rating :	1674 kg (3691 lb)	Order Number :	KKJW3Q
Build Date :	10/09/2006	Build Plant :	177A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AL0 - SENSOR INDICATOR INFLATABLE RESTRAINT, FRT PASS/CHILD PRESENCE DETECTOR
AR9 - DELUXE FRONT BUCKET SEAT	AT8 - RESTRAINT PROVISIONS CHILD, RR SEAT, RR FACING
B34 - FLOOR MATS, FRONT/REAR	B35 - REAR FLOOR MATS
B84 - BODY COLOR, BODYSIDE MOLDINGS	C67 - ELECT. FRONT AIR CONDITIONER
DC8 - MIRROR, O/S MANUAL FLDG, BLK	DT4 - ASHTRAY AND LIGHTER
D36 - MIRROR I/S R/V TILT	FE1 - SUSPENSION SYSTEM-SOFT RIDE
FE9 - FEDERAL EMISSIONS	FY1 - TRANS/AXLE 3.63 RATIO
IPB - INTERIOR TRIM DESIGN	J41 - BRAKE, FRONT DISC/REAR DRUM
K64 - 115 AMP GENERATOR	LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO
L61 - ENGINE, 2.2L DOHC 4V ECOTEC	MN5 - 4 SPEED AUTO TRANSMISSION
MX0 - TRANSMISSION, 4 SPD AUTOMATIC	NT7 - FEDERAL EMISSION TIER 2
N45 - 3 SPOKE STEERING WHEEL	PG1 - 15" STEEL WHEEL
QTU - P195/60R15 TOURING BW TIRES	R6K
R6P - PREMIUM PAINT	R9N - HEATED LEATHER APPOINTED FRONT BUCKET SEATS
SLM - STOCK ORDERS	UQ4 - BASE SPEAKER SYSTEM
US8 - AM/FM STEREO, CD PLAYER & MP3 PLAYER (REPLACES STD/OPT RADIO)	VK3 - FRONT LICENSE PLATE BRACKET

<http://198.208.187.167/gmvis/main/VehicleBuild?languageSelected=EN&VIN=1G1AK15...> 4/13/2009

VT7 - OWNERS MANUAL ENGLISH	V73 - STATEMENT OF VEHICLE CERT.- U.S. /CANADA
1LS - 1LS BASE PACKAGE	1SZ - OPTION PACKAGE DISCOUNT
14B - GRAY	14I - GRAY
6AR - FRONT SPRING	7AR - FRONT SPRING
74U - VICTORY RED	8AA - REAR SPRING
9AA - REAR SPRING	

© 1998-2005 General Motors Corporation. All Rights Reserved.

CDR File Information

User Entered VIN	1G1AK15F477
User	C. Garcia
Case Number	669566
EDR Data Imaging Date	Friday, May 22 2009
Crash Date	Wednesday, April 1 2009
Filename	1G1AK15F477 CDR
Saved on	Friday, May 22 2009 at 11:31:47 AM
Collected with CDR version	Crash Data Retrieval Tool 3.1.1
Reported with CDR version	Crash Data Retrieval Tool 3.1.1
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

IMPORTANT NOTICE: Robert Bosch LLC recommends that the latest production release of Crash Data Retrieval software be utilized when viewing, printing or exporting any retrieved data from within the CDR program. This ensures that the retrieved data has been translated using the most recent information including but not limited to that which was provided by the manufacturers of the vehicles supported in this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event contains Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also contains Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

- SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.
- Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.
- Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.
- SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:
 - significant changes in the tire's rolling radius
 - final drive axle ratio changes
 - wheel lockup and wheel slip
- Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.
- Pre-Crash data is recorded asynchronously.
- Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:
 - the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
 - no data is received from the module sending the pre-crash data
 - no module is present to send the pre-crash data

-Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.

-The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.

-If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.

-The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.

-Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value

1G1AK15F477

Page 1 of 11

Printed on: Friday, May 22 2009 at 11:32:43 AM

when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

Multiple Event Data

Associated Events Not Recorded	0
An Event(s) Preceded the Recorded Event(s)	No
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	No
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	No

System Status At AE

Vehicle Identification Number	**1AK15F*7*
Low Tire Pressure Warning Lamp (If Equipped)	Invalid
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Fourth Gear
Transmission Selector Position (If Equipped)	Fourth Gear
Traction Control System Active (If Equipped)	Invalid
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	80
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	Invalid	Invalid
Cruise Control Resume Switch Active (If Equipped)	Invalid	Invalid
Cruise Control Set Switch Active (If Equipped)	Invalid	Invalid


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	44	45	45	47	24
Engine Speed (RPM)	1536	1536	1600	1664	1152
Percent Throttle	38	39	37	36	20
Accelerator Pedal Position (percent)	17	18	14	13	0
Antilock Brake System Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Lateral Acceleration (feet/s ²) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Steering Wheel Angle (degrees) (If Equipped)	0	0	0	0	0


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Non-Deployment

Ignition Cycles At Investigation	3093
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	3078
Ignition Cycles At Event	3079
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	BUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Automatic Passenger SIR Suppression System Validity Status	Valid
Automatic Passenger SIR Suppression System Status	Air Bag Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	14.91
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	110
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	No
Vehicle Event Data (Pre-Crash) Associated With This Event	Yes
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-0.68	-2.71	-4.07	-5.42	-7.46	-8.81	-10.17	-12.20	-13.56	-14.23	-14.91	-14.91	0.00	0.00	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	-0.68	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 00 00 00 00 54 00 00
$02 30 00 00 00 00 00 00
$03 02 00 00 00 00 00 00
$04 02 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 04 0A 00 00 0A 39 15
$07 40 09 00 00 00 00 00
$08 00 FF 00 00 00 00 00
$09 00 86 85 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 01 0F 00 00 00
$0C 80 00 80 00 00 00 00
$0D 00 00 40 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F A0 00 00 00 00 00 00
$10 47 31 41 4B 31 35 46
$11 34 37 37 31 38 33 36
$12 34 32 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 03 03 02 02 00 00 00
$18 02 02 00 00 00 00 00
$19 07 07 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 02 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 4F 00 00 4F 00 01 00
$1F 33 C1 00 00 00 23 00
$20 40 00 00 00 00 00 00
$21 01 FF 00 00 D0 00 00
$22 00 98 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 00 FF F0 0C 12 00 00
$2F 00 FE 0C 15 0E 00 00
$30 9D 00 00 00 00 00 00
$31 00 20 24 2F 2B 00 00
$32 00 00 00 80 00 00 00
$33 33 5B 5E 64 62 00 00
$34 12 1A 19 18 18 00 00
$35 27 4B 49 48 46 00 00
$36 00 00 00 00 00 00 00
$37 00 00 00 04 04 00 E2
$38 85 00 40 00 03 C0 00
$39 00 00 00 00 00 80 00
$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00
$3C 00 00 00 00 00 00 C0
$3D 31 41 4B 31 35 46 00
```



```

$3E 37 18 36 42 00 00 00
$3F 00 00 90 00 00 00 00
$40 20 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 00 FF F0 0C 06 00 00
$43 FE 0C 07 00 00 00 00
$44 00 00 00 00 00 00 00
$45 00 00 00 00 00 00 00
$46 00 00 00 00 00 00 00
$47 00 FF 00 FC 00 FA 00
$48 00 F8 FF F5 00 F3 00
$49 00 F1 00 EE 00 EC 00
$4A 00 EB 00 EA 00 EA 00
$4B 00 00 00 00 00 00 00
$4C 00 00 00 00 00 00 00
$4D 00 00 00 00 00 00 00
$4E 00 00 00 00 00 00 00
$4F 00 00 00 00 00 00 00
$50 00 00 00 00 00 00 00
$51 D0 00 00 00 00 00 00
$52 00 00 00 00 00 00 00
$53 0B 01 E4 00 00 00 00
$54 00 00 00 00 00 00 00
$55 00 00 00 00 00 00 00
$67 00 00 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 36 32 35 30 31 45 45 44 4A
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 06 32 35 35 37 5A 37 53
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 37 35 E1 72 6A 74 91 9A
$22 39 15
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA

```

\$26 32 41 FA FA FA FA FA
\$40 00 00
\$41 3F 00 00 02 00 1A
\$42 D0 C4
\$43 00 00 8E 80
\$44 C6 00 00 FC C0 C0
\$45 07 01 07 01 05 01
\$46 FF 1B 1B 64 28
\$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
\$48 18 08 08
\$B0 58
\$B1 FD FE 00
\$B2 FF FF FF FF FF
\$B4 41 53 33 39 31 35 32 32 31 4B 42 35 20 20 20 20
\$B7 50 AA 04 0F 07
\$B8 43 48 70 02 09
\$C1 30 46 30 37
\$CA 30 46 30 37
\$CB 01 89 6E 6B
\$CC 01 89 6E 6B
\$D1 00 00
\$DB 00 00
\$DC 00 00

Comments

Location- 12020 US Hwy 301, Riverview, Fl

Connection- DLC

Power- External battery

Miles- not registered

SIR- Instrument sir lamp flashed and went off during key on power

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.

CDR File Information

User Entered VIN	1G1AK15F477 [REDACTED]
User	C. Garcia
Case Number	669566
EDR Data Imaging Date	Friday, May 22 2009
Crash Date	Wednesday, April 1 2009
Filename	1G1AK15F477 [REDACTED].CDR
Saved on	Friday, May 22 2009 at 11:31:47 AM
Collected with CDR version	Crash Data Retrieval Tool 3.1.1
Reported with CDR version	Crash Data Retrieval Tool 3.1.1
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

IMPORTANT NOTICE: Robert Bosch LLC recommends that the latest production release of Crash Data Retrieval software be utilized when viewing, printing or exporting any retrieved data from within the CDR program. This ensures that the retrieved data has been translated using the most recent information including but not limited to that which was provided by the manufacturers of the vehicles supported in this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event contains Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM. The second type of SDM recorded crash event is the Deployment Event. It also contains Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

- SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.
- Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.
- Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.
- SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:
 - significant changes in the tire's rolling radius
 - final drive axle ratio changes
 - wheel lockup and wheel slip
- Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.
- Pre-Crash data is recorded asynchronously.
- Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:
 - the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
 - no data is received from the module sending the pre-crash data
 - no module is present to send the pre-crash data

- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

Ignition Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$2F Bytes 3-4	\$0C15	Ignition Cycles at Investigation	3093	cycles

Vehicle Status Data (Pre-Crash)

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID Pack \$31 Byte 1	\$00	Accelerator Pedal Position (-1 sec)	0	% full throttle
DPID Pack \$31 Byte 2	\$20	Accelerator Pedal Position (-2 sec)	13	% full throttle
DPID Pack \$31 Byte 3	\$24	Accelerator Pedal Position (-3 sec)	14	% full throttle
DPID Pack \$31 Byte 4	\$2F	Accelerator Pedal Position (-4 sec)	18	% full throttle
DPID Pack \$31 Byte 5	\$2B	Accelerator Pedal Position (-5 sec)	17	% full throttle
DPID \$31 Byte 6 bit 7	\$00	Accelerator Pedal Position Validity Status	Valid	
DPID \$32 Byte 1 bit 7	\$00	Brake Switch State (-1 sec)	OFF	
DPID \$32 Byte 1 bit 6	\$00	Brake Switch State (-2 sec)	OFF	
DPID \$32 Byte 1 bit 5	\$00	Brake Switch State (-3 sec)	OFF	
DPID \$32 Byte 1 bit 4	\$00	Brake Switch State (-4 sec)	OFF	
DPID \$32 Byte 1 bit 3	\$00	Brake Switch State (-5 sec)	OFF	
DPID \$32 Byte 2 bit 7	\$00	Brake Switch State Validity Status	Valid	
DPID \$32 Byte 3 bit 7	\$00	Cruise Control Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 6	\$00	Cruise Control Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 5	\$00	Cruise Control Resume Switch Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 4	\$00	Cruise Control Resume Switch Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 3	\$00	Cruise Control Set Switch Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 2	\$00	Cruise Control Set Switch Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 1	\$00	Reduced Engine Power Mode (-1sec)	OFF	
DPID \$32 Byte 3 bit 0	\$00	Reduced Engine Power Mode (-2sec)	OFF	
DPID \$32 Byte 4 bit 7	\$80	Cruise Control Active Validity Status If Equipped	Invalid	
DPID \$33 Byte 1	\$33	Throttle Position (-1 sec)	20	% full throttle
DPID \$33 Byte 2	\$5B	Throttle Position (-2 sec)	36	% full throttle
DPID \$33 Byte 3	\$5E	Throttle Position (-3 sec)	37	% full throttle
DPID \$33 Byte 4	\$64	Throttle Position (-4 sec)	39	% full throttle
DPID \$33 Byte 5	\$62	Throttle Position (-5 sec)	38	% full throttle

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$33 Byte 6 bit 7	\$00	Throttle Position Validity Status	Valid	
DPID \$34 Byte 1	\$12	Engine Speed (-1 sec)	1152	RPM
DPID \$34 Byte 2	\$1A	Engine Speed (-2 sec)	1664	RPM
DPID \$34 Byte 3	\$19	Engine Speed (-3 sec)	1600	RPM
DPID \$34 Byte 4	\$18	Engine Speed (-4 sec)	1536	RPM
DPID \$34 Byte 5	\$18	Engine Speed (-5 sec)	1536	RPM
DPID \$34 Byte 6 bit 7	\$00	Engine Speed Validity Status	Valid	
DPID \$35 Byte 1	\$27	Vehicle Speed (-1 sec)	24	MPH
DPID \$35 Byte 2	\$4B	Vehicle Speed (-2 sec)	47	MPH
DPID \$35 Byte 3	\$49	Vehicle Speed (-3 sec)	45	MPH
DPID \$35 Byte 4	\$48	Vehicle Speed (-4 sec)	45	MPH
DPID \$35 Byte 5	\$46	Vehicle Speed (-5 sec)	44	MPH
DPID \$35 Byte 6 bit 7	\$00	Vehicle Speed Validity Status	Valid	
DPID \$36 Byte 1	\$00	Steering Wheel Angle (-1 sec) If Equipped	0	degrees
DPID \$36 Byte 2	\$00	Steering Wheel Angle (-2 sec) If Equipped	0	degrees
DPID \$36 Byte 3	\$00	Steering Wheel Angle (-3 sec) If Equipped	0	degrees
DPID \$36 Byte 4	\$00	Steering Wheel Angle (-4 sec) If Equipped	0	degrees
DPID \$36 Byte 5	\$00	Steering Wheel Angle (-5 sec) If Equipped	0	degrees
DPID \$36 Byte 6 bit 7	\$00	Steering Wheel Angle Validity Status If Equipped	Valid	
DPID \$37 Byte 1 bit 7	\$00	Antilock Brake System Active (-1 sec) If Equipped	No	
DPID \$37 Byte 1 bit 6	\$00	Antilock Brake System Active (-2 sec) If Equipped	No	
DPID \$37 Byte 1 bit 5	\$00	Antilock Brake System Active (-3 sec) If Equipped	No	
DPID \$37 Byte 1 bit 4	\$00	Antilock Brake System Active (-4 sec) If Equipped	No	
DPID \$37 Byte 1 bit 3	\$00	Antilock Brake System Active (-5 sec) If Equipped	No	
DPID \$37 Byte 2 bit 7	\$00	Traction Control System Active (-1 sec) If Equipped	No	
DPID \$37 Byte 3 bit 7	\$00	Vehicle Dynamics Control Active (-1 sec) If Equipped	No	
DPID \$37 Byte 3 bit 6	\$00	Vehicle Dynamics Control Active (-2 sec) If Equipped	No	
DPID \$37 Byte 3 bit 5	\$00	Vehicle Dynamics Control Active (-3 sec) If Equipped	No	
DPID \$37 Byte 3 bit 4	\$00	Vehicle Dynamics Control Active (-4 sec) If Equipped	No	
DPID \$37 Byte 3 bit 3	\$00	Vehicle Dynamics Control Active (-5 sec) If Equipped	No	
DPID \$37 Byte 4 bits 3-0	\$04	Transmission Range (-1 sec) If Equipped	Fourth Gear	
DPID \$37 Byte 5 bits 3-0	\$04	Transmission Selector Position (-1 sec) If Equipped	Fourth Gear	
DPID \$37 Byte 6 bit 7	\$00	Service Engine Soon (Non-Emission Related) Lamp (1 sec)	OFF	
DPID \$37 Byte 6 bit 6	\$00	Service Vehicle Soon Lamp (1 sec)	OFF	
DPID \$37 Byte 6 bit 3	\$00	Brake System Warning Lamp If Equipped	OFF	
DPID \$37 Byte 6 bit 1	\$00	Low Tire Pressure Warning Lamp If Equipped	OFF	
DPID \$37 Byte 7 bit 7	\$E2	Antilock Brake System Active Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 6	\$E2	Traction Control System Active Validity Status If Equipped	Invalid	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$37 Byte 7 bit 5	\$E2	Vehicle Dynamics Control Active Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 4	\$E2	Transmission Range Validity Status If Equipped	Valid	
DPID \$37 Byte 7 bit 3	\$E2	Transmission Selector Position Validity Status If Equipped	Valid	
DPID \$37 Byte 7 bit 2	\$E2	Service Engine Soon (Non-Emission Related) / Service Vehicle Soon Lamp Validity Status	Valid	
DPID \$37 Byte 7 bit 1	\$E2	Low Tire Pressure Warning Lamp Validity Status If Equipped	Invalid	
DPID \$38 Byte 1	\$85	Outside Air Temperature (-1 sec) If Equipped	80	
DPID \$38 Byte 2 bit 7	\$00	Outside Air Temperature Validity Status (-1 sec) If Equipped	Valid	
DPID \$38 Byte 5 bits 7-6	\$03	Left Front Door Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 5-4	\$03	Right Front Door Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 3-2	\$03	Rear Door(s) Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 1-0	\$03	Left Rear Door Status (-1 sec) If Equipped	Unused	
DPID \$38 Byte 6 bits 7-6	\$C0	Right Rear Door Status (-1 sec) If Equipped	Unused	
DPID \$38 Byte 7 bit 7	\$00	Left Front Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 6	\$00	Right Front Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 5	\$00	Rear Door(s) Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 4	\$00	Left Rear Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 3	\$00	Right Rear Door Validity Status If Equipped	Valid	
DPID \$39 Byte 1	\$00	Lateral Acceleration (-1 sec) If Equipped	0	feet/sec ²
DPID \$39 Byte 2	\$00	Lateral Acceleration (-2 sec) If Equipped	0	feet/sec ²
DPID \$39 Byte 3	\$00	Lateral Acceleration (-3 sec) If Equipped	0	feet/sec ²
DPID \$39 Byte 4	\$00	Lateral Acceleration (-4 sec) If Equipped	0	feet/sec ²
DPID \$39 Byte 5	\$00	Lateral Acceleration (-5 sec) If Equipped	0	feet/sec ²
DPID \$39 Byte 6 bit 7	\$80	Lateral Acceleration Validity Status If Equipped	Invalid	
DPID \$3A Byte 1	\$00	Yaw Rate (-1 sec) If Equipped	0	
DPID \$3A Byte 2	\$00	Yaw Rate (-2 sec) If Equipped	0	
DPID \$3A Byte 3	\$00	Yaw Rate (-3 sec) If Equipped	0	
DPID \$3A Byte 4	\$00	Yaw Rate (-4 sec) If Equipped	0	
DPID \$3A Byte 5	\$00	Yaw Rate (-5 sec) If Equipped	0	
DPID \$3A Byte 6 bit 7	\$80	Yaw Rate Validity Status If Equipped	Invalid	

VIN Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3D Byte 1	\$31	Vehicle Identification Number (VIN) Digit 3	1	
DPID \$3D Byte 2	\$41	Vehicle Identification Number (VIN) Digit 4	A	
DPID \$3D Byte 3	\$4B	Vehicle Identification Number (VIN) Digit 5	K	
DPID \$3D Byte 4	\$31	Vehicle Identification Number (VIN) Digit 6	1	
DPID \$3D Byte 5	\$35	Vehicle Identification Number (VIN) Digit 7	5	
DPID \$3D Byte 6	\$46	Vehicle Identification Number (VIN) Digit 8	F	
DPID \$3E Byte 1	\$37	Vehicle Identification Number (VIN) Digit 10	7	
DPID \$3E Byte 2 bits 7-4	\$18	Vehicle Identification Number (VIN) Digit 12	1	
DPID \$3E Byte 2 bits 3-0	\$18	Vehicle Identification Number (VIN) Digit 13	8	
DPID \$3E Byte 3 bits 7-4	\$36	Vehicle Identification Number (VIN) Digit 14	3	
DPID \$3E Byte 3 bits 3-0	\$36	Vehicle Identification Number (VIN) Digit 15	6	
DPID \$3E Byte 4 bits 7-4	\$42	Vehicle Identification Number (VIN) Digit 16	4	
DPID \$3E Byte 4 bits 3-0	\$42	Vehicle Identification Number (VIN) Digit 17	2	

Multiple Event Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3F Byte 1 bit 7	\$00	An Event(s) Preceded the Recorded Event(s)	No	
DPID \$3F Byte 1 bit 6	\$00	An Event(s) was in Between the Recorded Event(s)	No	
DPID \$3F Byte 1 bit 5	\$00	An Event(s) Followed the Recorded Event(s)	No	
DPID \$3F Byte 1 bit 4	\$00	The Event(s) Not Recorded was a Deployment Event(s)	No	
DPID \$3F Byte 1 bit 3	\$00	The Event(s) Not Recorded was a Non-Deployment Event(s)	No	
DPID \$3F Byte 1 bits 2-0	\$00	Associated Events Not Recorded	0	

Power Mode Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3F Byte 3 bits 7-6	\$90	Vehicle Power Mode Status	Run	
DPID \$3F Byte 3 bit 5	\$90	Remote Start Status If Equipped	Inactive	
DPID \$3F Byte 3 bit 4	\$90	Run/Crank Ignition Switch Logic Level	Active	

Non-Deployment Or Deployment #2 Event Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$40 Byte 1 bit 7	\$20	Crash Record Locked	No	
DPID \$40 Byte 1 bit 6	\$20	Deployment Event Recorded in the Non-Deployment Record	No	
DPID \$40 Byte 1 bit 5	\$20	Vehicle Event Data (Pre-Crash) Associated With This Event	Yes	
DPID \$40 Byte 2	\$A5	Event Recording Complete	Yes	
DPID \$41 Byte 1 bit 7	\$00	Driver 1st Stage Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 6	\$00	Driver 2nd Stage Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 5	\$00	Driver Side Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 4	\$00	Driver Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 3	\$00	Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 1 bit 2	\$00	Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 1 bit 1	\$00	Driver Knee Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 7	\$00	Passenger 1st Stage Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 6	\$00	Passenger 2nd Stage Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 5	\$00	Passenger Side Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 4	\$00	Passenger Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 3	\$00	Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 2 bit 2	\$00	Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 2 bit 1	\$00	Passenger Knee Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 7	\$00	Second Row Left Side Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 6	\$00	Second Row Left Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 5	\$00	Third Row Left Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 3 bit 4	\$00	Second Row Right Side Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 3	\$00	Second Row Right Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 2	\$00	Third Row Right Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 3 bit 1	\$00	Center Rear Pretensioner Deployment Loop Commanded	No	
DPID \$42 Byte 1 bit 7	\$00	SIR Warning Lamp Status	OFF	
DPID \$42 Bytes 2-3	FFFF0	SIR Warning Lamp ON/OFF Time Continuously	655200	seconds
DPID \$42 Bytes 4-5	\$0C06	Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	3078	cycles
DPID \$43 Byte 1	\$FE	Ignition Cycles Since DTCs Were Last Cleared	254	cycles
DPID \$43 Bytes 2-3	\$0C07	Ignition Cycles at Event	3079	cycles
DPID \$44 Bytes 1-2	\$0000	DTC number for fault #1	N/A	
DPID \$44 Byte 3	\$00	DTC fault type for fault #1	\$00	
DPID \$44 Bytes 4-5	\$0000	DTC number for fault #2	N/A	
DPID \$44 Byte 6	\$00	DTC fault type for fault #2	\$00	
DPID \$45 Bytes 1-2	\$0000	DTC number for fault #3	N/A	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$45 Byte 3	\$00	DTC fault type for fault #3	\$00	
DPID \$45 Bytes 4-5	\$0000	DTC number for fault #4	N/A	
DPID \$45 Byte 6	\$00	DTC fault type for fault #4	\$00	
DPID \$46 Bytes 1-2	\$0000	DTC number for fault #5	N/A	
DPID \$46 Byte 3	\$00	DTC fault type for fault #5	\$00	
DPID \$46 Bytes 4-5	\$0000	DTC number for fault #6	N/A	
DPID \$46 Byte 6	\$00	DTC fault type for fault #6	\$00	
DPID \$47 Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (10 ms after event enable or 70 ms before deployment)	0.00	MPH
DPID \$47 Byte 2	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (10 ms after event enable or 70 ms before deployment)	-0.68	MPH
DPID \$47 Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (20 ms after event enable or 60 ms before deployment)	0.00	MPH
DPID \$47 Byte 4	\$FC	SDM Recorded Vehicle Velocity Change for Axis #2 (20 ms after event enable or 60 ms before deployment)	-2.71	MPH
DPID \$47 Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (30 ms after event enable or 50 ms before deployment)	0.00	MPH
DPID \$47 Byte 6	\$FA	SDM Recorded Vehicle Velocity Change for Axis #2 (30 ms after event enable or 50 ms before deployment)	-4.07	MPH
DPID \$48 Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (40 ms after event enable or 40 ms before deployment)	0.00	MPH
DPID \$48 Byte 2	\$F8	SDM Recorded Vehicle Velocity Change for Axis #2 (40 ms after event enable or 40 ms before deployment)	-5.42	MPH
DPID \$48 Byte 3	\$FF	SDM Recorded Vehicle Velocity Change for Axis #1 (50 ms after event enable or 30 ms before deployment)	-0.68	MPH
DPID \$48 Byte 4	\$F5	SDM Recorded Vehicle Velocity Change for Axis #2 (50 ms after event enable or 30 ms before deployment)	-7.46	MPH
DPID \$48 Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (60 ms after event enable or 20 ms before deployment)	0.00	MPH
DPID \$48 Byte 6	\$F3	SDM Recorded Vehicle Velocity Change for Axis #2 (60 ms after event enable or 20 ms before deployment)	-8.81	MPH
DPID \$49 Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (70 ms after event enable or 10 ms before deployment)	0.00	MPH
DPID \$49 Byte 2	\$F1	SDM Recorded Vehicle Velocity Change for Axis #2 (70 ms after event enable or 10 ms before deployment)	-10.17	MPH
DPID \$49 Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (80 ms after event enable or at deployment)	0.00	MPH

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$49 Byte 4	\$EE	SDM Recorded Vehicle Velocity Change for Axis #2 (80 ms after event enable or at deployment)	-12.20	MPH
DPID \$49 Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (90 ms after event enable or 10 ms after deployment)	0.00	MPH
DPID \$49 Byte 6	\$EC	SDM Recorded Vehicle Velocity Change for Axis #2 (90 ms after event enable or 10 ms after deployment)	-13.56	MPH
DPID \$4A Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (100 ms after event enable or 20 ms after deployment)	0.00	MPH
DPID \$4A Byte 2	\$EB	SDM Recorded Vehicle Velocity Change for Axis #2 (100 ms after event enable or 20 ms after deployment)	-14.23	MPH
DPID \$4A Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (110 ms after event enable or 30 ms after deployment)	0.00	MPH
DPID \$4A Byte 4	\$EA	SDM Recorded Vehicle Velocity Change for Axis #2 (110 ms after event enable or 30 ms after deployment)	-14.91	MPH
DPID \$4A Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (120 ms after event enable or 40 ms after deployment)	0.00	MPH
DPID \$4A Byte 6	\$EA	SDM Recorded Vehicle Velocity Change for Axis #2 (120 ms after event enable or 40 ms after deployment)	-14.91	MPH
DPID \$4B Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (130 ms after event enable or 50 ms after deployment)	0.00	MPH
DPID \$4B Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (130 ms after event enable or 50 ms after deployment)	0.00	MPH
DPID \$4B Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (140 ms after event enable or 60 ms after deployment)	0.00	MPH
DPID \$4B Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (140 ms after event enable or 60 ms after deployment)	0.00	MPH
DPID \$4B Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (150 ms after event enable or 70 ms after deployment)	0.00	MPH
DPID \$4B Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (150 ms after event enable or 70 ms after deployment)	0.00	MPH
DPID \$4C Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (160 ms after event enable or 80 ms after deployment)	0.00	MPH
DPID \$4C Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (160 ms after event enable or 80 ms after deployment)	0.00	MPH
DPID \$4C Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (170 ms after event enable or 90 ms after deployment)	0.00	MPH
DPID \$4C Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (170 ms after event enable or 90 ms after deployment)	0.00	MPH

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$4C Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (180 ms after event enable or 100 ms after deployment)	0.00	MPH
DPID \$4C Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (180 ms after event enable or 100 ms after deployment)	0.00	MPH
DPID \$4D Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (190 ms after event enable or 110 ms after deployment)	0.00	MPH
DPID \$4D Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (190 ms after event enable or 110 ms after deployment)	0.00	MPH
DPID \$4D Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (200 ms after event enable or 120 ms after deployment)	0.00	MPH
DPID \$4D Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (200 ms after event enable or 120 ms after deployment)	0.00	MPH
DPID \$4D Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (210 ms after event enable or 130 ms after deployment)	0.00	MPH
DPID \$4D Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (210 ms after event enable or 130 ms after deployment)	0.00	MPH
DPID \$4E Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (220 ms after event enable or 140 ms after deployment)	0.00	MPH
DPID \$4E Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (220 ms after event enable or 140 ms after deployment)	0.00	MPH
DPID \$4E Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (230 ms after event enable or 150 ms after deployment)	0.00	MPH
DPID \$4E Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (230 ms after event enable or 150 ms after deployment)	0.00	MPH
DPID \$4E Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (240 ms after event enable or 160 ms after deployment)	0.00	MPH
DPID \$4E Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (240 ms after event enable or 160 ms after deployment)	0.00	MPH
DPID \$4F Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (250 ms after event enable or 170 ms after deployment)	0.00	MPH
DPID \$4F Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (250 ms after event enable or 170 ms after deployment)	0.00	MPH
DPID \$4F Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (260 ms after event enable or 180 ms after deployment)	0.00	MPH
DPID \$4F Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (260 ms after event enable or 180 ms after deployment)	0.00	MPH
DPID \$4F Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (270 ms after event enable or 190 ms after deployment)	0.00	MPH

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$4F Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (270 ms after event enable or 190 ms after deployment)	0.00	MPH
DPID \$50 Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (280 ms after event enable or 200 ms after deployment)	0.00	MPH
DPID \$50 Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (280 ms after event enable or 200 ms after deployment)	0.00	MPH
DPID \$50 Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (290 ms after event enable or 210 ms after deployment)	0.00	MPH
DPID \$50 Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (290 ms after event enable or 210 ms after deployment)	0.00	MPH
DPID \$50 Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (300 ms after event enable or 220 ms after deployment)	0.00	MPH
DPID \$50 Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (300 ms after event enable or 220 ms after deployment)	0.00	MPH
DPID \$51 Byte 1 bit 7	\$D0	Driver Belt Switch Circuit Status	BUCKLED	
DPID \$51 Byte 1 bit 6	\$D0	Driver Belt Switch Circuit Status Monitored	Yes	
DPID \$51 Byte 1 bit 5	\$D0	Passenger Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 1 bit 4	\$D0	Passenger Belt Switch Circuit Status Monitored	Yes	
DPID \$51 Byte 1 bit 3	\$D0	Front Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 1 bit 2	\$D0	Front Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 7	\$00	Second Row Left Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 6	\$00	Second Row Left Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 5	\$00	Second Row Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 4	\$00	Second Row Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 3	\$00	Second Row Right Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 2	\$00	Second Row Right Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 7	\$00	Third Row Left Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 6	\$00	Third Row Left Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 5	\$00	Third Row Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 4	\$00	Third Row Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 3	\$00	Third Row Right Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 2	\$00	Third Row Right Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 4 bit 7	\$00	Driver Seat Position Status	Rearward	
DPID \$51 Byte 4 bit 6	\$00	Driver Seat Position Status Monitored	No	
DPID \$51 Byte 4 bit 5	\$00	Passenger Seat Position Status	Rearward	
DPID \$51 Byte 4 bit 4	\$00	Passenger Seat Position Status Monitored	No	
DPID \$52 Byte 1 bit 7	\$00	Automatic Passenger SIR Suppression System Validity Status / Passenger SIR Suppression Switch Circuit Status Validity Status	Valid	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$52 Byte 1 bit 0	\$00	Automatic Passenger SIR Suppression System Status / Passenger SIR Suppression Switch Circuit Status	Air Bag Suppressed	
DPID \$52 Bytes 2-3	\$0000	SDM Synchronization Counter	0	
DPID \$52 Byte 4 bit 7-6	\$00	Rollover Sensor Message Status	No Rollover	
DPID \$52 Byte 4 bit 5	\$00	Side Air Bag(s) Were First Commanded to Deploy Due to Side Impact Event	No	
DPID \$52 Byte 4 bit 4	\$00	Side Air Bag(s) Were First Commanded to Deploy Due to Rollover Event	No	
DPID \$52 Byte 4 bits 3-0	\$00	Rollover Sensor Status	Last message received contained errors	
DPID \$53 Byte 1	\$0B	Time From Algorithm Enable to Maximum SDM Recorded Vehicle Velocity Change	110	msec
DPID \$53 Bytes 2-3	\$01E4	Maximum SDM Recorded Vehicle Velocity Change	14.91	MPH
DPID \$54 Byte 1 bit 7	\$00	Automatic Passenger SIR Suppression System Validity Status / Passenger SIR Suppression Switch Circuit Validity Status	Valid	
DPID \$54 Byte 1 bit 1	\$00	Automatic Passenger SIR Suppression System Status / Passenger SIR Suppression Switch Circuit Status	Air Bag Suppressed	
DPID \$54 Byte 2	\$00	Rollover Sensor - Time Between Successive Side Deploys	0	msec
DPID \$54 Byte 3	\$00	Rollover Sensor - Time From Rollover Enable to Deploy	0	msec
DPID \$55 Byte 1	\$00	Driver 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 2	\$00	Driver 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 3	\$00	Passenger 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 4	\$00	Passenger 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 5	\$00	Driver Side or Roof Rail/Head Curtain Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 6	\$00	Passenger Side or Roof Rail/Head Curtain Time From Algorithm Enable to Deployment Command Criteria Met	0	msec