




Logger 3315: noise PSD, 91 records




Logger 3376: noise PSD, 92 records




Logger 3250: noise PSD, 92 records




Logger 3274: noise PSD, 136 records



Logger 3275: noise PSD, 88 records





Injection-recovery into real IMOS background (200 per point)

