

Reference no. 22462653



PRE-PURCHASE

Inspection Report

Requested By : Customer

Requested On : 11 Jul 2024, 11:16 AM

Completed on : 11 Jul 2024, 11:16 AM

2015 MERCEDES-BENZ CLS- CLASS

VIN **Wdd2183752a171575**Registration no. **Yqh43j**Body Type **sedan**

Transmission	automatic
Exterior Colour	Black
Odometer Reading	83416
Mechanic	Luke

Inspection Summary

Overall Rating 

Recommend to buy **YES**

Recommended Purchase Price **Rs 10,40,000**

Repair Estimate **Rs 35,000**

Engine Warranty

6
Months

UPGRADE
TO 12
MONTHS

UPGRADE
TO 2
YEARS

Insurance 3rd Party

Rs 2890

BUY NOW

Insurance OD Premium
(IDV value Rs **5,50,000**)

Rs 6750

BUY NOW

Notes from the mechanic




Road test was good, power and performance was good also. Log book history is up to date and stamped in back of book. Spare keys also. Interior of vehicle is in good condition no major stains or marks. As pictured. Front and rear seats in good condition. Would just advise getting vehicle detailed. Exterior of vehicle is in good condition no major accident damage or marks. Just in a unclean condition been sitting for a few weeks in the garage. Being a black car easier to spot smaller scratches and marks. There were a few minor scratch marks around the rear boot area. But overall in good condition just would advise also a good detail and clean and polish to get minor scratches and marks out.

“

”

Engine



Interior**Exterior****Wheels****BodyCondition**

TrackDriving**RoadTest**

Engine	Interior	Exterior	Wheels	BodyCon
79	74	79	9	7

[Repair Estimate](#)[VIEW ESTIMATE](#)

Engine 79 points of 100



Engine bay presentation Good

Running noise Good

Oil level Good

Coolant level Good

Engine oil leaks NA

Can't see any oil leaks in
engine bay or under vehicle.

Coolant leaks

NA

Can't see any coolant leaks
in engine bay or under
vehicle.

Odometre Reading

YES



Washer fluid level

Good

Brake fluid level Good

Fluid leaks No

Mountings Good

Hoses & Pipes Good

Water pump/ Fan Good

Ignition System/Distributor **Good**

Fuel System **Good**

Battery Voltage **Good**

Battery terminal condition **Good**

Radiator & Cap **Good**

Drive belt & pulleys **Good**

Brake Booster **Good**

Master Cylinder/ABS **Good**

Faults detected during
diagnostic scan **NO**



Interior 74 points of 100

Owners manual/keys

YES



Dash board condition

Good



Seats

Good

Seat belts

Good

Floor mat condition

Good

Front floor mats have more wear than the rears.

Boot condition

Poor

Still has belonging in boot.
And in a dirty state.



Trims

Good

Door trims Good

Radio Good

Speaker operation Good

Rear window demister Good

Air Conditioning Good

Heater demister Good

Washers & Wipers Good

Horn working Good

Doors, locks & hinges Good

Window operation Good

Warning lights

YES

Only has the low tyre pressure light for back left tyre customer is pumping it back up now. But may need further diagnosis.



All interior lights working

YES

Gear level condition

Good



Exterior 79 points of 100



Rust

NO

Windscreen

Good

Windscreen Wiper Rubbers

Good

Evidence of Damage

NO

Glass/mirrors **Good**

Sunroof/Convertible
operation **Good**

Visible frames & members **Good**

Front suspension **Good**

Rear suspension Good

Steering Components Good

Exhaust Good

Differential Good

Drive Shafts Good

Underbody

YES

All exterior lights working

YES

Compliance plate

Good



Build plate


Good



General condition aside from **Good**
cleanliness



Wheels **9** points of 100



Spare tyre/rim/tool kit

YES

Space saver rim. Tools in
boot also.



Brake hoses / callipers

Good

Front brakes Good

Rear brakes Good

Park brake Good

RHR tyre condition Good



RHF rim condition Good



RHF tyre condition

Fair

Outer edge is slightly
wearing. May need wheel
alignment.



LHF rim condition

Good

Outer edge is slightly worn
also.



LHF tyre condition

Fair



LHR rim condition

Good



LHR tyre condition

Fair




RHR rim condition

Fair



BodyCondition 7 points of 100



Bonnet

Good



LHF fender

Good



RHF fender

Good



Front bumper bar

Good



LHF door

Good



RHF door

Good



LHR door

Good



RHFR door

Good



LH Side skirt

Good



RH Side skirt

Good



3/4 RH rear panel

Good



3/4 LH rear panel

Good



Rear bumper bar

Good



Roof

Good



Paint depth discrepancies

Good

TrackDriving 94 points of 100



Burnt rubber in wheels
arches NO

Tow hook cover (surround)
condition Good

Windscreen sand blasting NO

Front bar sand blasting NO

Bonnet sand blasting NO

Worn front tyre shoulders MIN

Worn rear tyres NO

Hot spots on brake discs NO

RoadTest **83** points of 100



Brake shudder NO

Cruise Control Good

Engine coolant temperature Good

4WD System NA

Engine noise GOOD

Turbocharger/wastegate
noise **GOOD**

Wheel bearings **GOOD**

Engine performance **Excellent**

Engine revving **Excellent**

Exhaust smoke/Emissions **GOOD**

Clutch Shudder **NA**

Gearbox operation **GOOD**

Differential noise **GOOD**

Transmission clunking **GOOD**

No clunking

Steering/Suspension **GOOD**

Clutch Engaging **NA**

Brake operation **Excellent**

Drivetrain slack **GOOD**

Instrument cluster operation **Excellent**

Ease of starting **GOOD**

Engine oil temperature **GOOD**

Engine operating
temperature **GOOD**

Rating Guide

Excellent

Brand new/
recently

replaced/ no
evidence of
fault detected

Good	Item found to be in working order with some signs of damage and/or deterioration, consistent with the age & kilometers of vehicle
Fair	Item found to be in working order with notable signs of damage and/or deterioration, consistent with the age & kilometers of vehicle
Poor	Item found to be in bad condition, needs urgent attention or replacement
N/A	Item not fitted to the vehicle or able to be checked

Terms and conditions Expand ▾