

DEFECT INSPECTION REPORT

Generated on 11/17/2025, 4:09:45 PM



Property / Inspection Details

Name	Client Name
Address	Address
Date of Inspection	2025-11-01
Weather	Clear
Building Type	2 Store Terrace House
Inspected By	Muhammad Fikri bin Ab Rahman – Building Surveyor, Registered under Royal Institution of Surveyors Malaysia (RISM)

Types Of Defect Stickers We Use

Sticker	Function
	We refer to hollow or drumming sound when swiped and then tapped. We use a tapping rod.
	We refer to finishing issues identified during the inspection, including uneven painting, inconsistent color tone, chalkiness, rough surfaces, cement debris, and stains. These were detected through visual and touch inspection. Rectification by a qualified contractor is recommended to restore a clean and consistent finish.
	We refer to minor damage, which includes issues such as cracks, dents, pin holes, chipping, exposed objects, detached ceiling boards, peeling paint, and other small-scale physical defects. These should be inspected and rectified to maintain overall workmanship quality.
	We refer to jointing issues observed during the inspection, such as inconsistent grout lines, discolored or gapped grout, uneven skirting joints, and improper sealing at fixtures and corners. These were identified through visual and touch inspection, and we recommend corrective work by a qualified contractor to ensure proper alignment and sealing.
	We refer to major defects identified during the inspection, which include leakages on walls, ceilings, or floors, signs of mold, and water marks, as well as window and door issues such as misalignment, difficulty in operation, or unusual sounds when opened or closed. These defects were noted through visual and touch inspection, and immediate attention by a qualified contractor is strongly recommended to prevent further deterioration and ensure safety.
	This indicates a particular defect noted during inspection, which has been described manually for accuracy. These may include issues such as cracks, stains, misalignments, or other irregularities that require attention. Identified through visual and physical inspection

General Disclaimer About This Report

Thank you for selecting Go Home Inspection for your property assessment needs. Our Home Defect Inspection Report has been meticulously prepared by our registered Building Surveyors under the Royal Institution of Surveyors Malaysia (RISM), ensuring that all evaluations adhere to current Malaysian standards and statutory requirements.

This report is based on the actual conditions observed during the inspection, conducted using limited visual and non-invasive methods. It is designed to provide an overview of the property's overall condition and to identify any readily apparent defects. The report covers general information, detailed defect descriptions, and recommendations for necessary repairs.

Our inspection process complies with numerous relevant standards and acts, including Malaysia Standard (MS), Suruhanjaya Tenaga (ST) Guidelines, SIRIM Certification Standards, Uniform Building By-Laws (UBBL), the Street, Drainage and Building Act 1974 (Act 133), the Fire Services Act 1988 (Act 341), the Electricity Supply Act 1990 (Act 447), the Water Services Industry Act 2006 (Act 655), the Occupational Safety and Health Act 1994 (Act 514), CIDB Construction Industry Standards (CIS) (OPTIONAL), and the Housing Development (Control and Licensing) Act 1966 (Act 118). These measures ensure that your property is assessed with the utmost precision, safety, and compliance.

Please note that while this report reflects our professional opinion, it does not serve as a guarantee or warranty of the property's condition. It is intended solely to enhance your understanding of the property's status and to highlight defects and potential safety risks observed at the time of inspection. For more comprehensive analyses of specific building systems, further assessments by specialist professionals are recommended.

Additionally, you have the right to submit this Defect Report—either digitally or in hard copy—to your developer. Under the terms of your Sales and Purchase Agreement and the Defects Liability Period (DLP), typically 24 months, the developer is obligated to rectify all identified defects. Should the developer or contractor fail to address these issues, the owner reserves the right to issue formal notice and pursue further actions in accordance with the applicable legislation.

We trust that the information provided in this report is clear and insightful, and we are available should you have any further inquiries or require additional clarification.

Thank you once again for choosing Go Home Inspection. We are committed to ensuring your property meets all safety, functionality, and compliance requirements.


General Information for Developer / Contractor

This report has been prepared based on the actual conditions observed during the inspection of this unit and in accordance with the Housing Development Act, the Building and Construction Industry Act, and other relevant statutory provisions. The unit is covered by a 24-month Defects Liability Period (DLP), during which the developer or contractor is required to rectify all identified defects to facilitate a smooth move-in process.


Should the developer or contractor fail to execute the necessary remedial work as specified herein, the owner reserves the right to issue formal notice of default and pursue appropriate actions under the applicable legislation, including the Housing Development Act and the relevant consumer protection statutes.

SAMPLE REPORT GOXPERT - INSPECTION

Floor Plan – Tag Overview (Plan 1)



Floor Plan – Tag Overview (Plan 2)



Summary

Total defects : **328**

- 1 Finding — Ceiling — **Accessories Defects**
- 2 Car Porch — View — **General Photos**
- 3 Car Porch — Floor — **Finishing issues**
- 4 Car Porch — Floor — **Finishing issues**
- 5 Car Porch — Floor — **Hollowness issues**
- 6 Car Porch — Floor — **Jointing Issue**
- 7 Car Porch — Floor — **Jointing Issue**
- 8 Car Porch — Floor — **Major defects**
- 9 Car Porch — Floor — **Major defects**
- 10 Car Porch — Floor — **Minor defects**
- 11 Car Porch — Floor — **Minor defects**
- 12 Car Porch — Floor — **Minor defects**
- 13 Car Porch — Wall — **Alignment issues**
- 14 Car Porch — Wall — **Finishing issues**
- 15 Car Porch — Wall — **Finishing issues**
- 16 Car Porch — Wall — **Minor defects**
- 17 Car Porch — Wall — **Minor defects**
- 18 Car Porch — Ceiling — **Finishing issues**
- 19 Car Porch — Ceiling — **Hollowness issues**
- 20 Car Porch — Ceiling — **Jointing Issue**
- 21 Car Porch — Ceiling — **Leaking issues**
- 22 Car Porch — Ceiling — **Leaking issues**
- 23 Car Porch — Ceiling — **Minor defects**
- 24 Car Porch — Ceiling — **Minor defects**
- 25 Car Porch — Plumbing & Sanitary Fitting — **Finishing issues**
- 26 Car Porch — Plumbing & Sanitary Fitting — **Finishing issues**
- 27 Car Porch — M&E — **Accessories Defects**
- 28 Car Porch — M&E — **Accessories Defects**
- 29 Car Porch — M&E — **Accessories Defects**
- 30 Car Porch — M&E — **Accessories Defects**
- 31 Car Porch — M&E — **Standard & Regulation**
- 32 Car Porch — TNB Compactment — **Accessories Defects**

Summary (cont.)

- 33** Car Porch — Mailbox — **Accessories Defects**
- 34** Car Porch — TNB Compactment — **Finishing issues**
- 35** Car Porch — TNB Compactment — **Finishing issues**
- 36** Car Porch — Mailbox — **Finishing issues**
- 37** Car Porch — TNB Compactment — **Functionality issues**
- 38** Car Porch — Mailbox — **Jointing Issue**
- 39** Car Porch — TNB Compactment — **Minor defects**
- 40** Car Porch — Main gate — **Minor defects**
- 41** Car Porch — Fence — **Minor defects**
- 42** Living and Dining Area — View — **General Photos**
- 43** Living and Dining Area — Floor — **Alignment issues**
- 44** Living and Dining Area — Floor — **Finishing issues**
- 45** Living and Dining Area — Floor — **Jointing Issue**
- 46** Living and Dining Area — Floor — **Minor defects**
- 47** Living and Dining Area — Wall — **Alignment issues**
- 48** Living and Dining Area — Wall — **Alignment issues**
- 49** Living and Dining Area — Wall — **Alignment issues**
- 50** Living and Dining Area — Wall — **Alignment issues**
- 51** Living and Dining Area — Wall — **Alignment issues**
- 52** Living and Dining Area — Wall — **Finishing issues**
- 53** Living and Dining Area — Ceiling — **Finishing issues**
- 54** Living and Dining Area — Ceiling — **Minor defects**
- 55** Living and Dining Area — Door — **Accessories Defects**
- 56** Living and Dining Area — Door — **Accessories Defects**
- 57** Living and Dining Area — Door — **Accessories Defects**
- 58** Living and Dining Area — Door — **Alignment issues**
- 59** Living and Dining Area — Door — **Finishing issues**
- 60** Living and Dining Area — Door — **Minor defects**
- 61** Living and Dining Area — Door — **Minor defects**
- 62** Living and Dining Area — M&E — **Accessories Defects**
- 63** Living and Dining Area — M&E — **Accessories Defects**
- 64** Utility room — View — **General Photos**
- 65** Utility room — Floor — **Hollowness issues**
- 66** Utility room — Wall — **Finishing issues**

Summary (cont.)

- 67 Utility room — Wall — **Minor defects**
- 68 Utility room — Ceiling — **Finishing issues**
- 69 Utility room — Ceiling — **Minor defects**
- 70 Utility room — Door — **Finishing issues**
- 71 Utility room — Door — **Minor defects**
- 72 Dry Kitchen — View — **General Photos**
- 73 Dry Kitchen — Floor — **Finishing issues**
- 74 Dry Kitchen — Floor — **Jointing Issue**
- 75 Dry Kitchen — Wall — **Alignment issues**
- 76 Dry Kitchen — Wall — **Alignment issues**
- 77 Dry Kitchen — Wall — **Alignment issues**
- 78 Dry Kitchen — Wall — **Alignment issues**
- 79 Dry Kitchen — Wall — **Finishing issues**
- 80 Dry Kitchen — Wall — **Finishing issues**
- 81 Dry Kitchen — Wall — **Hollowness issues**
- 82 Dry Kitchen — Wall — **Jointing Issue**
- 83 Dry Kitchen — Wall — **Leaking issues**
- 84 Dry Kitchen — Wall — **Minor defects**
- 85 Dry Kitchen — Ceiling — **Finishing issues**
- 86 Dry Kitchen — Ceiling — **Leaking issues**
- 87 Dry Kitchen — Ceiling — **Minor defects**
- 88 Dry Kitchen — Window — **Finishing issues**
- 89 Dry Kitchen — Plumbing & Sanitary Fitting — **Finishing issues**
- 90 Dry Kitchen — Plumbing & Sanitary Fitting — **Minor defects**
- 91 Dry Kitchen — Fixtures — **Accessories Defects**
- 92 Wet Kitchen — View — **General Photos**
- 93 Wet Kitchen — Floor — **Finishing issues**
- 94 Wet Kitchen — Floor — **Hollowness issues**
- 95 Wet Kitchen — Floor — **Jointing Issue**
- 96 Wet Kitchen — Wall — **Alignment issues**
- 97 Wet Kitchen — Wall — **Alignment issues**
- 98 Wet Kitchen — Wall — **Finishing issues**
- 99 Wet Kitchen — Wall — **Major defects**
- 100 Wet Kitchen — Wall — **Minor defects**

Summary (cont.)

- 101** Wet Kitchen — Ceiling — **Leaking issues**
- 102** Wet Kitchen — Ceiling — **Leaking issues**
- 103** Wet Kitchen — Ceiling — **Minor defects**
- 104** Wet Kitchen — Door — **Accessories Defects**
- 105** Wet Kitchen — Door — **Finishing issues**
- 106** Wet Kitchen — Door — **Minor defects**
- 107** Wet Kitchen — Plumbing & Sanitary Fitting — **Jointing Issue**
- 108** Wet Kitchen — Plumbing & Sanitary Fitting — **Jointing Issue**
- 109** Bedroom 4 — View — **General Photos**
- 110** Bedroom 4 — Floor — **Hollowness issues**
- 111** Bedroom 4 — Wall — **Alignment issues**
- 112** Bedroom 4 — Wall — **Alignment issues**
- 113** Bedroom 4 — Wall — **Alignment issues**
- 114** Bedroom 4 — Wall — **Alignment issues**
- 115** Bedroom 4 — Wall — **Finishing issues**
- 116** Bedroom 4 — Wall — **Minor defects**
- 117** Bedroom 4 — Ceiling — **Finishing issues**
- 118** Bedroom 4 — Ceiling — **Minor defects**
- 119** Bedroom 4 — Door — **Accessories Defects**
- 120** Bedroom 4 — Door — **Finishing issues**
- 121** Bedroom 4 — Door — **Jointing Issue**
- 122** Bedroom 4 — Window — **Finishing issues**
- 123** Bedroom 4 — Window — **Others**
- 124** Bedroom 4 — M&E — **Accessories Defects**
- 125** Bathroom 3 — View — **General Photos**
- 126** Bathroom 3 — Floor — **Minor defects**
- 127** Bathroom 3 — Wall — **Finishing issues**
- 128** Bathroom 3 — Wall — **Hollowness issues**
- 129** Bathroom 3 — Wall — **Minor defects**
- 130** Bathroom 3 — Ceiling — **Finishing issues**
- 131** Bathroom 3 — Ceiling — **Jointing Issue**
- 132** Bathroom 3 — Ceiling — **Leaking issues**
- 133** Bathroom 3 — Door — **Accessories Defects**
- 134** Bathroom 3 — Door — **Finishing issues**

Summary (cont.)

- 135** Bathroom 3 — Plumbing & Sanitary Fitting — **Jointing Issue**
- 136** Bathroom 3 — Plumbing & Sanitary Fitting — **Leaking issues**
- 137** Bathroom 3 — Plumbing & Sanitary Fitting — **Minor defects**
- 138** Bathroom 3 — Plumbing & Sanitary Fitting — **Poor Drainage System**
- 139** Bathroom 3 — M&E — **Jointing Issue**
- 140** Bathroom 3 — Fixtures — **Accessories Defects**
- 141** Bathroom 3 — Fixtures — **Jointing Issue**
- 142** Backyard — View — **General Photos**
- 143** Backyard — Floor — **Finishing issues**
- 144** Backyard — Floor — **Finishing issues**
- 145** Backyard — Floor — **Finishing issues**
- 146** Backyard — Floor — **Hollowness issues**
- 147** Backyard — Floor — **Jointing Issue**
- 148** Backyard — Wall — **Alignment issues**
- 149** Backyard — Wall — **Finishing issues**
- 150** Backyard — Wall — **Minor defects**
- 151** Backyard — Wall — **Minor defects**
- 152** Backyard — Window — **Jointing Issue**
- 153** Backyard — Fence — **Accessories Defects**
- 154** Backyard — Gate — **Minor defects**
- 155** Backyard — Fence — **Minor defects**
- 156** Backyard — Gate — **S&P Review**
- 157** Backyard — Fence — **Standard & Regulation**
- 158** Staircase — View — **General Photos**
- 159** Staircase — Floor — **Alignment issues**
- 160** Staircase — Floor — **Alignment issues**
- 161** Staircase — Floor — **Finishing issues**
- 162** Staircase — Floor — **Hollowness issues**
- 163** Staircase — Wall — **Alignment issues**
- 164** Staircase — Wall — **Finishing issues**
- 165** Staircase — Wall — **Minor defects**
- 166** Staircase — Ceiling — **Finishing issues**
- 167** Family Area — View — **General Photos**
- 168** Family Area — Floor — **Hollowness issues**

Summary (cont.)

- 169** Family Area — Wall — **Alignment issues**
- 170** Family Area — Wall — **Alignment issues**
- 171** Family Area — Wall — **Finishing issues**
- 172** Family Area — Wall — **Minor defects**
- 173** Family Area — Ceiling — **Finishing issues**
- 174** Family Area — Ceiling — **Minor defects**
- 175** Family Area — M&E — **Finishing issues**
- 176** Family Area — M&E — **Standard & Regulation**
- 177** Family Area — M&E — **Standard & Regulation**
- 178** Master Bedroom — Floor — **Hollowness issues**
- 179** Master Bedroom — Floor — **Jointing Issue**
- 180** Master Bedroom — Wall — **Alignment issues**
- 181** Master Bedroom — Wall — **Alignment issues**
- 182** Master Bedroom — Wall — **Alignment issues**
- 183** Master Bedroom — Wall — **Finishing issues**
- 184** Master Bedroom — Wall — **Minor defects**
- 185** Master Bedroom — Wall — **Stains/Water Mark**
- 186** Master Bedroom — Ceiling — **Jointing Issue**
- 187** Master Bedroom — Ceiling — **Minor defects**
- 188** Master Bedroom — Door — **Accessories Defects**
- 189** Master Bedroom — Door — **Finishing issues**
- 190** Master Bedroom — Door — **Minor defects**
- 191** Master Bedroom — Door — **Minor defects**
- 192** Master Bedroom — M&E — **Finishing issues**
- 193** Master Bathroom — View — **General Photos**
- 194** Master Bathroom — Floor — **Finishing issues**
- 195** Master Bathroom — Floor — **Jointing Issue**
- 196** Master Bathroom — Floor — **Jointing Issue**
- 197** Master Bathroom — Floor — **Minor defects**
- 198** Master Bathroom — Wall — **Finishing issues**
- 199** Master Bathroom — Wall — **Hollowness issues**
- 200** Master Bathroom — Wall — **Jointing Issue**
- 201** Master Bathroom — Wall — **Minor defects**
- 202** Master Bathroom — Ceiling — **Finishing issues**

Summary (cont.)

- 203** Master Bathroom — Ceiling — **Jointing Issue**
- 204** Master Bathroom — Ceiling — **Minor defects**
- 205** Master Bathroom — Door — **Accessories Defects**
- 206** Master Bathroom — Door — **Accessories Defects**
- 207** Master Bathroom — Door — **Finishing issues**
- 208** Master Bathroom — Door — **Jointing Issue**
- 209** Master Bathroom — Door — **Minor defects**
- 210** Master Bathroom — Door — **Minor defects**
- 211** Master Bathroom — Window — **Finishing issues**
- 212** Master Bathroom — Window — **Functionality issues**
- 213** Master Bathroom — Window — **Jointing Issue**
- 214** Master Bathroom — Window — **Jointing Issue**
- 215** Master Bathroom — Plumbing & Sanitary Fitting — **Accessories Defects**
- 216** Master Bathroom — Plumbing & Sanitary Fitting — **Jointing Issue**
- 217** Master Bathroom — Plumbing & Sanitary Fitting — **Leaking issues**
- 218** Master Bathroom — Plumbing & Sanitary Fitting — **Poor Drainage System**
- 219** Master Bathroom — Fixtures — **Accessories Defects**
- 220** Master Bathroom — Fixtures — **Jointing Issue**
- 221** Master Bathroom — Fixtures — **Jointing Issue**
- 222** Balcony — View — **General Photos**
- 223** Balcony — Floor — **Jointing Issue**
- 224** Balcony — Floor — **Major defects**
- 225** Balcony — Floor — **Minor defects**
- 226** Balcony — Wall — **Finishing issues**
- 227** Balcony — Wall — **Finishing issues**
- 228** Balcony — Wall — **Minor defects**
- 229** Balcony — Fixtures — **Minor defects**
- 230** Balcony — Sliding door — **Accessories Defects**
- 231** Balcony — Sliding door — **Jointing Issue**
- 232** Bedroom 2 — View — **General Photos**
- 233** Bedroom 2 — Floor — **Alignment issues**
- 234** Bedroom 2 — Floor — **Hollowness issues**
- 235** Bedroom 2 — Wall — **Alignment issues**
- 236** Bedroom 2 — Wall — **Alignment issues**

Summary (cont.)

- 237** Bedroom 2 — Wall — **Alignment issues**
- 238** Bedroom 2 — Wall — **Alignment issues**
- 239** Bedroom 2 — Wall — **Alignment issues**
- 240** Bedroom 2 — Wall — **Alignment issues**
- 241** Bedroom 2 — Wall — **Finishing issues**
- 242** Bedroom 2 — Wall — **Minor defects**
- 243** Bedroom 2 — Ceiling — **Jointing Issue**
- 244** Bedroom 2 — Door — **Accessories Defects**
- 245** Bedroom 2 — Door — **Finishing issues**
- 246** Bedroom 2 — Door — **Jointing Issue**
- 247** Bedroom 2 — Door — **Minor defects**
- 248** Bedroom 2 — Window — **Jointing Issue**
- 249** Bedroom 3 — View — **General Photos**
- 250** Bedroom 3 — Floor — **Finishing issues**
- 251** Bedroom 3 — Floor — **Hollowness issues**
- 252** Bedroom 3 — Floor — **Jointing Issue**
- 253** Bedroom 3 — Floor — **Minor defects**
- 254** Bedroom 3 — Wall — **Alignment issues**
- 255** Bedroom 3 — Wall — **Alignment issues**
- 256** Bedroom 3 — Wall — **Alignment issues**
- 257** Bedroom 3 — Wall — **Finishing issues**
- 258** Bedroom 3 — Wall — **Major defects**
- 259** Bedroom 3 — Wall — **Minor defects**
- 260** Bedroom 3 — Ceiling — **Finishing issues**
- 261** Bedroom 3 — Ceiling — **Minor defects**
- 262** Bedroom 3 — Door — **Finishing issues**
- 263** Bedroom 3 — Window — **Finishing issues**
- 264** Bedroom 3 — Window — **Jointing Issue**
- 265** Bath 2 — View — **General Photos**
- 266** Bath 2 — Floor — **Accessories Defects**
- 267** Bath 2 — Wall — **Finishing issues**
- 268** Bath 2 — Wall — **Hollowness issues**
- 269** Bath 2 — Wall — **Jointing Issue**
- 270** Bath 2 — Ceiling — **Finishing issues**

Summary (cont.)


- 271** Bath 2 — Ceiling — **Jointing Issue**
- 272** Bath 2 — Ceiling — **Minor defects**
- 273** Bath 2 — Door — **Finishing issues**
- 274** Bath 2 — Door — **Minor defects**
- 275** Bath 2 — Window — **Accessories Defects**
- 276** Bath 2 — Window — **Finishing issues**
- 277** Bath 2 — Window — **Functionality issues**
- 278** Bath 2 — Plumbing & Sanitary Fitting — **Accessories Defects**
- 279** Bath 2 — Plumbing & Sanitary Fitting — **Accessories Defects**
- 280** Bath 2 — Plumbing & Sanitary Fitting — **Jointing Issue**
- 281** Bath 2 — Plumbing & Sanitary Fitting — **Leaking issues**
- 282** Bath 2 — Plumbing & Sanitary Fitting — **Poor Drainage System**
- 283** Bath 2 — M&E — **Accessories Defects**
- 284** Bath 2 — Fixtures — **Finishing issues**
- 285** Bath 2 — Fixtures — **Jointing Issue**
- 286** Flat Roof — View — **General Photos**
- 287** Flat Roof — Floor — **Finishing issues**
- 288** Flat Roof — Floor — **Hollowness issues**
- 289** Flat Roof — Floor — **Jointing Issue**
- 290** Flat Roof — Floor — **Major defects**
- 291** Flat Roof — Floor — **Minor defects**
- 292** Flat Roof — Wall — **Finishing issues**
- 293** Flat Roof — Wall — **Hollowness issues**
- 294** Flat Roof — Wall — **Jointing Issue**
- 295** Flat Roof — Wall — **Minor defects**
- 296** Flat Roof — Wall — **Minor defects**
- 297** Flat Roof — Ceiling — **Major defects**
- 298** Flat Roof — Plumbing & Sanitary Fitting — **Accessories Defects**
- 299** Flat Roof — Fixtures — **Jointing Issue**
- 300** Water Tank Area — View — **General Photos**
- 301** Water Tank Area — Floor — **Finishing issues**
- 302** Water Tank Area — Floor — **Jointing Issue**
- 303** Water Tank Area — Floor — **Major defects**
- 304** Water Tank Area — Floor — **Major defects**

Summary (cont.)


- 305 Water Tank Area — Floor — **S&P Review**
- 306 Water Tank Area — Wall — **Jointing Issue**
- 307 Water Tank Area — Wall — **Minor defects**
- 308 Water Tank Area — Ceiling — **Jointing Issue**
- 309 Water Tank Area — Ceiling — **Major defects**
- 310 Water Tank Area — Plumbing & Sanitary Fitting — **Accessories Defects**
- 311 Water Tank Area — Plumbing & Sanitary Fitting — **Alignment issues**
- 312 Water Tank Area — Fixtures — **Accessories Defects**
- 313 Water Tank Area — Fixtures — **Major defects**
- 314 Water Tank Area — Other — **S&P Review**
- 315 Roof First Level — View — **General Photos**
- 316 Roof First Level — Wall — **Minor defects**
- 317 Roof First Level — Wall — **Minor defects**
- 318 Roof First Level — Ceiling — **Jointing Issue**
- 319 Roof First Level — Ceiling — **Minor defects**
- 320 Roof First Level — Roof — **Installation Issue**
- 321 Roof First Level — Roof — **Minor defects**
- 322 Roof First Level — Fixtures — **Accessories Defects**
- 323 Roof First Level — Fixtures — **Jointing Issue**
- 324 Top Roof — View — **General Photos**
- 325 Top Roof — Roof — **Installation Issue**
- 326 Top Roof — Roof — **Jointing Issue**
- 327 Top Roof — Roof — **Minor defects**
- 328 Top Roof — Fixtures — **Accessories Defects**

Analysis

Defects by Element




Defects by Area



Analysis (continued)

Defects by Type of Defect



No.	Type of Defect	No. of Defects
1	Finishing issues	68
2	Minor defects	63
3	Jointing Issue	49
4	Alignment issues	38
5	Accessories Defects	36
6	General Photos	19
7	Hollowness issues	17
8	Major defects	11
9	Leaking issues	10
10	Standard & Regulation	4
11	Functionality issues	3
12	Poor Drainage System	3
13	S&P Review	3
14	Installation Issue	2
15	Others	1
16	Stains/Water Mark	1

Findings

Location	Tag	Defect & Description	Pictures
Finding Ceiling	1	Accessories Defects There are no ceiling manhole to above ceiling area at 1st level	
Car Porch View	2	General Photos	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Car Porch Floor	3	Finishing issues Concrete stains	
Car Porch Floor	4	Finishing issues Stains on floor tile	 

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Car Porch Floor	5	Hollowness issues Hollowness floor tile	


Findings (cont.)

Location	Tag	Defect & Description	Pictures
Car Porch Floor	6	Jointing Issue Visible gaps	
Car Porch Floor	7	Jointing Issue Visible gaps at floor tile grouting	
Car Porch Floor	8	Major defects Crack on floor slab	


Findings (cont.)

Location	Tag	Defect & Description	Pictures
Car Porch Floor	9	Major defects Improper cutting on tiling	 
Car Porch Floor	10	Minor defects Crack on floor slab	 
Car Porch Floor	11	Minor defects Dented, chipping on floor slab	    


Findings (cont.)

Location	Tag	Defect & Description	Pictures
Car Porch Floor	12	Minor defects Crack on floor slab	 
Car Porch Wall	13	Alignment issues Wall mislained	     

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Backyard Gate	154	Minor defects Rusty on gate	
Backyard Fence	155	Minor defects Rusty on fence	
Backyard Gate	156	S&P Review Refer to floor plan, gate should have space between gate and boarder fence	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Backyard Fence	157	Standard & Regulation That have large gap between bottom fence and fence beam	  
Staircase View	158	General Photos	
Staircase Floor	159	Alignment issues Floor not aligned (senget)	 

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Staircase Floor	160	Alignment issues Uneven flooring tile (have gap)	   
Staircase Floor	161	Finishing issues Stains floor tile	 
Staircase Floor	162	Hollowness issues Hollowness floor tile	  


Findings (cont.)

Location	Tag	Defect & Description	Pictures	
Staircase Wall	163	Alignment issues wall misaligned		
Staircase Wall	164	Finishing issues Stains on painted wall		
Staircase Wall	165	Minor defects Crack on painted wall		
Staircase Ceiling	166	Finishing issues Stains on ceiling surface		

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Family Area View	167	General Photos	
Family Area Floor	168	Hollowness issues Hollowness floor tile	 
Family Area Wall	169	Alignment issues Wall misaligned	 

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Family Area Wall	170	Alignment issues Wall misaligned	  
Family Area Wall	171	Finishing issues Stains on painted wall	  


Findings (cont.)

Location	Tag	Defect & Description	Pictures
Family Area Wall	172	Minor defects Dented and crack on all painted wall	   
Family Area Ceiling	173	Finishing issues Stains on ceiling surface	 
Family Area Ceiling	174	Minor defects Crack and chipping on ceiling surface	  


Findings (cont.)

Location	Tag	Defect & Description	Pictures
Family Area M&E	175	Finishing issues Stains on socket	
Family Area M&E	176	Standard & Regulation Power circuit and light circuit in one RCCB. Refer to ST, Light circuit need to use 100mA and Power circuit need to use 30mA	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Family Area M&E	177	Standard & Regulation RCCD for water heater need to use 10mA and the best is use 2 RCCD with 10mA for 2 water heater	
Master Bedroom Floor	178	Hollowness issues Hollowness floor tile	

Findings (cont.)

Location	Tag	Defect & Description	Pictures	
Master Bedroom Floor	179	Jointing Issue Visible gaps at floor grouts and discolouration at floor tile grouting		
Master Bedroom Wall	180	Alignment issues Wall misaligned		
Master Bedroom Wall	181	Alignment issues		
Master Bedroom Wall	182	Alignment issues Wall misaligned		

Findings (cont.)

Location	Tag	Defect & Description	Pictures	
Master Bedroom Wall	183	Finishing issues Stains and uneven painting at all painted wall	  	
Master Bedroom Wall	184	Minor defects Crack at painted wall	  	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Master Bedroom Wall	185	Stains/Water Mark Water mark and moisture on painted wall near to sliding door	 
Master Bedroom Ceiling	186	Jointing Issue visible gaps between painted wall and ceiling surface joints	
Master Bedroom Ceiling	187	Minor defects Dented on ceiling surface	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Master Bedroom Door	188	Accessories Defects Stains on door knob	
Master Bedroom Door	189	Finishing issues Stains on door leaf	 
Master Bedroom Door	190	Minor defects Peeling paint on door frame and door leaf	  

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Master Bedroom Door	191	Minor defects Damaged on door leaf	
Master Bedroom M&E	192	Finishing issues Stains at socket	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Master Bathroom View	193	General Photos	
Master Bathroom Floor	194	Finishing issues Discoloration on the floor tiles grouting	
Master Bathroom Floor	195	Jointing Issue Improper grouting work / over grouting	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Master Bathroom Floor	196	Jointing Issue Visible gaps on floor tiles jointing	 
Master Bathroom Floor	197	Minor defects Chipping floor tiles	 
Master Bathroom Wall	198	Finishing issues Stain on wall tiles	   

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Bath 2 M&E	283	Accessories Defects Missing junction box cover	
Bath 2 Fixtures	284	Finishing issues Stains at toilet bowl	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Bath 2 Fixtures	285	Jointing Issue Visible gaps between wall tile and basin	
Flat Roof View	286	General Photos	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Flat Roof Floor	287	Finishing issues Construction left over on floor slab	
Flat Roof Floor	288	Hollowness issues Hollow sound on floor slab	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Flat Roof Floor	289	Jointing Issue Visible gaps on floor	
Flat Roof Floor	290	Major defects Crack on floor slab That have possible for leaking	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Flat Roof Floor	291	Minor defects Chipping and crack on floor slab	    
Flat Roof Wall	292	Finishing issues Stain and Uneven painting on wall surface	   

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Flat Roof Wall	293	Hollowness issues Hollow sound on partition wall	 
Flat Roof Wall	294	Jointing Issue That have crack between wall and floor	 
Flat Roof Wall	295	Minor defects Crack on partition wall	  

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Flat Roof Wall	296	Minor defects Crack on wall surface	
Flat Roof Ceiling	297	Major defects Damaged on ceiling board	


Findings (cont.)

Location	Tag	Defect & Description	Pictures
Flat Roof Plumbing & Sanitary Fitting	298	Accessories Defects Drainage filter hard to open	
Flat Roof Fixtures	299	Jointing Issue Visible gap on roof flushing	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Water Tank Area View	300	General Photos	  
Water Tank Area Floor	301	Finishing issues Construction leftover	 
Water Tank Area Floor	302	Jointing Issue Visible gaps between floor slab and wall	 

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Water Tank Area Floor	303	Major defects Improper plastering work, have gaps	
Water Tank Area Floor	304	Major defects Expose temporary timber support	
Water Tank Area Floor	305	S&P Review Refer to section plan, this area should have drop not slope	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Water Tank Area Wall	306	Jointing Issue Visible gaps at corner of wall	
Water Tank Area Wall	307	Minor defects Crack on painted wall	


Findings (cont.)

Location	Tag	Defect & Description	Pictures
Water Tank Area Ceiling	308	Jointing Issue Visible gaps	
Water Tank Area Ceiling	309	Major defects Missing ceiling board and improper support for ceiling	
Water Tank Area Plumbing & Sanitary Fitting	310	Accessories Defects Missing support for distribution pipe	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Water Tank Area Plumbing & Sanitary Fitting	311	Alignment issues Distribution pipe has alignment issues and causes of low water pressure for bathroom 2 and 3	 01/11/2025 11:36
Water Tank Area Fixtures	312	Accessories Defects Dirty inside water tank	 01/11/2025 11:37
Water Tank Area Fixtures	313	Major defects Detached roof flashing (not installed properly)	 01/11/2025 11:35

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Water Tank Area Other	314	S&P Review Refer to section plan, water tank should seat at platform	 
Roof First Level View	315	General Photos	
Roof First Level Wall	316	Minor defects Cutting Mark and crack on wall surface	   


Findings (cont.)

Location	Tag	Defect & Description	Pictures
Roof First Level Wall	317	Minor defects Damaged on window copping	
Roof First Level Ceiling	318	Jointing Issue Visible gap on ceiling	
Roof First Level Ceiling	319	Minor defects Crack on ceiling surface	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Roof First Level Roof	320	Installation Issue Roof tiles improper installation	 
Roof First Level Roof	321	Minor defects Chipping floor tiles and need to replace One on One. Cannot use silicon.	
Roof First Level Fixtures	322	Accessories Defects Rusty screw at roof flushing	

Findings (cont.)

Location	Tag	Defect & Description	Pictures
Roof First Level Fixtures	323	Jointing Issue Improper seal and visible gaps around roof flashing	 
Top Roof View	324	General Photos	
Top Roof Roof	325	Installation Issue Improper installation of roof tile	 
Top Roof Roof	326	Jointing Issue There are gaps between roof tile and fascia board	 

Findings (cont.)

Location	Tag	Defect & Description	Pictures	
Top Roof Roof	327	Minor defects Chipping roof tile		
Top Roof Fixtures	328	Accessories Defects Corrosion screw		

SAMPLE REPORT GOXPERT - INSPECTOR