

COLLAR TRACKER / VERIFIED PCB

r05l PCB DFM is complete. A fully assembled, working tracker is not released.

TOP / 40 x 32mm



BOTTOM / mirrored view



VERIFIED / UNCHANGED

Six copper layers; physical nano-SIM.

Native DRC / ERC / opens / parity: zero findings.

Both JLC PCB runs: 0 Danger / 0 Warning / 455 Good.

Same ZIP and rules; all 29 rows analyzed; SMT off.

81 fitted references / 44 candidate MPNs.

109 physical GND pads have local via paths.

Independent hardware hot/cold charge interlock.

REMAINING BEFORE A WORKING-DEVICE ORDER

Protected pack and lead-exit approval.

Dock holding and wire-end restraint.

Internal contact lugs / J3 wiring and joining process.

Factory sourcing, CPL rotation and SMT review.

Firmware, programming and functional tests.

Powered / RF / physical water and dust tests.

No purchase, supplier message or physical test made.

Gerber SHA256: c736c5d35ddfe4c4662e57606120f00f7358492e11d5fbb32eaf1d0ff6caf5d2

JLC records: 637366592129687553 / 637366801595977730