

COLLAR TRACKER / r05l PCB REVIEW

Charge interlock implemented. Two clean PCB DFM reports; assembled release remains on hold.

TOP / native copper and silkscreen



BOTTOM / mirrored component view



VERIFIED PCB

40 × 32 mm / six Cu layers / 87 footprints

Native DRC, ERC, connectivity and parity: zero findings

Two JLC runs: 0 Danger / 0 Warning / 455 Good each

Same ZIP, same rules, all 29 rows analyzed; SMT off

81 fitted references / 44 exact candidate MPNs

109 physical GND pads have local paths to vias

Two GND planes; 154/154 signal-via return screens pass

REQUIRED BEFORE WORKING DELIVERY

Charge window is implemented; corner model is conditional.

Thermal coupling, startup and fault transients need tests.

Protected pack, NTC attachment and antennas: open.

Firmware and factory programming/functional test: open.

Procurement, CPL rotations and SMT acceptance: open.

No physical powered, RF or water/dust result exists.

This package is for review; it is not an order release.

PCB SHA256: 241c84d6ba98793c37344e1e46ddc4918e7b05322ba87daea7c9a90ffb8379b3

JLC records: 637366592129687553 / 637366801595977730