

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 1 of 10

MST CONSUMER PRODUCTS CO., LTD
888/19 MOO.2, T SAMNAK THONG, A.MUEANG RAYONG, RAYONG 21100

The following sample(s) was/were submitted and identified by the client as:

Sample Description : DISPOSABLE FOOD CONTAINER WITH 20% PCR

Sample Quantity : PLEASE REFER TO THE FOLLOWING PAGE(S) :

Country of Origin : THAILAND

Country of Destination : USA

Sample Receiving Date : JUL. 06, 2026

Testing Period : JUL. 06, 2026 TO JUL. 15, 2026

Test Requested	Result
1. Leakage Test (As Per Client's Requirement)	Pass
2. Freezer Test (As Per Client's Requirement)	Pass
3. Microwave Safety Test (SGS In House Method)	See Result
4. Dishwasher Safety Test (SGS In House Method)	See Result
5. US California Proposition 65 - Bisphenol-A	Pass
6. US California Proposition 65 - Phthalate	Pass
7. US FDA 21 CFR 177.1520 - Density at 23°C	Pass
8. US FDA 21 CFR 177.1520 - Extractable fraction	Pass
9. US FDA 21 CFR 177.1520 - Soluble fraction in Xylene	Pass
10. US FDA 21 CFR 177.1520 - Melting Point	Pass
11. Halogen	See Result

Signed for and on behalf of
SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Ruby Gu

Ruby Gu
Authorized Signatory

Scan to see the report



NBHL26070075701CW
Verification:
check.sgsline.com.cn



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.
Hardlines

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层, 003幢5层B区, 009幢4层B区, 009幢4层B区-5层, 004幢5层B区, 004幢5层B区-5层, 008幢5层B区, 008幢5层B区-5层 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 2 of 10

Test Conducted:

1. Leakage Test (As Per Client's Requirement)

Number Of Tested Samples:	1 Piece
Test Procedure:	1. Visually check the samples and record any defects. 2. Fill container 3/4 water of the way full and hold it up on each side (4 sides) for 15 seconds each. 3. Inspecting the sample for any leakage and record.
Test Requirement:	There shall no leakage after performing test.
Test Result:	Pass

2. Freezer Test (As Per Client's Requirement)

Number Of Tested Samples:	1 Piece
Number Of Controlled Samples:	1 Piece
Test Procedure:	1. Visually check the sample and record any defects. 2. Start the operation as following procedure. 3. Set the environmental chamber to -18°C. When the temperature has reached equilibrium, place the sample in the chamber for 6 hours. 4. Remove the sample from the chamber and let the sample return to the ambient temperature. 5. Inspecting the sample for any damage.
Test Requirement:	There shall be no visible changes, damage or otherwise after performing test.
Test Result:	Pass

3. Microwave Safety Test (SGS In House Method)

Test conduct	Microwave Oven Test
Sample description	DISPOSABLE FOOD CONTAINER WITH 20%PCR
Number of test sample	1 pc
Number of control sample	1 pc
Type of sample	Other
Test method 1. Apply the staining solution to all interior and exterior surfaces of the sample and inspect closely for damage, do not continue the test with this sample, if anything other than superficial imperfections is found. (When applicable). 2. Except products made from glass or glass-ceramic or thermoplastic, water soak the sample for at least 15 minutes and then wipe the surface dry with a cotton cloth prior to test. (When applicable).	



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4区, 003幢5层5区, 009幢4层4区, 009幢5层5区, 004幢5层5区, 004幢4层4区, 008幢7层7区, 008幢7层8区, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 3 of 10

3. Fill the product with the specified amount of testing medium. (If not stated, the following condition is applied (If applicable, if the provided lids claimed for Microwave Safe, it shall fit securely before testing accordingly):
4. **For mugs, cups, bowls, pitchers, and teapots:** Fill samples two-thirds (2/3) full with 20±5°C (68±9°F) cold water and place into the microwave oven. Shut the microwave oven door.
5. **For dessert plates and saucers:** Place one-half (1/2) cup of cold cooked macaroni mixed with one tablespoon cooking oil on the dessert plate or saucer and place into the microwave oven. Shut the microwave oven door.
6. **For dinner plates and serving platters:** Place one (1) cup of cold cooked macaroni mixed with one tablespoon cooking oil on the dinner plate or serving platter and place into the microwave oven. Shut the microwave oven door.
7. **For others:** Fill samples four-fifth (4/5) full with 20±5°C (68±9°F) cold water with sufficient crumb foam placed on container as intended. Shut the microwave oven door.
8. Set the microwave to 800 watt output and run for 3 minutes.
9. Record any cracking, chipping, crazing, breakage, discoloration, deformation, or warping of product.
10. After 3 minutes remove product from microwave and immediately measure and record surface temperature with IR thermometer or thermocouple.
 - A. Measure temperature of mugs on top portion of handle.
 - B. Measure plate or bowl temperatures near top rim of plate or bowl (at a normal hand contact point).
 - C. All samples must have the surface temperatures measured and recorded within 1 minute after the oven has stopped heating. Only one sample should be removed from the oven at a time.
 - D. Only measure the surface temperature of the items after the first 3-minute cycle.
11. Let samples sit at room temperature for 5 minutes.
12. If necessary, add cold water to cups, mugs, bowls and pitchers to ensure that they are two-thirds (2/3) full of water.
13. Replace hot macaroni on plates, saucers, and serving platters with cold macaroni.
14. Run for five (5) cycles. Compare test samples to the untested standard and record any cracking, chipping, crazing, breakage, discoloration, deformation, or warping of product after five (5) complete microwave cycles.

Requirement

The product fails the microwave test if:

1. If the surface temperature of Graspable area greater than: Ceramic, glass-ceramic or glass: 56°C; Plastic, wooden: 60°C after the first 3 minutes (1st cycle).
2. When compared to the standard, any of the tested samples show signs of cracking, chipping, crazing, breakage, discoloration, deformation, or warping during or after 5 complete microwave cycles.

Test results:

Sample No.	Surface temperature (°C)	1 st cycle	2 nd cycle	3 rd cycle	4 th cycle	5 th cycle
1#	32.4	Pass	Pass	Pass	Pass	Pass

Remark:



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixi Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4室, 003幢5层5室, 009幢4层4室, 009幢5层5室, 004幢5层5室, 004幢7层7室, 008幢7层7室, 008幢9层9室, 008幢10层10室, 008幢11层11室, 008幢12层12室, 008幢13层13室, 008幢14层14室, 008幢15层15室, 008幢16层16室, 008幢17层17室, 008幢18层18室, 008幢19层19室, 008幢20层20室, 008幢21层21室, 008幢22层22室, 008幢23层23室, 008幢24层24室, 008幢25层25室, 008幢26层26室, 008幢27层27室, 008幢28层28室, 008幢29层29室, 008幢30层30室, 008幢31层31室, 008幢32层32室, 008幢33层33室, 008幢34层34室, 008幢35层35室, 008幢36层36室, 008幢37层37室, 008幢38层38室, 008幢39层39室, 008幢40层40室, 008幢41层41室, 008幢42层42室, 008幢43层43室, 008幢44层44室, 008幢45层45室, 008幢46层46室, 008幢47层47室, 008幢48层48室, 008幢49层49室, 008幢50层50室, 008幢51层51室, 008幢52层52室, 008幢53层53室, 008幢54层54室, 008幢55层55室, 008幢56层56室, 008幢57层57室, 008幢58层58室, 008幢59层59室, 008幢60层60室, 008幢61层61室, 008幢62层62室, 008幢63层63室, 008幢64层64室, 008幢65层65室, 008幢66层66室, 008幢67层67室, 008幢68层68室, 008幢69层69室, 008幢70层70室, 008幢71层71室, 008幢72层72室, 008幢73层73室, 008幢74层74室, 008幢75层75室, 008幢76层76室, 008幢77层77室, 008幢78层78室, 008幢79层79室, 008幢80层80室, 008幢81层81室, 008幢82层82室, 008幢83层83室, 008幢84层84室, 008幢85层85室, 008幢86层86室, 008幢87层87室, 008幢88层88室, 008幢89层89室, 008幢90层90室, 008幢91层91室, 008幢92层92室, 008幢93层93室, 008幢94层94室, 008幢95层95室, 008幢96层96室, 008幢97层97室, 008幢98层98室, 008幢99层99室, 008幢100层100室, 008幢101层101室, 008幢102层102室, 008幢103层103室, 008幢104层104室, 008幢105层105室, 008幢106层106室, 008幢107层107室, 008幢108层108室, 008幢109层109室, 008幢110层110室, 008幢111层111室, 008幢112层112室, 008幢113层113室, 008幢114层114室, 008幢115层115室, 008幢116层116室, 008幢117层117室, 008幢118层118室, 008幢119层119室, 008幢120层120室, 008幢121层121室, 008幢122层122室, 008幢123层123室, 008幢124层124室, 008幢125层125室, 008幢126层126室, 008幢127层127室, 008幢128层128室, 008幢129层129室, 008幢130层130室, 008幢131层131室, 008幢132层132室, 008幢133层133室, 008幢134层134室, 008幢135层135室, 008幢136层136室, 008幢137层137室, 008幢138层138室, 008幢139层139室, 008幢140层140室, 008幢141层141室, 008幢142层142室, 008幢143层143室, 008幢144层144室, 008幢145层145室, 008幢146层146室, 008幢147层147室, 008幢148层148室, 008幢149层149室, 008幢150层150室, 008幢151层151室, 008幢152层152室, 008幢153层153室, 008幢154层154室, 008幢155层155室, 008幢156层156室, 008幢157层157室, 008幢158层158室, 008幢159层159室, 008幢160层160室, 008幢161层161室, 008幢162层162室, 008幢163层163室, 008幢164层164室, 008幢165层165室, 008幢166层166室, 008幢167层167室, 008幢168层168室, 008幢169层169室, 008幢170层170室, 008幢171层171室, 008幢172层172室, 008幢173层173室, 008幢174层174室, 008幢175层175室, 008幢176层176室, 008幢177层177室, 008幢178层178室, 008幢179层179室, 008幢180层180室, 008幢181层181室, 008幢182层182室, 008幢183层183室, 008幢184层184室, 008幢185层185室, 008幢186层186室, 008幢187层187室, 008幢188层188室, 008幢189层189室, 008幢190层190室, 008幢191层191室, 008幢192层192室, 008幢193层193室, 008幢194层194室, 008幢195层195室, 008幢196层196室, 008幢197层197室, 008幢198层198室, 008幢199层199室, 008幢200层200室, 008幢201层201室, 008幢202层202室, 008幢203层203室, 008幢204层204室, 008幢205层205室, 008幢206层206室, 008幢207层207室, 008幢208层208室, 008幢209层209室, 008幢210层210室, 008幢211层211室, 008幢212层212室, 008幢213层213室, 008幢214层214室, 008幢215层215室, 008幢216层216室, 008幢217层217室, 008幢218层218室, 008幢219层219室, 008幢220层220室, 008幢221层221室, 008幢222层222室, 008幢223层223室, 008幢224层224室, 008幢225层225室, 008幢226层226室, 008幢227层227室, 008幢228层228室, 008幢229层229室, 008幢230层230室, 008幢231层231室, 008幢232层232室, 008幢233层233室, 008幢234层234室, 008幢235层235室, 008幢236层236室, 008幢237层237室, 008幢238层238室, 008幢239层239室, 008幢240层240室, 008幢241层241室, 008幢242层242室, 008幢243层243室, 008幢244层244室, 008幢245层245室, 008幢246层246室, 008幢247层247室, 008幢248层248室, 008幢249层249室, 008幢250层250室, 008幢251层251室, 008幢252层252室, 008幢253层253室, 008幢254层254室, 008幢255层255室, 008幢256层256室, 008幢257层257室, 008幢258层258室, 008幢259层259室, 008幢260层260室, 008幢261层261室, 008幢262层262室, 008幢263层263室, 008幢264层264室, 008幢265层265室, 008幢266层266室, 008幢267层267室, 008幢268层268室, 008幢269层269室, 008幢270层270室, 008幢271层271室, 008幢272层272室, 008幢273层273室, 008幢274层274室, 008幢275层275室, 008幢276层276室, 008幢277层277室, 008幢278层278室, 008幢279层279室, 008幢280层280室, 008幢281层281室, 008幢282层282室, 008幢283层283室, 008幢284层284室, 008幢285层285室, 008幢286层286室, 008幢287层287室, 008幢288层288室, 008幢289层289室, 008幢290层290室, 008幢291层291室, 008幢292层292室, 008幢293层293室, 008幢294层294室, 008幢295层295室, 008幢296层296室, 008幢297层297室, 008幢298层298室, 008幢299层299室, 008幢300层300室, 008幢301层301室, 008幢302层302室, 008幢303层303室, 008幢304层304室, 008幢305层305室, 008幢306层306室, 008幢307层307室, 008幢308层308室, 008幢309层309室, 008幢310层310室, 008幢311层311室, 008幢312层312室, 008幢313层313室, 008幢314层314室, 008幢315层315室, 008幢316层316室, 008幢317层317室, 008幢318层318室, 008幢319层319室, 008幢320层320室, 008幢321层321室, 008幢322层322室, 008幢323层323室, 008幢324层324室, 008幢325层325室, 008幢326层326室, 008幢327层327室, 008幢328层328室, 008幢329层329室, 008幢330层330室, 008幢331层331室, 008幢332层332室, 008幢333层333室, 008幢334层334室, 008幢335层335室, 008幢336层336室, 008幢337层337室, 008幢338层338室, 008幢339层339室, 008幢340层340室, 008幢341层341室, 008幢342层342室, 008幢343层343室, 008幢344层344室, 008幢345层345室, 008幢346层346室, 008幢347层347室, 008幢348层348室, 008幢349层349室, 008幢350层350室, 008幢351层351室, 008幢352层352室, 008幢353层353室, 008幢354层354室, 008幢355层355室, 008幢356层356室, 008幢357层357室, 008幢358层358室, 008幢359层359室, 008幢360层360室, 008幢361层361室, 008幢362层362室, 008幢363层363室, 008幢364层364室, 008幢365层365室, 008幢366层366室, 008幢367层367室, 008幢368层368室, 008幢369层369室, 008幢370层370室, 008幢371层371室, 008幢372层372室, 008幢373层373室, 008幢374层374室, 008幢375层375室, 008幢376层376室, 008幢377层377室, 008幢378层378室, 008幢379层379室, 008幢380层380室, 008幢381层381室, 008幢382层382室, 008幢383层383室, 008幢384层384室, 008幢385层385室, 008幢386层386室, 008幢387层387室, 008幢388层388室, 008幢389层389室, 008幢390层390室, 008幢391层391室, 008幢392层392室, 008幢393层393室, 008幢394层394室, 008幢395层395室, 008幢396层396室, 008幢397层397室, 008幢398层398室, 008幢399层399室, 008幢400层400室, 008幢401层401室, 008幢402层402室, 008幢403层403室, 008幢404层404室, 008幢405层405室, 008幢406层406室, 008幢407层407室, 008幢408层408室, 008幢409层409室, 008幢410层410室, 008幢411层411室, 008幢412层412室, 008幢413层413室, 008幢414层414室, 008幢415层415室, 008幢416层416室, 008幢417层417室, 008幢418层418室, 008幢419层419室, 008幢420层420室, 008幢421层421室, 008幢422层422室, 008幢423层423室, 008幢424层424室, 008幢425层425室, 008幢426层426室, 008幢427层427室, 008幢428层428室, 008幢429层429室, 008幢430层430室, 008幢431层431室, 008幢432层432室, 008幢433层433室, 008幢434层434室, 008幢435层435室, 008幢436层436室, 008幢437层437室, 008幢438层438室, 008幢439层439室, 008幢440层440室, 008幢441层441室, 008幢442层442室, 008幢443层443室, 008幢444层444室, 008幢445层445室, 008幢446层446室, 008幢447层447室, 008幢448层448室, 008幢449层449室, 008幢450层450室, 008幢451层451室, 008幢452层452室, 008幢453层453室, 008幢454层454室, 008幢455层455室, 008幢456层456室, 008幢457层457室, 008幢458层458室, 008幢459层459室, 008幢460层460室, 008幢461层461室, 008幢462层462室, 008幢463层463室, 008幢464层464室, 008幢465层465室, 008幢466层466室, 008幢467层467室, 008幢468层468室, 008幢469层469室, 008幢470层470室, 008幢471层471室, 008幢472层472室, 008幢473层473室, 008幢474层474室, 008幢475层475室, 008幢476层476室, 008幢477层477室, 008幢478层478室, 008幢479层479室, 008幢480层480室, 008幢481层481室, 008幢482层482室, 008幢483层483室, 008幢484层484室, 008幢485层485室, 008幢486层486室, 008幢487层487室, 008幢488层488室, 008幢489层489室, 008幢490层490室, 008幢491层491室, 008幢492层492室, 008幢493层493室, 008幢494层494室, 008幢495层495室, 008幢496层496室, 008幢497层497室, 008幢498层498室, 008幢499层499室, 008幢500层500室, 008幢501层501室, 008幢502层502室, 008幢503层503室, 008幢504层504室, 008幢505层505室, 008幢506层506室, 008幢507层507室, 008幢508层508室, 008幢509层509室, 008幢510层510室, 008幢511层511室, 008幢512层512室, 008幢513层513室, 008幢514层514室, 008幢515层515室, 008幢516层516室, 008幢517层517室, 008幢518层518室, 008幢519层519室, 008幢520层520室, 008幢521层521室, 008幢522层522室, 008幢523层523室, 008幢524层524室, 008幢525层525室, 008幢526层526室, 008幢527层527室, 008幢528层528室, 008幢529层529室, 008幢530层530室, 008幢531层531室, 008幢532层532室, 008幢533层533室, 008幢534层534室, 008幢535层535室, 008幢536层536室, 008幢537层537室, 008幢538层538室, 008幢539层539室, 008幢540层540室, 008幢541层541室, 008幢542层542室, 008幢543层543室, 008幢544层544室, 008幢545层545室, 008幢546层546室, 008幢547层547室, 008幢548层548室, 008幢549层549室, 008幢550层550室, 008幢551层551室, 008幢552层552室, 008幢553层553室, 008幢554层554室, 008幢555层555室, 008幢556层556室, 008幢557层557室, 008幢558层558室, 008幢559层559室, 008幢560层560室, 008幢561层561室, 008幢562层562室, 008幢563层563室, 008幢564层564室, 008幢565层565室, 008幢566层566室, 008幢567层567室, 008幢568层568室, 008幢569层569室, 008幢570层570室, 008幢571层571室, 008幢572层572室, 008幢573层573室, 008幢574层574室, 008幢575层575室, 008幢576层576室, 008幢577层577室, 008幢578层578室, 008幢579层579室, 008幢580层580室, 008幢581层581室, 008幢582层582室, 008幢583层583室, 008幢584层584室, 008幢585层585室, 008幢586层586室, 008幢587层587室, 008幢588层588室, 008幢589层589室, 008幢590层590室, 008幢591层591室, 008幢592层592室, 008幢593层593室, 008幢594层594室, 008幢595层595室, 008幢596层596室, 008幢597层597室, 008幢598层598室, 008幢599层599室, 008幢600层600室, 008幢601层601室, 008幢602层602室, 008幢603层603室, 008幢604层604室, 008幢605层605室, 008幢606层606室, 008幢607层607室, 008幢608层608室, 008幢609层609室, 008幢610层610室, 008幢611层611室, 008幢612层612室, 008幢613层613室, 008幢614层614室, 008幢615层615室, 008幢616层616室, 008幢617层617室, 008幢618层618室, 008幢619层619室, 008幢620层620室, 008幢621层621室, 008幢622层622室, 008幢623层623室, 008幢624层624室, 008幢625层625室, 008幢626层626室, 008幢627层627室, 008幢628层628室, 008幢629层629室, 008幢630层630室, 008幢631层631室, 008幢632层632室, 008幢633层633室, 008幢634层634室, 008幢635层635室, 008幢636层636室, 008幢637层637室, 008幢638层638室, 008幢639层639室, 008幢640层640室, 008幢641层641室, 008幢642层642室, 008幢643层643室, 008幢644层644室, 008幢645层645室, 008幢646层646室, 008幢647层647室, 008幢648层648室, 008幢649层649室, 008幢650层650室, 008幢651层651室, 008幢652层652室, 008幢653层653室, 008幢654层654室, 008幢655层655室, 008幢656层656室, 008幢657层657室, 008幢658层658室, 008幢659层659室, 008幢660层660室, 008幢661层661室, 008幢662层662室, 008幢663层663室, 008幢664层664室, 008幢665层665室, 008幢666层666室, 008幢667层667室, 008幢668层668室, 008幢669层669室, 008幢670层670室, 008幢671层671室, 008幢672层672室, 008幢673层673室, 008幢674层674室, 008幢675层675室, 008幢676层676室, 008幢677层677室, 008幢678层678室, 008幢679层679室, 008幢680层680室, 008幢681层681室, 008幢682层682室, 008幢683层683室, 008幢684层684室, 008幢685层685室, 008幢686层686室, 008幢687层687室, 008幢688层688室, 008幢689层689室, 008幢690层690室, 008幢691层691室, 008幢692层692室, 008幢693层693室, 008幢694层694室, 008幢695层695室, 008幢696层696室, 008幢697层697室, 008幢698层698室, 008幢699层699室, 008幢700层700室, 008幢701层701室, 008幢702层702室, 008幢703层703室, 008幢704层704室, 008幢705层705室, 008幢706层706室, 008幢707层707室, 008幢708层708室, 008幢709层709室, 008幢710层710室, 008幢711层711室, 008幢712层712室, 008幢713层713室, 008幢714层714室, 008幢715层715室, 008幢716层716室, 008幢717层717室, 008幢718层718室, 008幢719层719室, 008幢720层720室, 008幢721层721室, 008幢722层722室, 008幢723层723室, 008幢724层724室, 008幢725层725室, 008幢726层726室, 008幢727层727室, 008幢728层728室, 008幢729层729室, 008幢730层730室, 008幢731层731室, 008幢732层732室, 008幢733层733室, 008幢734层734室, 008幢735层735室, 008幢736层736室, 008幢737层737室, 008幢738层738室, 008幢739层739室, 008幢740层740室, 008幢741层741室, 008幢742层742室, 008幢743层743室, 008幢744层744室, 008幢745层745室, 008幢746层746室, 008幢747层747室, 008幢748层748室, 008幢749层749室, 008幢750层750室, 008幢751层751室, 008幢752层752室, 008幢753层753室, 008幢754层754室, 008幢755层755室, 008幢756层756室, 008幢757层757室, 008幢758层758室, 008幢759层759室, 008幢760层760室,

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 4 of 10

1. Pass=No cracking, chipping, crazing, breaking, discoloration, deformation or warping was found on the tested sample.

4. Dishwasher Safety Test (SGS In House Method)

Number Of Tested Samples:	1 Piece
Number Of Controlled Sample	1 Piece
Visual check before testing	Prior to testing, check any physical defect which may affect the result. Report it "as received" with photos.
Test Procedure:	1. Place the samples upside down or upright (avoid trapping water during testing) into the dishwasher along with the dummy items to make a full load. (If possible, place 1 sample in various orientations and racks within the dishwasher). 2. Check the loaded samples are not in direct contact with the walls of the dishwasher or other samples. 3. Ensure detergent dispenser is fully loaded with required amount of cleaning detergent and close it. 4. Close door to dishwasher. 5. Complete 1 full cycle for washing which includes a hot drying cycle. 6. Evaluate each sample for any discoloration, chipping, cracking, and / or other obvious changes compare from the control product visually, record on relative datasheet and photograph the samples that show signs of damage. 7. Stop further testing if any samples have broken, cracked or exhibit any change in shape or appearance. 8. Once the evaluation of the first cycle is complete, repeats the above procedures for a total of 5 cycles. 9. Any other observation affecting the product or its ability to function as intended must be recorded and including the report.
Test Requirement:	1. Test samples should not show structural or physical damage, breaks, chipping, crazing, cracking, splitting, fading of the glaze, peeling of decal, imperfections on the surface or change in shape or appearance such as warping or distortion or deformation due to the testing process. Discoloration of plastic ware; and corrosion or tarnishing, blisters and objectionable defects of metal ware also need to be considered respectively. Cutlery, kitchen utensils and uncoated metal products or components must not emerge pitted or corroded. 2. If the products with painted, printed, enamelled and similarly coloured or decorative finishes should be graded as follows, and products described as "Dishwasher Safe" must achieve a grade A condition. For products classified as budget ranges or where there will be a low frequency of use, then grade B may be acceptable. Grade A – No deterioration or noticeable change compared to reference standard. Grade B – Slight pitting of finish, blurring of design or fading of colour. Grade C – Moderate pitting of finish, blurring of design or fading of colour. Grade D – Significant change in finish, appearance or colour.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 3, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingnan Road, Meixia Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4室, 003幢5层5室, 009幢4层4室, 009幢4层5室, 004幢5层5室, 004幢5层4室, 008幢5层5室, 008幢5层4室, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 5 of 10


	3. If 1 sample fails the product is not acceptable for dishwasher use and should not be labeled “Dishwasher Safe”.						
Test Result:							
	Washing Cycle Sample No.	1	2	3	4	5	Result
	1	Pass Grade A	Pass Grade A	Pass Grade A	Pass Grade A	Pass Grade A	Pass Grade A

Remark:

- Power detergent: "Cascade" dishwasher detergent.

Sample Photo:

Test sample



Test Sample During the Freezer Test




SGS-CSTC (China) Technical Services (Shanghai) Co., Ltd.
Hardlines

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixia Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层, 003幢5层B区, 009幢4层B区, 009幢4层B区-5层, 004幢5层B区, 004幢5层B区-5层, 008幢5层B区, 008幢5层B区-5层 sgs.china@sgs.com

Test Sample After the Freezer Test



Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	NGB26-0007512-0001.C001	Transparent plastic box
SN2	A2	NGB26-0007512-0001.C002	Purple translucent plastic lid

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) “-” = Not Regulated

5. US California Proposition 65 - Bisphenol-A

Test Method: With reference to Part II Section D2 of Testing Methods for Foodstuffs, Implements, Containers and Packaging, Toys, Detergents, JETRO, Japan External Trade Organization, 2009, analysis was performed by HPLC-MS/LC-MS/MS.

Test Item(s)	CAS No.	Limit	Unit(s)	MDL	A1	A2
Bisphenol A(BPA)	80-05-7	★	mg/kg	0.1	ND	ND
Conclusion					Pass	Pass

Notes:

- (1) ★:Recommend limit: not detected(ND)
 - (2) The limit is referenced to the requirement as stated in County of Alameda Case No RG18891707 .
 - (3) The reference limit applied in testing is based on particular California Proposition 65 settlements that are most similar to the tested product in the opinion of the lab. The testing in this report does not reflect a user's actual exposure to the tested chemical.
- A manufacturer or retailer that is not named in the referenced settlement is not bound by that settlement, and



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 3 / 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingnan Road, Meixi Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4区, 003幢5号数层4区, 009幢4号数层2-5层, 004幢5号数层, 004幢5号数层4区, 008幢7号数层4区, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 7 of 10

may choose to comply with California Proposition 65 by clearly informing the consumer of potential exposure.

6. US California Proposition 65 - Phthalate

Test Method: With reference to CPSC-CH-C1001-09.4, analysis was performed by GC-MS.

Test Item(s)	CAS No.	Limit	Unit(s)	MDL	A1	A2
Benzyl Butyl Phthalate(BBP)	85-68-7	1000	mg/kg	50	ND	ND
Dibutyl Phthalate(DBP)	84-74-2	1000	mg/kg	50	ND	ND
Bis-(2-ethylhexyl) Phthalate(DEHP)	117-81-7	1000	mg/kg	50	ND	ND
Diisodecyl Phthalate (DIDP)	26761-40-0 /68515-49-1	1000	mg/kg	50	ND	ND
Diisononyl Phthalate (DINP)	28553-12-0 /68515-48-0	1000	mg/kg	50	ND	ND
Di-n-Hexyl Phthalate(DnHP)	84-75-3	1000	mg/kg	50	ND	ND
Conclusion					Pass	Pass

Notes:

(1) The limit is referenced to the requirement specified in Settlement Agreement between Marin Court Case No. CIV 091146 and County of Santa Clara Case No. 114CV267501.

(2) The reference limit applied in testing is based on particular California Proposition 65 settlements that are most similar to the tested product in the opinion of the lab. The testing in this report does not reflect a user's actual exposure to the tested chemical. A manufacturer or retailer that is not named in the referenced settlement is not bound by that settlement, and may choose to comply with California Proposition 65 by clearly informing the consumer of potential exposure.

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description	Material (claimed by the client)
SN1	A1	NGB26-0007513-0001.C001	Transparent plastic box	PP
SN2	A2	NGB26-0007513-0001.C002	Purple translucent plastic lid	PP

Remarks:

- (1) mg/dm² = milligram per square decimeter
mg/inch² = milligram per square inches
µg/cm² = microgram per square centimeter
mg/L = milligram per litre
mg/kg = milligram per kilogram
- (2) °C = degree Celsius
°F = degree Fahrenheit
- (3) < = less than



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingnan Road, Meixia Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
 中国·浙江·宁波市高新区梅墟街道灵源路1177号007幢4层4区, 003幢5层5区, 009幢4层4区, 009幢5层5区, 004幢5层5区, 004幢4层4区, 004幢3层3区, 008幢5层5区, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 8 of 10

- (4) RL = Reporting Limit
(5) ND = Not Detected (< RL).

7. US FDA 21 CFR 177.1520 - Density at 23°C

Test Method: With reference to US FDA 21 CFR 177.1520d(1).

Test Item(s)	Limit	Unit(s)	A1	A2
Density at 23°C	0.880-0.913	g/cm ³	0.904	0.902
Comment			Pass	Pass

8. US FDA 21 CFR 177.1520 - Extractable fraction

Test Method: With reference to US FDA 21 CFR 177.1520(d)(3)(i).

Simulant used	Test Condition	Limit	Unit(s)	RL	A1	Comment
n-Hexane	Reflux Temperature, 2 hrs	6.4	%(w/w)	0.5	1.0	Pass

Simulant used	Test Condition	Limit	Unit(s)	RL	A2	Comment
n-Hexane	Reflux Temperature, 2 hrs	6.4	%(w/w)	0.5	1.2	Pass

9. US FDA 21 CFR 177.1520 - Soluble fraction in Xylene

Test Method: With reference to US FDA 21 CFR 177.1520 (d) 4 (i).

Test Item(s)	Limit	Unit(s)	RL	A1	A2
Soluble Fraction in Xylene	9.8	%(w/w)	0.5	1.3	1.5
Comment				Pass	Pass

10. US FDA 21 CFR 177.1520 - Melting Point

Test Method: With reference to US FDA 21 CFR 177.1520 (d) (2).

Test Item(s)	Limit	Unit(s)	A1	A2
Melting Point	160-180	°C	165.6	164.7
Comment			Pass	Pass



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingnan Road, Meixia Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
中国·浙江·宁波市高新区梅墟街道灵源路1177号007幢4层, 003幢5层, 009幢4层, 009幢5层, 004幢5层, 004幢4层, 008幢5层, 008幢4层, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 9 of 10

Sample Photo:



Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	CZX26-0008682-0001.C001	Transparent plastic
SN2	A2	CZX26-0008682-0001.C002	Transparent purple plastic

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) “-” = Not Regulated

11. Halogen

Test Method: With reference to EN 14582:2016, analysis was performed by IC.

Test Item(s)	Unit(s)	MDL	A1	A2
Fluorine(F)	mg/kg	20	ND	ND
Chlorine(Cl)	mg/kg	50	ND	ND
Bromine(Br)	mg/kg	50	ND	ND
Iodine(I)	mg/kg	50	ND	ND

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.

Remark: The tests of Halogen were subcontracted to SGS Changzhou lab.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道凌云路1177号07幢4层401室, 003幢4层401室, 009幢4层401室, 004幢4层401室, 004幢4层401室, 008幢4层401室, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 10 of 10

Sample Photo:



SGS authenticate the photo on original report only

Remark:

1. Since the data and / or information above division line of front page is provided by the applicant, the relevant results or conclusions of this report are only made for these data and / or information, SGS shall not be responsible for the authenticity and integrity of such data and information and the validity of the results and / or conclusions arising therefrom. Testing results only apply to the sample as received.
2. The declaration of conformity is based on acceptance limits chosen based on simple acceptance ($w = 0$, $AL = TL$).

Statements of conformity are reported as:

Passed - The measured values were observed in tolerance at the points tested.

Failed - One or more measured values were observed out of tolerance at the points tested.

End of Report



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC (Shanghai) Technical Services Co., Ltd.
Hardlines

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4层, 003幢5层5层, 009幢4层4层, 009幢5层5层, 004幢5层5层, 004幢6层6层, 008幢7层7层, 008幢8层8层, 5区 sgs.china@sgs.com