

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 1 of 10

MST CONSUMER PRODUCTS CO., LTD
888/19 MOO.2, T SAMNAK THONG, A.MUEANG RAYONG, RAYONG 21100

The following sample(s) was/were submitted and identified by the client as:

Sample Description : DISPOSABLE FOOD CONTAINER WITH 20% PCR

Sample Quantity : PLEASE REFER TO THE FOLLOWING PAGE(S) :

Country of Origin : THAILAND

Country of Destination : USA

Sample Receiving Date : JUL. 06, 2026

Testing Period : JUL. 06, 2026 TO JUL. 15, 2026

Test Requested	Result
1. Leakage Test (As Per Client's Requirement)	Pass
2. Freezer Test (As Per Client's Requirement)	Pass
3. Microwave Safety Test (SGS In House Method)	See Result
4. Dishwasher Safety Test (SGS In House Method)	See Result
5. US California Proposition 65 - Bisphenol-A	Pass
6. US California Proposition 65 - Phthalate	Pass
7. US FDA 21 CFR 177.1520 - Density at 23°C	Pass
8. US FDA 21 CFR 177.1520 - Extractable fraction	Pass
9. US FDA 21 CFR 177.1520 - Soluble fraction in Xylene	Pass
10. US FDA 21 CFR 177.1520 - Melting Point	Pass
11. Halogen	See Result

Signed for and on behalf of
SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Ruby Gu

Ruby Gu
Authorized Signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层, 003幢5层B区, 009幢4层B区, 009幢4层B区-5层, 004幢5层B区, 004幢5层B区-5层, 008幢5层B区, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 2 of 10

Test Conducted:

1. Leakage Test (As Per Client's Requirement)

Number Of Tested Samples:	1 Piece
Test Procedure:	1. Visually check the samples and record any defects. 2. Fill container 3/4 water of the way full and hold it up on each side (4 sides) for 15 seconds each. 3. Inspecting the sample for any leakage and record.
Test Requirement:	There shall no leakage after performing test.
Test Result:	Pass

2. Freezer Test (As Per Client's Requirement)

Number Of Tested Samples:	1 Piece
Number Of Controlled Samples:	1 Piece
Test Procedure:	1. Visually check the sample and record any defects. 2. Start the operation as following procedure. 3. Set the environmental chamber to -18°C. When the temperature has reached equilibrium, place the sample in the chamber for 6 hours. 4. Remove the sample from the chamber and let the sample return to the ambient temperature. 5. Inspecting the sample for any damage.
Test Requirement:	There shall be no visible changes, damage or otherwise after performing test.
Test Result:	Pass

3. Microwave Safety Test (SGS In House Method)

Test conduct	Microwave Oven Test
Sample description	DISPOSABLE FOOD CONTAINER WITH 20%PCR
Number of test sample	1 pc
Number of control sample	1 pc
Type of sample	Other
Test method 1. Apply the staining solution to all interior and exterior surfaces of the sample and inspect closely for damage, do not continue the test with this sample, if anything other than superficial imperfections is found. (When applicable). 2. Except products made from glass or glass-ceramic or thermoplastic, water soak the sample for at least 15 minutes and then wipe the surface dry with a cotton cloth prior to test. (When applicable).	



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F, to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4区, 003幢5层5区, 009幢4层4区, 009幢5层5区, 004幢5层5区, 004幢4层4区, 008幢7层7区, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 3 of 10

3. Fill the product with the specified amount of testing medium. (If not stated, the following condition is applied (If applicable, if the provided lids claimed for Microwave Safe, it shall fit securely before testing accordingly):
4. **For mugs, cups, bowls, pitchers, and teapots:** Fill samples two-thirds (2/3) full with 20±5°C (68±9°F) cold water and place into the microwave oven. Shut the microwave oven door.
5. **For dessert plates and saucers:** Place one-half (1/2) cup of cold cooked macaroni mixed with one tablespoon cooking oil on the dessert plate or saucer and place into the microwave oven. Shut the microwave oven door.
6. **For dinner plates and serving platters:** Place one (1) cup of cold cooked macaroni mixed with one tablespoon cooking oil on the dinner plate or serving platter and place into the microwave oven. Shut the microwave oven door.
7. **For others:** Fill samples four-fifth (4/5) full with 20±5°C (68±9°F) cold water with sufficient crumb foam placed on container as intended. Shut the microwave oven door.
8. Set the microwave to 800 watt output and run for 3 minutes.
9. Record any cracking, chipping, crazing, breakage, discoloration, deformation, or warping of product.
10. After 3 minutes remove product from microwave and immediately measure and record surface temperature with IR thermometer or thermocouple.
 - A. Measure temperature of mugs on top portion of handle.
 - B. Measure plate or bowl temperatures near top rim of plate or bowl (at a normal hand contact point).
 - C. All samples must have the surface temperatures measured and recorded within 1 minute after the oven has stopped heating. Only one sample should be removed from the oven at a time.
 - D. Only measure the surface temperature of the items after the first 3-minute cycle.
11. Let samples sit at room temperature for 5 minutes.
12. If necessary, add cold water to cups, mugs, bowls and pitchers to ensure that they are two-thirds (2/3) full of water.
13. Replace hot macaroni on plates, saucers, and serving platters with cold macaroni.
14. Run for five (5) cycles. Compare test samples to the untested standard and record any cracking, chipping, crazing, breakage, discoloration, deformation, or warping of product after five (5) complete microwave cycles.

Requirement

The product fails the microwave test if:

1. If the surface temperature of Graspable area greater than: Ceramic, glass-ceramic or glass: 56°C; Plastic, wooden: 60°C after the first 3 minutes (1st cycle).
2. When compared to the standard, any of the tested samples show signs of cracking, chipping, crazing, breakage, discoloration, deformation, or warping during or after 5 complete microwave cycles.

Test results:

Sample No.	Surface temperature (°C)	1 st cycle	2 nd cycle	3 rd cycle	4 th cycle	5 th cycle
1#	32.4	Pass	Pass	Pass	Pass	Pass

Remark:



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixi Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
 中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4区, 003幢5层5区, 009幢4层4区, 009幢5层5区, 004幢5层5区, 004幢7层7区, 008幢7层7区, 008幢9层9区, 008幢10层10区, 008幢11层11区, 008幢12层12区, 008幢13层13区, 008幢14层14区, 008幢15层15区, 008幢16层16区, 008幢17层17区, 008幢18层18区, 008幢19层19区, 008幢20层20区, 008幢21层21区, 008幢22层22区, 008幢23层23区, 008幢24层24区, 008幢25层25区, 008幢26层26区, 008幢27层27区, 008幢28层28区, 008幢29层29区, 008幢30层30区, 008幢31层31区, 008幢32层32区, 008幢33层33区, 008幢34层34区, 008幢35层35区, 008幢36层36区, 008幢37层37区, 008幢38层38区, 008幢39层39区, 008幢40层40区, 008幢41层41区, 008幢42层42区, 008幢43层43区, 008幢44层44区, 008幢45层45区, 008幢46层46区, 008幢47层47区, 008幢48层48区, 008幢49层49区, 008幢50层50区, 008幢51层51区, 008幢52层52区, 008幢53层53区, 008幢54层54区, 008幢55层55区, 008幢56层56区, 008幢57层57区, 008幢58层58区, 008幢59层59区, 008幢60层60区, 008幢61层61区, 008幢62层62区, 008幢63层63区, 008幢64层64区, 008幢65层65区, 008幢66层66区, 008幢67层67区, 008幢68层68区, 008幢69层69区, 008幢70层70区, 008幢71层71区, 008幢72层72区, 008幢73层73区, 008幢74层74区, 008幢75层75区, 008幢76层76区, 008幢77层77区, 008幢78层78区, 008幢79层79区, 008幢80层80区, 008幢81层81区, 008幢82层82区, 008幢83层83区, 008幢84层84区, 008幢85层85区, 008幢86层86区, 008幢87层87区, 008幢88层88区, 008幢89层89区, 008幢90层90区, 008幢91层91区, 008幢92层92区, 008幢93层93区, 008幢94层94区, 008幢95层95区, 008幢96层96区, 008幢97层97区, 008幢98层98区, 008幢99层99区, 008幢100层100区, 008幢101层101区, 008幢102层102区, 008幢103层103区, 008幢104层104区, 008幢105层105区, 008幢106层106区, 008幢107层107区, 008幢108层108区, 008幢109层109区, 008幢110层110区, 008幢111层111区, 008幢112层112区, 008幢113层113区, 008幢114层114区, 008幢115层115区, 008幢116层116区, 008幢117层117区, 008幢118层118区, 008幢119层119区, 008幢120层120区, 008幢121层121区, 008幢122层122区, 008幢123层123区, 008幢124层124区, 008幢125层125区, 008幢126层126区, 008幢127层127区, 008幢128层128区, 008幢129层129区, 008幢130层130区, 008幢131层131区, 008幢132层132区, 008幢133层133区, 008幢134层134区, 008幢135层135区, 008幢136层136区, 008幢137层137区, 008幢138层138区, 008幢139层139区, 008幢140层140区, 008幢141层141区, 008幢142层142区, 008幢143层143区, 008幢144层144区, 008幢145层145区, 008幢146层146区, 008幢147层147区, 008幢148层148区, 008幢149层149区, 008幢150层150区, 008幢151层151区, 008幢152层152区, 008幢153层153区, 008幢154层154区, 008幢155层155区, 008幢156层156区, 008幢157层157区, 008幢158层158区, 008幢159层159区, 008幢160层160区, 008幢161层161区, 008幢162层162区, 008幢163层163区, 008幢164层164区, 008幢165层165区, 008幢166层166区, 008幢167层167区, 008幢168层168区, 008幢169层169区, 008幢170层170区, 008幢171层171区, 008幢172层172区, 008幢173层173区, 008幢174层174区, 008幢175层175区, 008幢176层176区, 008幢177层177区, 008幢178层178区, 008幢179层179区, 008幢180层180区, 008幢181层181区, 008幢182层182区, 008幢183层183区, 008幢184层184区, 008幢185层185区, 008幢186层186区, 008幢187层187区, 008幢188层188区, 008幢189层189区, 008幢190层190区, 008幢191层191区, 008幢192层192区, 008幢193层193区, 008幢194层194区, 008幢195层195区, 008幢196层196区, 008幢197层197区, 008幢198层198区, 008幢199层199区, 008幢200层200区, 008幢201层201区, 008幢202层202区, 008幢203层203区, 008幢204层204区, 008幢205层205区, 008幢206层206区, 008幢207层207区, 008幢208层208区, 008幢209层209区, 008幢210层210区, 008幢211层211区, 008幢212层212区, 008幢213层213区, 008幢214层214区, 008幢215层215区, 008幢216层216区, 008幢217层217区, 008幢218层218区, 008幢219层219区, 008幢220层220区, 008幢221层221区, 008幢222层222区, 008幢223层223区, 008幢224层224区, 008幢225层225区, 008幢226层226区, 008幢227层227区, 008幢228层228区, 008幢229层229区, 008幢230层230区, 008幢231层231区, 008幢232层232区, 008幢233层233区, 008幢234层234区, 008幢235层235区, 008幢236层236区, 008幢237层237区, 008幢238层238区, 008幢239层239区, 008幢240层240区, 008幢241层241区, 008幢242层242区, 008幢243层243区, 008幢244层244区, 008幢245层245区, 008幢246层246区, 008幢247层247区, 008幢248层248区, 008幢249层249区, 008幢250层250区, 008幢251层251区, 008幢252层252区, 008幢253层253区, 008幢254层254区, 008幢255层255区, 008幢256层256区, 008幢257层257区, 008幢258层258区, 008幢259层259区, 008幢260层260区, 008幢261层261区, 008幢262层262区, 008幢263层263区, 008幢264层264区, 008幢265层265区, 008幢266层266区, 008幢267层267区, 008幢268层268区, 008幢269层269区, 008幢270层270区, 008幢271层271区, 008幢272层272区, 008幢273层273区, 008幢274层274区, 008幢275层275区, 008幢276层276区, 008幢277层277区, 008幢278层278区, 008幢279层279区, 008幢280层280区, 008幢281层281区, 008幢282层282区, 008幢283层283区, 008幢284层284区, 008幢285层285区, 008幢286层286区, 008幢287层287区, 008幢288层288区, 008幢289层289区, 008幢290层290区, 008幢291层291区, 008幢292层292区, 008幢293层293区, 008幢294层294区, 008幢295层295区, 008幢296层296区, 008幢297层297区, 008幢298层298区, 008幢299层299区, 008幢300层300区, 008幢301层301区, 008幢302层302区, 008幢303层303区, 008幢304层304区, 008幢305层305区, 008幢306层306区, 008幢307层307区, 008幢308层308区, 008幢309层309区, 008幢310层310区, 008幢311层311区, 008幢312层312区, 008幢313层313区, 008幢314层314区, 008幢315层315区, 008幢316层316区, 008幢317层317区, 008幢318层318区, 008幢319层319区, 008幢320层320区, 008幢321层321区, 008幢322层322区, 008幢323层323区, 008幢324层324区, 008幢325层325区, 008幢326层326区, 008幢327层327区, 008幢328层328区, 008幢329层329区, 008幢330层330区, 008幢331层331区, 008幢332层332区, 008幢333层333区, 008幢334层334区, 008幢335层335区, 008幢336层336区, 008幢337层337区, 008幢338层338区, 008幢339层339区, 008幢340层340区, 008幢341层341区, 008幢342层342区, 008幢343层343区, 008幢344层344区, 008幢345层345区, 008幢346层346区, 008幢347层347区, 008幢348层348区, 008幢349层349区, 008幢350层350区, 008幢351层351区, 008幢352层352区, 008幢353层353区, 008幢354层354区, 008幢355层355区, 008幢356层356区, 008幢357层357区, 008幢358层358区, 008幢359层359区, 008幢360层360区, 008幢361层361区, 008幢362层362区, 008幢363层363区, 008幢364层364区, 008幢365层365区, 008幢366层366区, 008幢367层367区, 008幢368层368区, 008幢369层369区, 008幢370层370区, 008幢371层371区, 008幢372层372区, 008幢373层373区, 008幢374层374区, 008幢375层375区, 008幢376层376区, 008幢377层377区, 008幢378层378区, 008幢379层379区, 008幢380层380区, 008幢381层381区, 008幢382层382区, 008幢383层383区, 008幢384层384区, 008幢385层385区, 008幢386层386区, 008幢387层387区, 008幢388层388区, 008幢389层389区, 008幢390层390区, 008幢391层391区, 008幢392层392区, 008幢393层393区, 008幢394层394区, 008幢395层395区, 008幢396层396区, 008幢397层397区, 008幢398层398区, 008幢399层399区, 008幢400层400区, 008幢401层401区, 008幢402层402区, 008幢403层403区, 008幢404层404区, 008幢405层405区, 008幢406层406区, 008幢407层407区, 008幢408层408区, 008幢409层409区, 008幢410层410区, 008幢411层411区, 008幢412层412区, 008幢413层413区, 008幢414层414区, 008幢415层415区, 008幢416层416区, 008幢417层417区, 008幢418层418区, 008幢419层419区, 008幢420层420区, 008幢421层421区, 008幢422层422区, 008幢423层423区, 008幢424层424区, 008幢425层425区, 008幢426层426区, 008幢427层427区, 008幢428层428区, 008幢429层429区, 008幢430层430区, 008幢431层431区, 008幢432层432区, 008幢433层433区, 008幢434层434区, 008幢435层435区, 008幢436层436区, 008幢437层437区, 008幢438层438区, 008幢439层439区, 008幢440层440区, 008幢441层441区, 008幢442层442区, 008幢443层443区, 008幢444层444区, 008幢445层445区, 008幢446层446区, 008幢447层447区, 008幢448层448区, 008幢449层449区, 008幢450层450区, 008幢451层451区, 008幢452层452区, 008幢453层453区, 008幢454层454区, 008幢455层455区, 008幢456层456区, 008幢457层457区, 008幢458层458区, 008幢459层459区, 008幢460层460区, 008幢461层461区, 008幢462层462区, 008幢463层463区, 008幢464层464区, 008幢465层465区, 008幢466层466区, 008幢467层467区, 008幢468层468区, 008幢469层469区, 008幢470层470区, 008幢471层471区, 008幢472层472区, 008幢473层473区, 008幢474层474区, 008幢475层475区, 008幢476层476区, 008幢477层477区, 008幢478层478区, 008幢479层479区, 008幢480层480区, 008幢481层481区, 008幢482层482区, 008幢483层483区, 008幢484层484区, 008幢485层485区, 008幢486层486区, 008幢487层487区, 008幢488层488区, 008幢489层489区, 008幢490层490区, 008幢491层491区, 008幢492层492区, 008幢493层493区, 008幢494层494区, 008幢495层495区, 008幢496层496区, 008幢497层497区, 008幢498层498区, 008幢499层499区, 008幢500层500区, 008幢501层501区, 008幢502层502区, 008幢503层503区, 008幢504层504区, 008幢505层505区, 008幢506层506区, 008幢507层507区, 008幢508层508区, 008幢509层509区, 008幢510层510区, 008幢511层511区, 008幢512层512区, 008幢513层513区, 008幢514层514区, 008幢515层515区, 008幢516层516区, 008幢517层517区, 008幢518层518区, 008幢519层519区, 008幢520层520区, 008幢521层521区, 008幢522层522区, 008幢523层523区, 008幢524层524区, 008幢525层525区, 008幢526层526区, 008幢527层527区, 008幢528层528区, 008幢529层529区, 008幢530层530区, 008幢531层531区, 008幢532层532区, 008幢533层533区, 008幢534层534区, 008幢535层535区, 008幢536层536区, 008幢537层537区, 008幢538层538区, 008幢539层539区, 008幢540层540区, 008幢541层541区, 008幢542层542区, 008幢543层543区, 008幢544层544区, 008幢545层545区, 008幢546层546区, 008幢547层547区, 008幢548层548区, 008幢549层549区, 008幢550层550区, 008幢551层551区, 008幢552层552区, 008幢553层553区, 008幢554层554区, 008幢555层555区, 008幢556层556区, 008幢557层557区, 008幢558层558区, 008幢559层559区, 008幢560层560区, 008幢561层561区, 008幢562层562区, 008幢563层563区, 008幢564层564区, 008幢565层565区, 008幢566层566区, 008幢567层567区, 008幢568层568区, 008幢569层569区, 008幢570层570区, 008幢571层571区, 008幢572层572区, 008幢573层573区, 008幢574层574区, 008幢575层575区, 008幢576层576区, 008幢577层577区, 008幢578层578区, 008幢579层579区, 008幢580层580区, 008幢581层581区, 008幢582层582区, 008幢583层583区, 008幢584层584区, 008幢585层585区, 008幢586层586区, 008幢587层587区, 008幢588层588区, 008幢589层589区, 008幢590层590区, 008幢591层591区, 008幢592层592区, 008幢593层593区, 008幢594层594区, 008幢595层595区, 008幢596层596区, 008幢597层597区, 008幢598层598区, 008幢599层599区, 008幢600层600区, 008幢601层601区, 008幢602层602区, 008幢603层603区, 008幢604层604区, 008幢605层605区, 008幢606层606区, 008幢607层607区, 008幢608层608区, 008幢609层609区, 008幢610层610区, 008幢611层611区, 008幢612层612区, 008幢613层613区, 008幢614层614区, 008幢615层615区, 008幢616层616区, 008幢617层617区, 008幢618层618区, 008幢619层619区, 008幢620层620区, 008幢621层621区, 008幢622层622区, 008幢623层623区, 008幢624层624区, 008幢625层625区, 008幢626层626区, 008幢627层627区, 008幢628层628区, 008幢629层629区, 008幢630层630区, 008幢631层631区, 008幢632层632区, 008幢633层633区, 008幢634层634区, 008幢635层635区, 008幢636层636区, 008幢637层637区, 008幢638层638区, 008幢639层639区, 008幢640层640区, 008幢641层641区, 008幢642层642区, 008幢643层643区, 008幢644层644区, 008幢645层645区, 008幢646层646区, 008幢647层647区, 008幢648层648区, 008幢649层649区, 008幢650层650区, 008幢651层651区, 008幢652层652区, 008幢653层653区, 008幢654层654区, 008幢655层655区, 008幢656层656区, 008幢657层657区, 008幢658层658区, 008幢659层659区, 008幢660层660区, 008幢661层661区, 008幢662层662区, 008幢663层663区, 008幢664层664区, 008幢665层665区, 008幢666层666区, 008幢667层667区, 008幢668层668区, 008幢669层669区, 008幢670层670区, 008幢671层671区, 008幢672层672区, 008幢673层673区, 008幢674层674区, 008幢675层675区, 008幢676层676区, 008幢677层677区, 008幢678层678区, 008幢679层679区, 008幢680层680区, 008幢681层681区, 008幢682层682区, 008幢683层683区, 008幢684层684区, 008幢685层685区, 008幢686层686区, 008幢687层687区, 008幢688层688区, 008幢689层689区, 008幢690层690区, 008幢691层691区, 008幢692层692区, 008幢693层693区, 008幢694层694区, 008幢695层695区, 008幢696层696区, 008幢697层697区, 008幢698层698区, 008幢699层699区, 008幢700层700区, 008幢701层701区, 008幢702层702区, 008幢703层703区, 008幢704层704区, 008幢705层705区, 008幢706层706区, 008幢707层707区, 008幢708层708区, 008幢709层709区, 008幢710层710区, 008幢711层711区, 008幢712层712区, 008幢713层713区, 008幢714层714区, 008幢715层715区, 008幢716层716区, 008幢717层717区, 008幢718层718区, 008幢719层719区, 008幢720层720区, 008幢721层721区, 008幢722层722区, 008幢723层723区, 008幢724层724区, 008幢725层725区, 008幢726层726区, 008幢727层727区, 008幢728层728区, 008幢729层729区, 008幢730层730区, 008幢731层731区, 008幢732层732区, 008幢733层733区, 008幢734层734区, 008幢735层735区, 008幢736层736区, 008幢737层737区, 008幢738层738区, 008幢739层739区, 008幢740层740区, 008幢741层741区, 008幢742层742区, 008幢743层743区, 008幢744层744区, 008幢745层745区, 008幢746层746区, 008幢747层747区, 008幢748层748区, 008幢749层749区, 008幢750层750区, 008幢751层751区, 008幢752层752区, 008幢753层

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 4 of 10

1. Pass=No cracking, chipping, crazing, breaking, discoloration, deformation or warping was found on the tested sample.

4. Dishwasher Safety Test (SGS In House Method)

Number Of Tested Samples:	1 Piece
Number Of Controlled Sample	1 Piece
Visual check before testing	Prior to testing, check any physical defect which may affect the result. Report it "as received" with photos.
Test Procedure:	1. Place the samples upside down or upright (avoid trapping water during testing) into the dishwasher along with the dummy items to make a full load. (If possible, place 1 sample in various orientations and racks within the dishwasher). 2. Check the loaded samples are not in direct contact with the walls of the dishwasher or other samples. 3. Ensure detergent dispenser is fully loaded with required amount of cleaning detergent and close it. 4. Close door to dishwasher. 5. Complete 1 full cycle for washing which includes a hot drying cycle. 6. Evaluate each sample for any discoloration, chipping, cracking, and / or other obvious changes compare from the control product visually, record on relative datasheet and photograph the samples that show signs of damage. 7. Stop further testing if any samples have broken, cracked or exhibit any change in shape or appearance. 8. Once the evaluation of the first cycle is complete, repeats the above procedures for a total of 5 cycles. 9. Any other observation affecting the product or its ability to function as intended must be recorded and including the report.
Test Requirement:	1. Test samples should not show structural or physical damage, breaks, chipping, crazing, cracking, splitting, fading of the glaze, peeling of decal, imperfections on the surface or change in shape or appearance such as warping or distortion or deformation due to the testing process. Discoloration of plastic ware; and corrosion or tarnishing, blisters and objectionable defects of metal ware also need to be considered respectively. Cutlery, kitchen utensils and uncoated metal products or components must not emerge pitted or corroded. 2. If the products with painted, printed, enamelled and similarly coloured or decorative finishes should be graded as follows, and products described as "Dishwasher Safe" must achieve a grade A condition. For products classified as budget ranges or where there will be a low frequency of use, then grade B may be acceptable. Grade A – No deterioration or noticeable change compared to reference standard. Grade B – Slight pitting of finish, blurring of design or fading of colour. Grade C – Moderate pitting of finish, blurring of design or fading of colour. Grade D – Significant change in finish, appearance or colour.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 3, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingnan Road, Meixia Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
 中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4室, 003幢5号整层整区, 007幢4号整层整区, 009幢4号整层整区, 004幢5号整层整区, 004幢5号整层整区, 008幢5号整层整区, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 5 of 10


	3. If 1 sample fails the product is not acceptable for dishwasher use and should not be labeled “Dishwasher Safe”.						
Test Result:							
	Washing Cycle Sample No.	1	2	3	4	5	Result
	1	Pass Grade A	Pass Grade A	Pass Grade A	Pass Grade A	Pass Grade A	Pass Grade A

Remark:

- Power detergent: "Cascade" dishwasher detergent.

Sample Photo:

Test sample



Test Sample During the Freezer Test




Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC (Shanghai) Technical Services Co., Ltd.
Hardlines

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixia Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层, 003幢5层B区, 009幢4层B区, 009幢4层B区-5层, 004幢5层B区, 004幢5层B区-5层, 008幢5层B区, 008幢5层B区-5层 sgs.china@sgs.com

Test Sample After the Freezer Test



Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	NGB26-0007512-0001.C001	Transparent plastic box
SN2	A2	NGB26-0007512-0001.C002	Purple translucent plastic lid

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) “-” = Not Regulated

5. US California Proposition 65 - Bisphenol-A

Test Method: With reference to Part II Section D2 of Testing Methods for Foodstuffs, Implements, Containers and Packaging, Toys, Detergents, JETRO, Japan External Trade Organization, 2009, analysis was performed by HPLC-MS/LC-MS/MS.

Test Item(s)	CAS No.	Limit	Unit(s)	MDL	A1	A2
Bisphenol A(BPA)	80-05-7	★	mg/kg	0.1	ND	ND
Conclusion					Pass	Pass

Notes:

- (1) ★:Recommend limit: not detected(ND)
 - (2) The limit is referenced to the requirement as stated in County of Alameda Case No RG18891707 .
 - (3) The reference limit applied in testing is based on particular California Proposition 65 settlements that are most similar to the tested product in the opinion of the lab. The testing in this report does not reflect a user's actual exposure to the tested chemical.
- A manufacturer or retailer that is not named in the referenced settlement is not bound by that settlement, and



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 3 / 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixi Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4区, 003幢5号整层4区, 009幢4号整层2-5层, 004幢5号整层, 004幢5号整层4区, 008幢7号整层4区, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 7 of 10

may choose to comply with California Proposition 65 by clearly informing the consumer of potential exposure.

6. US California Proposition 65 - Phthalate

Test Method: With reference to CPSC-CH-C1001-09.4, analysis was performed by GC-MS.

Test Item(s)	CAS No.	Limit	Unit(s)	MDL	A1	A2
Benzyl Butyl Phthalate(BBP)	85-68-7	1000	mg/kg	50	ND	ND
Dibutyl Phthalate(DBP)	84-74-2	1000	mg/kg	50	ND	ND
Bis-(2-ethylhexyl) Phthalate(DEHP)	117-81-7	1000	mg/kg	50	ND	ND
Diisodecyl Phthalate (DIDP)	26761-40-0 /68515-49-1	1000	mg/kg	50	ND	ND
Diisononyl Phthalate (DINP)	28553-12-0 /68515-48-0	1000	mg/kg	50	ND	ND
Di-n-Hexyl Phthalate(DnHP)	84-75-3	1000	mg/kg	50	ND	ND
Conclusion					Pass	Pass

Notes:

(1) The limit is referenced to the requirement specified in Settlement Agreement between Marin Court Case No. CIV 091146 and County of Santa Clara Case No. 114CV267501.

(2) The reference limit applied in testing is based on particular California Proposition 65 settlements that are most similar to the tested product in the opinion of the lab. The testing in this report does not reflect a user's actual exposure to the tested chemical. A manufacturer or retailer that is not named in the referenced settlement is not bound by that settlement, and may choose to comply with California Proposition 65 by clearly informing the consumer of potential exposure.

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description	Material (claimed by the client)
SN1	A1	NGB26-0007513-0001.C001	Transparent plastic box	PP
SN2	A2	NGB26-0007513-0001.C002	Purple translucent plastic lid	PP

Remarks:

- (1) mg/dm² = milligram per square decimeter
mg/inch² = milligram per square inches
μg/cm² = microgram per square centimeter
mg/L = milligram per litre
mg/kg = milligram per kilogram
- (2) °C = degree Celsius
°F = degree Fahrenheit
- (3) < = less than



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingnan Road, Meixia Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道灵源路1177号007幢4层4区, 003幢4层4区, 009幢4层4区, 004幢4层4区, 006幢4层4区, 008幢4层4区, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 8 of 10

- (4) RL = Reporting Limit
(5) ND = Not Detected (< RL).

7. US FDA 21 CFR 177.1520 - Density at 23°C

Test Method: With reference to US FDA 21 CFR 177.1520d(1).

Test Item(s)	Limit	Unit(s)	A1	A2
Density at 23°C	0.880-0.913	g/cm ³	0.904	0.902
Comment			Pass	Pass

8. US FDA 21 CFR 177.1520 - Extractable fraction

Test Method: With reference to US FDA 21 CFR 177.1520(d)(3)(i).

Simulant used	Test Condition	Limit	Unit(s)	RL	A1	Comment
n-Hexane	Reflux Temperature, 2 hrs	6.4	%(w/w)	0.5	1.0	Pass

Simulant used	Test Condition	Limit	Unit(s)	RL	A2	Comment
n-Hexane	Reflux Temperature, 2 hrs	6.4	%(w/w)	0.5	1.2	Pass

9. US FDA 21 CFR 177.1520 - Soluble fraction in Xylene

Test Method: With reference to US FDA 21 CFR 177.1520 (d) 4 (i).

Test Item(s)	Limit	Unit(s)	RL	A1	A2
Soluble Fraction in Xylene	9.8	%(w/w)	0.5	1.3	1.5
Comment				Pass	Pass

10. US FDA 21 CFR 177.1520 - Melting Point

Test Method: With reference to US FDA 21 CFR 177.1520 (d) (2).

Test Item(s)	Limit	Unit(s)	A1	A2
Melting Point	160-180	°C	165.6	164.7
Comment			Pass	Pass



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixia Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层, 003幢5层, 009幢4层, 009幢5层, 004幢5层, 004幢4层, 008幢5层, 008幢4层, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 9 of 10

Sample Photo:



Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	CZX26-0008682-0001.C001	Transparent plastic
SN2	A2	CZX26-0008682-0001.C002	Transparent purple plastic

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) “-” = Not Regulated

11. Halogen

Test Method: With reference to EN 14582:2016, analysis was performed by IC.

Test Item(s)	Unit(s)	MDL	A1	A2
Fluorine(F)	mg/kg	20	ND	ND
Chlorine(Cl)	mg/kg	50	ND	ND
Bromine(Br)	mg/kg	50	ND	ND
Iodine(I)	mg/kg	50	ND	ND

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.

Remark: The tests of Halogen were subcontracted to SGS Changzhou lab.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixi Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com

中国·浙江·宁波市高新区梅墟街道凌云路1177号07幢4层401室, 003幢4层401室, 009幢4层401室, 004幢4层401室, 004幢4层401室, 008幢4层401室, 5区 sgs.china@sgs.com

Test Report

No.: NBHL26070075701CW

Date: JUL. 15, 2026

Page: 10 of 10

Sample Photo:



SGS authenticate the photo on original report only

Remark:

1. Since the data and / or information above division line of front page is provided by the applicant, the relevant results or conclusions of this report are only made for these data and / or information, SGS shall not be responsible for the authenticity and integrity of such data and information and the validity of the results and / or conclusions arising therefrom. Testing results only apply to the sample as received.
2. The declaration of conformity is based on acceptance limits chosen based on simple acceptance ($w = 0$, $AL = TL$).

Statements of conformity are reported as:

Passed - The measured values were observed in tolerance at the points tested.

Failed - One or more measured values were observed out of tolerance at the points tested.

End of Report



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SGS-CSTC (Shanghai) Technical Services Co., Ltd.
Hardlines

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgs.com
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层4层, 003幢5层5层, 009幢4层4层, 009幢5层5层, 004幢5层5层, 004幢6层6层, 008幢7层7层, 008幢8层8层, 5区 sgs.china@sgs.com