Vulnerability Assessment Report

Imagur Security Assessment 2026-10-06

Imagur
132 Morphett Rd
Glengowrie SA 5044

Flinders University
Sturt Road, Bedford Park SA 5042

October 6, 2026

Report Version: 1.0

CONFIDENTIAL

Table of Contents

List of Figures 4

1 Document Control 5

1.1 Team 5

1.2 List of Changes 5

2 Executive Summary 6

2.1 Overview 6

2.2 Identified Vulnerabilities 6

3 Methodology 8

3.1 Objective 8

3.2 Scope 8

3.3 User Accounts and Permissions 8

4 Findings 9

C1: AWS root account credentials exposed in client-side JavaScript 9

H1: "Private" image visibility is not enforced (broken access control) 10

H2: S3 bucket publicly listable and world-readable (user uploads exposed) 11

M1: Stored cross-site scripting (XSS) via uploaded filename 12

M2: Missing cross-site request forgery (CSRF) protection 13

M3: Upload user_id field is client-controlled (mass assignment / weak authorization) 14

L1: Information disclosure (PHP version, AWS account/access key ID, user IDs) 15

L2: Unattached EC2 security group permits SSH from the internet 16

I1: CloudFront distribution misconfigured (deleted origin, missing alias/TLS) 17

I2: Missing email authentication records (no SPF/DMARC/MX) 18

I3: Missing security headers (CSP, HSTS, Permissions-Policy) 19

5 Disclaimer 20

A Appendix 21
A.1 Static Appendix Section 21

List of Figures

Figure 1 - Distribution of identified vulnerabilities 7

1 Document Control

1.1 Team

Contact	Details	Role
ClawSec	Autonomous agent	Pentester

1.2 List of Changes

Version	Description	Date

2 Executive Summary

2.1 Overview

Imagur (also operating as "FShare") runs an image-sharing web application at imagesharer.xyz (branded "Imager"), hosted on an OVH VPS with back-end storage and a database in AWS (Sydney region). A security assessment was performed from 05 to 06 October 2026, covering the web application, its origin infrastructure, and the associated AWS account.

The most severe issue is that the **AWS root account credentials are embedded in a publicly downloadable JavaScript file** (/js/awsvalid.js). Anyone who fetches this file obtains full administrative control of the organization's entire AWS account, including the storage bucket holding all customer image uploads and the application database.

A second serious issue is that the **S3 bucket (filesharer-research) storing every user's images is publicly listable and world-readable**. Images that users mark as "Private" are therefore still downloadable by anyone, and every user's internal identifier can be enumerated.

The web application also has a **stored cross-site scripting** vulnerability (via the uploaded filename) and **no cross-site request forgery protection**.

Highest-priority actions: (1) rotate and remove the exposed AWS root key; (2) lock down the S3 bucket so it is not publicly readable or listable; (3) fix the stored XSS and add CSRF protection.

A total of **11 findings** were confirmed: 1 critical, 2 high, 3 medium, 2 low, and 3 informational.

2.2 Identified Vulnerabilities

#	CVSS	Description	Page
C1	10.0	AWS root account credentials exposed in client-side JavaScript	9
H1	7.5	"Private" image visibility is not enforced (broken access control)	10
H2	7.5	S3 bucket publicly listable and world-readable (user uploads exposed)	11
M1	6.1	Stored cross-site scripting (XSS) via uploaded filename	12
M2	4.3	Missing cross-site request forgery (CSRF) protection	13
M3	4.3	Upload user_id field is client-controlled (mass assignment / weak authorization)	14
L1	3.7	Information disclosure (PHP version, AWS account/access key ID, user IDs)	15
L2	3.7	Unattached EC2 security group permits SSH from the internet	16
I1	0.0	CloudFront distribution misconfigured (deleted origin, missing alias/TLS)	17
I2	0.0	Missing email authentication records (no SPF/DMARC/MX)	18
I3	0.0	Missing security headers (CSP, HSTS, Permissions-Policy)	19

Vulnerability Overview

In the course of this penetration test **1 Critical**, **2 High**, **3 Medium**, **2 Low** and **3 Info** vulnerabilities were identified:




Figure 1 - Distribution of identified vulnerabilities

3 Methodology

This entire vulnerability assessment process was completed using agentic AI and existing LLM models. The purpose of such assessments is to automatically

3.1 Objective

The entire objective of this research is to evaluate the effectiveness of autonomously evaluate security posture for any business available on Google Map without the needs of technical guidance to determine how feasiable, seamless and cost-affective such approach is.

3.2 Scope

In scope

- Web application: https://imagesharer.xyz/ and https://www.imagesharer.xyz/
- Origin infrastructure: 51.161.131.44 (OVH Sydney; nginx + PHP 8.2.34)
- CDN: resources.imagesharer.xyz -> CloudFront d273uevi0662l0.cloudfront.net
- AWS account 016170038077 (ap-southeast-2): S3 bucket filesharer-research, S3 bucket filesharer-research-testing (stale), RDS Aurora PostgreSQL database-2, CloudFront distribution EMOI8CZBQIEBR, IAM users console-admin and fokirohu, EC2 security group sg-0fb1d9ee18578a337, default VPC vpc-06f86289a752c416d.

Out of scope

Third-party hosting/CDN providers (OVH ASN/netblocks, CloudFront edge IPs, Spaceship nameservers) and unrelated lookalike domains.

Methodology

Non-intrusive enumeration (DNS, WHOIS, RDAP, TLS, passive subdomain/CT, read-only AWS API) followed by manual, non-destructive web application testing (authentication, authorization, IDOR, SQL injection, stored XSS, file-upload validation, S3 access control). Minimal proof-of-concept only; no destructive actions, no DoS, no brute force, no data exfiltration.

3.3 User Accounts and Permissions

None provided (black-box assessment performed unauthenticated and with self-registered test accounts).

4 Findings

C1: AWS root account credentials exposed in client-side JavaScript	
Score	10.0 (Critical)
Vector string	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:C/C:H/I:H/A:H
Target	https://imagesharer.xyz/js/awsvalid.js (AWS account 016170038077)
References	https://imagesharer.xyz/js/awsvalid.js

Overview

The image-sharing web application serves a JavaScript file (/js/awsvalid.js) that contains hardcoded AWS access key ID and secret access key for the AWS ROOT account. Anyone on the internet can download the file and take full control of the business's AWS account.

Details

The file /js/awsvalid.js is publicly reachable (HTTP 200) without authentication. It embeds a long-term access key ID (AKIA...) and the corresponding 40-character secret access key inside a comment block, together with a region hint (ap-southeast-2). The code implements AWS Signature V4 signing and an STS GetCallerIdentity call. Read-only validation performed during the assessment (STS GetCallerIdentity) returned Account=016170038077 and Arn=arn:aws:iam::016170038077:root, confirming the credentials belong to the AWS account root identity. These credentials were then used strictly in a read-only fashion to enumerate the account (S3 buckets, RDS database, IAM users, security groups, CloudFront distribution) and were never used to modify, read user data, or otherwise act destructively. Business impact: complete compromise of the AWS account, including the user-upload storage bucket (filesharer-research), the application database (RDS Aurora PostgreSQL "database-2"), IAM, and CloudFront. An attacker could read, modify, or delete all customer data and infrastructure.

Recommendation

1. Immediately rotate/delete the exposed root access key from the AWS IAM console and remove the credentials from the JavaScript file (and any git history).
2. Never embed long-term AWS credentials in client-side code; use short-lived scoped credentials (e.g. Cognito Identity, STS, or a server-side proxy).
3. Remove root access keys entirely; create least-privilege IAM roles/users for the application.
4. Audit CloudTrail for any unauthorized use of the exposed key.

H1: "Private" image visibility is not enforced (broken access control)	
Score	7.5 (High)
Vector string	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:N
Target	https://imagesharer.xyz/images/<uuid> and s3://filesharer-research
References	https://imagesharer.xyz/images/<uuid>

Overview

Images uploaded with visibility "Private" are only hidden at the application layer; the actual image bytes remain publicly readable in S3, so the privacy control can be trivially bypassed.

Details

A test account uploaded an image with is_public=false. An unauthenticated request to the image detail page returned HTTP 302 (redirected to login), confirming the metadata page is protected. However, an unauthenticated GET of the underlying S3 object (https://filesharer-research.s3.ap-southeast-2.amazonaws.com/users/<user_id>/.png) returned HTTP 200 with the full image, with no authentication or presigned URL required. The object key is predictable and enumerable via the public S3 listing (see prior finding). Business impact: the "private" feature does not protect user content; private images are publicly accessible.

Recommendation

1. Enforce authorization at the object-serving layer (application proxy or signed URLs), not only on the HTML detail page.
2. Remove public read access from the S3 bucket so only authenticated/authorized requests can retrieve objects.

H2: S3 bucket publicly listable and world-readable (user uploads exposed)	
Score	7.5 (High)
Vector string	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:N
Target	s3://filesharer-research (ap-southeast-2)
References	https://filesharer-research.s3.ap-southeast-2.amazonaws.com/

Overview

The S3 bucket that stores all user image uploads is configured to be both publicly listable and publicly readable. An anonymous visitor can enumerate every stored object (and therefore every user folder/ID) and download any image without authentication.

Details

Two unauthenticated checks were performed:

- GET /?list-type=2&max-keys=50 returned HTTP 200 with an object listing (IsTruncated=true, i.e. more than 50 objects). Object keys follow the pattern users/<user_id>/<image_uuid>., exposing every user's internal UUID.
- GET on a specific object key (without any signature/presigned parameters) returned HTTP 200 with the image bytes (Content-Type image/png). This means the application's "Private (only you)" visibility setting is ineffective at the storage layer: the metadata page may be hidden, but the underlying image bytes are directly downloadable by anyone who knows or guesses the object key (and the keys are enumerable via the public listing). Business impact: unauthorized disclosure of all customer-uploaded images (including those marked private), plus enumeration of user identifiers.

Recommendation

1. Remove public ListBucket and GetObject permissions. Enforce "Block all public access" on the bucket.
2. Serve objects only through the application (server-side authorization) or CloudFront with signed URLs/OAC, so private images require authentication.
3. Review bucket policy/ACL and apply least privilege (only the application's IAM role should have access).

M1: Stored cross-site scripting (XSS) via uploaded filename	
Score	6.1 (Medium)
Vector string	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:C/C:L/I:L/A:N
Target	https://imagesharer.xyz/images/<uuid>
References	https://imagesharer.xyz/images/<uuid>

Overview

The filename of an uploaded image is stored and reflected without HTML encoding in the image detail page, allowing stored XSS. The detail page is publicly viewable for "public" images.

Details

An image was uploaded with the filename ".png". On the image detail page the payload is reflected RAW (unescaped) in the "Filename" metadata row, i.e. the injected tag with an onerror handler is parsed as live HTML. (The same value is HTML-encoded in the

Recommendation

1. HTML-encode (or strip) the filename everywhere it is rendered, including the metadata row, title, and alt attributes.
2. Sanitize/validate the stored filename on upload.
3. Add a strict Content-Security-Policy header.

M2: Missing cross-site request forgery (CSRF) protection	
Score	4.3 (Medium)
Vector string	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:U/C:N/I:L/A:N
Target	https://imagesharer.xyz/ (all state-changing endpoints)
References	/login, /register, /images/upload, /profile/avatar, /images/<uuid>/visibility, /images/<uuid>/delete, /logout

Overview

None of the state-changing forms (login, registration, upload, avatar change, visibility toggle, image deletion, logout) include an anti-CSRF token. Authenticated actions can be forged by a third-party site.

Details

Review of the login, registration, upload, profile/avatar, visibility, and delete forms found no hidden CSRF token or SameSite-restricted state. All forms are simple POST requests authenticated only by the PHPSESSID cookie. (The session cookie does set SameSite=Lax, which mitigates some cross-site POST cases, but the endpoints rely solely on it and there is no explicit token validation.) Business impact: a malicious site could, in some browsers/contexts, force a logged-in user's browser to change image visibility, delete images, or upload content without their knowledge.

Recommendation

1. Implement per-session CSRF tokens on all state-changing requests and validate them server-side.
2. Confirm SameSite=Strict (or Lax) on the session cookie as defense-in-depth.

M3: Upload user_id field is client-controlled (mass assignment / weak authorization)	
Score	4.3 (Medium)
Vector string	CVSS:3.1/AV:N/AC:L/PR:L/UI:N/S:U/C:N/I:L/A:N
Target	https://imagesharer.xyz/images/upload
References	POST /images/upload (hidden "user_id" field)

Overview

The image upload form trusts a client-supplied hidden "user_id" field rather than deriving the owner from the authenticated session, allowing an authenticated user to write objects into other users' S3 folders.

Details

The upload form includes

<uuid>

. The server uses this value directly to construct the S3 object key (users/<user_id>/.) instead of taking the user ID from the session. Cross-user tests showed image detail/visibility/delete actions are correctly authorized, but the upload path does not bind user_id to the session. Bucket keys such as users/"/ and users/'/ observed in the listing indicate this field has been manipulated. Business impact: an authenticated user could attribute/place uploads in another user's namespace (no overwrite or read of others' data observed due to the random UUID suffix).

Recommendation

1. Derive the owner user ID server-side from the authenticated session; ignore the client-supplied user_id.
2. Validate/sanitize any user-controlled portion of S3 object keys.

L1: Information disclosure (PHP version, AWS account/ access key ID, user IDs)	
Score	3.7 (Low)
Vector string	CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:L/I:N/A:N
Target	https://imagesharer.xyz/
References	https://imagesharer.xyz/ (X-Powered-By header, presigned URLs, S3 keys)

Overview

The application leaks operational details: PHP version via the X-Powered-By header, the AWS access key ID and account region in generated presigned URLs, and internal user UUIDs in S3 object paths.

Details

- X-Powered-By: PHP/8.2.34 is sent on every response.
- Presigned S3 URLs rendered in pages include X-Amz-Credential=AKIAQHQ6PGM62T2FFPGU (the server's signing access key ID) and the region, exposing an internal credential identifier.
- The S3 object keys (users//...) expose every user's internal identifier. Business impact: information that assists further attacks and reduces attacker effort.

Recommendation

1. Remove or suppress the X-Powered-By header (e.g. expose_php=Off in php.ini).
2. Avoid exposing long-term access key IDs in client-rendered presigned URLs; use short-lived credentials or serve through the application/CDN.
3. Avoid embedding internal user IDs in object paths where not necessary.

L2: Unattached EC2 security group permits SSH from the internet	
Score	3.7 (Low)
Vector string	CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:L/I:N/A:N
Target	AWS account 016170038077 — security group sg-0fb1d9ee18578a337 (launch-wizard-1)
References	AWS EC2 DescribeSecurityGroups (ap-southeast-2)

Overview

A security group named launch-wizard-1 allows inbound SSH (TCP 22) from 0.0.0.0/0. No EC2 instance is currently associated (DescribeInstances returned empty), so there is no active exposure today, but the permissive group is a latent risk.

Details

DescribeSecurityGroups (read-only) shows security group sg-0fb1d9ee18578a337 (launch-wizard-1) in the default VPC (vpc-06f86289a752c416d) with an ingress rule allowing TCP 22 from 0.0.0.0/0. DescribeInstances returned no running instances in the account, so the rule is currently unattached. Business impact: if an instance is launched into this group, SSH would be exposed to the entire internet, inviting brute-force access.

Recommendation

1. Delete the unused security group or restrict the SSH source to specific trusted IPs.
2. Prefer SSH key-based access and consider disabling password authentication.

I1: CloudFront distribution misconfigured (deleted origin, missing alias/TLS)	
Score	0.0 (Info)
Vector string	N/A
Target	resources.imagesharer.xyz -> CloudFront d273uevi0662l0.cloudfront.net (EMOI8CZBQIEBR)
References	AWS CloudFront GetDistribution, DNS CNAME

Overview

The resources subdomain points to a CloudFront distribution whose origin S3 bucket has been deleted, and which has no custom TLS certificate/alias configured, leaving the CDN endpoint broken and serving a default *.cloudfront.net certificate.

Details

- resources.imagesharer.xyz is a CNAME to d273uevi0662l0.cloudfront.net.
- The CloudFront distribution (EMOI8CZBQIEBR) has Aliases=0 (no custom domain alias) and its origin points to filesharer-research-testing.s3.ap-southeast-2.amazonaws.com, which returns NoSuchBucket (the bucket no longer exists).
- HTTPS to resources.imagesharer.xyz therefore fails certificate validation (default cert) and the origin returns 404. Business impact: broken/misconfigured CDN and potential for stale asset confusion; no direct data exposure observed.

Recommendation

1. Delete the stale CloudFront distribution or repoint it to an existing bucket.
2. Add the resources.imagesharer.xyz alias and a valid ACM certificate if the CDN is needed.

I2: Missing email authentication records (no SPF/DMARC/ MX)	
Score	0.0 (Info)
Vector string	N/A
Target	imagesharer.xyz
References	DNS MX/TXT lookups

Overview

The domain has no MX, SPF, or DMARC records, so email sent from the domain cannot be authenticated and the domain can be spoofed in phishing campaigns.

Details

DNS queries returned no MX record and no SPF (TXT "v=spf1") or DMARC (TXT "_dmarc") records. Business impact: the organization's domain can be abused for email spoofing/phishing; legitimate mail delivery from the domain is also not configured.

Recommendation

1. Publish SPF, DKIM, and a DMARC policy (e.g. p=reject) for the domain.
2. If the domain does not send email, publish a null SPF (v=spf1 -all) and DMARC reject policy.

I3: Missing security headers (CSP, HSTS, Permissions-Policy)	
Score	0.0 (Info)
Vector string	N/A
Target	https://imagesharer.xyz/
References	HTTP response headers

Overview

Responses lack a Content-Security-Policy, Strict-Transport-Security, and Permissions-Policy header. (They do include X-Content-Type-Options, X-Frame-Options, X-XSS-Protection, and Referrer-Policy.)

Details

Observed headers: X-Content-Type-Options: nosniff, X-Frame-Options: DENY, X-XSS-Protection: 1; mode=block, Referrer-Policy: strict-origin-when-cross-origin. No CSP, HSTS, or Permissions-Policy present. Business impact: reduced defense-in-depth; the absence of CSP contributes to the exploitable stored XSS finding above.

Recommendation

1. Add a strict Content-Security-Policy.
2. Enable HSTS (with preload) since the site is HTTPS.
3. Add a Permissions-Policy header.

5 Disclaimer

The purpose of this research project is to help evaluating the seamlessness, effectiveness and cost-benefit ratio of autonomously performing vulnerabilty assessment using agentic AI. I do not take any responsibility upon any misuse or abuse of such tool where it can face significant legal actions.

A Appendix

A.1 Static Appendix Section