Basic Tree Risk Assessment Form

Client Field test 1 Date _____ Time _____

Address/Tree location Eleanor river access, 1st parking lot Tree no. 1 Sheet 1 of 1

Tree species Quercus agrifolia dbh 20" Height 54' Crown spread dia. 40'

Assessor(s) _____ Time frame 18th month assessment Tools used measuring tape, binoculars

Target Assessment

Target number	Target description	Target zone: Target within drip line	Target zone: Target within 1 x Ht.	Target zone: Target within 1.5 x Ht.	Occupancy rate (1 – rare, 2 – occasional, 3 – frequent, 4 – constant)	Practical to move target?	Restriction practical?
1 1	ParkingLot	X			2		
2							
3							
4							

Site Factors

History of failures No history of failures **Topography** Flat ☒ Slope ☐ _____% **Aspect** _____

Site changes None ☒ Grade change ☐ Site clearing ☐ Changed soil hydrology ☐ Root cuts ☐ Describe Large urban park

Soil conditions Limited volume ☐ Saturated ☐ Shallow ☐ Compacted ☐ Pavement over roots ☒ 30 % Describe Pavement over roots, 30%

Prevailing wind direction W **Common weather** Strong winds ☒ Ice ☐ Snow ☐ Heavy rain ☒ Describe Strong winds, heavy rain

Tree Health and Species Profile

Vigor Low ☐ Normal ☐ High ☒ **Foliage** None (seasonal) ☐ None (dead) ☐ Normal 100 % Chlorotic _____% Necrotic _____%

Pests No pests observed **Abiotic** No abiotic stress observed

Species failure profile Branches ☒ Trunk ☒ Roots ☐ Describe Extended branches over parking lot, trunk impacts.

Load Factors

Wind exposure Protected ☐ Partial ☒ Full ☐ Wind funneling ☐ _____ **Relative crown size** Small ☐ Medium ☐ Large ☒

Crown density Sparse ☐ Normal ☐ Dense ☒ **Interior branches** Few ☐ Normal ☐ Dense ☒ **Vines/Mistletoe/Moss** ☐ No vines/mistletoe/moss observed

Recent or planned change in load factors None noted

Tree Defects and Conditions Affecting the Likelihood of Failure

— Crown and Branches —

Unbalanced crown ☐ LCR 70 %

Dead twigs/branches ☒ 5 % overall Max. dia. 1"

Broken/Hangers Number _____ Max. dia. _____

Over-extended branches ☒

Pruning history

Crown cleaned ☐ Thinned ☐ Raised ☐

Reduced ☐ Topped ☐ Lion-tailed ☐

Flush cuts ☐ Other professionally maintained

Cracks ☐ _____ Lightning damage ☐

Codominant ☐ _____ Included bark ☐

Weak attachments ☐ _____ Cavity/Nest hole ____% circ.

Previous branch failures ☒ possible Similar branches present ☐

Dead/Missing bark ☐ Cankers/Galls/Burls ☐ Sapwood damage/decay ☐

Conks ☐ Heartwood decay ☐ _____

Response growth _____

Main concern(s) The main concern are the branches hanging over the parking lot, and that's it.

Load on defect N/A ☐ Minor ☐ Moderate ☐ Significant ☐

Likelihood of failure Improbable ☐ Possible ☐ Probable ☐ Imminent ☐

— Trunk —

Dead/Missing bark ☐ Abnormal bark texture/color ☒

Codominant stems ☒ Included bark ☐ Cracks ☐

Sapwood damage/decay ☐ Cankers/Galls/Burls ☒ Sap ooze ☒

Lightning damage ☐ Heartwood decay ☐ Conks/Mushrooms ☐

Cavity/Nest hole _____% circ. Depth _____ Poor taper ☐

Lean _____° Corrected? _____

Response growth _____

Main concern(s) the sap ooze in the, there is a, yes, there is sap ooze coming from a crack on the north

Load on defect N/A ☐ Minor ☐ Moderate ☐ Significant ☐

Likelihood of failure

Improbable ☐ Possible ☐ Probable ☐ Imminent ☐

— Roots and Root Collar —

Collar buried/Not visible ☒ Depth 4" Stem girdling ☐

Dead ☐ Decay ☐ Conks/Mushrooms ☐

Ooze ☐ Cavity ☐ 30 % circ.

Cracks ☐ Cut/Damaged roots ☐ Distance from trunk _____

Root plate lifting ☐ Soil weakness ☐

Response growth _____

Main concern(s) the pavement that covers thirty percent of the roots

Load on defect N/A ☐ Minor ☐ Moderate ☐ Significant ☐

Likelihood of failure

Improbable ☐ Possible ☐ Probable ☐ Imminent ☐

Risk Categorization

Condition number	Tree part	Conditions of concern	Part size	Fall distance	Target number	Target protection	Likelihood: Failure: Improbable	Likelihood: Failure: Possible	Likelihood: Failure: Probable	Likelihood: Failure: Imminent	Likelihood: Impact: Very low	Likelihood: Impact: Low	Likelihood: Impact: Medium	Likelihood: Impact: High	Likelihood: Failure & Impact (from Matrix 1): Unlikely	Likelihood: Failure & Impact (from Matrix 1): Somewhat	Likelihood: Failure & Impact (from Matrix 1): Likely	Likelihood: Failure & Impact (from Matrix 1): Very likely	Consequences: Negligible	Consequences: Minor	Consequences: Significant	Consequences: Severe	Risk rating of part (from Matrix 2)
1	Crown	extended branches over the parking lot	1-2"	40'	1			X					X		X					X			low
1 2	Trunk	sap ooze	8"			none	X						X		X							X	low
2																							
3																							
4																							

Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impacting Target			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely

Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low





Notes, explanations, descriptions The assessment took place at El Manto River Access, focusing on oaks over the parking lot. A healthy Quercus agrifolia was examined, showing ooze trails and horizontal boreholes, but overall appears healthy with new growth.

Mitigation options keep pruning and maintaining it well **Residual risk** low

Residual risk _____

Residual risk _____

Residual risk _____

Overall tree risk rating Low ☒ Moderate ☐ High ☐ Extreme ☐ **Work priority** 1 ☒ 2 ☐ 3 ☐ 4 ☐

Overall residual risk Low ☒ Moderate ☐ High ☐ Extreme ☐ **Recommended inspection interval** 18 months

Data ☐Final ☐Preliminary **Advanced assessment needed** ☐No ☐Yes-Type/Reason _____

Inspection limitations ☐None ☐Visibility ☐Access ☐Vines ☐Root collar buried Describe _____

This datasheet was produced by the International Society of Arboriculture (ISA) and is intended for use by Tree Risk Assessment Qualified (TRAQ) arborists – 2013