

Figure 2. Experimental crack trajectories of double-edge notched specimens of concrete, before the compression failure of the loaded part of specimen. (a) 2h = 75 mm. (b) 2h = 150 mm.




Figure 3. Series of photos showing the sequence of appearance of cracks.