[Risk&DC FE] CI 输出单元测试报告

- 现状与目的
- Jest 配置
- CI 配置
 - 测试覆盖率解析
- 具体案例
- 相关文档

	日期	说明	责任人
	2022/01/11	新建方案	Yadong Ma
	2022/01/13	增加增量测试报告方案	Yadong Ma

现状与目的

目前虽然单元测试接入 GitLab CI, 但是并没有实际的效果,多数情况 CI 执行结果均会执行失败,并且无人关注。主要原因:

- 单测并未真正落实,多数代码并无单测用例
- 测试报告查看依赖 sonar ,但是目前 sonar 已经无人维护,存在很大风险,这也是导致 CI 经常执行时失败的原因
- 单次报告查看不直观,不能直接在 MR 页面查看,需要登录 sonar 才能查看

基于以上问题,本次方案决定弃用 sonar 的模式,采用 GitLab CI 本身对 test 的支持实现测试用例报告直接在 GItLab Job 结果中查看。

Jest 配置

jest.config.js

```
module.exports = {
                                                         verbose: true,
                                                         //
                                                         testMatch: ["**/__tests__/**/*.ts"],
                                                         // junit GitLab CI
                                                         reporters: [
                                                                  "default",
                                                                            "jest-junit",
                                                                                 ancestorSeparator: " > ",
                                                                                  suiteNameTemplate: "{filename}",
                                                                                  classNameTemplate: "{classname}",
                                                                                  titleTemplate: "{title}",
                                                                                                                         outputDirectory: "coverage/",
                                                                          },
                                                                ],
                                                         ],
                                                         // GitLab CI cobertura MR changes
                                                         // text log GitLab log
                                                         coverageReporters: ["cobertura", "text"],
                                                         collectCoverage: true,
                                                         collectCoverageFrom: ["./src/**", "!**/__tests__/**"],
                                                         // jest jest pipeline
                                                         coverageThreshold: {
                                                                 global: {
                                                                          statements: 80,
                                                       },
                                                };
ORECON 1 202 OF THE CHARLES TO SERVICE STREET AND THE CHARLES THE STREET AND THE CHARLES THE STREET AND THE CHARLES THE CHARLE
```

.gitlab-ci.yml


```
# git nodejs git
# image
image: harbor.shopeemobile.com/shopee/credit/risk_fe_ci_runner:0.1
cache:
 key: "node_modules"
 paths:
   - .node_modules/
stages:
  - unit-test
# MR
unit-test-all:
 stage: unit-test
 script:
   - npm install
   - npm test
 artifacts:
   reports:
         # cobertura changes
     cobertura: coverage/cobertura-coverage.xml
         # junit
      junit:
       - coverage/junit.xml
 coverage: '/All files[^|]*\|[^|]*\s+([\d\.]+)/'
 only:
    - merge_requests
unit-test-new:
 stage: unit-test
 script:
        - git fetch --no-tags --depth=1 origin ${CI_MERGE_REQUEST_TARGET_BRANCH_NAME}
   - npm test -- --ci --changedSince=origin/${CI_MERGE_REQUEST_TARGET_BRANCH_NAME}
 artifacts:
   reports:
     cobertura: coverage/cobertura-coverage.xml
     junit:
       - coverage/junit.xml
  //
 coverage: '/All files[^|]*\|[^|]*\s+([\d\.]+)/'
 only:
    - merge_requests
```

测试覆盖率解析

可直接参考上文在 CI Job 中配置 coverage 的正则表达式进行解析,则无需进行下面的设置,两种方案任选一种即可


GitLab → Project → Settings → CI/CD → General pipelines → Test coverage parsing

GitLab 通过正则解析脚本输出的 log,从 log 文本中读取中的覆盖率,因此 jest 配置需要输出 `text` 或 `text-summary` 报告到 log 才能计算。



匹配原理:可以通过 https://rubular.com/ 测试正则表达式


匹配结果为 50



具体案例


MR 内查看单元测试结果:

单元测试覆盖率包括 **全量测试覆盖率** 和 增量测试覆盖率,分别由两个 Job 输出:




测试报告详情:

点击 Jobs 查看增量覆盖率和全量覆盖率对应的测试结果:



点击 Tests 查看各个 Job 测试用例执行结果:

注意: 该处的成功率为测试用例执行的成功率,而非测试覆盖率。此处仅会列出所执行的测试用例及其执行情况:



具体的测试用例:



MR Changes 查看行覆盖情况:

```
+3 -0
          No test coverage
Special 1292 of 18 15:15:23
     export const add = (a, b) => {
```