

DFM analysis report_JLCDFM


File name : Manufacturables 10-12.zip

Report generated at : 2026-08-18 20:04:57

PCB layers : 4

PCB size : 3.4x3.4cm

Analyze project : ☒ PCB DFM ☐ SMT DFM



PCB DFM>Routing layer analysis

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
Sharp trace corner (Check for sharp corners in traces)	No	No	No	Danger: 0 Warning: 0 Good: 0
BGA pad (Check BGA pads on the board)	No	No	No	Danger: 0 Warning: 0 Good: 0
Via placed within a pad (Check if there is a via placed within a pad)	No	No	No	Danger: 0 Warning: 0 Good: 0
Trace to board edge (Detect traces too close to the board edge)	No	No	No	Danger: 0 Warning: 0 Good: 0
Trace spacing (Measure spacing between adjacent parallel traces)	0.2mm Good		Manufacturables 10-12VAG328X-B_Cu.gbr Manufacturables 10-12VAG328X-F_Cu.gbr	Danger: 0 Warning: 0 Good: 17
Unconnected trace end (Free-standing trace ends not connected to pads)	No	No	No	Danger: 0 Warning: 0 Good: 0
Trace width (Trace width information)	0.2mm Good		Manufacturables 10-12VAG328X-B_Cu.gbr Manufacturables 10-12VAG328X-F_Cu.gbr	Danger: 0 Warning: 0 Good: 59
Fiducial (Detect fiducial marks on the board)	No	No	No	Danger: 0 Warning: 0 Good: 0
Pad to board edge (Measure distance of pads from the board edge)	No	No	No	Danger: 0 Warning: 0 Good: 0
Pad spacing (Measure pad to pad spacing)	0.19mm Good		Manufacturables 10-12VAG328X-B_Cu.gbr Manufacturables 10-12VAG328X-F_Cu.gbr	Danger: 0 Warning: 0 Good: 100
Plated through-hole to trace clearance (Measure clearance of plated through-holes to traces)	0.35mm Good		Manufacturables 10-12VAG328X-B_Cu.gbr Manufacturables 10-12VAG328X-F_Cu.gbr	Danger: 0 Warning: 0 Good: 25
Annular ring (Annular ring width of pads compared to holes)	0.1mm Danger		Manufacturables 10-12VAG328X-B_Cu.gbr Manufacturables 10-12VAG328X-F_Cu.gbr	Danger: 4 Warning: 81 Good: 0
tht to smd (Detect clearance of vias to pads)	1.06mm Danger		Manufacturables 10-12VAG328X-B_Cu.gbr Manufacturables 10-12VAG328X-F_Cu.gbr	Danger: 15 Warning: 51 Good: 34
Via to pad (Detect clearance of vias to pads)	0.04mm Danger		Manufacturables 10-12VAG328X-B_Cu.gbr Manufacturables 10-12VAG328X-F_Cu.gbr	Danger: 1 Warning: 1 Good: 2

PCB DFM>Soldermask layer analysis

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
Soldermask bridge (Detect distance between parallel soldermask opening edges)	0.16mm Good		Manufacturables 10-12VAG328X-F_Mask.gbr Manufacturables 10-12VAG328X-B_Mask.gbr	Danger: 0 Warning: 0 Good: 6
Solder mask opening exposing trace (Detect clearance of solder mask openings to nearby traces)	0.07mm Danger		Manufacturables 10-12VAG328X-F_Mask.gbr Manufacturables 10-12VAG328X-B_Mask.gbr	Danger: 1 Warning: 6 Good: 54
Soldermask opening with multiple segments (Check if solder mask openings are constructed from multiple geometric shapes)	null Warning		Manufacturables 10-12VAG328X-F_Mask.gbr Manufacturables 10-12VAG328X-B_Mask.gbr	Danger: 0 Warning: 4 Good: 0
Negative soldermask expansion (Detect solder mask openings smaller than their corresponding pads)	0.04mm Warning		Manufacturables 10-12VAG328X-F_Mask.gbr Manufacturables 10-12VAG328X-B_Mask.gbr	Danger: 0 Warning: 12 Good: 0

PCB DFM>Silkscreen layer analysis

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
Silkscreen to pad (Detect clearance of silkscreen to pads)	0.08mm Danger		Manufacturables 10-12VAG328X-F_Silkscreen.gbr Manufacturables 10-12VAG328X-B_Silkscreen.gbr	Danger: 100 Warning: 0 Good: 0
Silkscreen to hole (Detect clearance of silkscreen to holes)	0mm Danger		Manufacturables 10-12VAG328X-F_Silkscreen.gbr Manufacturables 10-12VAG328X-B_Silkscreen.gbr	Danger: 38 Warning: 6 Good: 13
Silkscreen line width (Check silkscreen line width)	0.05mm Danger		Manufacturables 10-12VAG328X-F_Silkscreen.gbr Manufacturables 10-12VAG328X-B_Silkscreen.gbr	Danger: 2 Warning: 69 Good: 14

PCB DFM>Drill layer analysis

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
Unconnected via (Detect isolated unconnected vias)	No	No	No	Danger: 0 Warning: 0 Good: 0
Missing plated through-hole (Detect top and bottom pads at the same location without plated through-holes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Unconnected via (Detect isolated unconnected vias)	No	No	No	Danger: 0 Warning: 0 Good: 0
Plated through-hole spacing (Measure spacing between plated through-holes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Short slot detection (Detect slots shorter than twice their width)	No	No	No	Danger: 0 Warning: 0 Good: 0
Slot width check (Measure slot width)	0.6mm Danger		Manufacturables 10-12VAG328X-PTH.drl	Danger: 4 Warning: 0 Good: 0
Via to PTH spacing (Measure spacing of vias to plated through-holes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Unconnected via (Detect isolated unconnected vias)	No	No	No	Danger: 0 Warning: 0 Good: 0