

COFFEE PACKAGING QUALITY INSPECTION REPORT

Real-Time AI Seal Inspection and Physical Leak Detection

1. Report Information

Packet ID	PKT-20260828023108-E54C
Report ID	RPT-20260828-383E50
Inspection Date	28 August 2026
Inspection Time	02:42:25 AM
Inspection Module	Packet Seal and Leak Quality Inspection

2. Overall Inspection Summary

Inspection	Result
Real-Time AI Overheat Inspection	NO_OVERHEAT_DETECTED
Physical Packet Leak Test	GOOD
Overall Quality Decision	ACCEPT

3. Final Quality Decision

ACCEPT

No overheat defect was detected during the real-time inspection and the packet passed the physical leak test.


4. Real-Time Two-Stage AI Inspection

Detected Seal Regions	3
Overheat Detected	NO
Highest Overheat Confidence	0.0%
AI Inspection Status	NO_OVERHEAT_DETECTED

Seal-by-Seal Results

Seal	Seal Confidence	Overheat	Overheat Confidence
Seal 1	82.8%	NO	-
Seal 2	79.7%	NO	-
Seal 3	72.6%	NO	-

Real-Time Inspection Evidence



5. Physical Packet Leak Detection

Leak Test Result	GOOD
Initial Value	8388607
Average Value	-1.0
Threshold	286000
Minimum	-1
Maximum	-1
Range	0
Reading Count	10
Final Device Status	TOP_REACHED

Load Cell Readings

Reading Number	Sensor Value
1	-1
2	-1
3	-1
4	-1
5	-1
6	-1
7	-1
8	-1
9	-1
10	-1

6. Recommended Action

- Packet passed the current automated quality checks.
- Proceed according to the normal production quality-control process.

7. Inspection System Information

AI Stage 1	Seal Region Object Detection
AI Stage 2	Overheat Defect Object Detection
Camera	IP Webcam Real-Time Video

Physical Controller	Arduino Uno
Force Measurement	HX711 Load Cell System
Mechanical Test	Motorized Packet Pressure Mechanism
Safety / Position Control	Top and Bottom Limit Switches

This report was generated automatically using the coffee packet quality inspection system.