

Figure C8.3 Susceptible Bays for Ponding Evaluation for Roof with Slope of 1/4 In./Ft or Greater.




Figure C8-4 Roof with Slope of 1/4 In./Ft or More. All Bays Susceptible to Ponding.