



六类状态代表样本的低频频谱


正常 | Motor-2 | 1480 rpm




转子不平衡 | Motor-4 | 2070 rpm




联轴器不对中 | Motor-4 | 2070 rpm



松动 | Motor-2 | 1110 rpm



轴承故障 | Motor-2 | 1110 rpm



汽蚀 | Motor-4 | 2070 rpm

