

DIMENSIONAL & VISUAL INSPECTION FLANGE / COLLAR Doc. No : FM-C3.2-21 / Rev. No. : 6/ Issue Date : Mar 22^{tn}, 2018

Customer

: PT - Sout Pacific Indonesia


Project

: CS2 Adjointion Plant 2 : DN 100 Floringe AMSI CL # 150 FF

Dwg No.

: 2929 - ORP- 13 A6C - GA - 0001

Resin Batch No.



Hardener Batch No. WR Batch No C Veil Batch No. CSM Batch No.

Insp Point	Standard	Tolerance	Daycode							
			AR 129 CAP2 001		AR 120) UNP2 003	AP 120) (AP 2.004				
OD	228.6	-1.0 /4 2.0	229	229	220	920)				
PCD	190.5	1 1.5	190	190	190	190				
ID	1.00		100	100	100	100			,	
N	. 3		8	. 8	8	8				
øΗ	19.0	-0-2 /4 3.2	20	20	20	20				and the same at a first per large section of the same at a section of t
D1	127		128	128	n8	128				
t	A.3	-a /4 12.5 %	4.8	4.7	47	4.7	,			
L	200	1 1.5	201	201	201	201				
L1	5A		55	55	45	拓			17	
T	18	0/13.0	20.3	20	10)	10)				7/
R	. 5		ole	ok	ole	olc				
Roundness		olc	alc	alc	ok					
Flatness			ok	. olc	ale	. ak				
Barcol			23	39	39	23				
Visual Before Coating			yk.	ok	ok	OF				
Visual After Coating			ok	alc	olc	ak				
Hammer Test After Lathe*			NG OK	NG O	NG OK	NG OK	☐NG ☐OK	NG OK	□NG □OK	NG OK
Hammer Test Finishing Process*			NG OK	NG O	NG OK		■ NG ■ OK	NG OK	☐ NG ☐ OK	NG O
Result			Pass	Pass	Pass	Pass				
					12 /09 /22	12 /05 /22				
Note: * Only for the color Resin (all diameter)					Prepared		Checked		Approved	
eg .					The		,			
					Inspector		Supervisor		Dept. Head	