

DIMENSIONAL & VISUAL INSPECTION TEE EQUAL / TEE REDUCER


Doc. No : FM-C3.2-25 / Rev. No. : 4 / Issue Date : Jan 23th, 2018

Customer Project

PT. South Pacific Indonesia CS2 Adsorption Plant 2 DN 500 Equal Tec

Dwg No. : 2224-027-1346C-64-0001

Type of Fitting



insp	Standard	Tolerance	Daycode							
Point			AR 140 CAP2 001	AR IAO CAP2 002	#	Coose				
ID 1	500		500	500					1	
TI	8.5	4 12.5 %	2.5	9.4						
ID 2	500	•	500	500						
T2	8.5	1 12.5 %	2.9	2.4						
L	820	4 6.0	826	824						
LI	410		413	412						
H	410	4 6.0	A13	414						
Rad	8		ok							
Roundness		. ok								
Barcol		33						-		
Visual Before Coating			ok							
Visual After Coating			ole							
Result			Pass							
Date of Inspection			23 /05 /24							

Insp	Standard	Tolerance	Daycode							
Point						I				
ID 1			4	-	-				Disassing of the Control of the Cont	
Ti I										
ID2										
T2						-				
L										
Li									Committee of the Commit	
H							_			
Rad						ļ				
Round	ness									
Barcol	A.				1					
Visual Before Coating										
Visual After Coating				1	-					
Result					1					
Date of Inspection					·		-			
				Pre	Prepared		Checked		Approved	
			CHROSTOPAN	CRESCO CANADA CONTRA CANADA CA						
				Insp	Inspector		Supervisor		Dept. Head	