


Fig. 6. Current disturbance argmax explanation



Representative case: SSO_SLG_Fault_Bus23
Target bus 23 (Zone4), argmax bus 23 (Zone4)

