

Lamborghini
MANSORY 2021

05/May/2026



Car Inspection Report

For Help: +971-545-095-755



Scan To
Verify



Advance 360 Test (Luxury & Hyper Cars)



Car Details


Customer Name MR. MARSELO	Model 2021	Engine Capacity 4.0L
Fuel Type PETROL	Chassis ZPBEA1ZL3MLA15451	Engine NIL
Mileage 61550KM	Color YELLOW	Inspection Date 2026-05-02
Emirates DUBAI	Regional Specs EUROPE	Transmission AUTOMATIC
Plate NIL	Service History NOT AVAILABLE	Inspector Id 5
No. of Keys 1 AVAILABLE	No. of Doors 4	No. of Cylinders 8

SUMMARY

Overall Rating: 9.4/10

Exterior Body Condition	100%	Body Frame Accident Checklist	100%
Interior	90%	Ac/Heater	95%
Electrical & Electronics	95%	Brakes	90%
Wind Screen & Exterior Lights	95%	Engine/ Transmission/ Clutch	95%
Suspension/ Steering	95%	Tyres	70%
Flood/Rust	100%		

Exterior Body Condition



Legend

- P:** Paint marked

U1: Small Dent

A1: Small Scratch

● Minor Scratches/Dents
- B2:** Dent with scratch (size like flat of the hand)

B1: Small dent with scratch (size like a thumb)

U3: Big Dent

Bonnet	Okay	
Front Right Fender	Okay	
Front Right Door	Okay	
View Image		
Rear Right Door	Okay	
View Image		
Rear Right Fender	Okay	
View Image		
Trunk	Okay	
View Image		
Rear Left Fender	Okay	
View Image		
Rear Left Door	Okay	
View Image		
Front Left Door	Okay	
View Image		
Front Left Fender	Okay	
Roof	Okay	

Reports

Obd scanner Report	View
--------------------	-----------------

Tire and brake disc report

[View](#)

Battery alternator report

[View](#)

Body Frame Accident Checklist 100%

Radiator Core Support View Image	Okay	
Right Strut Tower Apron View Image	Okay	
Left Strut Tower Apron View Image	Okay	
Cowl Panel Firewall	Okay	
Right A Pillar View Image	Okay	
Left A Pillar View Image	Okay	
Right B Pillar View Image	Okay	
Left B Pillar View Image	Okay	
Right C Pillar	Okay	

View Image		
Left C Pillar View Image	Okay	
Boot Floor View Image	Okay	
Boot Lock Pillar View Image	Okay	

Interior 90%

Steering controls

Steering Wheel Condition View Image	Okay	
Steering Wheel Buttons View Image	Working	
Horn	Working	
Lights Lever / Switch (High / Low Beams , Indicators) View Image	Working	
Wiper / Washer Lever (Washer, Speeds) View Image	Working	

Dash / roof controls

Glove Box View Image	Working	
Interior Lightings View Image	Working	
Dash Controls - A/C	Working	
Dash Controls - De-Fog	Working	
Dash Controls - Hazzard Lights	Working	
Dash Controls - Others View Image	Working	
Audio/Video	Working	
Rear View Camera	Working	
Trunk Release Lever / Button View Image	Working	
Fuel Cap Release Lever / Button	Working	
Bonnet Release Lever / Button View Image	Working	
Sun Roof Control Button View Image	Working	

Mirrors

Right Side Mirror View Image	Working	
Left Side Mirror View Image	Working	
Rear View Mirror Dimmer View Image	Showing Reflection	

Seats

Right Front Seat Electric Function View Image	Working	
Left Front Seat Electric Function View Image	Working	
Right Seat Belt	Working	
Left Seat Belt	Working	
Rear Seat Belts	Working	

Upholstery

Roof Headliner View Image	Good	
Floor Mat	Good	

View Image		
Front Right Seat Fabric/Leather View Image	Good	
Front left Seat Fabric/Leather View Image	Good	
Rear Seat Poshish	Good	
Dashboard Condition	Good	
Door card Vinyl View Image	Okay	

Power / manual windows & central locking

Front Right Power Window/Manual Lever	Working	
Front Left Power Window/Manual Lever	Working	
Rear Right Power Window/Manual Lever	Working	
Rear Left Power Window/Manual Lever	Working	
Auto Lock Button	Working	
Window Safety Lock	Working	

Equipment

Tools	Complete	
-------	----------	--

Ac/Heater 95%

Ac / heater check up

AC Fitted	Yes	
AC Operational	Yes	
Blower	Excellent Air Throw	
Cooling	Excellent	
Heating	Excellent	

Electrical & Electronics 95%

Computer check up

Computer Check up / Malfunction Check	Error Found	
Battery Warning Light	Not Present	
Oil Pressure Low Warning Light	Not Present	
Temperature Warning Light / Gauge	Not Present	
Air Bag Warning Light	Not Present	
Power Steering Warning Light	Not Present	

ABS Warning Light	Not Present	
Key Fob Battery Low Light	Not Present	
Tire Pressure Sensor Light	Not Present	

Instrument cluster

Gauges View Image	Working	
---------------------------------	---------	--

Brakes 90%

Mechanical check

Front Right Disc View Image	Not Linings	
Front Left Disc View Image	Not Linings	
Front Right Brake Pad View Image	Okay	
Front Left Brake Pad	Okay	
Parking / Hand Brake View Image	Okay	

Wind Screen & Exterior Lights 95%

Car frame

Trunk Lock	Okay	
Front Windshield Condition View Image	Okay	
Rear Windshield Condition View Image	Okay	
Front Right Door Window	Okay	
Front Left Door Window	Okay	
Rear Right Door Window	Okay	
Rear Left Door Window	Okay	
Windscreen Wiper	Okay	
Sun Roof Glass View Image	Okay	

Exterior lights

Right Headlight (Working)	Working	
Left Headlight (Working)	Working	
Right Headlight (Condition) View Image	Okay	

Left Headlight (Condition) View Image	Okay	
Right Taillight (Working)	Working	
Left Taillight (Working)	Working	
Right Taillight (Condition) View Image	Okay	
Left Taillight (Condition) View Image	Okay	
Fog Lights (Working)	Working	

Engine/ Transmission/ Clutch 95%

Fluids/filters check

Engine Oil Level	Okay	
Engine Oil Leakage View Image	No Leakage	
Transmission Oil Leakage	No Leakage	
Transfer Case Oil Leakage View Image	No Leakage	

Coolant Leakage View Image	No Leakage	
Brake Oil Leakage View Image	No Leakage	
Power Steering Oil Leakage	No Leakage	
Differential Oil Leakage View Image	No Leakage	

Mechanical check

Belts (Fan)	Okay	
Wires (Wiring Harness) View Image	Okay	
Engine Blow (Manual Check)	Not Present	
Engine Noise	No Noise	
Engine Vibration	No Vibration	
Cold Start	Okay	
Engine Mounts View Image	Okay	
Pulleys (Adjuster)	Okay	
Hoses	Okay	

View Image		
-----------------------	--	--

Exhaust check

Exhaust Sound View Image	Okay	
--	------	--

Engine cooling system

Radiator	Okay	
Suction Fan	Working	

Transmission check / power train

Transmission / Power Train Check View Image	Okay	
---	------	--

Engine electronics

Starter Operation	Okay	
-------------------	------	--

Suspension/ Steering 95%

Front suspension

Steering Wheel Play	Okay	
Right Ball Joint View Image	Okay	
Left Ball Joint View Image	Okay	

Right Z Links View Image	Okay	
Left Z Links View Image	Okay	
Right Tie Rod End View Image	Okay	
Left Tie Rod End View Image	Okay	
Front Right Boots View Image	Okay	
Front Left Boots View Image	Okay	
Front Right Bushes	Okay	
Front Left Bushes View Image	Okay	
Front Right Shock View Image	Okay	
Front Left Shock View Image	Okay	

Rear suspension

Rear Right Bushes View Image	Okay	
Rear Left Bushes View Image	Okay	
Rear Right Shock View Image	Okay	
Rear Left Shock View Image	Okay	

Tyres 70%

Front Right Tyre Brand View Image	TEMPESTA	
Front Right Tyre View Image	2024	
Front Left Tyre Brand	TEMPESTA	
Front Left Tyre	2024	
Rear Right Tyre Brand	ULTRAC	
Rear Right Tyre	2022	
Rear Left Tyre Brand View Image	ULTRAC	
Rear Left Tyre	2021	

View Image		
Tyre Size View Image	295/30ZR24	
Rims View Image	24 inches	
Wheel Caps	Not include	

Flood/Rust 100%

Flood	No	
Rust	No	

Test Drive 100%













Engine Pick	Okay	
Drive Shaft Noise	No Noise	
Differential Noise	No Noise	
Gear Shifting (Automatic)	Smooth	
4X4 Shifting	Working	
Front Propeller Shaft	No Noise	
Rear Propeller Shaft	No Noise	
Brake Pedal Operation	Timely Response	

ABS Operation	Timely Response	
Front Suspension (While Driving)	No Noise	
Rear Suspension (While Driving)	No Noise	
Steering Operation (While Driving)	Smooth	
Steering Wheel Alignment (While Driving)	Centered	
Heater Operation (While Driving)	Working	
AC Operation (While Driving)	Working	
Speedometer (While Driving)	Working	
Test Drive Done By	Inspector	

Car Summary

The vehicle has PPF coating, with visible PPF patches on the rear right fender and rear bumper. Paint gauge readings are consistent across the vehicle; the micron values (including both original paint and PPF layer) appear uniform. No signs of body filler or accident damage were detected. Additionally, the rear tires are worn and require replacement Engine & transmission all clear. Only minor electrical/communication faults: door lights, rear screens, TPMS low pressure, and telematics coding. No major issues. Just needs TPMS reset, check door lighting, and clear faults.

Mr. Marselo - Vehicle Pictures

			
Front View	Oblique Front -Right	Oblique Rear - Right	Rear View
			
Oblique Rear - Left	Oblique Front - Left	Chassis No	Engine No
			
Odometer	Engine Compartment	Front Interior	Rear Interior
			
Tool kit	Trunk Open	Key/Remote	Roof

 Car Image

 Car Image

 Car Image

 Car Image

Additional Image 2

Additional Image 1

Additional Image 3

Additional Image 4