


FIGURE 3-4a



Map of Debris and Obstructions in Gowanus Canal in 2005  
Upper Canal  
Gowanus Canal  
Brooklyn, New York



0 150 300  
Feet



**FIGURE 3-4b**  
Map of Debris and Obstructions in Gowanus Canal in 2005  
Middle Canal  
Gowanus Canal  
Brooklyn, New York



**FIGURE 3-4c**  
Map of Debris and Obstructions in Gowanus Canal in 2005  
Lower Canal  
Gowanus Canal  
Brooklyn, New York

Side Scan Sonar Target No.	Description
11	Pile of large blocks and debris
11a	Pile of debris
11b	Long pile of rip rap
17	Pile of hard, square debris
24	Suspected part of a tree
26	U-shaped object
28	Linear object
31	Small boat wreck
31a	Sunken boat hull
31b	Hard, rectangular feature
31c	Two rectangular features
37	Long section of rubble and rip rap
37a	Sunken barge
37b	Barge hull and small boat wreck
37c	Two hard rectangular features
39	Two rectangular objects

The complete side scan sonar survey report with imagery is provided in Appendix M.





FIGURE 3-4d

Map of Debris and Obstructions in Gowanus Canal in 2010

Upper Canal


Gowanus Canal

Brooklyn, New York



Side Scan Sonar Target No.	Description
9a	Scattered debris
11	Pile of large blocks and debris
11a	Pile of debris
11b	Long pile of rip rap
35	Scattered debris
37	Long section of rubble and rip rap
37a	Sunken barge
37b	Barge hull and small boat wreck
37c	Two hard rectangular features
39	Two rectangular objects
42	Pile of rip rap
42a	Box-like object
42b	Pile of rip rap
48	Scattered debris

The complete side scan sonar survey report with imagery is provided in Appendix M.



**FIGURE 3-4e**  
Map of Debris and Obstructions in Gowanus Canal in 2010  
Middle Canal  
Gowanus Canal  
Brooklyn, New York




FIGURE 3-4f

Map of Debris and Obstructions in Gowanus Canal in 2010

Lower Canal

Gowanus Canal

Brooklyn, New York

