

District Report

Gorkha

15-21 December 2017


Activity Summary

Activity	Contact Person	Reference Document
HRRP Gorkha attended HRRP General Meeting & District Exhibition, 13 December: the HRRP presentation from the meeting is available here and a live recording of the event can be accessed here . The Gorkha district exhibition materials are also available in the link provided below: Gorkha	Minar@hrrpnepal.org ; info@hrrpnepal.org ;	(CLICK HERE)
HRRP Gorkha organized NRA/HRRP coordination meeting chaired by Mr. Shiva Lal Paudel, Chief, NRA secretariat of district coordination committee, Gorkha and attended by 20 participants on 18 th December 2017. Participants discussed on following agenda: 1. NRA request and updates 2. Partners/HRRP updates and gaps 3. Winterization support? (MoUD/MoHA/Shelter cluster) 4. Upcoming Events and programs	minar@hrrpnepal.org ; techcord.gorkha@hrrpnepal.org ; dc.gorkha@hrrpnepal.org ;	Meeting minutes in English (CLICK HERE)
HRRP facilitated meeting between Build up Nepal and Gorkha DUDBC/DLPIU's Chief Mr. Roshan Shrestha at DUDBC office on 19 th December, 2017 to discuss and plan about upcoming one day orientation to DLPIU engineers on CSEB blocks manufacture process, designs and construction procedure on 28 th -29 th Dec 2018 with purpose to train around 90 technical person to cover all geological areas of Gorkha district which will strengthen DLPIU engineers understanding to support an alternative materials house construction.	Minar@hrrpnepal.org ; dlpiugorkha@gmail.com ; pratik@buildupnepal.com ;	
HRRP Gorkha team met Government officials (LDO, DTO, DUDBC, DCC staff) and partners (CRS, EHRP, CFP, CN) to introduce HRRP Gorkha district technical coordinator (Er. Atit Shrestha) as part of handover activity from Minar Thapa Magar. Handover process will continue till 30 th December to newly deployed HRRP Gorkha coordination team.	minar@hrrpnepal.org ; techcord.gorkha@hrrpnepal.org ; dc.gorkha@hrrpnepal.org	
Gorkha HRRP team send invitation for half orientation session on HRRP IM products(9:00-1:00pm) for IMO, RO, database officers and orientation on Retrofitting manuals (2:00 pm -5:00 pm) for government and partners technical persons on 27 th December 2017 at Hotel Miracle, Gorkha.	techcord.gorkha@hrrpnepal.org ; dc.gorkha@hrrpnepal.org	

News & Updates

NRA Gorkha chief Mr. Shiva Lal Paudel participated in 3 days workshop organized by NRA and UNWOMEN in Kathmandu on 20th -22nd December 2017.

Challenges and Way Forward

Challenge	Way Forward
Lack of coordination between POs door to door technical staff and DLPIU/NRA engineers at field. (Middle and Northern areas of Gorkha)	Organizations need to strengthen coordination and communication mechanism between partners' and government field engineers and staff as a partnership approach.
People of northern Gorkha spends more in transportation of construction materials as a good quality local construction materials are not available in some areas?	Alternative construction materials such as hollow blocks and CSEB blocks must be promoted and supported for people where stones are not available and extra support should be provided to remote areas through top up or other assistance.
Vulnerable and safe lands to be identified by government for people to plan their relocation and reconstruction as fast as possible.	NRA should send geologist to prepare detail geological assessment report to assess and identify safe and vulnerable land within community along with proposed relocation land.
Beneficiaries need to come to district to get recommendation to transfer agreement from husband to wife or to closet relatives in case of death and previous beneficiaries is outside of country even though they got recommendation from rural municipality to get tranche.	If bank will accept recommendation from rural municipality then those beneficiaries doesn't need to come to district headquarter to get recommendation/verification of relation to receive government tranche.
	
 About 100+ beneficiaries visit DCC office everyday to find out status of their file as tranche release is long process with different level and beneficiaries come to district and goes to bank, dcc, nra and dudbc-dlpiu to find out satutus of their ispection forms and tranche.	Database management system of inspection process and tracking of inspected files from MoUD-DLPIU and DCC must be done with regular dissemination of recommended and tranche release name list to rural municipality so that beneficiaries can get same information from rural municipality level.

Challenges and Way Forward

Challenge	Way Forward
 Inspected/Recommened files are not manged safely in District coordination office(DCC), Gorkha as these files should be confidentially protected but due to lack of manpower and utilities they are carelessly hold in districts without any type of digital documentation. "If we need to search some person's file then we need to dig from these files"	Resources and manpower should be provided to district coordination committee i.e. MoFALD-DLPIU to manage and digitize all these files and maintain master database so that they can provide quick and relevant information to beneficiaries and even can share regular updates with NRA, HRRP and all rural/municipalities.

Housing Typology Report



Typology: Stone in Cement, flexible roof
Gumda, Dharche Rural Municipality-5, 2 storey house with front wall extension more than 1 m which made this house non-compliance and correction can be done by adding up 1 m wall from front face in both corners but people are not ready to do corrections.



Typology: Stone in Mud, Flexible roof
Gumda, Dharche Rural municipality-5, 2 storey House constructed with timber banding and with mud mortar and non-compliance based on guidelines.



Typology: Stone in Cement/Mixed Structure, Flexible roof
Gumda, Dharche-5, 2 storey house first floor constructed with timber structure and ground floor with stone and mud.



Typology: Dry stone/Flexible Roof
Kerauja, Dharche rural municipality ward-2, 2 storey house was constructed in dry stone (Non-compliance) and correction measures are very difficult to apply and people construct 2 stories house in these areas based on their requirements.