

District Report

Sindhupalchok

3-9 November 2017

Activity Summary

Activity	Contact Person	Reference Document
Field Visit	Aarju Basnet	
Survey on Hollow Concrete Blocks	Aarju Basnet	
Contact list, mason training database update and preparation of SM training	Manisha Rai	

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
SM Training	14-16 Nov	Aarju and Manisha

Field Visit Reports

Date	Location	Participants	
11/07/2017	Bhimtar, Indrawati Gaupalika-11, Sindhupalchok	Aarju Basnet	
Objective(s)	• To observe the houses made up of interlocking blocks made by Sweta Shree Foundation • To observe the houses made up of solid concrete blocks made by WOREC Nepal • To observe the houses made up of hollow concrete blocks made by World Vision, ARSOW Nepal and Build Change		
Summary	While on the field visit to survey the hollow concrete block houses, other two nearby sites were also visited. The area is occupied by fishers and is known as “Majhi Basti”. World Vision, ARSOW Nepal and Build Change have constructed 26 houses of hollow concrete blocks for OJT and they have an agreement with 307 households for technical support and also to provide hollow concrete blocks. WOREC Nepal has a machine to make solid concrete blocks which produce 600-700 blocks per day and has created employment opportunities to the locals as well.		
Challenges / Issues Identified	Action Required	Responsible	Timeframe
• WOREC Nepal hasn’t been able to process files for 2nd tranche as the houses have vertical posts of 75mm*75mm instead of reinforced bars.	Approval required from the Government	• Government and WOREC Nepal	End of Poush

Photos



Majhi Basti, Bhimtar, Indrawati Gaupalika, Sindhupalchok. A house made up of hollow concrete blocks constructed in OJT by World Vision, ARSOW Nepal and Build Change.



Majhi Basti, Bhimtar, Indrawati Gaupalika, Sindhupalchok. A house made up of interlocking blocks constructed by Sweta Shree Foundation.




Majhi Basti, Bhimtar, Indrawati Gaupalika, Sindhupalchok. A house made up of solid concrete blocks constructed by WOREC Nepal. The houses have vertical posts of 75mm*75mm instead of reinforced bars and they are on hold for the 2nd tranche.



Majhi Basti, Bhimtar, Indrawati Gaupalika, Sindhupalchok. Production of solid concrete blocks. At a single time, 3 solid concrete blocks and 2 cutoff blocks are produced. The blocks are in the ratio of 1:3:6 and the test has been performed and approved.



Majhi Basti, Bhimtar, Indrawati Gaupalika, Sindhupalchok. A house made up of interlocking blocks constructed by Sweta Shree Foundation.



Majhi Basti, Bhimtar, Indrawati Gaupalika, Sindhupalchok. The progress of the houses made by WOREC Nepal however, the files haven't been forwarded for 2nd tranche.


Field Visit Reports

Date	Location	Participants	
11/6/2017	Tarkeghyang, Melamchighyang	Aarju Basnet	
Objective(s)	- To observe the reconstruction pace in Tarkeghyang and Melamchighyang, identify issues and challenges - To motivate the locals for reconstruction		
Summary	Helambu is one of the touristic destination of Sindhupalchok. Tarkeghyang and Melamchighyang lie inside Langtang National Park in Helambu, and they lie in the trekking route of Gosainkunda and Langtang Himal. The entire houses in those two villages had collapsed in the earthquake and the reconstruction pace is almost null there. The area is mostly inhabited by Tibetans and Sherpas.		
Challenges / Issues Identified	Action Required	Responsible	Timeframe
In their culture, room size is very large compared to the Government’s standards. Since, it’s freezing cold, kitchen and bed room lie inside a same room. The corpse is worshipped inside the room for several days and everyone gathers inside the room during the worship due to which room size and area is large.	The Government should prepare designs to address their culture. As it is a touristic destination, aesthetic and cultural values of such areas need to be preserved.		
Masons training haven’t been conducted in those areas, and people are asked to come to Timbu, a place 6 hours of walking distance from those villages to attend the	Mason training should be conducted in those areas. In Tarkeghyang, there are 10-15 youngsters willing to attend the training and		

training. The phone network is not good and the villagers complain that they were informed on the starting day of the training due to which they couldn't participate. Since those areas are far and expensive to stay, mason training hasn't been conducted.	it will also create employment opportunities.		
The rubbles in Tarkeghyang still lie in the same place and it's expensive to manage them and construct a new house in those areas.	Provide equipment to manage the rubbles and motivate the locals to do it.		
The locals are unhappy with the Government for providing designs which do not address their needs.	Provide designs that can be accepted by the locals.		
In monsoon, the areas aren't accessible. In winter, cement sets quickly because of cold weather. So, they can only construct houses during certain seasons. Shortage of adequate masons.	Provide mason trainings and produce enough masons in the area.		



Melamchighyang, Helambu. An example of the type of house that the locals prefer.



Melamchighyang, Helambu. The kitchen and room lie together in their culture.



Melamchighyang, Helambu. Beautifully decorated interiors in their culture.	Tarkeghyang, Helambu. The remains of dismantled houses are still in the ground. Lack of proper equipment and manpower are the main reasons for it.