

District Report

Kathmandu Valley

5 – 11 January 2018

Activity Summary

Activity	Contact Person	Reference Document
Orientation and interaction program on Grievances Management was organized by Central NRA Office at Dakshikali Municipality on 05 January 2018. Key attendees of this program were the locally elected Municipality head and deputy head, ward chairperson, ward members and ward secretaries. The agendas of the interaction program were as follows: → To interact with elected representatives of Dakshinkali Municipality about achievements of reconstruction efforts. → To orient on various provisions related to grant support provided by government and its release processes. → To inform about grievances management of the reconstruction issues. The major highlights of the interaction program were as follows: → Grievances handling committee has been formed at each ward level. Gaps and issues related to the housing reconstruction needs to be forwarded to ward chairperson for proper addressing and actions. → The grievances that are raised from ward level should be registered at Ward office. Further, files are forwarded from ward to central level. → Frequent communication is essential among beneficiaries and engineers involved along with concerned elected representatives to address the reconstruction issues raised by beneficiaries. → Grievances related to land should be supported by proper documents; lack of strong evidences will keep the issues in pending stage. DLPIU itself cannot forward files of beneficiaries without any proper recommendation. → There are plenty of inspection mechanisms that are cross checking the transactions of NRA's grant flow to beneficiaries, hence proper documents as evidence is highly recommended to compile. → Beneficiaries, who provide claims of unregistered land from ward office through public inquiry deed, are provided additional grant of NPR 200000 to buy	Mr. Prem Prasad Ghimire Chief, NRA Kathmandu, ghimirepp2011@yahoo.com	

Activity Summary

land. → Beneficiaries with minor non-compliance housing cases can secure 2nd tranche through amending the housing construction following the Exception and Correction manual as recommended, guided and inspected by technical personnel. → To handle special kinds of land cases such as Guthi, Rokka, Parti, Mohi, Talsing, concerned line authorities (Ward office, Guthi Corporation, District Land Revenue Office etc.) should be consulted with proper documents in coordination with Ward Chairperson. Further, Justice Committee formed at ward level under the chairmanship of elected Ward Chairperson is responsible to address the special types of land cases.		
Mason training has been organized by DLPIU Kathmandu in Mitrapark, Kathmandu from 7-13 January 2017. There are 33 participants including 1 female mason who are from different parts of Nepal and working particularly in Kathmandu .	Rachana Paudel rachu.poudel5@gmail.com	

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
General Coordination Meeting of NRA Lalitpur	17 January 2018 11 AM, NRA Lalitpur	Ambika Amatya dc.ktm@hrrpnepal.org
General Coordination Meeting of NRA Kathmandu	19 January 2018, NRA Kathmandu	Ambika Amatya dc.ktm@hrrpnepal.org
General Coordination Meeting of NRA Bhaktapur	21 January 2018, NRA Bhaktapur	Ambika Amatya dc.ktm@hrrpnepal.org
Local Level Orientation on Earthquake Housing Reconstruction to elected local bodies of Lalitpur District		Mr. Yam Nath Giri Monitoring and Evaluation Specialist Lalitpur and Rasuwa EHRP, DLPIU-MOFALD yamnathgiri2014@gmail.com , 9851239785, 9841886093
To include details of upcoming events and meetings in the next bulletin, please share details with dc.ktm@hrrpnepal.org by COB Wednesday of each week.		

News & Updates

• Tranche update from Lalitpur district

Reconstruction update	Total
First tranche	20743
Reconstruction started	3455
Inspection completed for second tranche	3353
Compliance cases	2889
Non- compliance cases	136
Houses ready for inspection for second tranche	446
Request for third tranche	1349
Compliance cases(third tranche)	1080
Non-compliance cases (third tranche)	27
Houses ready for inspection for second tranche	214
Reconstruction Completed	873

Field Visit Reports


Date	Location	Participants	
9 January 2018	Ward no. 4 and 5 of Changunarayan Municipality	- Er. Narakanta Sapkota, M and E Consultant, CLPIU -MoUD - Ambika Amatya, District Coordinator, Kathmandu Valley, HRRP Nepal - Sweata Sijapati, District Technical Coordinator, HRRP Nepal - DLPIU Engineer, Changunarayan Municipality	
Objective(s)	- To inspect the houses that are in reconstruction phase. - To provide technical feedbacks to the beneficiaries for earthquake resistant construction		
Summary	A visit to Pikhel (ward no 5), Pokhrel Gaun (ward no. 4) and Duwakot (ward no. 1) of Changunarayan municipality was conducted on 9 January 2018 along with Monitoring and Evaluation Consultant, DLPIU-MoUD, Kathmandu, HRRP Kathmandu team and with DLPIU engineer. The reconstruction process of 10 houses were monitored and inspected by the team; the technical inputs were provided by M & E consultant to the beneficiaries to carry forward to reconstruct houses as well as to secure further grant support from the government. Beneficiaries that have nearly completed construction of houses were suggested to proceed for 3rd tranche claim, while beneficiaries who have yet not started the construction were advised to abide by the government’s deadline of reconstructing the house by Chaitra end 2074. The reconstruction in Pikhel and Duwakot are still at slow pace with beneficiaries receiving 1st tranche, whereas in Pokhrel Gaun where almost all the houses were destroyed, about 90% of the beneficiaries have started reconstructed and have inspection conducted for 2nd and 3rd tranches. This type of community oriented towards reconstruction is an example in Changunarayan Municipality.		
Challenges / Issues Identified	Action Required	Responsible	Timeframe
Though majority of households have received 1 st tranche. reconstruction has	Community orientation and awareness program must be	Ward Office, NRA, DLPIU	

still not begun.	conducted in the area to encourage beneficiaries for reconstruction of houses in time. Engineers should also notify the timeframe set by the NRA for those who have already received the 1 st tranche.	Changunarayan Municipality	
There is still lack of orientation in some parts of Changunarayan Municipality regarding the reconstruction, tranche distribution and relevant organization to seek assistance in reconstruction.	DPLIU engineer should find the gap area where reconstruction have not begun and conduct orientation program in such area.	DLPIU-MOUD/NRA	

Photos



Pikhel ward no 5, Changunarayan Municipality, 2 storey load bearing structure. The window frames of the old house have been used. The 2nd tranche request has been forwarded to DLPIU Bhaktapur.



Pokharel gaun, Ward no 4, Changunarayan municipality one storey load bearing structure. Beneficiary have requested for the third tranche.



Pikhel ward no 5, Changunarayan Municipality, 2 storey Load bearing structure. The new house has been joined with the old house. The 2nd tranche request has been forwarded to DLPIU Bhaktapur.



Ward no 1, Changunarayan municipality, load bearing structure completed till plinth level. Beneficiary has received first tranche but the house is missing the vertical reinforcement in the opening sections so correction measures must be applied for the house to

be eligible to receive further tranches.

Housing Typology Report



Ashrang-ward no 6, load bearing structure, Brick in cement mortar and CGI roofing. Beneficiary has received all the tranche. House supported by LWF with implementing partner ICDO.



Ashrang-ward no 6, Load bearing structure, stone in cement mortar. Beneficiary has received all the tranche. House supported by LWF with implementing partner ICDO.



Ghusel-ward no 1, RCC structure with CGI roofing. House supported by LWF with implementing partner Solve Nepal.



Gimdi ward no 7, Load bearing structure, Brick in cement mortar with RC roofing. Beneficiary has received all the tranche. House supported by LWF with implementing partner ICDO.

Challenges and Way Forward

Challenge	Way Forward
Majority of elected ward representatives in Dakshinkali Municipality has a version that actual beneficiaries haven't received 1 st tranche. If this type of case perpetuates, then reconstruction efforts and targets of many agencies is questionable.	→ Placement of elected representatives on board should review this type of issue to facilitate beneficiaries of their wards who have yet not taken 1st tranche. Elected bodies should coordinate with DCC so that DCC will do the data verification of beneficiaries' along with review of housing agreement. If needed, NRA Kathmandu can again conduct the survey for beneficiaries in question. → NRA Kathmandu should mobilize engineers in field frequently to collect such types of cases that is delaying the reconstruction rates.
Beneficiaries has been facing difficulties in acquiring building permit in special types of traditional settlements such as Guthi land, whereby depriving large number of such land-type users away from permanent shelters.	→ To solve issues of Guthi land, beneficiaries should take this issue to concerned District Guthi Corporation Office for reference letter addressed to the concerned municipality for providing the building permit. Further, in special kinds of land types that are causing troubles for beneficiaries to reconstruct houses, request should be taken to people's representatives of municipalities as all concerned agencies should play role in moving the beneficiaries to permanent shelters.