

District Report

Okhaldhunga

April 30 - 4 May 2018


Activity Summary

Activity	Contact Person	Reference Document
4w has been updated and uploaded in the google drive. In 4w this week there is no nay changes	Uttam Parajuli Im.okhaldhunga@hrrpnepal.org	Please click here for 4w
Contac list has been updated and uploaded in the google drive. There is no any change in contact list this week	UttamParajuli Im.okhaldhunga@hrrpnepal.org	Please click here for Contact list
Enrollment Matrix has been updated and uploaded in the google drive.	UttamParajuli Im.okhaldhunga@hrrpnepal.org	Please click here

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
Palika Level meeting at Lekhu Rural municipality and field monitoring visit. Main Discussion point - Reconstruction Status - Challenge and issues on reconstruction - Gap analysis at Palika level - Sharing of HRRP IM tools	7 th May to 9 th May 2018 Lekhu , Molung RM	Prakash Basnet prakash@hrrpnepal.org /Sagar Chandra Adhikari techcord.okhaldhunga@hrrpnepal.org
Genera Coordination Meeting	16 th May 2018 NRA Meeting Hall Okhaldhunga.	Prakash Basnet prakash@hrrpnepal.org /Sagar Chandra Adhikari techcord.okhaldhunga@hrrpnepal.org
To include details of upcoming events and meetings in the next bulletin, please share details with prakash@hrrpnepal.org by COB Wednesday of each week.		

Housing Typology Report (Sankhuwashava)



Chainpur Municipality ward-11, Sankhuwasavha: Lopchan Katwal 2 room Stone Masonry in Mud mortar with Wooden horizontal bands is in under construction Beneficiary has received first tranche and the file for second tranche has been forwarded but still beneficiary he is unknown how and when he could get the tranche. Trained masons are used to construct the house. Lack of technical assistance leads more confusion and slow in construction.



Chainpur Municipality ward-11, Sankhuwasavha : Nagendra Bahadur Katwal 2 room Stone Masonry in Mud mortar with Wooden horizontal bands is in under construction. He followed the design SMC1.1 catalogue provided by NRA. Instead of using cement mortar he used mud mortar. Beneficiary has received first tranche and the file for second tranche has been forwarded.



Chainpur Municipality ward-11, Sankhuwasavha: PAbitra Majhi : Non-Compliance Hybrid Structure ground floor wall of stone in mud mortar. And upper part is open till now. This house has been completed without any technical support 1 year back. Beneficiary has received first tranche and hoping for the second tranche.



Khandbari Municipality ward-8, Sankhuwasavha:Govinda Bahadur Shrestha: Under construction house with Brick in mud-mortar. this house is being constructed under the supervision of NRA field engineer with the help of un trained masons. RCC Bands is provided the opening is ok and it seems Compliance till now. The beneficiary has received the first tranche and waiting for the second tranche.



Khandbari Municipality ward-8, Sankhuwasavha: Govinda Sher Bahadur Katwal: Non Compliance structure constructed with stone in mud mortar in ground floor and sun dried brick in first floor. This house was constructed before technical assistance in the district. He has received first tranche and waiting for the second tranche.



Khandbari Municipality ward-8, Sankhuwasavha: Dilli Rii RCC framed structure having 998sqft plinth area, which is compliance and used 16 nos 12" *12" Columns. The house is three story with underground. The technical person are confusing whether it is compliance or not. The structure is approved from the municipality office .