

District Report

Dhading

6-19 July 2018

Summary of events during this period

Name of activity/event	Event date	Participants summary		Contact Person	Reference Document
		Male	Female		
Market evaluation for price and material quality of hardware items with ADO, TI-N and HRRP.	10 July, 2018	5	0	TI-Nepal	Refer to News and Event section
District Coordination Meeting				HRRP-DC	Link
District Disaster Management Committee meeting Dhading.				DDMC-officer	Link
Joint monitoring field visit with MOUD-CLPIU	2-6 July 2018			HRRP-team & MOUD-CLPIU: M&E	
Coordination with rural/urban municipality regarding verification of probable beneficiaries whose name list having alternative house for resident. The verified copied should be collected and submitted at NRA/GMALI office Dhading.	17-20 July 2018	2	0	HRRP – team	Refer to field visit section

Upcoming Events & Meetings

Name of activity/event	Date, Time, and Location	Organizer	Contact Person
Follow up on NRA vulnerable list.	9-11 July 2018.	HRRP	dc.dhading@hrrpnepal.org
Dissemination of Non-Beneficiary list to Ga.Pa. and Ward offices for dated-signature of beneficiaries.	24-27 July 2018	HRRP	dc.dhading@hrrpnepal.org
District Orientation on NRA 5W	23 rd July, 2018 on 11:00 AM at Hotel Janajibika	HRRP	dc.dhading@hrrpnepal.org

To include details of upcoming events and meetings in the next bulletin, please share details with dc.dhading@hrrpnepal.org by COB Wednesday of each week.

News & Updates

- NRA land support grant of NPR.2 lakhs for victims' of 2015 earthquake. The program is supported by CSRC and PIN at Dhading district. Out of 267 land grant beneficiaries, 163 beneficiaries have received this support from NRA.




Photo: DTO, Er. Rajendra K.C. distributing land certificate to beneficiary

- Market analysis and evaluation through monitoring of prices and material quality of hardware items with DAO, TI-Nepal, media, journalist and HRRP.



On 10 July 2018, district administrative office along with media (radio and television), Transparency Int. Nepal, HRRP and district police office. All hardware shops were inspected and advised to follow actual price rate with less margins. District administrative Office suggested all businessman to keep board showing all item prices so that there is equal market prices among all.



Prices Vs quality of materials were found to be much similar in the market. Some additional costs had to be added by businessman on transportation and delivery of goods.

Field Visit /RM Coordination Meeting

Visit 1

02-06 July, 2018

Thakre ward: , Galchhi ward: &
Gajuri ward: ,Rural Municipality

- Pradip Sharma (HRRP-DTC)
- Prabin Gautam (HRRP-DC)
- Khagendra Awasti (MOUD-CLPIU)

Objective(s)

- Reconstruction Update/ Housing Reconstruction Challenges
- Sharing of Information about Reconstruction to newly elected members
- Interaction between government agencies, implementing partners and local people
- Collection of Typologies of Houses

Summary

- ❖ Reconstruction Update/ Housing Reconstruction Challenges
Joint visit was conducted by HRRP Dhading along with MoUD/ CLPIU Monitoring and Evaluation (Khagendra Awasthi), NRA Engineer (Naresh Bhatta) and NRA District Support Engineer (Rajesh Shrestha). The field visit gave an opportunity to NRA and HRRP to observe, supervise and monitor ongoing construction of Houses (Compliance & Non-Compliance houses) at Thakre, Galchhi & Gajuri Rural Municipality. The number of beneficiaries in Thakre RM are 6384 among them 5980 received the first Tranche while 4100 received the Second tranche while 1501 received the third Tranche and Galchhi RM are 5997 among them 5652 received the first Tranche while 4270 received the Second tranche while 1501 received the third Tranche and Gajuri RM among them 5105 received the first Tranche while 3680 received the Second tranche while 1248 received the third Tranche.
In Thakre Rural Municipality, at bazar area maximum house are RCC Framed Structure building while in rural area we found Load bearing structures. The Constructed houses are Stone Masonry with Cement Mortar, timber framed structure, Mixed the Constructed houses are Stone Masonry with Cement Mortar, timber framed structure, Mixed structure (Stone masonry with mud/ cement mortar in Ground Floor while light materials like CGI Sheet in First Floor, Timber in timber frame/ metal frame structure).

In Galchhi Rural Municipality, at bazar area maximum house are RCC Framed Structure building while in rural area we found Load bearing structures. The Constructed houses are Stone Masonry with Cement Mortar, timber framed structure, Mixed. The Constructed houses are Stone Masonry with Cement Mortar, timber framed structure, Mixed structure (Stone masonry with mud/ cement mortar in Ground Floor while light materials like CGI Sheet in First Floor, Timber in timber frame/ metal frame structure).

In Gajuri Municipality, at bazar area maximum house are RCC Framed Structure building while in rural area we found Load bearing structures. The Constructed houses are Stone Masonry with Cement Mortar, timber framed structure, Mixed structure. Kiranchok VDC is having good Complaints Rate as compared to other VDC in Dhading District.

❖ Some Non-Compliance Cases in Thakre:-

The accounts of 20 beneficiaries were blocked since technical person has forwarded non-compliance buildings for second tranche. These houses are analysed by DSE team and only 3 houses were found to be unsafe and accounts of 17 beneficiaries are unblocked.



Some of the Key points that make Galchhi a good compliant VDC

Easily Availability of Local Material i.e. Stone, Timber, Sand etc.

Availability of Mason, Skilled & Un-skilled manpower.

Skilled Manpower = 1000

Un-Skilled Manpower = 800

Housing Reconstruction Challenges in Thakre and Gajuri:-

- ✓ Water scarcity hindering the construction of buildings at Thakre Vdc
- ✓ NRA lengthy approval process (community buildings, mason trainings, Shelter).
- ✓ Different perception and view of newly elected ward leaders has created obstacles in work as they have high expectation from Partner Organizations (POs).

- ✓ Housing Reconstruction Challenges in Galchhi :-
- ✓ Due to the Poor Coordination between District Administration Office and Crusher, they must travel Gajuri for sand which is a bit more expensive.
- ✓ Very Slow Process from District Forest Office in approval of wood to the beneficiaries.
- ✓ Huge lack of Awareness at local level
- ✓ Door to door technical Assistance is insufficient
- ✓ High expectation of community as well as government agencies.
- ✓ Inconsistency in decision of Government body.
- ✓ NRA lengthy approval process (community buildings, mason trainings, Shelter).
- ✓ Unavailability of government engineers for technical support to beneficiaries at municipalities and rural municipalities.
- ✓ Challenge in transportation of construction materials at most of the areas of Galchhi Vdc.

Sharing of Information about Reconstruction to newly elected members

The visit provided opportunities to share Information to newly elected members & DLPIU Engineers. During the visit, we suggest DLPIU Engineers to make local people aware of using earthquake resilience techniques. We shared soft copy, orient them to use manual. The challenges and reconstruction progress were also shared. VDC wise Enrolment status, District Profile, NRA Policy & guidelines, Info Pack etc. are being shared and discussed with the newly elected members.

Interaction between government agencies, implementing partners and local people

The visit provided opportunities to agencies to raise queries and verify them. Local people also got involved in the interaction and did bilateral talks. During the visit, We suggest local people to use earthquake resilience techniques that are available through NRA and seek help from various organizations working at the locality.

Collection of Typologies of Houses

During the field visit housing typologies of newly constructed and on-going houses were collected. The typologies were collected from (Thakre, Galchhi & Gajuri RM). The major factors affecting the typology of the houses were Availability of Manpower, Social-need Economic conditions, tradition, prevailing condition etc.

Photos



The house located at Galchhi VDC - 07, Dhading Antari Tamang, the house owner, had received first Tranche but not approve for Second Tranche. It is a two storey Load Bearing Building before earthquake but now it's just a one storey with CGI sheet roofing. Key Points: - Stone Masonry in mud mortar Highly damaged No Tie beam, bands etc Flexible roofing	Similar, Manoj Tamang, residence of Kalleri VDC-07, Dhading had received first Tranche and get approved for second tranche too. Key Points: - Load Bearing Structure Tie Beam provided Sill Band Lintel Band Roof Band CGI roofing Proper bonding in junction
	
Ram Badhaur Tamang, residence of Thakre VDC - 07, had constructed a Load Bearing Structure (Block masonry in Cement Mortar). 1 storey building Get 1st tranche Unable to get 2nd tranche	Thulikanchhi Tmang, residence of Galchhi VDC, is complete a Load Bearing Structure (Stone masonry in Cement Mortar. She received first Tranche and gets approved for second tranche too.

Field Visit

Visit 2

17-20 July, 2018	Benighat-Rorang (all wards), Galchi (all wards), Dhunibesi (all wards) and Gajuri RM office.	- Prabin Gautam (HRRP-DC) - Pradip Sharma (HRRP-DTC)
Objective(s)	- Information dissemination on non-beneficiaries list of NRA. - Identification of non-beneficiaries by ward authorities for dated-signature in respective wards. - Sharing of NRA procedures to claim reverification resurvey by beneficiary. - Palika consultation on vulnerable list.	
Summary	All 14 district non-beneficiary list has been published by NRA. These lists consist of those names who were registered through grievance registration process and thus were identified as having dual residential houses. Those beneficiaries who possess more than	

one residential house which has not been damaged by 2015 Gorkha are not eligible to receive any government grant and thus, NRA had identified those households with multiple buildings for residential.

If victims want to go against NRA identified list, he/she can claim through legal court process addressing his/her actual issue. If such claims be found to be a false one, then there will be legal punishment as per court decision.

As per the procedure of NRA, the grievance registered household must receive the information regarding being in a non-beneficiary list. Once it has been informed to beneficiary, he/she must sign at ward office with respective date. The signature date will be used as a legal date to claim for the issue faced through court process. It has been mentioned that the claim must be made within 35 days of received and sign-dated information being non-beneficiary else no claim will be accepted once these 35 days are past.

Rural/urban municipalities were requested to support on verification of most vulnerable list. These beneficiaries will be supported for construction of house from partner organizations in coming days.

HRRP-team orientating Municipality mayor regarding non-beneficiary list of NRA.



Housing Typology Report



Mixed Structure
Stone masonry with mud mortar in Ground floor and CGI Sheet framing in first floor



The picture shows a building constructed before earthquake. Building has no horizontal bands and vertical rebars constructed with stone masonry. The building is still on use since no damage is seen.



RCC Framed Structure(L-shaped) building at Thakre.



RCC Framed Structure building (Column size 9"X12") at Benighat.

Questions Collected

Question	Who Asked the Question?	Response Provided (By Whom)
How can we bound those beneficiaries who have already received government grant even having multiple residential house?	Ward leader	Hope that NRA will formulate more action plan on this regard.
What will be the type of support given to most vulnerable beneficiary?	Ward leader	Reconstruction support for most vulnerable beneficiaries may vary according to their need and capacity of partner organizations. (HRRP)