

Monthly District Report

Kathmandu Valley

15 March – 11 April 2019

Summary of events during this period

Name of activity/event	Event date	Participants summary		Contact Person	Reference Document
		Male	Female		
The general coordination meeting of Lalitpur was organized at DLPIU- GMaLI Lalitpur office. The coordination meeting was attended by officials of DLPIU- GMaLI Lalitpur, POs, staff members of EHRP/DLPIU GMaLI Lalitpur, DLPIU- Education Lalitpur, Patan Durbar Square Monument Protection Office and HRRP. The main objective of the meeting was to discuss on reconstruction status and updates from government and Partner Organization.	18 March 2019	5	12	Ms. Ambika Amatya District Coordinator HRRP Kathmandu Valley dc.ktm@hrrpnepal.org Contact: 9841356409	
HRRP Kathmandu Valley organized half day Orientation on HCB Manual for technical staffs of Bhaktapur district.	19 March 2019	14	41	Ms. Sweeta Sijapati District Technical Coordinator HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org	
DLPIU Building Kathmandu and Lalitpur have organized 2 days Orientation on Resurvey and Reverification of Grievances to engineer working in Municipalities of Kathmandu and Lalitpur district. 2 engineers from each municipality participated in the program.	30 March- 1 April 2019			Er. Chandra Kaji Gurung Senior Division Engineer/ Chief-DLPIU Building Kathmandu and Lalitpur district Contact: 9841576783	
DLPIU Building Bhaktapur have organized 2 days Orientation on Resurvey and Reverification of Grievances to engineer working in Municipalities of Bhaktapur district. 2 engineers from each municipality participated in the program	2 -3 April 2019			Er Mahalaxmi Joshi Senior Division Engineer Chief-DLPIU Building Bhaktapur Contact: 9751090249	
DLPIU Building Kathmandu have organized half day Orientation on Resurvey and Reverification of Grievances to elected local heads and chief administrative officers of Municipalities of Kathmandu district	4 April 2019			Er. Chandra Kaji Gurung Senior Division Engineer/ Chief-DLPIU Building Kathmandu and Lalitpur district Contact: 9841576783	
DLPIU Building Bhaktapur have organized half day Orientation on Resurvey and Reverification of Grievances to elected local heads and chief administrative officers of Municipalities of Bhaktapur district	4 April 2019			Er Mahalaxmi Joshi Senior Division Engineer Chief-DLPIU Building Bhaktapur Contact: 9751090249	
Half day Orientation on Resurvey and Reverification of Grievances to elected local heads and chief administrative officers of Municipalities of Lalitpur district	8 April 2019			Er. Chandra Kaji Gurung Senior Division Engineer/ Chief-DLPIU Building Kathmandu and Lalitpur district	

Summary of events during this period

				Contact: 9841576783	
Joint Monitoring Visit of DLPIU- Building Bhaktapur and HRRP Kathmandu Valley to Changuarayan Municipality was conducted.	10 April 2019	4	5	Ms. Sweata Sijapati District Technical Coordinator HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org	
Testing and Collection of Housing Typology HRRP survey using Mobile App in Bhaktapur district	10 April 2019			Ms. Sweata Sijapati District Technical Coordinator HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org	
Action plan and Palika Profile update of the Municipalities of Kathmandu Valley	15 March- 11 April 2019			Ms. Manisha Rai IM Officer HRRP Kathmandu Valley im.ktm@hrrpnepal.org Contact: 9842062006	
Upload of training database and relevant other information has been updated in 5W.	15 March – 11 April 2019			Ms. Manisha Rai IM Officer HRRP Kathmandu Valley im.ktm@hrrpnepal.org Contact: 9842062006	
Update of the Housing Typology in google drive and HRRP Flickr account	15 March – 11 April 2019			Ms. Sweata Sijapati District Technical Coordinator HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org	
Collection of Transportation/material cost of Kathmandu valley	15 March – 11 April 2019			Ms. Sweata Sijapati District Technical Coordinator HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org	

Upcoming Events & Meetings

Name of activity/event	Date, Time, and Location	Organizer	Contact Person
Half day orientation session on hollow concrete block (HCB) manual for the technical staffs of Kathmandu district.	Status: TBD	HRRP Kathmandu valley team	Ms. Sweata Sijapati District Technical Coordinator HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org
Half day orientation session on hollow concrete block (HCB) manual for technical staffs of Lalitpur district.	Status: TBD	HRRP Kathmandu valley team	Ms. Sweata Sijapati District Technical Coordinator HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org
Follow up for the uploading of the action plan and Palika profile in the municipality's website of Kathmandu, Bhaktapur and Lalitpur district.	12 April – 11 May 2019	HRRP Kathmandu valley team	Ms. Ambika Amatya District Coordinator HRRP Kathmandu Valley dc.ktm@hrrpnepal.org Contact: 9841356409
Joint M & E visit to observe reconstruction efforts of beneficiaries in districts of Kathmandu Valley	12 April – 11 May 2019	HRRP Kathmandu valley team	Ms. Sweata Sijapati District Technical Coordinator HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org

Upcoming Events & Meetings

Municipality level and Ward level Coordination meeting to be conducted by HRRP Kathmandu Valley team in coordination with concerned Municipalities of Kathmandu valley	12 April – 11 May 2019	HRRP Kathmandu valley team	Ms. Ambika Amatya District Coordinator HRRP Kathmandu Valley dc.ktm@hrrpnepal.org Contact: 9841356409
Update of the Housing Typology in google drive and HRRP Flickr account	12 April – 11 May 2019	HRRP Kathmandu valley team	Ms. Sweata Sijapati District Technical Coordinator HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org

News & Updates

- The Resurvey and Reverification of grievances that were unaddressed earlier will be started from 3rd week of April 2019 onwards in Urban and Rural Municipalities of Kathmandu valley. For this, 2 each engineer will be deployed in each Municipality of Kathmandu valley for the resurvey and reverification works. For effective support in resurvey and reverification works, each municipality will conduct a ward level meeting which will further progress in publishing a public notice at Ward level about requesting beneficiaries for submitting grievances for final time.
- DLPIU Building offices of Kathmandu, Lalitpur and Bhaktapur have urged local government bodies to support in providing authentic information on beneficiaries who have registered grievances, whose grievances were not heard and who wants to be listed into earthquake beneficiaries.
- Er. Samar Bahadur Khanal, Chief, DLPIU-Building has been retired and Er. Hari Prasad Ojha has been appointed as the acting chief of GMAI Kathmandu from 21 March 2019.

Tranche Update

Kathmandu Reconstruction Update as of 14 March 2019

Rural /Municipality	Kageshwori NP	Kathmandu MNP	Kirtipur NP	Gokarneshwor NP	Chandragiri NP	Tokha NP	Tarkeshwor NP	Dakshinkali NP	Nagarjun NP	Budhanilkant ha NP	Shankharapur NP
Total HHs Eligible	3667	7496	2935	2935	5695	1746	6151	4085	4338	2693	6058
Total HHs Enrolled	3279	5973	2475	2523	4986	1579	5191	3784	4106	2060	5545
First Tranche	3257	5944	2460	2516	4986	1557	5169	3758	4102	2060	5508
Second Tranche	1718	1378	912	1332	1220	668	1793	1377	1362	986	2472
Third Tranche	967	1378	722	1044	1036	489	1457	874	1071	726	1578
Total HH Constructed	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Grievance Registered	N/A	N/A	1275	1962	1291	369	2493	1096	851	547	1665
Grievance Addressed	N/A	N/A	208	1158	695	335	2186	753	545	308	340
RF HH Eligible	75	173	44	20	128	48	107	52	38	11	110
RF HH Enrolled	23	30	16	7	46	25	33	30	5	2	40
RF 1st Tranche	23	30	16	7	46	25	33	30	5	0	40
RF 2nd Tranche	0	0	0	0	0	0	0	0	0	0	0
Non-Compliance Registered	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Non-Compliance Addressed	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
--------------------------	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----




Bhaktapur Reconstruction Update as of 10 April 2019

Rural /Municipality	Bhaktapur NP	Changunarayan NP	Madhyapur Thimi NP	Suryabinayak NP
Total HHs Eligible	7622	10937	2333	7416
Total HHs Enrolled	5607	9712	2059	6969
First Tranche	5607	9712	2059	6969
Second Tranche	1617	3086	661	2499
Third Tranche	1431	2841	613	2319
Total HH Constructed	N/A	N/A	N/A	N/A
Grievance Registered	1592	2096	2407	1926
Grievance Addressed	1542	1692	1431	1665
RF HH Eligible	148	212	101	233
RF HH Enrolled	42	88	56	101
RF 1st Tranche	42	88	56	101
RF 2nd Tranche	0	0	0	0
Non-Compliance Registered	N/A	N/A	N/A	N/A
Non-Compliance Addressed	N/A	N/A	N/A	N/A



Lalitpur Reconstruction Update as of 18 March 2019

Rural /Municipality	Lalitpur MPC	Godawari UM	Mahalaxmi UM	Mahankal RM	Bagmati RM	Konjyosom RM
Total HHs Eligible	7373	9597	3662	2271	3370	2154
Total HHs Enrolled	6322	7988	3096	2236	3084	2058
First Tranche	6300	7907	3068	2235	3072	2050
Second Tranche	1228	2517	839	1736	2494	1731
Third Tranche	765	1992	690	985	1695	1301
Total HH Constructed	N/A	N/A	N/A	N/A	N/A	N/A
Grievance Registered	3229	2405	927	549	883	927
Grievance Addressed	2296	1777	822	294	713	514
RF HH Eligible	275	325	90	61	252	372
RF HH Enrolled	123	66	21	52	89	257
RF 1st Tranche	117	66	19	51	85	245
RF 2nd Tranche	0	0	0	0	0	0
Non-Compliance Registered	N/A	N/A	N/A	N/A	N/A	N/A
Non-Compliance Addressed						


Graph of Reconstruction Status in Kathmandu as of 14 March 2019:



Bhaktapur Reconstruction Update as of 10 April 2019




RETROFITTING STATUS: BHAKTAPUR DISTRICT




Lalitpur Reconstruction Update as of 18 March 2019


Tranche Status in Lalitpur District



RETROFITTING STATUS: LALITPUR DISTRICT



GRIEVANCE STATUS: LALITPUR DISTRICT



Field Visit /Joint Field Monitoring Visit Reports

Visit 1

Date	Location	Participants from HRRP and stakeholders
------	----------	---

4 April 2019	Ward no 3, 4, 7 Changunarayan Municipality	- Narakanta Sapkota, M & E Consultant, DLPIU NRA Building Kathmandu - Prabesh Adhikari, D.S.E, Bhaktapur - Ramesh Paudyal, MIS Officer, Bhaktapur - Bibha Saiju, Engineer, DLPIU Bhaktapur - Ranjana Suwal, Engineer, DLPIU Bhaktapur - Manisha Rai, IM Officer, HRRP, Kathmandu Valley - Sweata Sijapati, Technical Coordinator, HRRP, Kathmandu Valley
Objective(s)	- To interact with beneficiaries and provide suggestions for correcting the non-complaint structures. - To take case study of vulnerable beneficiaries that have taken up to 1st tranche but not reconstructed houses.	
Summary	HRRP Kathmandu valley team along M & E Consultant from DLPIU NRA Building Bhaktapur conducted joint field monitoring at Ward no 3, 4 and 7 of Changunarayan Municipality, Bhaktapur district. The field visit was mainly focused on the observation of the Non-compliance cases and beneficiaries claiming for the 2nd and 3rd tranches in the area. The visit was accompanied by the DSE who suggested the possible correction measures and way forward to the beneficiaries for being eligible for the tranche. In total 5 houses were visited among which majority of the houses were constructed immediately after the earthquake and found to be unsafe after the structural analysis. Similarly, the other non -compliance case was load bearing structure with missing earthquake resilient elements, Colum size of 9"X12" and so on. Meeting with DLPIU – Building, Bhaktapur A brief meeting with the SDE Mahalaxmi Joshi, Chief, DLPIU – Building Bhaktapur was conducted with an objective of knowing the planned activities for the technical staffs in the district. The orientation related to the resurvey and reverification of the beneficiaries in the district has been successfully conducted and the responsible engineers have been provided with the necessary logistic support. Similarly, a workshop for the local elected representatives of the municipalities and ward offices with an objective to inform them about the grievance collection as well as for their support in the matter was e was also successfully conducted. The resurvey and reverification data collected will be started after the ward level meeting of the engineer and ward representatives will be conducted in the respective municipalities of the district. She also informed that a week-long district wise program to mark the 4th year of the Gorkha Earthquake will be conducted in the district with joint coordination of DLPIUs (GMaLI, Building and Education). The details of the program will be shared in later date. Meeting with DLPIU- GMaLI, Bhaktapur A brief meeting with the Mr. Durba Gaida, Chief, DLPIU- GMaLI was conducted with an objective of knowing the planned activities of GMaLI. He informed that the resurvey and reverification of the grievance has been initiated in the district and GMaLI and Building with support from the local elected representatives are expecting that no earthquake affected people will be left out from getting the government grant. He also informed that the with the initiation of GMaLI- Bhaktapur and support from the Changunarayan Municipality a retention wall will be built in Pokhrel Gaun, Ward no. 4, Changunarayan Municipality. During the rainy season of 2018 the continuous rainfall loosened the soil in the slope which consequently resulted in the landslide on the morning of July 12, 2018. The landslide swept away the part of the hills nearby exposing the house to edge of the	

	hill. Ms. Bhawani Damai whose reconstructed house was on the edge of the hill had been going to ward office, Municipality to request for the support from the government for the implication of the landslide preventive measures in the area. GMaLI Bhaktapur has also visited the site and has noted down the issue. GMaLI chief, Mr. Durba Gaida informed that NRP 170, 000 has been collected from GMaLI and Municipality for the construction of the retention wall in three steps so that the beneficiary who has lost the land during the landslide will also be able to construct the house in the same place. All the necessary procedure has been completed and the construction will begin very soon with the completion target before the rainy season.
--	--

Challenges / Issues Identified	Action Required	Responsible	Timeframe
Many houses constructed immediately after the earthquake are Non-compliance and are difficult to be addressed by the correction measures.	Engineer should collect the data of such houses and try to suggest the correction measure wherever applicable. Details of such cases needs to be reported to the DLPIU and CLPIU building for further analysis. If needed such issues should be taken to NRA for its proper solution.	Ward office, Municipality office, DLPIU Engineers, CLPIU	As soon as possible
Municipality has been approving the design and giving building permit to RC structure with 9"X12" pillar size for 3 storey and more which is found to be unsafe during the structural analysis.	As per MRT the 12"X12" column so Technical staffs of Municipality should not promote such construction practice and disapprove such houses.	Municipality, DLPIU- Building, CLPIU- Building	As soon as possible

Photos



Beneficiary name: Jiban Prasad Pradhan, Duwakot, ward no 2, Changunarayan Municipality, Bhaktapur. 2 and half storey 10 roomed Reinforced Cement Concrete Framed Building (RCC) structure with 9"X12" column. The structure was found to be unsafe by the structural analysis conducted by the DSE. At present the file cannot be forward for the tranche.



Beneficiary name: Pabitra Poudel, Ward no 4, Changunarayan Municipality. 1 storey, 4 roomed Load Bearing Brick and Cement Mortar Masonry structure. The house was listed as non-compliance as the beam, bands and vertical reinforcement were missing in the house. Correction measures such as addition of bands, reinforcements were suggested to the beneficiary. The house was constructed immediately after the earthquake.



Beneficiary name: Shyam Krishna Nepal, Bageshwori, ward no 7, Changunarayan Municipality. 2 storey , 8 roomed structure. The beneficiary claims the structure to be confined masonry with the use of 9"X9" column. The house is not as per the build drawing. The detail of the house couldn't be observed as the house was completed and painted. DLPIU- Bhaktapur will be discussing on the issue and possible measures will be suggested soon.



Beneficiary name: Bhairab Bahadur Thapa, ward no. 4, 1 storey Load Bearing Brick and Cement Mortar Masonry structure. The house was constructed immediately after the earthquake and the earthquake resistant elements such as beam, and bands are missing. The beneficiary also expressed interest in adding another storey to the house. Monitoring team suggested the beneficiary not to do so as the structure will be at risk.

Housing Typology Report



Beneficiary name: Mohan Khadka, Ward no 10, Khadka Gaun, Suryabinayak Municipality. 1 storey load bearing BMC structure with CGI roof. The beneficiary has requested for 2nd and 3rd tranche together at the time of inspection.



Beneficiary name: Suman Pariyar, Ward no. 10, Khadka Gaun, Suryabinayak Municipality. 1 storey RC structure has beam missing during inspection. Beneficiary has received 1st tranche.

Challenges and Way Forward

Challenge	Way Forward
There is likely of rise in disputes among beneficiaries during resurvey and reverification process.	Currently, the resurvey and reverification process as suggested by NRA is for the final time, therefore, the authentic information on beneficiaries as well as the proper damage assessment of the shelters helps in listing the unheard beneficiaries into the mainstream beneficiaries list. Hence, the local government bodies should support NRA and involve actively too by providing reliable information on beneficiaries and their grievances that were unheard during earlier verifications.