

District Report

Ramechhap

22 June - 5 July 2018

Summary of events during this period

Name of activity/event	Event date	Participants summary		Contact Person	Reference Document
		Male	Female		
Light Timber Steel Frame Structure Manual Orientation program was completed on 13th June 2018 in District Technical Office (DTO) meeting Hall, Ramechhap Manthali. The orientation program was targeted to the technical staffs of DLPIU, Rural/Municipality and Partner Organizations who have been working in housing sector in Ramechhap District. The program began with the brief introduction of all participants and resource person. A total of 20 technical personnel were participated from different GON and Non-government organization in the program including District Support Engineer and District Technical office chief. Mr. Krishnalal Piya appreciated HRRP in conducting the program and briefed the need and importance of such programs. Though the timber structures are rare in the district, this program will build the capacity of the technical persons of reconstruction. This program will help the technical persons to implement such structures and study about them in future. If anyone needs technical assistance regarding such structures, the technical person will be able to assist the house owners.	13/04/2018	20	0	Tulasi Ram Lamichhane	click here
District Coordination meeting program was completed in Ramechhap, District on 18th June 2018. A total of 20 persons were participate in the meeting. The participants were from partner organization, DLPIU and Gmali. A Coordination meeting program was chaired by Mr. Krishna lal Piya chief of Gmali/NRA/DTO. In the program all partner organization had presented their progress, update and challenges. Mr. Krishnalal Piya appreciated HRRP in conducting the program and briefed the need and importance of such programs and thanks to all the participants for their presence and support.	18/06/2018	18	2	Prakash Bishwakarma	
Some Highlights of the meeting: ○ Build Change and UNOPS is new partner organization is working in Ramechhap					

Summary of events during this period

district to support in reconstruction. They are working in following fields: - Door to Door visit for technical support. - Community Awareness program regarding earthquake. - Retrofitting training: Coordination with NRA/DLPIU for retrofitting and making coordination to household for retrofitting. - Capacity based training - 2hr package training for local construction worker (mason) - Capacity based training (on the job training) ○ After completion of the earthquake study in the community then only retrofitting work will start. ○ A total of 1296 household was agreement to support from Mediar. Among them 310 households were for financial support. ○ 62 households were fully completed in ward 3 and 6 at Likhu Tamakoshi at Bejulikot. ○ Beside Technical support Mediar also work in Livelihood, Health and Sanitation program in Likhu Tamakhosi Rural Municipality. ○ In coming days MEDIAR is going to organize refresh training for mason. ○ CRCS sustainable project is going to support for 150 identified vulnerable beneficiaries for documentation. ○ Soon they are planning to resettlement the 6 housees of Kasthali village of Umakunda Rural Municipality. ○ Gmail request all partner organization to support Ward level and rural municipality to assessment of vulnerable status. ○ Coordination meeting made decision that partner organization in respective Rural Municipality should support to the Rural municipality and Ward office to collect the data regarding vulnerable stats of the VDC.					
Joint field visit to Gakulganga Rural Municipality (Betani). A total of 4 people were take participant in the joint monitoring visit. The objective of the field visit was to interaction with the beneficiaries in regards to discussion on noncompliance house.	20/06/2018	4	0	Prakash Bishwakarma	

Summary of events during this period


Coordination activity was conducted in Ramechhanp district with an objective to make good relation and coordination among partner organization and government office.	03/07/2018	3	0	Prakash Bishwakarma	
- Short meeting was done with DLPIU-Building chief Praikshit Kadariya in regards to update the status of reconstruction and plan of HRRP in coming month. - Coordination meeting with Gmali Chief and Gmali MIS specialist in regards to the collection the data of Vulnerable. - Coordination with M&E to discussion the field visits.					

Upcoming Events & Meetings

Name of activity/event	Date, Time, and Location	Organizer	Contact Person
Joint monitoring visit to Likhu Tamakhusi Rural Municipality	4 th -6 th July 2018	HRRP/CLPIU M&E	Prakash Bishwakarma
Joint monitoring visit to Gakulganga Rural Municipality	4 th -6 th July 2018		

News & Updates

Reconstruction Status of Ramechhanp District up to 6th Ashard 2075



Field Visit /Joint Field Monitoring Visit Reports

Visit 1

Date	Location	Participants from HRRP and stakeholders
20 th June 2018	Gakulganga Rural Municipality (Bethani)	Prakash Bishwakarma (HRRP), Nimesh Maharjan (DSE), Anil Mahat (DLPIU Engineer), Suresh Shani (VDC Engineer) and Manoj Karki (Asst. Engineer)
Objective(s)	- To observe the reconstruction status of the beneficiaries - To provide inputs to the beneficiaries in regards of housing reconstruction and for grant receive process - Interaction with the local representatives and beneficiaries to find the challenges and issues in the reconstruction.	
Summary	Ramechhap, one of the districts of province number 3 is one of the 14 most earthquake affected districts. It comprises of 6 Rural Municipalities and 2 Municipalities. Among 6 Rural municipalities Gakulganga is one of the rural municipality of Ramechhap district. It is about 45 km far away from the District headquarter, Manthali to the north east. Bethani is one of the village located in the Gokulganga Rural Municipality. The area was severely damaged during the Gorkha Earthquake 2015. The most of the damage houses were of traditional type design mostly of stone in mud mortar. A total of 1287 were beneficiaries in Bethani village. In Bethani almost all beneficiaries who have signed PA agreement have started the reconstruction. The house under construction are mostly of stone in mud and cement mortar as stone locally available. But the availability of other construction materials such as bricks, cement and iron is difficult due to high cost of transportation. One Engineer (Suresh Shahi) and an Assistant Engineer (Manoj karki) have been deployed in the area by DLPIU- Ramechhap. With the effort from the technical person of DLPIU the work and reconstruction rate of the area is very good. The government staffs have been conducting community orientation and door to door technical assistant on regular basis. The continuous effort from them and community people enthusiasm has resulted as a good work and reconstruction rate is found satisfactory. In this regards on 20th June 2018 a joint monitoring visit was successfully completed with an objective to interaction with the beneficiaries and discussion about the challenges and issues regarding reconstruction. A total of 4 persons were participants in the monitoring program from DLPIU and HRRP. <u>Some Highlights from field visit:</u> 33 noncompliance household was made inspection in Bethali village of Gakulgang Rural municipality. - Reconstruction status of the village is as below: - Total beneficiaries: 1287 1st Tranche: 1287 2nd Tranche :1196 3rd Tranche: 676 - The technical person deployed from DLPIU have been monitoring and conducting regular inspection of the houses of different level of reconstruction process and also motivating the noncompliance houses to make correction for the final government grant.	

Challenges / Issues Identified	Action Required	Responsible	Timeframe
33 houses were in noncompliance status	Correction manual should use for the government grant.	House owner /DLPIU engineer / VDC engineer should support for correction	AS soon as possible.

Photos



Participants of Orientation program on light timber/steel frame structures on DTO Hall Manthali.



District Technical Coordinator of Ramechhap presenting the slides of orientation on light timber/steel frame structures



NRA/GMaLI Chief giving his closing remarks on Orientation on Light Timber/ Steel Frame Structures



DLPIU Engineer and HRRP team monitoring the Non-compliant house at Bethani of Gakulganga Rural Municipality.



NRA/DLPIU Engineer inspection a house at ward-8, Bethani Gokulganga Rural municipality.



DSE Mr. Nimesh Maharjan is discussion with house owner at Bethani Ward-8 while monitoring visit.



Discussion at General coordination meeting



Partner Organization participant updating their program to the meeting participants in general coordination meeting.



NRA/Gmaili Chief putting his remarks at District General Coordination meeting



One room house at Bethani Gokulganga Rural Municipality

Housing Typology Report



The house of Sakkal Bahadur Sarki constructed in Gothgaun, Ramechhap-1. The house has been constructed using stone in mud mortar and RCC Bands have been provided. The gable wall was constructed using heavy materials without gable band. After the consultation of the NRA Engineer, the heavy gable wall has been removed and will be replaced by light structures. The house owner has received second tranche of reconstruction grant



The house of Nar Bahadur Sarki constructed in Gothgaun, Ramechhap-1. The house has been constructed using stone in mud mortar and RCC Bands have been provided. The gable wall was constructed using heavy materials without gable band. After the consultation of the NRA Engineer, the heavy gable wall has been removed and has been replaced by light structures. The house owner has received second tranche of reconstruction grant and has been forwarded for the third tranche.



The house of Menuka Sarki constructed in Gothgaun, Ramechhap-1. The house has been constructed using stone in mud mortar and RCC Bands have been provided. The gable wall was constructed using heavy materials without gable band. After the consultation of the NRA Engineer, the heavy gable wall has been removed and has been replaced by light structures. The house owner has received second tranche of reconstruction grant and has been forwarded for third tranche. The external buttress wall has been provided in the house along with the inter partition wall.



The house of Sukamaya Sarki constructed in Gothgaun, Ramechhap-1. The house has been constructed using stone in mud mortar and RCC Bands have been provided. The gable has been constructed using heavy materials without gable band. After the consultation of the NRA Engineer, the house owner has agreed to replace the heavy gable wall by light structures. The house owner has received second tranche of reconstruction grant.



The house of Kalu Sarki constructed in Gothgaun, Ramechhap-1. The house has been constructed using stone in mud mortar and RCC Bands have been provided. The gable wall was constructed using heavy materials without gable band. After the consultation of the NRA Engineer, the heavy gable wall has been removed and has been replaced by light structures. The house owner has received second tranche of reconstruction grant and has been forwarded for the third tranche.



The house of Ros Bahadur Nepali constructed in Gothgaun, Ramechhap-1. The house has been constructed using stone in mud mortar and RCC Bands have been provided. The gable wall has been constructed using heavy materials without gable band. The house owner has received second tranche of reconstruction grant.



The house of Ghamanda Maya Budhathoki constructed in Gothgaun, Ramechhap-1. The house has been constructed using stone in mud mortar and RCC Bands and timber bands combinedly have been provided. The gable wall has been constructed using heavy materials without gable band. The attic height has exceeded three feet. The house owner has received second tranche of reconstruction grant



The house of Top Nath Ghimire constructed in Bethani, Gokulganga-8. The house has been constructed using stone in mud mortar and RCC Bands has been provided. The house is non-compliant because the plinth band has been missed. The house owner has received second tranche of reconstruction.