

Exploring complex normal faulting systems through physics-based dynamic rupture modeling

10-12 min talk!

Hugo S.

Institut de Recherche pour le Développement IRD - ISTerre

O., Scotti, S., Hok, A.-A. Gabriel and T. Taufiqurrahman

ANR EQTIME Project

January 13, 2023

Motivation

Settings

Motivation

Seismic Hazard in Central Italy

IRSN





Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47° . The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the $N210^{\circ}$ segment and the $N155^{\circ}$ fault.



Modified by O. Scotti from Scognamiglio et al. (2018)

Map based on Walker et al. (2021)

Seismic Hazard in Central Italy

IRSN





Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47° . The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the $N210^{\circ}$ segment and the $N155^{\circ}$ fault.



Modified by O. Scotti from Scognamiglio et al. (2018)

Map based on Walker et al. (2021)

Seismic Hazard in Central Italy

IRSN





Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47° . The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.



Modified by O. Scotti from Scognamiglio et al. (2018)

Map based on Walker et al. (2021)

Seismic Hazard in Central Italy

IRSN





Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.




Modified by O. Scotti from Scognamiglio et al. (2018)

Map based on Walker et al. (2021)

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...


In Central Italy:



- Complex normal faulting systems

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...


In Central Italy:



- Complex normal faulting systems
- Potential larger magnitudes?

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...


In Central Italy:



- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...


In Central Italy:



- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?
- Geometry

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...


In Central Italy:



- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?
 - Geometry
 - Stress conditions

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...


In Central Italy:



- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?
 - Geometry
 - Stress conditions
- To enhance SHA!

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...


In Central Italy:



- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?
 - Geometry
 - Stress conditions
- To enhance SHA!


Investigate the physical conditons
promoting rupture jumps across step overs
regarding normal fault systems

Settings



Geometry and parameters explored

IRSN




| Parameter | min | Δ | max |
|-------------|-----|----------|-----|
| Offset (km) | -5 | 2.5 | +5 |

www.seissol.org

(e.g., Wollherr et al., 2018; Ulrich et al., 2019)

Geometry and parameters explored


IRSN



| Parameter | min | Δ | max |
|-------------|-----|----------|-----|
| Offset (km) | -5 | 2.5 | +5 |
| Gap (km) | -5 | 1 | +5 |

www.seissol.org


(e.g., Wollherr et al., 2018; Ulrich et al., 2019)



| Parameter | min | Δ | max |
|-------------|-----|----------|-----|
| Offset (km) | -5 | 2.5 | +5 |
| Gap (km) | -5 | 1 | +5 |
| S | 0.1 | 0.1 | 0.3 |

Geometry and parameters explored

IRSN




www.seissol.org

(e.g., Wollherr et al., 2018; Ulrich et al., 2019)

| Parameter | min | Δ | max |
|---------------------------|-----|----------|-----|
| Offset (km) | -5 | 2.5 | +5 |
| Gap (km) | -5 | 1 | +5 |
| S | 0.1 | 0.1 | 0.3 |
| SH_{max} ($^{\circ}$) | 330 | 10 | 350 |

Geometry and parameters explored


IRSN



www.seissol.org

(e.g., Wollherr et al., 2018; Ulrich et al., 2019)

| Parameter | min | Δ | max |
|----------------------------|-----|----------|-----|
| Offset (km) | -5 | 2.5 | +5 |
| Gap (km) | -5 | 1 | +5 |
| S | 0.1 | 0.1 | 0.3 |
| SH_{\max} ($^{\circ}$) | 330 | 10 | 350 |



References

References

- Bai, K. and Ampuero, J.-P. (2017). Effect of seismogenic depth and background stress on physical limits of earthquake rupture across fault step overs. *Journal of Geophysical Research: Solid Earth*, 122(12):10–280.
- Galis, M., Pelties, C., Kristek, J., Moczo, P., Ampuero, J.-P., and Mai, P. M. (2015). On the initiation of sustained slip-weakening ruptures by localized stresses. *Geophysical Journal International*, 200(2):890–909.
- Hu, F., Zhang, Z., and Chen, X. (2016). Investigation of earthquake jump distance for strike-slip step overs based on 3-d dynamic rupture simulations in an elastic half-space. *Journal of Geophysical Research: Solid Earth*, 121(2):994–1006.
- Li, G. and Liu, Y. (2020). Earthquake rupture through a step-over fault system: An exploratory numerical study of the leech river fault, southern vancouver island. *Journal of Geophysical Research: Solid Earth*, 125(11):e2020JB020059.
- Oglesby, D. (2008). Rupture termination and jump on parallel offset faults. *Bulletin of the Seismological Society of America*, 98(1):440–447.
- Scognamiglio, L., Tinti, E., Casarotti, E., Pucci, S., Villani, F., Cocco, M., Magnoni, F., Michelini, A., and Dreger, D. (2018). Complex fault geometry and rupture dynamics of the mw 6.5, 30 october 2016, central italy earthquake. *Journal of Geophysical Research: Solid Earth*, 123(4):2943–2964.
- Ulrich, T., Vater, S., Madden, E. H., Behrens, J., van Dinther, Y., Van Zelst, I., Fielding, E. J., Liang, C., and Gabriel, A.-A. (2019). Coupled, physics-based modeling reveals earthquake displacements are critical to the 2018 palu, sulawesi tsunami. *Pure and Applied Geophysics*, 176(10):4069–4109.
- Walker, J., Boncio, P., Pace, B., Roberts, G., Benedetti, L., Scotti, O., Visini, F., and Peruzza, L. (2021). Fault2sha central apennines database and structuring active fault data for seismic hazard assessment. *Scientific data*, 8(1):1–20.
- Wollherr, S., Gabriel, A.-A., and Uphoff, C. (2018). Off-fault plasticity in three-dimensional dynamic rupture simulations using a modal discontinuous galerkin method on unstructured meshes: implementation, verification and application. *Geophysical Journal International*, 214(3):1556–1584.