Exploring complex normal faulting systems through physics-based dynamic rupture modeling

10-12 min talk!

Hugo S.

Institut de Recherche pour le Développement IRD - ISTerre

O., Scotti, S., Hok, A.-A. Gabriel and T. Taufiqurrahman

ANR EQTIME Project

January 17, 2023

Outline

Motivation

Settings

Results

Conclusions

Motivation

Seismic Hazard in Central Italy



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

Modified by O. Scotti from Scognamiglio et al. (2018)



Map based on Walker et al. (2021)

Seismic Hazard in Central Italy



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

Modified by O. Scotti from Scognamiglio et al. (2018)



Map based on Walker et al. (2021)

Seismic Hazard in Central Italy



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

Modified by O. Scotti from Scognamiglio et al. (2018)



Map based on Walker et al. (2021)

Seismic Hazard in Central Italy



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

Modified by O. Scotti from Scognamiglio et al. (2018)



Map based on Walker et al. (2021)

Rupture jumps across step-overs

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...

Rupture jumps across step-overs

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

In Central Italy:

- Complex normal faulting systems

Rupture jumps across step-overs

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

In Central Italy:

- Complex normal faulting systems
- Potential larger magnitudes?

Rupture jumps across step-overs

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

In Central Italy:

- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?

Rupture jumps across step-overs

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

In Central Italy:

- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?
  - Geometry

Rupture jumps across step-overs

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

In Central Italy:

- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?
  - Geometry
  - Stress conditions

Rupture jumps across step-overs

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

In Central Italy:

- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?
  - Geometry
  - Stress conditions
- To enhance SHA!

Rupture jumps across step-overs

Previous studies focused on strike-slip fault systems: Galis et al. (2015); Hu et al. (2016); Bai and Ampuero (2017); Li and Liu (2020); Oglesby (2008), and more ...



Figure 11. Comparison between the slip distributions imaged on the VBFS fault during the 24 August (red contours; Tinti et al., 2016) and the 30 October 2016 main shocks (blue contours; this study) projected on the same fault striking 155° and dipping 47°. The red and blue stars are the two main shocks hypocentral locations. The black line is the intersection of the N210° segment and the N155° fault.

In Central Italy:

- Complex normal faulting systems
- Potential larger magnitudes?
- Conditions promoting this?
  - Geometry
  - Stress conditions
- To enhance SHA!

Investigate the physical conditons promoting rupture jumps across step overs regarding normal fault systems

Settings

Geometry and parameters explored



Stress-Strength dimensionless ratio

$$S = \frac{\tau_p - \tau_0}{\tau_0 - \tau_r}$$

158 Simulations

Parameter	min	Δ	max

Simulations using: www.seissol.org

linear slip weakening law

(e.g., Wollherr et al., 2018; Ulrich et al., 2019)

Geometry and parameters explored



Stress-Strength dimensionless ratio

$$S = \frac{\tau_p - \tau_0}{\tau_0 - \tau_r}$$

158 Simulations

Parameter	min	Δ	max
Offset (km)	-5	2.5	+5

Simulations using: www.seissol.org

linear slip weakening law

(e.g., Wollherr et al., 2018; Ulrich et al., 2019)

Geometry and parameters explored



Stress-Strength dimensionless ratio

$$S = \frac{\tau_p - \tau_0}{\tau_0 - \tau_r}$$

158 Simulations

Parameter	min	Δ	max
Offset (km)	-5	2.5	+5
Gap (km)	-5	1	+5

Simulations using: www.seissol.org

linear slip weakening law

(e.g., Wollherr et al., 2018; Ulrich et al., 2019)

Geometry and parameters explored



Stress-Strength dimensionless ratio

$$S = \frac{\tau_p - \tau_0}{\tau_0 - \tau_r}$$

158 Simulations

Parameter	min	Δ	max
Offset (km)	-5	2.5	+5
Gap (km)	-5	1	+5
S	0.1	0.1	0.3

Simulations using: www.seissol.org

linear slip weakening law

(e.g., Wollherr et al., 2018; Ulrich et al., 2019)

Geometry and parameters explored



Stress-Strength dimensionless ratio

$$S = \frac{\tau_p - \tau_0}{\tau_0 - \tau_r}$$

Simulations using: www.seissol.org

linear slip weakening law

(e.g., Wollherr et al., 2018; Ulrich et al., 2019)

158 Simulations

Parameter	min	Δ	max
Offset (km)	-5	2.5	+5
Gap (km)	-5	1	+5
S	0.1	0.1	0.3
SH_{max} (^{o})	330	10	350

Geometry and parameters explored



Stress-Strength dimensionless ratio

$$S = \frac{\tau_p - \tau_0}{\tau_0 - \tau_r}$$

Simulations using: www.seissol.org

linear slip weakening law

(e.g., Wollherr et al., 2018; Ulrich et al., 2019)

158 Simulations

Parameter	min	Δ	max
Offset (km)	-5	2.5	+5
Gap (km)	-5	1	+5
S	0.1	0.1	0.3
SH_{max} (^{o})	330	10	350

Initial stress & medium velocity model

Initial stress state



τ_{dip}=10.7 MPa ,
P_n =5.6 MPa



On the faults:

μ_s=0.6

μ_d=0.4



Velocity structure from Herrmann et al. (2011).

Static analysis ... jump? break-away?



Are jumps and breakaway behavior prone to happen in both cases?

Is a static analysis enough to determine such behaviors?

Static analysis:
Both cases might break!

Results

Results ... summary from 158 simulations



Results ... summary from 158 simulations



Let's see in detail some results at

a given offset ... at offset $= -2.5$ km ($\frac{1}{4}$ overlaped)

Results: Hangig/foot wall Asymmetric behavior



Cases:

● jump & break-away

○ jump & arrested

◐ no jump

Results: Hangig/foot wall Asymmetric behavior



Hanging/foot wall Asymmetry



Cases:

- ● jump & break-away
- ○ jump & arrested
- ◐ no jump

Results: Hangig/foot wall Asymmetric behavior



Cases:

● jump & break-away ○ jump & arrested

◐ no jump

Hanging/foot wall Asymmetry



☞ **Hanging/foot wall asymmetry:**

When the 2nd fault is on the hanging wall (Gap < 0), the rupture is more likely to

- be triggered
- be sustained

Results: Stress shadow ☞ expected magnitudes



Cases:

● jump & break-away ○ jump & arrested

◐ no jump

Results: Stress shadow ☞ expected magnitudes



Cases:

- ● jump & break-away
- ○ jump & arrested
- ◐ no jump

Proximity VS magnitude



Results: Stress shadow ☞ expected magnitudes



Cases:

- ● jump & break-away
- ○ jump & arrested
- ◐ no jump

Proximity VS magnitude



☞ **Stress shadow:**

The final energy released (M_w proxy) increases/decreases according to the distance between faults.

Results: Stress shadow ☞ expected magnitudes



Cases:

- ● jump & break-away
- ○ jump & arrested
- ◐ no jump

Proximity VS magnitude



☞ **Stress shadow:**

The final energy released (M_w proxy) increases/decreases according to the distance between faults.

The closer $\longrightarrow$ rupture jump

Results: Stress shadow ☞ expected magnitudes



Cases:

- ● jump & break-away
- ○ jump & arrested
- ◐ no jump

Proximity VS magnitude



☞ **Stress shadow:**

The final energy released (M_w proxy) increases/decreases according to the distance between faults.

The closer $\longrightarrow$ rupture jump

The closer $\longrightarrow$ less magnitude

Special case: offset −2.5 km, gap ±5.0 km



Special case: offset -2.5 km, gap ± 5.0 km



Special case: offset −2.5 km, gap ±5.0 km



Special case: offset -2.5 km, gap ± 5.0 km



Special case: offset -2.5 km, gap ± 5.0 km

Special case: offset -2.5 km, gap ± 5.0 km



Special case: offset -2.5 km, gap ± 5.0 km



Special case: offset −2.5 km, gap ±5.0 km



Special case: offset -2.5 km, gap ± 5.0 km



Special case: offset -2.5 km, gap ± 5.0 km

Last snapshot: Rupture occured for both cases,
but with different behaviors



Conclusions & discusion

Conclusion & discusion

To sum up:

Conclusion & discusion

To sum up:

- ☞ Static analyses seem to be insufficient to precisely determine a rupture jump and beak-away behaviors.

To sum up:

- ☞ Static analyses seem to be insufficient to precisely determine a rupture jump and beak-away behaviors.
- ☞ It is necessary to have an enough large area where ΔCFF$>$0 to ensure a sustained rupture after it jumped across the step-over.

To sum up:

- ☞ Static analyses seem to be insufficient to precisely determine a rupture jump and beak-away behaviors.
- ☞ It is necessary to have an enough large area where ΔCFF$>$0 to ensure a sustained rupture after it jumped across the step-over.
- ☞ Behaviors such as “stress shadow” and ”asymmetric response” were observed as for strike-slip faults.

To sum up:

- ☞ Static analyses seem to be insufficient to precisely determine a rupture jump and beak-away behaviors.
- ☞ It is necessary to have an enough large area where ΔCFF$>$0 to ensure a sustained rupture after it jumped across the step-over.
- ☞ Behaviors such as “stress shadow” and ”asymmetric response” were observed as for strike-slip faults.
- ☞ The 2nd fault rupture seems to be dynamically triggered by the strong stopping phase arriving from behind.

To sum up:

- ☞ Static analyses seem to be insufficient to precisely determine a rupture jump and beak-away behaviors.
- ☞ It is necessary to have an enough large area where ΔCFF$>$0 to ensure a sustained rupture after it jumped across the step-over.
- ☞ Behaviors such as "stress shadow" and "asymmetric response" were observed as for strike-slip faults.
- ☞ The 2nd fault rupture seems to be dynamically triggered by the strong stopping phase arriving from behind.
- ☞ Using this configuration, 5 km seems to be the largest distance that the rupture can jump, considering very high stress levels and favorable physical conditions.

Thank you for listening!

Questions?

References

References

Bai, K. and Ampuero, J.-P. (2017). Effect of seismogenic depth and background stress on physical limits of earthquake rupture across fault step overs. *Journal of Geophysical Research: Solid Earth*, 122(12):10–280.

Galis, M., Pelties, C., Kristek, J., Moczo, P., Ampuero, J.-P., and Mai, P. M. (2015). On the initiation of sustained slip-weakening ruptures by localized stresses. *Geophysical Journal International*, 200(2):890–909.

Hu, F., Zhang, Z., and Chen, X. (2016). Investigation of earthquake jump distance for strike-slip step overs based on 3-d dynamic rupture simulations in an elastic half-space. *Journal of Geophysical Research: Solid Earth*, 121(2):994–1006.

Li, G. and Liu, Y. (2020). Earthquake rupture through a step-over fault system: An exploratory numerical study of the leech river fault, southern vancouver island. *Journal of Geophysical Research: Solid Earth*, 125(11):e2020JB020059.

Oglesby, D. (2008). Rupture termination and jump on parallel offset faults. *Bulletin of the Seismological Society of America*, 98(1):440–447.

Scognamiglio, L., Tinti, E., Casarotti, E., Pucci, S., Villani, F., Cocco, M., Magnoni, F., Michelini, A., and Dreger, D. (2018). Complex fault geometry and rupture dynamics of the mw 6.5, 30 october 2016, central italy earthquake. *Journal of Geophysical Research: Solid Earth*, 123(4):2943–2964.

Ulrich, T., Vater, S., Madden, E. H., Behrens, J., van Dinther, Y., Van Zelst, I., Fielding, E. J., Liang, C., and Gabriel, A.-A. (2019). Coupled, physics-based modeling reveals earthquake displacements are critical to the 2018 palu, sulawesi tsunami. *Pure and Applied Geophysics*, 176(10):4069–4109.

Walker, J., Boncio, P., Pace, B., Roberts, G., Benedetti, L., Scotti, O., Visini, F., and Peruzza, L. (2021). Fault2sha central apennines database and structuring active fault data for seismic hazard assessment. *Scientific data*, 8(1):1–20.

Wollherr, S., Gabriel, A.-A., and Uphoff, C. (2018). Off-fault plasticity in three-dimensional dynamic rupture simulations using a modal discontinuous galerkin method on unstructured meshes: implementation, verification and application. *Geophysical Journal International*, 214(3):1556–1584.