AI & COMPUTER-VISION BASED SURFACE & PRODUCT DEFECT INSPECTION


Automated Quality Inspection Report

Inspection ID:	DEF-2026-0318	**Date & Time:**	2026-11-02 13:50:24
Product / Part:	Unnamed Product	**Batch / Lot:**	-
Product Line:	GENERAL MANUFACTURED	**Station:**	Line 1 · Final QC
Inspector:	Line Supervisor	**Outcome:**	**REVIEW**

DEFECT SUMMARY

Defect Type	Count	Critical	High	Medium	Low
Scratch	1	0	0	1	0

ANNOTATED VISUAL EVIDENCE



DETECTION LOG

#	Type	Severity	Confidence	Location (px)	Detector	Review
1	Scratch	**MEDIUM**	77%	252,441 - 424,759	YOLO_SEG +ANOMALY	CONFIRMED

ROOT-CAUSE HINTS

Scratch (1)
• Abrasive contact during conveyor transfer or manual handling
• Burrs or debris on guide rails, fixtures, or tooling
• Insufficient protective film / interleaving between stacked parts
→ Inspect and deburr guide rails, grippers, and transfer chutes
→ Add protective film or separators at stacking and packing stations

DETERMINATION & SIGN-OFF

Inspector Remarks: Defect inspection reviewed and signed off by quality inspector

---

Analysed by: Defect Inspection Engine (YOLO_SEG+ANOMALY)

Quality Sign-off:
_____