

Fig. 1. Collecting data schematics




Fig. 2. Comparative graphic image of ESP8266 module signal gain

TABLE I. RECOVERY TIME DATA RETRIEVAL

Environment	Recovery Time (Second)
Without Obstacle	5
With a 0.5 cm thick glass barrier	7.9
With Floor Differences	8

TABLE II. MESH DATA RETRIEVAL WITH WALL OBSTACLES

Total Client Node	Maximum Transmission Distance (Meters)	Environmental conditions
1	8	With Wall Barriers
2	16	
3	24	
4	30	
5	37	

TABLE III. SYSTEM LATENCY AND JITTER EXPERIMENT

Total Client Node	Average Latency (ms)	Jitter (ms)
-------------------	----------------------	-------------

1	3.13	0.0714
2	7.20	0.0357
3	9.23	0.178
4	9.27	0.1428



Fig. 3. Front view of the client node



Fig. 4. Overall client node view



Fig. 5. Overall system view