

a
CHINA
NEPAL
INDIA
Rasuwagadhi
Flood source
20 km
c
Syabrubesi
40 km
GORKHA
RASUWA
d
60 km
Betrawati
e
DHADING
NUWAKOT
Bidur
80 km
160 km
140 km
Malekhu
120 km
100 km
0
10
20 km
28°15'N
28°00'N
27°45'N
84°45'E
85°00'E
85°15'E
85°30'E
Flood inundation
Flood source
Distance from source, every 20 km
Towns
Hydropower structure damaged
Bridge washed away
Bridge damaged
Inset areas (panels c-e)
District boundaries
Hillshade: Copernicus DEM GLO-30.
b
Flood arrival times in Nepal Time (UTC+05:45)
source
Rasuwagadhi 08:44
Syabrubesi 08:50
Betrawati 09:24
Bidur 09:38
Devighat
Malekhu
Mugling
Elevation (m)
4000
2000
0
Buildings in flood inundation (per 5 km)
1,129
1000
500
0
6,012 buildings
Road length (km per 5 km)
20
10
0
Highways & main roads
Local roads & tracks
Within 100 m of flood inundation
108 km in flood inundation (31 km main) +185 km within 100 m
Hydropower
13 hydropower structures
Bridges
78 bridges washed away or damaged
0
20
40
60
80
100
120
140
160
Distance from source along the flow path (km)
Hydropower structure damaged
Bridge washed away (65)
Bridge damaged (13)
Bridge intact (28)
No information (12)
c Rasuwagadhi–Timure (18–26 km)
20 km
Rasuwagadhi
Rasuwagadhi
Timure
25 km
0
0.5
1 km
Vantor WorldView-3, 27 Aug 2026
d Upper Trishuli hydropower (51–64 km)
Upper Trishuli-1
Mailun Khola
Upper Trishuli-3A
55 km
Ghale Gaun
Upper Trishuli-3A
60 km
Trishuli 3B Hub Substation
0
1
2 km
Upper Trishuli-3B DAM
Sentinel-2, 21 Sep 2026
e Trishuli–Bidur (67–80 km)
Trishuli-DAM
70 km
Trishuli Bazaar
75 km
Trishuli-Powerhouse
Bidur
Devighat
0
1
2 km
Vantor WorldView-2, 8 Sep 2026
Flood inundation
Road in flood inundation
Bridge washed away
Distance from source (km)
Building in flood inundation
Hydropower structure damaged
Bridge damaged