

c Rasuwagadhi–Timure, km 18–26
20 km
Rasuwagadhi
Rasuwagadhi
Timure
25 km
0 0.5 1 km
Vantor WorldView-3, 27 Aug 2026
d Upper Trishuli hydropower, km 51–64
Upper Trishuli-1
Mailun Khola
Upper Trishuli-3A
55 km
Ghale Gaun
Upper Trishuli-3A
60 km
Trishuli 3B Hub Substation
Upper Trishuli-3B DAM
0 1 2 km
Sentinel-2 (Copernicus), post-event, Aug-Oct 2026
e Trishuli–Bidur, km 67–80
Trishuli-DAM
70 km
Trishuli Bazaar
Trishuli-Powerhouse
75 km
Bidur
Devighat
0 1 2 km
Vantor WorldView-2, 8 Sep 2026
Flood inundation
Road in flood inundation
Bridge destroyed, washed away
Distance from source (km)
Building in flood inundation
Hydropower structure, fully damaged
Bridge damaged, needs repair