
c
d
e
source
Rasuwagadhi 08:44
Syabrubesi 08:50
Betrawati 09:24
Bidur 09:38
Devighat
Malekhu
Mugling
Elevation (m)
4000
2000
0
Buildings in flood zone (per 5 km)
1,521 at km 65-70
1000
0
6,012 buildings
Road length (km per 5 km)
Highways & main roads
Local roads & tracks
Within 100 m of flood edge
20
10
0
145 km in zone (46 km main) +163 km within 100 m
Hydropower
13 hydropower structures
Bridges
78 bridges destroyed or damaged
0
20
40
60
80
100
120
140
160
Distance from source along the flow path (km)
Hydropower structure, fully damaged
Bridge destroyed (65)
Bridge damaged (13)
Bridge intact (28)
No information (12)